



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDL 5141H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R/F WHEEL ALLOY (CONSISTENT) (WCP)	CUT	530.00	530.00
1	R/F WHEEL HUB (CONSISTENT) (WCP)	NOT NECESSARY	850.00	-
1	R/F WING (CONSISTENT) (WCP)	BENT	440.00	440.00
1	R/F WING BADGE (CONSISTENT) (WCP)	NECESSARY	35.00	35.00
1	R/F WING MOULDING (CONSISTENT) (WCP)	NECESSARY	45.00	45.00
	COST PLUS 15%		285.00	157.50
			2,185.00	1,207.50
	<u>LABOUR</u>			
	PANEL /MECHANICAL .		207.00	207.00
	PAINTWORK.		220.50	220.50
	VISUAL ALIGNMENT WORK.		99.00	99.00
	PAINT/MATERIAL COSTS.		67.30	67.30
			593.80	593.80
	GRAND TOTAL		2,778.80	1,801.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CC4/ASM18019414/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.