

REF:

2200F

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No.

FBE 7205G

at Workshop m/s

Southern Motor

of

1006, BM LN 2 # 61-16

Insured:

FCI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBE 7205G

Yr Regn

2010

Type: M/Car ☒ M/Cycle ☐ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA 427 R15

C.C.

150

Colour

GREEN

A/C:

Insured / Std / NI / NA

Sp. Reading:

099321

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ME120P022A 2005 755

Gen. Cond: Good ☒ Fair ☐ Poor ☐ BurntSteering: In order ☒ Jammed ☐ Leaked ☐ Burnt orBrake: In order ☒ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☒ Rim ☐ STD A/Rim or

Tyre Size:

F:

70/90-17

R:

80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR (SUMI /

TOYO / YOKO or

VUELTA

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/10/18

D.O.I.

25/10/18

Survey held at

Southern Motor

Des. of Damages: Frt ☒ Rear ☒ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 14 JAN 2019

02/04/19 Re-open for finalise (closed) 02/04/19

04/04/19 Confirmed L/S \$1,500/- @ 4 days with Resv 1
(\$430.20 Red. 33%)

File pass to typist after re-open.

Date/Time, File Pass to?

04/04/19



Preli. Report



Final Report

1)

Typist

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

1,500/- L/S

110

50

52

212

Shirley Hiew (LKK Auto)

From: Southern Motor <soumotor@hotmail.com>
Sent: Tuesday, 2 April 2019 3:42 PM
To: Rasul (LKKAuto)
Subject: Re: FBE 7205E DOA : 11/10/18

Dear Mr Rasul,

We confirm the finalised amount
for \$1500.00 at 4days lump sum

Thank you

From Southern Motor

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Tuesday, April 2, 2019 11:28 AM
To: soumotor@hotmail.com
Cc: Shirley Hiew (LKK Auto)
Subject: FBE 7205E DOA : 11/10/18

Hi Mr Lim,

Refer to attachment
Finalised amount is \$ 1,500.00 / 4 days lump sum
Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



南方摩哆 SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730309 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 14th October 2018

Motor Claims Department

First Capital Insurance Ltd
36 Robinson Rd #16-01 City House
Singapore 068877

Dear Sirs

Re: Cost of repair for Yamaha YZF-R15 - RE720SE

1 pc of Front mudguard - repair	PR	75.00	
" Front fairing - scd		230.00	
" Centre fairing - scd		110.00	
" Centre fairing cap - scd		85.00	
" Side box - scd		80.00	
" Exhaust pipe cover - scd		160.00	1333
" Brake pedal - scd		65.00	10%
" Signal light - scd		45.00	
" Mirror - scd		70.00	1199.70
" Top brake pump - scd		120.00	
" Brake lever - Bro		15.00	
" Front fairing bracket - ? XSWC		125.00	
" Handle bar PA		85.00	
" Radiator cover - dx		140.00	
" Hand phone holder - PA		65.00	
		1,525.00	
		152.80	
		1,677.80	

Resul
Hp 9001068
4 days
45

Trans 10%

Net

Alignment fork
spray painting
1. u

Labour

850 60
3,500 250
1,600 scd
2,150 180
2,330.00

LKK Auto Consultants hereby acknowledge the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for repair
- Parts prices are subject to confirmation
- The repair is carried out without Prejudice
- Yours faithfully, **SOUTHERN MOTOR**
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Email: motorclaims@firstcapital.com.sg

Tel 65072848

Fax 65072849

Oct 24 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18019428/R1sd3s2

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 14-01-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6226X	Veh. Inspected	FBE 7205E
Policy No.		Coverage (\$)	0.00
Claim No.	D18007462MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	24/10/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA YZF R15	c.c	150
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	ME120P022A2005755	Colour	GREY
Odometer	099321	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	VUELTA	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	VUELTA	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/10/2018	Inspection Date	25/10/2018
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 7205E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGAURD	TO REPAIR SEE LABOUR	75.00	-
1	FRONT FAIRING	SCRATCHED	220.00	220.00
1	CENTRE FAIRING	SCRATCHED	110.00	110.00
1	CENTRE FAIRING CAP	SCRATCHED	85.00	85.00
1	SIDE BOX	SCRATCHED	80.00	80.00
1	EXHAUST PIPE COVER	SCRATCHED	160.00	160.00
1	BRAKE PEDAL	SCRATCHED	65.00	65.00
1	SIGNAL LIGHT	SCRATCHED	45.00	45.00
1	MIRROR	SCRATCHED	70.00	70.00
1	TOP BRAKE PUMP	SCRATCHED	180.00	180.00
1	BRAKE LEVER	BROKEN	15.00	15.00
1	FRONT FAIRING BRACKET	SERVICEABLE	125.00	-
1	HANDLE BAR	BENT	93.00	93.00
1	RADIATOR COVER	DEFORMED	140.00	140.00
1	HAND PHONE HOLDER	BENT	65.00	65.00
	LESS 10% DISCOUNT		-152.80	-132.80
			1,375.20	1,195.20
	<u>SPECIAL NETT ITEMS</u>			
1	I.U (SN)	SCRATCHED	165.00	165.00
			165.00	165.00
	<u>LABOUR</u>			
	ALIGNMENT FORK.		90.00	60.00
	SPRAY PAINTING.		350.00	250.00
	LABOUR, INCLUSIVE OF THE REPAIR OF FRONT MUDGAURD.		250.00	180.00
			690.00	490.00
	GRAND TOTAL		2,230.20	1,850.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00



Report Ref No. CS/FCI18019428/R1sd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.