



Your Ref : S8M00X66

Date: 14<sup>th</sup> December 2018

Our Ref : CS/ASM18019433/Nqd3s2

**M/s AXA Insurance Pte Ltd**  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: CB 6956G  
ACCIDENT ON 08/09/2018**

Instruction was received to inspect the vehicle Reg. No. CB 6956G. The inspection was conducted on 25/10/2018 at the premises of M/s UCB Engineering Pte Ltd, 2C Jalan Pesawat, Jurong, Singapore 619359.

The following vehicle information was recorded:

Registration Number	: CB 6956G
Make/Model	: Zhong Tong LCK6107H
Year of Registration	: 2012
Body Colour	: Multi Colour
Chassis Number	: LDY6KS9D8B0004831
Engine Capacity	: 6693 cc

The vehicle sustained damages at the n/s, o/s centre portion and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	40,000.00
Less: LTA Reimbursement Value (RV)	(S\$	0.00)
Nett Liability	S\$	40,000.00

Vehicle Inspected By:



MUHD NAZRIL (NAZ)

Technical Investigator

LL.B. (Hons) London



K.K. LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),

AM CATARI(CAN), M. MATA(USA), M. Mdata(USA),

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.