

REF:

CT1

TAX/10/18/2086

Assignment: NA2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 711B Yr Regn: 12 SEP 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS C.C. 1,798

Colour: MAROON A/C: Insur. d / Std / NI / NA

Sp. Reading: 470,682 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN364705748463

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles (F) Foker (R)

Front Rear

R/Bal. 5 mm R/Bal. 6 mm

L/Bal. 5 mm L/Bal. 6 mm

D.O.A. 23/10/18 D.O.I. 23/10/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45 \$2,200.00
CROW: \$4,097.16 (65%)

Date/Time, File Pass to? ☐ : Preli: Report

☐ : Final Report

1) Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I. (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS \$ _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18019449/Nwb3

Date: 25.10.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB711B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.10.2018 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,297.16
Revised Estimate Amount	: S\$	2,046.89
"Check" Items Amount	: S\$	991.57
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. NAZRIL
Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18019449/Nwb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 25-10-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 4741M	Veh. Inspected	SHB 711B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	25/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/10/2018	Inspection Date	23/10/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Case Details

Case Reference Number : TAX/10/18/2086

Type of Repair : Accident Repair

Vehicle Registration Number : SHB711B

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4265-ID

Assigned By : Kok Wah Wong

Insurance Company Name : China Taiping

Insurance (Singapore) Pte Ltd

Accident Date and Time : 21/10/2018 10:25 PM

Vehicle Age(In Months) : 49

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace MIS
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace NEL
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace MIS
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace NEL
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace MIS
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace MIS
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace MIS
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace NEL
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace NEL
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace CRK
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Giv X SVL
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check ?
One Time Key In	Main			STOPPER, REAR BUMPER, UPPER	2	4.10	8.20	25.00	6.15	Replace	0	0	Check ?
Total Spare Part Cost									3,558.16		Surveyor Total	1,186.89	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									2,846.53		Final Sur Total	949.51	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Giv
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Giv
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Giv
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Giv
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Giv
Total Spare Part Cost									3,558.16		Surveyor Total	1,186.89	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									2,846.53		Final Sur Total	949.51	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	845.00	400	
Total:		845.00	400.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY REAR FENDER LH	378.00	200	
2	TO RESPRAY REAR FENDER RH	378.00	0	NN
3	TO REPSRAY REAR BUMPER	378.00	200	
Total:		1,134.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	NN
5	TO REPLACE SUNDRY PARTS	100.00	0	NN
6	TO WASH AND VACUUM	60.00	0	NN
Total:		760.00	60.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,846.53	949.51
Total Labour Cost	0.00	400.00
Total Spray Painting	0.00	400.00
Other	0.00	60.00
Overall Total	2,846.53	2,046.89
Lump Sum Repair Option	☒	☒
Lump Sum Total	2,850.00	2,050.00
Surveyor Approved Amount		2,050.00
No of Repair Days*	5	3
Remarks	-	LUMP SUM REPAIR. 3 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		
Survey Date	25/10/2018	

Save Clear

Naz LKK
23/10/18
L/S
3 DAYS
CHECK ITEMS PHOTOS.
AFTER REPAIR PHOTOS.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

JN

Section A - Accident Details

Registration Number	SHB711B
Case Reference Number	TAX/10/18/2086
Registration Date	12/09/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	PONG TECK HUAT ANTHONY
Type of Accident	Side Swipe
Accident Date and Time	22/10/18 6:25 AM
Accident Reported Date and Time	22/10/18 8:49 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098407
Special Instruction to ARC, if any	CHINA TAIPING - LKK
Prepared Date and Time	24/10/18 11:14 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left/Driver Side

Finalized

- No2 -

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,134.00	\$400.00
Total Spare Part Cost	\$4,051.72	\$1,344.36
Total Other Cost	\$760.00	\$60.00
TOTAL COST	\$6,790.72	\$2,204.36
Lump Sum Total	\$6,800.00	\$2,200.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / CHINA TAIPING
ARC / Surveyor Sign Off Date		
Signature		
Remarks	LUMP SUM REPAIR. 3 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1810-0624	Invoice Number	
Quotation Date	30.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

7249.80

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$400.00 ✓
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO REPSRAY REAR BUMPER	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$1,134.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$760.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace ✓
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace ✓
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace ✓
		52592-47021	BUMPER SEAL, RR LH	1.00	\$88.90	25.00	\$66.68	Replace	Replace ✓
		52591-47021	BUMPER SEAL, RR RH	1.00	\$65.70	25.00	\$49.28	Replace	Replace ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	25.00	\$0.00	Replace	Not Given X
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	25.00	\$0.00	Replace	Check X
		52599-68030	STOPPER, REAR BUMPER, UPPER	0.00	\$4.10	25.00	\$0.00	Replace	Check X
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	25.00	\$0.00	Replace	Not Given X
		81561-47170	TAIL LAMP LH	0.00	\$548.40	10.00	\$0.00	Replace	Check ✓
		61602-47091	FENDER RR/LH	1.00	\$766.80	25.00	\$0.00	Replace	Repair X
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
		65638-47021	FENDER LINER RR/LH	0.00	\$141.30	25.00	\$0.00	Replace	Check X
		61604-47090	FENDER RR/RH	0.00	\$766.80	25.00	\$0.00	Replace	Not Given X
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X

			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X	NN
		65637-47021	FENDER LINER RR/RH	0.00	\$141.30	25.00	\$0.00	Replace	Not Given	X	SUL
Total					\$4,436.31		\$1,186.90				

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81561-47170	TAIL LAMP LH	1.00	\$548.40	10.00	\$493.56	Replace	Replace
Total					548.40		493.56		

\$1680.46 ✓
 - 20%
 \$1344.36 ✓
 + \$ 400.00 ✓
 + \$ 460.00 ✓

 2204.36 ✓

 415 \$2200/- ✓

CONFIRMED LUMP SUM REPAIR \$2,200.00 / 3 DAYS

202 LKX
 fil

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX 10/18/2086	Date of Collection	1 / 1
Vehicle No	SUB 211 B	Date of Request	26 11/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	1 XNN

S/N	Part Number	Part Description	Quantity	Unit Price
		TAIL LAMP LH	1pc	CRK

<<<Please submit photographs for damaged parts>>>

I, (Name) H 26/10/18
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 26 October 2018 3:41 PM
To: Shu Pei (LKKAuto)
Cc: Chong Boon Sen
Subject: RE: Direct Settlement - Accident Involving PC4741M (OI : CTI - SNM18D05042C02) AND SHB711B (TP : LKK REF - CC3/CTI18019449/Nwb3) on 22/10/2018
Attachments: leeSZ_SNM18D05042C01-PC4741M-LKKDirectSettlementAccidentLtr_CLCR95.374.pdf; MJAS18137440-01-PC4741M.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Friday, 26 October, 2018 10:13 AM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Lucas Lee; Admin A; Vivian Lau (LKKAuto)
Subject: Direct Settlement - Accident Involving PC4741M (OI : CTI - TBA) AND SHB711B (TP : LKK REF - CC3/CTI18019449/Nwb3) on 22/10/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 711B at M/s SMRT Automotive Services Pte Ltd - Woodlands on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.tg.chinataiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D05042/C01/1**

Date: **26 OCTOBER 2018**

via Ordinary & Registered Mail

**GUILLEMARD BUS SERVICE
52 FOWLIE ROAD**

SINGAPORE 428496

Dear Sir / Madam

**ACCIDENT INVOLVING PC4741M AND SHB711B ON 22 OCTOBER 2018
ALONG 33 SIMEI RISE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB711B**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC: LKK Auto Consultants Pte Ltd

Attn: VIVIAN

Ref: CC3/CT18019449/NWB3

Contact No: 68418625

via Email: VIVIAN@LKKAUTO.COM

CC: Agent - (AN0580A) - ODDS & EVEN

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18019449/Nhb3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-08-2019		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 4741M	Veh. Inspected	SHB 711B	
Policy No.	DMB1SN3086591700	Coverage (\$)	0.00	
Claim No.	SNM18D05042/C01/1	Excess (\$)	0.00	
Assign From		Assign Date	23/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U705748463	Colour	MAROON	
Odometer	470682	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ACHILLES	5 mm	
L/H Front Tyre	195/65 R15	ACHILLES	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2018	Inspection Date	23/10/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 711B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	MISSING	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER LIP COVER RR/LH (DISC 25%)	MISSING	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%)	MISSING	118.10	88.58
1	BUMPER LIP REAR (DISC 25%)	MISSING	228.90	171.68
1	BUMPER SEAL,RR LH (DISC 25%)	NECESSARY	88.90	66.68
1	BUMPER SEAL,RR RH (DISC 25%)	NECESSARY	65.70	49.28
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CRACKED	94.80	71.10
1	TAIL LAMP LH (DISC 10%)	CRACKED	548.40	493.56
1	SENSOR REVERSE (SN)	MISSING	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	UNDER COVER SUBASSY,RR FLOOR	SERVICEABLE	514.50	-
1	STOPPER,REAR BUMPER,UPPER	SERVICEABLE	4.10	-
1	TAIL LAMP BRACKET,RH	SERVICEABLE	30.70	-
1	FENDER LINER RR/LH	SERVICEABLE	141.30	-
1	FENDER RR/RH	SERVICEABLE	766.80	-
1	FENDER LINER RR/RH	SERVICEABLE	141.30	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
			4,510.80	1,680.46
LABOUR				
PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF FENDER RR/LH.			845.00	400.00
SPRAY PAINT.			1,134.00	400.00
TO CHECK WIRING AND SYSTEM FUNCTION.		NOT NECESSARY	80.00	-
TO APPLY RUST-PROOFING ON AFFECTED AREA.			200.00	40.00

Report Ref No. CC3/CTI18019449/Nhb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,739.00	860.00
GRAND TOTAL			7,249.80	2,540.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CC3/CT118019449/Nhb3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.