

ASS. REC. BY:

REF: CS/CT118019450/K+d3m2

Special Instruction:

Surveyor
Menimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine cheong

of

CT1

Date/Time:

25/10/18 @ 4:32pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 5990C

Insured:

SLF 8427B

at Workshop m/s

Hui Yang Motor

Tel:

6451 5752

of

176 Sin Ming Drive #04-02

Policy No:

MSD/VPCB/18-000130

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

5:35pm @ 25/10/18

Person Contacted:

Belle

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 5990C-X
	SLF 8427B-X
13/11	2830.55 email & confirm
	(Red: 3480, 37%)

ASS. REC. BY:

REF: MSG / C11Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yang

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ 5990C Yr Regn: 07, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy CLHR c.c. 1.797Colour: M. Brown A/C: Insured / Std / NI / NASp. Reading: 33261 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 84X10 2042614Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R17
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 24/10/18

Survey held at _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 25/10/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

110 File pass to Catherine

RECEIVED 15 NOV 2018

Date/Time, File Pass to?

1) File Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$Report Format: TP

Lump Sum / I.B.I: (\$

2830.55220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2018 15:08		25 Oct 2018 16:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CAR CLUB PTE LTD, Co. Reg. No.: -	
Main Claimant:	HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K	
Vehicle Reg. No.:	SLQ5990C	Date of Loss: 24/10/2018 00:00 - :59 [15 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.: MSD/VPCB/18-000130 Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	SLF8427B	Policy No. (Claimant):
		Excess:
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/10/2018]	
Adj Asg. Remarks:	Liability unclear. Non Reporting. TP want to use Kenneth Kong from LKK to survey the vehicle. Contact Person: Marcus Loh / 6451 5752.	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete																				
<table style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Due Date</th> <th style="text-align: left;">Priority</th> <th style="text-align: left;">Type</th> <th style="text-align: left;">Task Group</th> <th style="text-align: left;">Subject</th> <th style="text-align: left;">Handler</th> <th style="text-align: left;">Assigned By</th> <th style="text-align: left;">Completed On</th> <th style="text-align: left;">Created On</th> <th style="text-align: left;">Done?</th> </tr> <tr> <td colspan="10">No results.</td> </tr> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

MSL

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

24/10/2018

Owner: HYMS CAR LEASING PTE LTD

Not Notarised
1-B.1
Penny Bepain
\$ 2830.55
4 days

ESTIMATE TO REPAIR TOYOTA CHR 1.8 - SLQ5990C

1pc	rear tailgate
1pc	rear tailgate outer garnish
1pc	rear tailgate "TOYOTA" logo
1pc	rear tailgate "HYBRID" emblem
1pc	rear tailgate "C-HR" emblem
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
1pc	rear bumper
2pcs	rear bumper side retainer @\$45.00
2pcs	rear bumper side reflector @\$60.00
2pcs	rear bumper side reflector garnish @\$75.00
1pc	rear bumper diffuser
8pcs	rear bumper diffuser clip @\$1.50
1pc	rear bumper towing cover
1pc	rear bumper reinforcement
2pcs	rear bumper centre parking sensor @\$150.00
1pc	rear end panel
1pc	rear end panel inner garnish
1set	rear windscreen moulding

Bz	\$	480.00	✓
Sm	\$	350.00	✗
M	\$	55.00	—
M	\$	55.00	—
M	\$	40.00	—
SK		240.00	x
Sm	\$	150.00	x
Sm	\$	160.00	✗
Bz	\$	220.00	✓
Sm	\$	90.00	x
Sm	\$	120.00	x
Sm	\$	150.00	✗
Ref/hts	\$	180.00	✓
M	\$	12.00	✓
Ref	\$	25.00	—
Bz	\$	190.00	✓
Sm	\$	300.00	✗
R	\$	280.00	x
Sm	\$	160.00	✗
M	\$	100.00	✓

cost + 15%

\$	3,357.00
\$	503.55
\$	3,860.55

remove & refit rear windscreen glass
tuffkote
wiring
spray painting

\$	120.00	✓
\$	150.00	301
\$	80.00	201
\$	1,200.00	6001
\$	900.00	5001
\$	6,310.55	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019450/KTD3N2

Date: 16/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCB/18-000130
 Claimant Vehicle No: SLQ5990C Insured Vehicle No: SLF8427B
 Date of Loss: 24/10/2018 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ5990C Engine No: 2ZR8115622
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Chassis No: ZYX102042614
 Reg. Date: 17/07/2017 (Man. Year: 2017) Odometer: 33261 km
 Colour: Metallic Brown
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,860.55	1,560.55	2,300.00	59.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,270.00	1,180.00	48.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,310.55	2,830.55	3,480.00	55.15
+ GST 7.00/7.00% (S\$)	441.74	198.14	243.60	55.15
Nett Amount (S\$)	6,752.29	3,028.69	3,723.60	55.15

INSPECTION

Date of Assignment: 25/10/2018
 Date Inspected: 25/10/2018 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming
 AutoCare
 Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)	
Parts: M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLQ5990C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE (WCP)	Bent	480.00 F	*480.00 F
2	1	*REAR TAILGATE OUTER GARNISH (WCP)	Serviceable	350.00 F	*- F
3	1	*REAR TAILGATE TOYOTA LOGO (WCP)	Necessary	55.00 F	*55.00 F
4	1	*REAR TAILGATE HYBRID EMBLEM (WCP)	Necessary	55.00 F	*55.00 F
5	1	*REAR TAILGATE C-HR EMBLEM (WCP)	Necessary	40.00 F	*40.00 F
6	1	*REAR TAILGATE INNER LOCK (WCP)	Repair	240.00 F	*- F
7	1	*REAR TAILGATE INNER RUBBER (WCP)	Serviceable	150.00 F	*- F
8	1	*REAR TAILGATE INNER GARNISH (WCP)	Serviceable	160.00 F	*- F
9	1	*REAR BUMPER (WCP)	Buckled	220.00 F	*220.00 F
10	2	*REAR BUMPER SIDE RETAINER (WCP)	Serviceable	90.00 F	*- F
11	2	*REAR BUMPER SIDE REFLECTOR (WCP)	Serviceable	120.00 F	*- F
12	2	*REAR BUMPER SIDE REFLECTOR GARNISH (WCP)	Serviceable	150.00 F	*- F
13	1	*REAR BUMPER DIFFUSER (WCP)	Dented/Cut	180.00 F	*180.00 F
14	8	*REAR BUMPER DIFFUSER CLIP (WCP)	Necessary	12.00 F	*12.00 F
15	1	*REAR BUMPER TOWING COVER (WCP)	Dented	25.00 F	*25.00 F
16	1	*REAR BUMPER REINFORCEMENT (WCP)	Bent	190.00 F	*190.00 F
17	2	*REAR BUMPER CENTRE PARKING SENSOR (WCP)	Serviceable	300.00 F	*- F
18	1	*REAR END PANEL (WCP)	Repair	280.00 F	*- F
19	1	*REAR END PANEL INNER GARNISH (WCP)	Serviceable	160.00 F	*- F
20	1	*SET REAR WINDSCREEN MOULDING (WCP)	Necessary	100.00 F	*100.00 F

F=Franchise part.

Sub Total (\$\$)	3,357.00	1,357.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	503.55	203.55
Total Parts (\$\$)	3,860.55	1,560.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	TUFFKOTE	New	150.00	30.00
3	WIRING	New	80.00	20.00
4	SPRAY PAINTING	New	1,200.00	600.00
5	LABOUR CHARGES	New	900.00	500.00
Gross Labour Cost (\$\$)			2,450.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >