

ASS. REC. BY:

REF:

CS/MSB18019450/K/d3m2

Special Instruction:

Surveyor  
Menmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

Meth

Date/Time:

25/10/18 @ 4:32pm

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 5990C

Insured:

SLF 8427B

at Workshop m/s

Hui Yang Motor

Tel:

6451 5752

of

176 Sin Ming Drive #04-02

Policy No:

MSD/VPCB/18-000130

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

5:35pm @ 25/10/18

Person Contacted:

Belle

Vehicle:

☒ IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SLQ 5990C-X                     |
|           | SLF 8427B-X                     |
| 13/11     | @ 2830.55 email & confirm       |
|           | (Red: 3430, 35%)                |

ASS. REC. BY:

REF:

MSG / C11

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLQ 5990C

Yr Regn:

07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Tq C11R

c.c.

1.797

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

33261

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

84X10

2042614

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

110 File pass to Catherine

RECEIVED 15 NOV 2018

Date/Time, File Pass to?

1) 15/11/2018

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trlp:

1

Survey Fee:

Transportation

S + RS \$

Fees

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

2830.55

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified             | Est. Submitted | Adj. Assigned                                  | Adj. Rpt | Adj. Submitted | Ins. Auth'd | Status                                               |
|------|----------------------|----------------|------------------------------------------------|----------|----------------|-------------|------------------------------------------------------|
| Main | 25 Oct 2018<br>15:08 |                | 25 Oct 2018<br>16:24<br><a href="#">Assign</a> |          |                |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |                                                                                                                                       |                        |                                                                             |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------------------------|
| Insured:                    | CAR CLUB PTE LTD, Co. Reg. No.: -                                                                                                     |                        |                                                                             |
| Main Claimant:              | HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K                                                                                    |                        |                                                                             |
| Vehicle Reg. No.:           | SLQ5990C                                                                                                                              | Date of Loss:          | 24/10/2018 00:00 - :59<br>[15 Months and 7 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP                                                                                                                                    | Policy/Cover Note No.: | MSD/VPCB/18-000130<br>Coverage: 01/01/2018 - 31/12/2018                     |
| Vehicle Reg. No. (Insured): | SLF8427B                                                                                                                              | Policy No. (Claimant): |                                                                             |
|                             |                                                                                                                                       | Excess:                |                                                                             |
| Repairer:                   | Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752                             |                        |                                                                             |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]                            |                        |                                                                             |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/10/2018]                                                    |                        |                                                                             |
| Adj. Asg. Remarks:          | Liability unclear. Non Reporting. TP want to use Kenneth Kong from LKK to survey the vehicle. Contact Person: Marcus Loh / 6451 5752. |                        |                                                                             |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.

MSL

# 輝陽汽車有限公司

## HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

24/10/2018

Owner: HYMS CAR LEASING PTE LTD

Not Notarised  
1-B.1  
Rummy B6 paim  
8 2830.55  
4 days

### ESTIMATE TO REPAIR TOYOTA CHR 1.8 - SLQ5990C

|      |                                             |
|------|---------------------------------------------|
| 1pc  | rear tailgate                               |
| 1pc  | rear tailgate outer garnish                 |
| 1pc  | rear tailgate "TOYOTA" logo                 |
| 1pc  | rear tailgate "HYBRID" emblem               |
| 1pc  | rear tailgate "C-HR" emblem                 |
| 1pc  | rear tailgate inner lock                    |
| 1pc  | rear tailgate inner rubber                  |
| 1pc  | rear tailgate inner garnish                 |
| 1pc  | rear bumper                                 |
| 2pcs | rear bumper side retainer @\$45.00          |
| 2pcs | rear bumper side reflector @\$60.00         |
| 2pcs | rear bumper side reflector garnish @\$75.00 |
| 1pc  | rear bumper diffuser                        |
| 8pcs | rear bumper diffuser clip @\$1.50           |
| 1pc  | rear bumper towing cover                    |
| 1pc  | rear bumper reinforcement                   |
| 2pcs | rear bumper centre parking sensor @\$150.00 |
| 1pc  | rear end panel                              |
| 1pc  | rear end panel inner garnish                |
| 1set | rear windscreen moulding                    |

|         |    |        |   |
|---------|----|--------|---|
| B1      | \$ | 480.00 | ✓ |
| Sm      | \$ | 350.00 | ✗ |
| Me      | \$ | 55.00  | — |
| Me      | \$ | 55.00  | — |
| Me      | \$ | 40.00  | — |
| SH      |    | 240.00 | x |
| Sm      | \$ | 150.00 | x |
| Sm      | \$ | 160.00 | ✗ |
| Bur     | \$ | 220.00 | ✓ |
| Sm      | \$ | 90.00  | x |
| Sm      | \$ | 120.00 | x |
| Sm      | \$ | 150.00 | ✗ |
| Red/hts | \$ | 180.00 | — |
| Me      | \$ | 12.00  | ✓ |
| Red     | \$ | 25.00  | — |
| B1      | \$ | 190.00 | ✓ |
| Sm      | \$ | 300.00 | ✗ |
| R       | \$ | 280.00 | ✓ |
| Sm      | \$ | 160.00 | ✗ |
| Me      | \$ | 100.00 | ✓ |

cost + 15%

\$ 3,357.00  
\$ 503.55  
\$ 3,860.55

remove & refit rear windscreen glass

tuffkote

wiring

spray painting

labour charges

Total

\$ 120.00 ✓  
\$ 150.00 301  
\$ 80.00 201  
\$ 1,200.00 6001  
\$ 900.00 5001  
\$ 6,310.55

LKK Auto Consultants hence notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019450/KTD3N2

Date: 16/11/2018

## REFERENCE

|                       |                                      |                      |                    |
|-----------------------|--------------------------------------|----------------------|--------------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | MSD/VPCB/18-000130 |
| Claimant Vehicle No : | SLQ5990C                             | Insured Vehicle No : | SLF8427B           |
| Date of Loss:         | 24/10/2018                           | Nature of Claim:     | TP                 |
|                       |                                      | Claim No:            | N/A                |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | SLQ5990C                          | Engine No:  | 2ZR8115622   |
| Make & Model:               | TOYOTA C-HR HYBRID, 1.8 S CVT (A) | Chassis No: | ZYX102042614 |
| Reg. Date:                  | 17/07/2017 (Man. Year: 2017)      | Odometer:   | 33261 km     |
| Colour:                     | Metallic Brown                    |             |              |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | Market Value/New Car Price        |             |              |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 215/60R17        | Rear Tyre Size:  | 215/60R17        |
| Front Left Side:  | Bridgestone 7 mm | Rear Left Side:  | Bridgestone 7 mm |
| Front Right Side: | Bridgestone 7 mm | Rear Right Side: | Bridgestone 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 3,860.55        | 1,560.55        | 2,300.00        | 59.58        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 2,450.00        | 1,270.00        | 1,180.00        | 48.16        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>6,310.55</b> | <b>2,830.55</b> | <b>3,480.00</b> | <b>55.15</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>441.74</b>   | <b>198.14</b>   | <b>243.60</b>   | <b>55.15</b> |
| <b>Nett Amount (S\$)</b>      | <b>6,752.29</b> | <b>3,028.69</b> | <b>3,723.60</b> | <b>55.15</b> |

## INSPECTION

|                             |            |                                     |
|-----------------------------|------------|-------------------------------------|
| Date of Assignment:         | 25/10/2018 |                                     |
| Date Inspected:             | 25/10/2018 | Inspected At:                       |
|                             |            | Hui Yang Motor Pte Ltd (HQ)         |
|                             |            | 176 Sin Ming Drive #04-02, Sin Ming |
|                             |            | AutoCare                            |
|                             |            | Singapore 575721                    |
| Estimated Period of Repair: | 4.0 days   |                                     |

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                            |                                                                                                                                                                              |  |
|----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 16 Nov 2018)                                                                                                                                |  |
| <b>Parts:</b> M1-SUV       | TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)                                                                                                           |  |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)                                                                                                                                            |  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SLQ5990C)                                                                                                                                    |  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |  |

### Recommended Parts

| No. | Qty | Part No. Particulars                      | Condition   | Repairer's | Amount    |
|-----|-----|-------------------------------------------|-------------|------------|-----------|
| 1   | 1   | *REAR TAILGATE (WCP)                      | Bent        | 480.00 F   | *480.00 F |
| 2   | 1   | *REAR TAILGATE OUTER GARNISH (WCP)        | Serviceable | 350.00 F   | *- F      |
| 3   | 1   | *REAR TAILGATE TOYOTA LOGO (WCP)          | Necessary   | 55.00 F    | *55.00 F  |
| 4   | 1   | *REAR TAILGATE HYBRID EMBLEM (WCP)        | Necessary   | 55.00 F    | *55.00 F  |
| 5   | 1   | *REAR TAILGATE C-HR EMBLEM (WCP)          | Necessary   | 40.00 F    | *40.00 F  |
| 6   | 1   | *REAR TAILGATE INNER LOCK (WCP)           | Repair      | 240.00 F   | *- F      |
| 7   | 1   | *REAR TAILGATE INNER RUBBER (WCP)         | Serviceable | 150.00 F   | *- F      |
| 8   | 1   | *REAR TAILGATE INNER GARNISH (WCP)        | Serviceable | 160.00 F   | *- F      |
| 9   | 1   | *REAR BUMPER (WCP)                        | Buckled     | 220.00 F   | *220.00 F |
| 10  | 2   | *REAR BUMPER SIDE RETAINER (WCP)          | Serviceable | 90.00 F    | *- F      |
| 11  | 2   | *REAR BUMPER SIDE REFLECTOR (WCP)         | Serviceable | 120.00 F   | *- F      |
| 12  | 2   | *REAR BUMPER SIDE REFLECTOR GARNISH (WCP) | Serviceable | 150.00 F   | *- F      |
| 13  | 1   | *REAR BUMPER DIFFUSER (WCP)               | Dented/Cut  | 180.00 F   | *180.00 F |
| 14  | 8   | *REAR BUMPER DIFFUSER CLIP (WCP)          | Necessary   | 12.00 F    | *12.00 F  |
| 15  | 1   | *REAR BUMPER TOWING COVER (WCP)           | Dented      | 25.00 F    | *25.00 F  |
| 16  | 1   | *REAR BUMPER REINFORCEMENT (WCP)          | Bent        | 190.00 F   | *190.00 F |
| 17  | 2   | *REAR BUMPER CENTRE PARKING SENSOR (WCP)  | Serviceable | 300.00 F   | *- F      |
| 18  | 1   | *REAR END PANEL (WCP)                     | Repair      | 280.00 F   | *- F      |
| 19  | 1   | *REAR END PANEL INNER GARNISH (WCP)       | Serviceable | 160.00 F   | *- F      |
| 20  | 1   | *SET REAR WINDSCREEN MOULDING (WCP)       | Necessary   | 100.00 F   | *100.00 F |

F=Franchise part.

|                                                  |                 |                 |
|--------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                          | <b>3,357.00</b> | <b>1,357.00</b> |
| <b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b> | <b>503.55</b>   | <b>203.55</b>   |
| <b>Total Parts (\$\$)</b>                        | <b>3,860.55</b> | <b>1,560.55</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                          | Lab.Type | Repairer's      | Amount          |
|-------------------------|--------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                      |          |                 |                 |
| 1                       | REMOVE & REFIT REAR WINDSCREEN GLASS | New      | 120.00          | 120.00          |
| 2                       | TUFFKOTE                             | New      | 150.00          | 30.00           |
| 3                       | WIRING                               | New      | 80.00           | 20.00           |
| 4                       | SPRAY PAINTING                       | New      | 1,200.00        | 600.00          |
| 5                       | LABOUR CHARGES                       | New      | 900.00          | 500.00          |
| Gross Labour Cost (S\$) |                                      |          | <b>2,450.00</b> | <b>1,270.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >