

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AXA18019500/T1QBS2

Date: 15/11/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1528079
Claimant Vehicle No :	SBS6382J	Insured Vehicle No :	XB4874Z
Date of Loss:	03/10/2016	Nature of Claim:	TP
		Claim No:	C0434240

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6382J	Engine No:	902926C0994020
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Chassis No:	WEB62808323124771
Reg. Date:	01/04/2013 (Man. Year: 2012)	Odometer:	0 km
Colour:	Green		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/80 22.5	Rear Tyre Size:	275/80 22.5 (D)
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8/8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,265.72	4,265.72	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	2,200.00	600.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,065.72	6,465.72	600.00	8.49
+ GST 7.00/7.00% (S\$)	494.60	452.60	42.00	8.49
Nett Amount (S\$)	7,560.32	6,918.32	642.00	8.49

INSPECTION

Date of Assignment: 24/10/2018

Date Inspected: 01/11/2018 Inspected At:

TOWER TRANSIT SINGAPORE PTE LTD
21 BULIM DRIVE
SINGAPORE 648170

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

11/15/2018

Adjuster Report

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT NOT AGREED WITH OUR OFFER.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Nov 2018)

Parts: N/A MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS6382J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP	REPLACED	598.72 F	*598.72 F
2	1		*RADIATOR FLAP	REPLACED	3,181.98 F	*3,181.98 F
3	1		*O/S BUMPER	REPLACED	485.02 F	*485.02 F
Total Parts (S\$)					4,265.72	4,265.72

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE / REPAIR THE DAMAGED PARTS.	New	2,000.00	1,600.00
2	SPRAY PAINTING.	New	800.00	600.00
Gross Labour Cost (S\$)			2,800.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >