

REF: AIG

ASSIGNMENT

From: Date: 25/10/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKR 2857G

at Workshop m/s

Tolly Maths

of 1kaki Bukit Ave 6 #02-02

Insured:

Policy No.

Claims No.

Sum insured:

Excess:

(Client's Record)

After 9:30am

Make of Veh:

Nigel : 8228 9818

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKR 2857G. Yr Regn: 2015 Jan.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City

C.C

1497

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading

65536

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHGM6660EP000259

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Normal / Jammed / Leaked / Burnt orBrake: ☒ Normal / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16.

R:

205/50R16.

☒ BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

26

mm

R/Bal.

26

mm

L/Bal.

26

mm

L/Bal.

26

mm

D.O.A.

D.O.I.

25/10/18

Survey held at

Polymath.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

\$4,800/-

R (\$9,343.57/6%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RE \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18019512/Ajb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 26-10-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 5727D	Veh. Inspected	SKR 2857G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/10/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/10/2018	Inspection Date	25/10/2018
Survey held at	POLYMATH		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



25/10/2018

Estimated repair checklist

Vehicle Registration No. : SKR2857G

Vehicle Make/Model : Honda/City

Qty	List Items	Amount \$
1	Rear boot lid <i>Dented</i>	656.60 ✓
1	Rear boot emblem "H"	38.60 ✓
1	Rear boot emblem "CITY" <i>2 per</i>	32.70 ✓
1	Rear boot emblem "i-vtec"	32.70 ✓
1	Rear boot chrome moulding <i>new</i>	196.30 ✗
2	Rear boot lamps - L/R @ 260.20 <i>cut</i>	520.40 ✓
2	Rear boot licence lamps @ 42.20 <i>Not Nec</i>	84.40 ✗
1	Rear boot inner lock <i>Damaged</i>	183.60 ✓
1	Rear boot lock striker <i>new</i>	28.60 +
1	Rear boot inner pull pocket <i>new</i>	89.60 +
1	Rear boot inner trim <i>new</i>	261.60 ✗
10	Rear boot inner trim clips @ 4.50 <i>new</i>	45.00 30
2	Rear boot hinges - L/R @ 66.90 <i>new</i>	133.80 +
2	Rear boot stoppers @ 28.60 <i>new</i>	57.20 +
1	Rear boot w/strip <i>cut</i>	110.20 ✓
1	Rear bumper <i>Distorted</i>	510.60 ✓
2	Rear bumper side retainers - L/R @ 48.20 <i>new</i>	96.40 ✓
6	Rear bumper clips @ 4.50 <i>new</i>	27.00 ✓
2	Rear bumper reflectors - L/R @ 86.60 <i>new</i>	128.86 ✗
2	Rear end panel <i>Dented</i>	535.60 ✓
1	Rear end panel garnish <i>Deformed</i>	126.20 ✓
1	Rear exhaust silencer <i>new</i>	612.40 +
1	Rear exhaust insulator <i>new</i>	116.90 +
2	Rear exhaust mountings @ 28.20 <i>new</i>	56.40 +
1	Rear floor board <i>Replaced</i>	386.90 +
1	Rear floor panel <i>Repair</i>	811.60 ✗
2	Rear floor panel side members - L/R @ 235 <i>Repair</i>	470.00 ✗
1	Rear spare wheel retainer lock <i>Replaced</i>	48.60 ✗
2	Rear fenders - L/R @ 851.60 <i>Repair</i>	4071.20 ✗
2	Rear fender inner trims - L/R @ 292.60 <i>new</i>	3256.96 ✗
10	Rear fender inner trim clips @ 4.50 <i>new</i>	45.00 ✓
2	Rear fender inner shields - L/R @ 51.20 <i>new</i>	102.40 ✗
2	Rear taillamps - L/R @ 391.20 <i>LH cracked, RH cut</i>	782.40 ✓
2	Rear taillamp panels - L/R @ 155.10 <i>Dented</i>	310.20 ✗
2	Rear taillamp lower brackets - L/R @ 16.50 <i>Repair</i>	33.00 ✗
1 set	Rear windscreen moulding <i>new</i>	82.60 ✗
Sub-total		10,041.96
Less 20%		2,008.39
Total List		8,033.57



Polymath garage

Polymath Garage Pte Ltd
AutoBay@Kaki Bukit, 1 Kaki Bukit Ave 6 #02-02
Singapore 417883
24 Hour : +65 8228 9818
Phone: +65 6871 8861 | Fax: +65 6871 8814
Email : enquiry@polymathgarage.com.sg

25/10/2018

Estimated repair checklist

Vehicle Registration No. : SKR2857G

Vehicle Make/Model : Honda/City

Special Nett Items

1 set Rear	no. plate with holder	Best	60.00	✓
1 set	reverse sensor - 4 PCS	Revised	480.00	300
1 set	windscreen sealant	102 m	80.00	x
1 Rear	reverse camera	102 m	80.00	x
Total Special Nett			700.00	

Labour charges

Towing charges	100.00	x
To remove, refix rear interior trims to assist repair	150.00	60
To check rear electrical wiring	80.00	30
To remove, refix rear reverse sensor/camera	80.00	✓
To remove, refix rear windscreen	180.00	+
To remove, refix rear exhaust systems	120.00	+
To respray undercoating	200.00	60
To respray painting and etc	1,500.00	1000
Panel beating, cut, weld remove & replacing above parts	3,000.00	1200
Total Labour	5,410.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

14,143.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King, total: 6046.8
L/S 25/10/18. H/S: 48K
07 days.
96893735.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 27 February 2019 4:20 PM
To: 'Yong, Ivy-AV'; Joy Irene (LKKAuto)
Cc: Admin A
Subject: RE: #2116912384SG003#SLK5727D //LKK REF: CC6/LCR18019512/Ajb3

Hi Ivy,

Noted.

By copy to Joy,

FYNA. CC6/LCR18019512/Ajb3

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yong, Ivy-AV <Ivy-AV.Yong@aig.com>
Sent: Tuesday, 26 February 2019 3:07 PM
To: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: #2116912384SG003#SLK5727D

Hi Hsiao Tong,

LOD received, please let us have your finalizer report and your invoice in merimen.

Thank you

Ivy Yong

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +64191637

Ivy-AV.Yong@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2018 Edit Reg		25 Oct 2018 00:00 Edit Adj Rpt	S\$4,800.00 Edit Estimates	S\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	MAH CHAO HOCK (MA CHAOFU), ID: S7232221E		
Vehicle Reg. No.:	SKR2857G	Date of Loss:	24/10/2018 13:00 - :59 [44 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2116912384SG	Policy/Cover Note No.:	0999994810 (Comprehensive)
Vehicle Reg. No. (Insured):	SLK5727D	Policy No. (Claimant):	5103645651
		Excess:	
Repairer:	Polymath Garage Pte Ltd (HQ) 1 KAKI BT AVENUE 6 #02-02 AUTOBAY, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

*SKR2857G (2116912384SG)
[SLK5727D]

TP
MAH CHAO HOCK (MA CHAOFU)
Oct 24 2018 1:00PM
[LCRF PTE LTD]
Polymath Garage Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	11/12/18 13:45	General View									Load JPG	☒	
2	11/12/18 13:45	General View									Load JPG	☒	
3	11/12/18 13:45	General View									Load JPG	☒	
4	11/12/18 13:45	General View									Load JPG	☒	
5	11/12/18 13:45	General View									Load JPG	☒	
6	11/12/18 13:45	General View									Load JPG	☒	
7	11/12/18 13:45	General View									Load JPG	☒	
8	11/12/18 13:45	General View									Load JPG	☒	
9	11/12/18 13:45	General View									Load JPG	☒	
10	11/12/18 13:45	General View									Load JPG	☒	
11	11/12/18 13:45	General View									Load JPG	☒	
12	11/12/18 13:45	General View									Load JPG	☒	
13	11/12/18 13:45	General View									Load JPG	☒	
14	11/12/18 13:45	General View									Load JPG	☒	
15	11/12/18 13:45	General View									Load JPG	☒	
16	11/12/18 13:45	General View									Load JPG	☒	
17	11/12/18 13:45	General View									Load JPG	☒	
18	11/12/18 13:45	General View									Load JPG	☒	
19	11/12/18 13:45	General View									Load JPG	☒	
20	11/12/18 13:45	General View									Load JPG	☒	
21	11/12/18 13:45	General View									Load JPG	☒	
22	11/12/18 13:45	General View									Load JPG	☒	
23	11/12/18 13:45	General View									Load JPG	☒	
24	11/12/18 13:45	General View									Load JPG	☒	
25	11/12/18 13:45	General View									Load JPG	☒	
26	11/12/18 13:45	General View									Load JPG	☒	
27	11/12/18 13:45	General View									Load JPG	☒	
28	11/12/18 13:45	General View									Load JPG	☒	
29	11/12/18 13:45	General View									Load JPG	☒	
30	11/12/18 13:45	General View									Load JPG	☒	
31	11/12/18 13:45	General View									Load JPG	☒	
32	11/12/18 13:45	General View									Load JPG	☒	
33	11/12/18 13:45	General View									Load JPG	☒	
34	11/12/18 13:45	General View									Load JPG	☒	
35	11/12/18 13:45	General View									Load JPG	☒	
36	11/12/18 13:45	General View									Load JPG	☒	
37	11/12/18 13:45	General View									Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
39	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
40	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
41	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
42	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
43	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
44	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
45	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
46	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
47	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
48	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
49	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
50	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
51	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
52	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
53	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
54	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
55	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
56	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
57	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
58	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
59	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
60	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
61	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
62	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
63	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
64	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
65	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
66	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
67	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
68	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
69	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
70	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
71	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
72	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
73	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
74	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
75	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
76	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
77	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
78	11/12/18 13:46	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/18 09:28	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/10/18 09:57	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18019512/AJB3Q2

Date: 01/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994810

Claimant Vehicle No: SKR2857G

Insured Vehicle No: SLK5727D

Date of Loss: 24/10/2018

Nature of Claim: TP

Claim No: 2116912384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR2857G

Make & Model: HONDA CITY, 1.5 SV CVT (A)

Engine No: L15Z11422131

Reg. Date: 29/01/2015 (Man. Year: 2014)

Chassis No: MRHGM6660EP000259

Colour: Blue

Odometer: 65536 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,733.57	3,616.96	5,116.61	58.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,410.00	2,430.00	2,980.00	55.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,143.57	6,046.96	8,096.61	57.25
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	14,143.57	4,800.00	9,343.57	66.06

INSPECTION

Date of Assignment: 25/10/2018

Date Inspected: 25/10/2018 Inspected At:

Polymath Garage Pte Ltd (HQ)
1 KAKI BT AVENUE 6 #02-02 AUTOBAY
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	656.60 FL	*656.60 FL
2	1		*REAR BOOT EMBLEM H	Necessary	38.60 FL	*38.60 FL
3	1		*REAR BOOT EMBLEM CITY	Necessary	32.70 FL	*32.70 FL
4	1		*REAR BOOT EMBLEM I-VTEC	Necessary	32.70 FL	*32.70 FL
5	1		*REAR BOOT CHROME MOULDING	Not Necessary	196.30 FL	*- FL
6	2		*REAR BOOT LAMPS -L/R	Cut	520.40 FL	*520.40 FL
7	2		*REAR BOOT LICENCE LAMPS	Not Necessary	84.40 FL	*- FL
8	1		*REAR BOOT INNER LOCK	Damaged	183.60 FL	*183.60 FL
9	1		*REAR BOOT LOCK STRIKER	Not Necessary	28.60 FL	*- FL
10	1		*REAR BOOT INNER PULL POCKET	Not Necessary	89.60 FL	*- FL
11	1		*REAR BOOT INNER TRIM	Not Necessary	261.60 FL	*- FL
12	10		*REAR BOOT INNER TRIM CLIPS	Necessary	45.00 FL	*30.00 FL
13	2		*REAR BOOT HINGES -L/R	Not Necessary	133.80 FL	*- FL
14	2		*REAR BOOT STOPPERS	Not Necessary	57.20 FL	*- FL
15	1		*REAR BOOT W/STRIP	Cut	110.20 FL	*110.20 FL
16	1		*REAR BUMPER	Distorted	510.60 FL	*510.60 FL
17	2		*REAR BUMPER SIDE RETAINER -L/R	Necessary	96.40 FL	*96.40 FL
18	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
19	2		*REAR BUMPER REFLECTORS -L/R	Not Necessary	128.86 FL	*- FL
20	2		*REAR END PANEL	Dented	535.60 FL	*535.60 FL
21	1		*REAR END PANEL GARNISH	Deformed	126.20 FL	*126.20 FL
22	1		*REAR EXHAUST SILENCER	Not Necessary	612.40 FL	*- FL
23	1		*REAR EXHAUST INSULATOR	Not Necessary	116.90 FL	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	56.40 FL	*- FL
25	1		*REAR FLOOR BOARD	Not Necessary	386.90 FL	*- FL
26	1		*REAR FLOOR PANEL	Repair	811.60 FL	*- FL
27	2		*REAR FLOOR PANEL SIDE MEMBERS -L/R	Repair	470.00 FL	*- FL
28	1		*REAR SPARE WHEEL RETAINER LOCK	Not Necessary	48.60 FL	*- FL
29	2		*REAR FENDERS -L/R	Repair	1,703.20 FL	*- FL
30	2		*REAR FENDER INNER TRIMS -L/R	Not Necessary	584.40 FL	*- FL
31	10		*REAR FENDER INNER TRIM CLIPS	Necessary	45.00 FL	*45.00 FL
32	2		*REAR FENDER INNER SHIELD -L/R	Not Necessary	102.40 FL	*- FL
33	2		*REAR TAILLAMP -L/R	N/S Cracked / O/S Cut	782.40 FL	*782.40 FL
34	2		*REAR TAILLAMP PANELS -L/R	Dented	310.20 FL	*310.20 FL
35	2		*REAR TAILLAMP LOWER BRACKETS -L/R	Damaged	33.00 FL	*33.00 FL
36	1		*SET REAR WINDSCREEN MOULDING	Not Necessary	82.60 FL	*- FL
37	1		*SET REAR NO .PLATE WITH HOLDER	Bent	60.00 FS	*60.00 FS
38	1		*SET REVERSE SENSOR (4 PCS)	Damaged	480.00 FS	*300.00 FS
39	1		*SET WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR REVERSE CAMERA	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	10,741.96	4,431.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,008.39	814.24

Total Parts (S\$)	8,733.57	3,616.96
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	0.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	60.00
3	TO CHECK REAR ELECTRICAL WIRING	New	80.00	30.00
4	TO REMOVE,REFIX REAR REVERSE SENSOR /CAMERA	New	80.00	80.00
5	TO REMOVE,REFIX REAR WINDSCREEN	New	180.00	0.00
6	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	120.00	0.00
7	TO RESPRAY UNDERCOATING	New	200.00	60.00
8	TO RESPRAY PAINTING AND ETC	New	1,500.00	1,000.00
9	PANEL BEATING ,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	3,000.00	1,200.00
Gross Labour Cost (\$\$)			5,410.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >