



Your Ref : S8M010N3

Date: 06<sup>th</sup> March 2019

Our Ref : CC4/ASM18019517/Kjb3s2

**M/s AXA Insurance Pte Ltd**  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Cynthia Loh

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO  
SJL 2565S ACCIDENT ON 25/10/2018 INSURED SKA 787C**

Instruction was received to inspect the vehicle Reg. No. SJL 2565S. The inspection was conducted on 26/10/2018 at the premises of M/s T&T Auto Services Pte Ltd, Blk 160 Sin Ming Drive #08-14 Sin Ming Autocity Singapore 575722.

The following information were recorded: -

Registration Number	: SJL 2565S
Make & Model	: Honda Airwave (A)
Year of Registration	: 2008
Engine Capacity	: 1496 cc
Body Colour	: Metallic Black
Chassis Number	: GJ11305971
Speedometer Reading	: 421157 km

The vehicle sustained damages at the rear n/s portion. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.


Market Value	S\$	8,500.00
Less: LTA Reimbursement Value (RV)	(S\$	7,863.00)
Nett Liability	S\$	<u>637.00</u>

Vehicle Inspected By:



KONG SENG CHEONG

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.