

22/03/2001

ASS. REC. BY:

REF: CS/SPF18019519/Tlv d34 Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person):

Frankie Thay

of

SPF

Date/Time:

26/10/2018

Estimated Cost:

Bill to:

OD ☒ TP + WS + TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDV 7948G

Insured:

QX910X

at Workshop m/s

Burneo Motors

Tel:

98476178

of

2 Pandan Crescent

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/10/2018

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time: 1:53pm 26/10/18

Person Contacted:

Wally

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SDV 7948G - X

QX910X - X

7/1/18

Submit preli report

13/2/19

To re-open & Submit final report

Final fig \$ 33,066.60 (Red 16,605.00, 33%), 13 days ^{Calculated} 14/2/19.

15/4/19 1st case date 13/11/18, re-open ref only ↓

Tayfkh

RCP:

SP F

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no/s

of

Insured

Policy No

Claims No.

Sum Insured


Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est Repairs

days

Res.: Yes or No

Lump Sum

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Reg No: SDV 7948 G Yr Regn: 12
 Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

Lexus LS460

4608

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

46872

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

JTHGL46 F105047449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ SR / ☐ STD A/Rim or

Tyre Size

F:

245/45R19

R:

- - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26/10/18

Survey held at

Borneo Pardon

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop

or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 07 NOV 2018

Date/Time: File Pass to:



Prel. Report



Final Report

Date/Time: File Return to:

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee

Transportation

Fuel

Parking

Food

Tools

Misc

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Workload (\$)

Report Format:

Lump Sum / I.B. /

280

280

7/11 - typist



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	51000020/TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68356837
	Document No 0	
	Document Date 25/10/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L5	USF41R	03/12/2012	SN0001	0	16144
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
THGL48F105047449	IUR0304501	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				80
2	B	BP-LAB CHECK WIRING SYSTEM AND FOCUS HEADLAMP.			✓ 100%	204.00
3	B	BP-LAB REMOVE/REFIX FRONT PARKING SENSORS.			✓	204.00
4	B	BP-MECH REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING, FIT NEW PARTS AND REGAS. photo			X ?	816.00
5	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS, L/F WHEEL HOUSING, CUT AND WELD PANEL AND FIT NEW PARTS.			✓	3264 4080.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						5384

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25/10/2018

14:28

SN0001



Borneo Motor



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg
Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	51000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68398637
	Document No 0	
	Document Date 25/10/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L5	03/12/2012	SN0001	0	16144	

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
THGL46F105047449	1UR0304501	60	Wally Tan G H	--/--/--	0.00	--/--/-- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
6	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED FRONT PORTION OF CAR.			✓	3000 3250.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT) (BONNET, SUPPORT PANEL)			✓	200.00
8	L	BP-LPO SUPPLY REGN PLATE (PO# FRONT (NETT)			✓	96.00
9	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.			✓	204.00
10	B	BP-LAB REMOVE/REFIX REVERSE SENSORS.			✓	204.00
11	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION.			✓	204.00
12	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.			✓	816.00
13	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN, REAR END PANEL, SPARE WHEEL PAN, BOOT, CUT AND WELD PANEL AND FIT NEW PARTS.			✓	2448.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						1632

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

25/10/2018
14:28

SN0001

ACCOUNTS



Borneo Motors



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd.

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238623 Attn: Mr Eugene Lim Poh Hian Work: 68356637	
		Document No 0		
		Document Date 25/10/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGRW	L5	USF41R	03/12/2012	SN0001	0	16144

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
THGL46F105047449	IURO304501	60	Wally Tan G H	---	0.00	---

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
14	B	SP-RES	SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.			✓ 2/100	2600.00
15	Z	SP-SLANT	SUPPLY SEALANT (NETT) (REAR END PANEL)			ny X ?	100.00
16	B	SP-ECU	TO RESET ECU AND REPROGRAMME			✓	204.00
17	L	SP-LPO	SUPPLY REGN PLATE (PO#) REAR (NETT)			nnX	96.00
18	1	L53301-50100	HOOD SUB-ASSY 2754.60	1.00	2739.00	bt /	2739.00
19	2	T90467-09050	CLIP 28.80	12.00	2.40	ny /	28.80
20	3	T68723-28220	LABEL, COOLER 11.60	1.00	11.50	na /	11.50
21	4	L74533-47010	LABEL, HEADLAMP 6.10	1.00	6.10	we /	6.10
22	5	T45248-30020	LABEL, STEERING 4	1.00	4.00	we /	4.00
23	6	L11293-31120	LABEL, ENGINE 4.10	1.00	4.10	we /	4.10
24	7	L53629-50060	FRT BONNET LOCK COVER, 79.60	1.00	79.20	de /	79.20
25	8	L53519-50112	FRT BONNET LOCK, 1895.80	1.00	165.70	ny X ?	165.70
26	9	L53802-50200	FENDER SUB-ASSY, FR	1.00	1885.10	bt /	1885.10
27	0	L55783-30110	PAD, COWL TOE	2.00	36.20	ny X ?	36.20
28	1	L53629-50010	PROTECTOR, FR	1.00	7.90	ny X ?	7.90
29	2	T53879-50030	RETAINER, FR FENDER 10.30	1.00	10.30	de /	10.30
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.					8042.90		

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

25/10/2018
14:28

SN0001

ACCOUNTS



Borneo Motor



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg
Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail

Account No

S1000020 / TPCLAIM

Customer Detail

THIRD PARTY CLAIM

Document No

0

Document Date

25/10/2018

M/s Prime Minister's Office
0 Orchard Road
Istana
Singapore 238823
Attn: Mr Eugene Lim Poh Hian
Work: 68356837

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	ASZGHW	L5	USF41R	03/12/2012	SN0001	0	16144

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
PTHGL46F105047449	1UR0304501	60	Wally Tan G H	---	0.00	---

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	3	T90467-07206 CLIP	2.00	2.30	nh X	4.60
31	4	L81185-50680 UNIT, HEADLAMP 6040.00	1.00	6006.10	nh X	6006.10
32	5	L81158-50730 BRACKET, HEADLAMP, 64	1.00	63.60	nh X	63.60
33	6	L81107-60F10 COMPUTER SUB-ASSY	1.00	710.00	nh X	710.00
34	7	T90075-23002 RING, O	1.00	7.10	nh X	7.10
35	8	L90981-20024 BULB, HEADLAMP	1.00	384.20	nh X	384.20
36	9	L90981-13084 BULB HEADLAMP NO.1	1.00	85.00	nh X	85.00
37	0	T90467-07214 CLIP	8.00	2.20	nh X	17.60
38	1	L53119-50060 PROTECTOR, RADIATOR 61.00	1.00	60.80	nh X	60.80
39	2	L53100-50501 GRILLE ASSY, 1991	1.00	1991.00	nh X	1991.00
40	3	L90975-02133 EMBLEM, SYMBOL 580.70	1.00	577.40	nh X	577.40
41	4	S52161-0K040 BUMPER CLIPS 30	8.00	4.00	nh X	32.00
42	5	L52535-50090 RETAINER, BUMPER RH 68.20	1.00	67.90	nh X	67.90
43	6	L52536-50080 RETAINER, BUMPER LH 68.20	1.00	67.90	nh X	67.90
44	7	L52537-50040 RETAINER, BUMPER RH 39.80	1.00	39.50	nh X	39.50
45	8	L52538-50030 RETAINER, BUMPER 39.80	1.00	39.50	nh X	39.50
46	9	L52131-50102 REINFORCEMENT, FR	1.00	723.80	nh X	723.80
47	0	L52611-50160 ABSORBER, FR BUMPER 137.50	1.00	136.60	nh X	136.60
48	1	L52614-50040 ABSORBER, BUMPER LWR	1.00	97.70	nh X	97.70
49	2	L52119-5C904 COVER, FRONT BUMPER 918.70	1.00	913.50	nh X	913.50

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

12071.30

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

12071.30

25/10/2018
14:28

SN0001

ACCOUNTS



Borneo Motor

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel No.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Peh Hian Work: 66356637
	Document No 0	
	Document Date 25/10/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L5	USF41R	03/12/2012	SN0001	0	16144

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
PTHGL46F105047449	1U00304501	60	Wally Tan G H	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
50	3	L52112-50901 EXTENSION, FR BUMPER 312.50	1.00	370.40		370.40
51	4	L52128-50070 COVER, FR BUMPER 32.40	1.00	33.20		33.20
52	5	L53112-50300 GRILLE, RADIATOR LWR	1.00	162.90		162.90
53	6	L81402-50040 COVER, FOG LAMP, LH	1.00	99.10		99.10
54	7	L52114-50260 BRACKET, FR BUMPER 179.30	1.00	178.20		178.20
55	8	T52197-30040 BRACKET, RR BUMPER	2.00	7.50		15.00
56	9	L47749-50090 CLIP 6	4.00	1.50		6.00
57	0	T53879-50020 RETAINER, FR FENDER 48.80	4.00	12.10		48.40
58	1	L85361-50050 BRACKET, WASHER, 28.90	1.00	28.80		28.80
59	2	L85362-50050 BRACKET, WASHER, 28.90	1.00	28.80		28.80
60	3	L85272-50051 CLAMP, HEADLAMP	1.00	22.20		22.20
61	4	L85273-50051 CLAMP, HEADLAMP	1.00	22.20		22.20
62	5	L81220-50100 LAMP ASSY, FOG, LH	1.00	2078.80		2078.80
63	6	L89341-50060 B6 SENSOR, ULTRASONIC,	1.00	536.10		536.10
64	7	L89341-50060 A2 SENSOR, ULTRASONIC	2.00	536.80		1073.60
65	8	L89348-50060 RETAINER, ULTRASONIC 32.60	2.00	16.20		32.40
66	9	L89348-50020 RETAINER, ULTRASONIC 94.40	4.00	23.50		94.00
67	0	L89348-50040 CLIP, ULTRASONIC 70.80	4.00	17.60		70.40
68	1	L53201-50080 SUPPORT SUB-ASSY, 640.40	1.00	1691.40		1691.40
69	2	L57107-50031 FRT BUMPER MOUNTING	1.00	458.40		458.40
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.			7055.30			

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

25/10/2018
14:28

SN0001

ACCOUNTS

**Borneo Motor**



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6831 1388

ESTIMATE

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238023 Attn: Mr Eugene Lim Poh Hian Work: 68356637	
		Document No 0		
		Document Date 25/10/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AK2GHV	L5	03/12/2012	SN0001	0	16144	

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
PTHGL46F105047449	1UR0304501	60	Wally Tan G H		0.00	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
70	3	COVER, RADIATOR	1.00	157.00	un X de	157.00
71	4	SEAL, RADIATOR 77.40	1.00	77.00	net ✓ ?	77.00
72	5	CLIP	3.00	2.90	un X ?	8.70
73	6	CLIPS 30.00	14.00	2.30	net ✓ ?	32.20
74	7	SMOG SENSOR 290	1.00	288.40	net ✓ ?	288.40
75	8	THERMISTOR, COOLER	1.00	111.30	un X ?	111.30
76	9	CONDENSER ASSY	1.00	2070.10	un X ?	2070.10
77	0	JAR, HEADLAMP	1.00	232.20	un X de	232.20
78	1	PLATE, LEXUS	1.00	77.70	un X ?	77.70
79	2	SUPPORT, RR BUMPER RH 105.60	1.00	105.10	net ✓	105.10
80	3	SUPPORT, RR BUMPER LH 105.60	1.00	105.10	net ✓	105.10
81	4	RETAINER, BUMPER RH 111.60	1.00	110.90	net ✓	110.90
82	5	RETAINER, RR BUMPER 111.60	1.00	110.90	net ✓	110.90
83	6	RETAINER, BUMPER RH 293	1.00	291.30	net ✓	291.30
84	7	RETAINER, BUMPER RH 278.90	1.00	277.30	net ✓	277.30
85	8	ABSORBER, RR BUMPER	1.00	197.60	un X ?	197.60
86	9	RR BUMPER PROTECTOR	2.00	3.10	un X ?	6.20
87	0	BUMPER BRACKET, 15	2.00	7.50	net ✓	15.00
88	1	COVER, REAR BUMPER 1058.80	1.00	1052.90	de ✓	1052.90
89	2	PIECE, RR BUMPER, RH 19.90	1.00	19.90	net ✓	19.90
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.				5361.00		

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

5361.20

25/10/2018
14:28

SN0001

ACCOUNTS



Borneo Moto



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Prime Minister's Office 8 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68356637
	Document No 0	
	Document Date 25/10/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AE3GHW	L5	USF41R	03/12/2012	SN0001	0	16144

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTRGL46F105047449	1UR0304501	60	Wally Tan G-H	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
90	3	L52162-50905 PIECE, RR BUMPER, LH 2010	1.00	19.90		19.90
91	4	L52169-50050 COVER, RR BUMPER LOWER	1.00	322.30		322.30
92	5	L52535-28020 RETAINER, FR BUMPER SIDE 32	8.00	4.00		32.00
93	6	L89341-50060 A2 SENSOR, ULTRASONIC	2.00	536.80		1073.60
94	7	L89348-50020 RETAINER, ULTRASONIC	4.00	23.50		94.00
95	8	L89348-50040 CLIP, ULTRASONIC	4.00	17.60		70.40
96	9	L90375-02212 REAR BOOT LID EMBLEM	1.00	62.70		62.70
97	0	L75443-50110 PLATE, LUGGAGE COMPT	1.00	77.70		77.70
98	1	L52023-50090 REAR BKR REINFORCEMENT, 728.60	1.00	724.50		724.50
99	2	L58307-50072 PANEL, LAMP LOWER	1.00	853.80		853.80
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.				3335.20		49,671.80

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 32,768.50 Labour 15,534.00 Materials 192.00 Lubrication/Fluid 0.00 Others 0.00	GST: 7.00% 3,394.62 Less 0.00 Amount Due 51,889.12

25/10/2018
14:28

SN0001

ACCOUNTS



Borneo Motor

Veron Chen (LKKAUTO)

From: Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>
Sent: Tuesday, 22 January 2019 5:58 PM
To: Veron Chen (LKKAUTO); Wally Tan TCBC
Cc: Taufikh (LKKAUTO); SUR
Subject: RE: Final bill for SN1 (SDV7948G)

Dear Veron,


For your info,

Item 54 is "Reinforcement Clip" which is necessary to change.

Thank you.

ALVIN LEE

MAIN LINE +65 66-31- 1500 | DIRECT LINE +65 66-31- 1491 | FAX +65 64-72- 9103
Borneo Motors (Singapore) Pte Ltd
Mailing Address: Level 4, Inchcape Centre, 2 Pandan Crescent, Singapore 128462
www.borneomotors.com.sg | www.lexus.com.sg



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, January 22, 2019 4:45 PM
To: Wally Tan TCBC <wally.tan@borneomotors.com.sg>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>; SUR <sur@lkkauto.com>
Subject: FW: Final bill for SN1 (SDV7948G)

Dear Wally,

Item for No 54 ?

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Wally Tan TCBC <wally.tan@borneomotors.com.sg>
Sent: Monday, 21 January 2019 5:25 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>

Cc: Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>
Subject: RE: Final bill for SN1 (SDV7948G)

Hi Taufikh,

Please find attached final bill of SN1 (SDV7948G) for your kind perusal.

Regards
Wally

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



Attn: Taufik
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68356637
	Document No 0	
	Document Date 21/01/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
2	AEZGHW	L5	03/12/2012	SN0001	45454	16144	64TP//SN0001/101016

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
THGL46F105047449	1UR0304501	60	Wally Tan G H	29/10/2018	8.00	13/11/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE:10.10.18 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY:26.10.18 NO OF REPAIR DAYS: BY:TAUFIKH (LKK) AUTHORISED ON:				80.00
2	B	BP-LAB CHECK WIRING SYSTEM AND FOCUS HEADLAMP.	*			204.00
3	B	BP-LAB REMOVE/REFIX FRONT PARKING SENSORS.	*			204.00
4	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS, L/F WHEEL HOUSING, CUT AND WELD PANEL AND FIT NEW PARTS.	*			3264.00
5	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED FRONT PORTION OF CAR.	*			3000.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT) (BONNET, SUPPORT PANEL)				200.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/01/2019
TIME 17:14

VEHICLE NO SN0001

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 /TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68356637
	Document No 0	
	Document Date 21/01/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L5	USF41R	03/12/2012	SN0001	45454	16144 64TP//SN0001/10101E

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
1THGL46F105047449	1UR0304501	60	Wally Tan G H	29/10/2018	8.00	13/11/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	L	BP-LPO SUPPLY REGN PLATE (PO#3748) FRONT (NETT)	E33			96.00
8	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.	*			204.00
9	B	BP-LAB REMOVE/REFIX REVERSE SENSORS.	*			204.00
10	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION.	*			204.00
11	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.	*			816.00
12	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN, REAR END PANEL, SPARE WHEEL PAN, BOOT, CUT AND WELD PANEL AND FIT NEW PARTS.	*			1632.00
13	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.	*			2100.00
14	B	BP-ECU TO RESET ECU AND REPROGRAMME	18			204.00
15	B	BP-LAB REMOVE/REPAIR FRONT FLAG POLE ASSY.				(A) 816.00
16	1	L53301-50100 HOOD SUB-ASSY	1.00	2754.60		2754.60
17	2	T90467-09050 CLIP	12.00	2.40		28.80

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 21/01/2019

TIME 17:14

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SN0001

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Moto**



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MP-8500000-9

ESTIMATE

Borneo Motors (Singapore)

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 /TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68356637	
		Document No		
		Document Date		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L5	USF41R	03/12/2012	SN0001	45454	16144 64TP//SN0001/10101E

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
THGL46F105047449	1UR0304501	60	Wally Tan G H	29/10/2018 8.00	13/11/2018 18.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
18	3	L53802-50200 FENDER SUB-ASSY, FRONT LH	1.00	1895.80		1895.80
19	4	L81185-50680 UNIT HEADLAMP, LH	1.00	6040.20		6040.20
20	5	L53100-50501 GRILLE ASSY,	1.00	1991.00		1991.00
21	6	L90975-02133 EMBLEM, RADIATOR	1.00	580.70		580.70
22	7	S52161-0K040 PIECE, RR BUMPER	8.00	4.00		32.00
23	8	L52536-50080 RETAINER, BUMPER LH	1.00	68.20		68.20
24	9	L52538-50030 RETAINER, BUMPER	1.00	39.80		39.80
25	0	L52611-50160 ABSORBER, FR BUMPER	1.00	137.50		137.50
26	1	L52119-5C904 COVER, FR BUMPER	1.00	918.70		918.70
27	2	L52128-50070 COVER, BUMPER	1.00	33.40		33.40
28	3	L47749-50090 CLIP, PIN HOLD	4.00	1.50		6.00
29	4	T53879-50020 RETAINER, FR FENDER	4.00	12.20		48.80
30	5	L85361-50050 BRACKET, WASHER,	1.00	28.90		28.90
31	6	L85362-50050 BRACKET, WASHER,	1.00	28.90		28.90
32	7	L89348-50060 RETAINER, ULTRASONIC	2.00	16.30		32.60
33	8	L89348-50020 RETAINER, ULTRASONIC	2.00	23.60		47.20
34	9	L52155-50070 SUPPORT, RR BUMPER RH	1.00	105.60		105.60
35	0	L52156-50060 SUPPORT, RR BUMPER LH	1.00	105.60		105.60
36	1	L52567-50040 RETAINER, BUMPER RR	1.00	111.60		111.60
37	2	L52568-50040 RETAINER, RR BUMPER	1.00	111.60		111.60
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

SECURITY GUARD

DATE 21/01/2019
TIME 17:14

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SN0001

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 68356637	
		Document No 0		
		Document Date 21/01/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L5	USF41R	03/12/2012	SN0001	45454	16144 64TP//SN0001/10101E
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
THGL46F105047449	1UR0304501	60	Wally Tan G H	29/10/2018	8.00	13/11/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
38	3	L52565-50070 RETAINER, BUMPER RR	1.00	293.00		293.00
39	4	L52566-50050 RETAINER, BUMPER RR	1.00	278.90		278.90
40	5	L52197-30040 BRACKET, BUMPER	2.00	7.50		15.00
41	6	L52159-50932 COVER, RR BUMPER	1.00	1058.80		1058.80
42	7	L52161-50905 PIECE, RR BUMPER, RH	1.00	20.10		20.10
43	8	L52162-50905 PLATE, RR BUMPER	1.00	20.10		20.10
44	9	L52535-28020 RETAINER, FR BUMPER SIDE	8.00	4.00		32.00
45	0	T88723-28220 LABEL, COOLER	1.00	11.60		11.60
46	1	L74533-47010 LABEL, HEADLAMP	1.00	6.10		6.10
47	2	T45248-30020 LABEL, STEERING	1.00	4.00		4.00
48	3	L11293-31120 LABEL, ENGINE	1.00	4.20		4.20
49	4	L81158-50730 BRACKET, HEADLAMP,	1.00	64.00		64.00
50	5	L90467-07211 CLIPS	14.00	2.30		32.20
51	6	L52535-50090 RETAINER, BUMPER RH	1.00	68.20		68.20
52	7	L52537-50040 RETAINER, BUMPER RH	1.00	39.80		39.80
53	8	L52023-50090 REINFORCEMENT, RR	1.00	728.60		728.60
54	9	L81119-50280 F65248-16496 Reinforcement clip	1.00	1.70		1.70
55	0	T53879-50020 RETAINER, FR FENDER	1.00	12.20		12.20
56	1	L89348-50040 CLIP, ULTRASONIC	4.00	17.70		70.80
57	2	L53119-50060 PROTECTOR, RADIATOR	1.00	61.20		61.20

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/01/2019
TIME 17:14

VEHICLE NO SN0001

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd.

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Prime Minister's Office 0 Orchard Road Istana Singapore 238823 Attn: Mr Eugene Lim Poh Hian Work: 66356837
	Document No 0	
	Document Date 21/01/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
2	AEZGHW	L5	USF41R	03/12/2012	SN0001	45454	16144 64TP//SN0001/101018

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
THGL46F105047449	1U0304501	60	Wally Tan G H	29/10/2018	8.00	13/11/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
58	3	L89348-50020 RETAINER, ULTRASONIC	2.00	23.60		47.20
59	4	T52112-50901 EXTENSION, FR BUMPER	1.00	372.50		372.50
60	5	T52114-50260 BRACKET, FR BUMPER	1.00	179.30		179.30
61	6	T53203-50902 SUPPORT SUB-ASSY,	1.00	640.40		640.40
62	7	T53292-50070 SEAL, RADIATOR	1.00	77.40		77.40
63	8	T88898-50031 SENSOR, SMOG	1.00	290.00		290.00
64	9	L53629-50060 FRT BONNET LOCK COVER,	1.00	79.60		79.60
65	0	L82114-50050 WIRE, ENGINE ROOM, (A)	1.00	182.20		at✓ 182.20
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary		Total	33,066.60
	Please acknowledge receipt of vehicle	Parts	19,838.60	GST 7.00%	2,314.66
		Labour	13,132.00		
		Materials	96.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	35,381.26

PLEASE TEAR ALONG PERFORATED LINE

SECURITY GUARD

DATE 21/01/2019
TIME 17:14

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SN0001

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 7948G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SEALANT (BONNET, SUPPORT PANEL) (SN)	NECESSARY	200.00	200.00
1	REGN PLATE (PO#) FRONT (SN)	BENT	96.00	96.00
1	SEALANT (REAR END PANEL) (SN)	NOT NECESSARY	100.00	-
1	REGN PLATE (PO#) REAR (SN)	NOT NECESSARY	96.00	-
1	HOOD SUB-ASSY (SN)	BENT	2,754.60	2,754.60
12	CLIP (SN)	NECESSARY	28.80	28.80
1	LABEL, COOLER (SN)	NECESSARY	11.60	11.60
1	LABEL, HEADLAMP (SN)	NECESSARY	6.10	6.10
1	LABEL, STEERING (SN)	NECESSARY	4.00	4.00
1	LABEL, ENGINE (SN)	NECESSARY	4.20	4.20
1	FRT BONNET LOCK COVER (SN)	DEFORMED	79.60	79.60
1	FRT BONNET LOCK (SN)	NOT NECESSARY	165.70	-
2	FENDER SUB-ASSY, FR (SN)	BENT	1,895.80	1,895.80
1	PAD, COWL TOP (SN)	NOT NECESSARY	72.40	-
1	PROTECTOR, FR FENDER (SN)	NOT NECESSARY	7.90	-
1	RETAINER, FR FENDER (SN)	NECESSARY	12.20	12.20
2	CLIP (SN)	NOT NECESSARY	4.60	-
1	UNIT, HEADLAMP (SN)	CRACKED	6,040.20	6,040.20
1	BRACKET, HEADLAMP (SN)	NECESSARY	64.00	64.00
1	COMPUTER SUB-ASSY (SN)	NOT NECESSARY	710.00	-
1	RING, O (SN)	NOT NECESSARY	7.10	-
1	BULB, HEADLAMP (SN)	NOT NECESSARY	384.20	-
1	BULB HEADLAMP NO.1 (SN)	NOT NECESSARY	85.00	-
8	CLIP (SN)	NOT NECESSARY	17.60	-
1	PROTECTOR, RADIATOR (SN)	NECESSARY	61.20	61.20
1	GRILLE ASSY (SN)	CRACKED	1,991.00	1,991.00
1	EMBLEM, SYMBOL (SN)	CUT	580.70	580.70
8	BUMPER CLIPS (SN)	NECESSARY	32.00	32.00
1	RETAINER, BUMPER RH (SN)	NECESSARY	68.20	68.20
1	RETAINER, BUMPER LH (SN)	NECESSARY	68.20	68.20
1	RETAINER, BUMPER RH (SN)	NECESSARY	39.80	39.80
1	RETAINER, BUMPER (SN)	NECESSARY	39.80	39.80
1	REINFORCEMENT, FR (SN)	NOT NECESSARY	723.80	-
1	ABSORBER, FR BUMPER (SN)	DEFORMED	137.50	137.50

Report Ref No. CS/SPF18019519/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABSORBER, BUMPER LWR (SN)	NOT NECESSARY	97.70	-
1	COVER, FRONT BUMPER (SN)	CRACKED	918.70	918.70
1	EXTENSION, FR BUMPER (SN)	DEFORMED	372.50	372.50
1	COVER, FR BUMPER (SN)	CUT	33.40	33.40
1	GRILLE, RADIATOR LWR (SN)	NOT NECESSARY	162.90	-
1	COVER, FOG LAMP, LH (SN)	NOT NECESSARY	99.10	-
1	BRACKET, FR BUMPER (SN)	NECESSARY	179.30	179.30
2	BRACKET, RR BUMPER (SN)	NOT NECESSARY	15.00	-
4	CLIP (SN)	NECESSARY	6.00	6.00
4	RETAINER, FR FENDER (SN)	NECESSARY	48.80	48.80
1	BRACKET, WASHER (SN)	NECESSARY	28.90	28.90
1	BRACKET, WASHER (SN)	NECESSARY	28.90	28.90
1	CLAMP, HEADLAMP (SN)	NOT NECESSARY	22.20	-
1	CLAMP, HEADLAMP (SN)	NOT NECESSARY	22.20	-
1	LAMP ASSY, FOG, LH (SN)	NOT NECESSARY	2,078.80	-
1	SENSOR, ULTRASONIC (SN)	NOT NECESSARY	536.10	-
2	SENSOR, ULTRASONIC (SN)	NOT NECESSARY	1,073.60	-
2	RETAINER, ULTRASONIC(SN)	NECESSARY	32.60	32.60
4	RETAINER, ULTRASONIC (SN)	NECESSARY	94.40	94.40
4	CLIP, ULTRASONIC (SN)	NECESSARY	70.80	70.80
1	SUPPORT SUB-ASSY (SN)	BENT	1,691.40	640.40
1	FRT BUMPER MOUNTING (SN)	NOT NECESSARY	458.40	-
1	COVER, RADIATOR (SN)	NOT NECESSARY	157.60	-
1	SEAL, RADIATOR (SN)	NECESSARY	77.40	77.40
3	CLIP (SN)	NOT NECESSARY	8.70	-
14	CLIPS (SN)	NECESSARY	32.20	32.20
1	SMOG SENSOR (SN)	CRACKED	290.00	290.00
1	THERMISTOR, COOLER (SN)	NOT NECESSARY	111.30	-
1	CONDENSER ASSY (SN)	NOT NECESSARY	2,070.10	-
1	JAR, HEADLAMP (SN)	NOT NECESSARY	232.20	-
1	PLATE, LEXUS (SN)	NOT NECESSARY	77.70	-
1	SUPPORT, RR BUMPER RH (SN)	NECESSARY	105.60	105.60
1	SUPPORT, RR BUMPER LH (SN)	NECESSARY	105.60	105.60
1	RETAINER, BUMPER RR (SN)	NECESSARY	111.60	111.60
1	RETAINER, RR BUMPER (SN)	NECESSARY	111.60	111.60
1	RETAINER, BUMPER RR (SN)	NECESSARY	293.00	293.00

Report Ref No. CS/SPF18019519/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RETAINER, BUMPER RR (SN)	NECESSARY	278.90	278.90
1	ABSORBER, RR BUMPER (SN)	NOT NECESSARY	197.60	-
2	RR BUMPER PROTECTOR (SN)	NOT NECESSARY	6.20	-
2	BUMPER BRACKET (SN)	NECESSARY	15.00	15.00
1	COVER, REAR BUMPER (SN)	DEFORMED	1,058.80	1,058.80
1	PIECE, RR BUMPER, RH (SN)	NECESSARY	20.10	20.10
1	PIECE, RR BUMPER, LH (SN)	NECESSARY	20.10	20.10
1	COVER, RR BUMPER LOWER (SN)	NOT NECESSARY	322.30	-
8	RETAINER, FR BUMPER SIDE (SN)	NECESSARY	32.00	32.00
2	SENSOR, ULTRASONIC (SN)	NOT NECESSARY	1,073.60	-
4	RETAINER, ULTRASONIC (SN)	NOT NECESSARY	94.00	-
4	CLIP, ULTRASONIC (SN)	NOT NECESSARY	70.40	-
1	REAR BOOT LID EMBLEM (SN)	NOT NECESSARY	62.70	-
1	PLATE, LUGGAGE COMPT (SN)	NOT NECESSARY	77.70	-
1	REAR BPR REINFORCEMENT (SN)	BENT	728.60	728.60
1	PANEL, LAMP LOWER (SN)	TO REPAIR SEE LABOUR	853.80	-
1	F65248-16496 REINFORCEMENT CLIP (SN) (ADDITIONAL)	NECESSARY	1.70	1.70
1	WIRE, ENGINE ROOM (SN) (ADDITIONAL)	CUT	182.20	182.20
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			33,621.80	20,214.60
	LABOUR			
	CHECK WIRING SYSTEM AND FOCUS HEADLAMP.		204.00	204.00
	REMOVE / REFIX FRONT PARKING SENSORS.		204.00	204.00
	REMOVE / REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING, FIT NEW PARTS AND REGAS.	NOT NECESSARY	816.00	-
	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS, L/F WHEEL HOUSING, CUT AND WELD PANEL AND FIT NEW PARTS. INCLUSIVE OF THE REPAIR OF PANEL, LAMP LOWER.		4,080.00	3,264.00
	SPRAY PAINT ON DAMAGED AFFECTED FRONT PORTION OF CAR.		3,250.00	3,000.00
	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.		204.00	204.00
	REMOVE / REFIX REVERSE SENSORS.		204.00	204.00
	REMOVE / REFIX REAR BUMPER LOWER EXTENSION.		204.00	204.00

Report Ref No. CS/SPF18019519/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.		816.00	816.00
	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN, REAR END PANEL, SPARE WHEEL PAN, BOOT, CUT AND WELD PANEL AND FIT NEW PARTS.		2,448.00	1,632.00
	SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.		2,600.00	2,100.00
	TO RESET ECU AND REPROGRAMME.		204.00	204.00
	REMOVE / REPAIR FRONT FLAG POLE ASSY. (ADDITIONAL)		816.00	816.00
			16,050.00	12,852.00
GRAND TOTAL			49,671.80	33,066.60

RECOMMENDED COST OF REPAIRS				33,066.60
-----------------------------	--	--	--	-----------

Report Ref No. CS/SPF18019519/T1vd3e2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$45,000-\$50,000

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.