



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLG9154BMake & Model : HONDA SHUTTLE 1.5 HYBRID CYear of Manufacture : 2016Chassis No. : GP71043128Ins Company : AIG VS AXAEngine No. : LEB4262913Excess : -Policy No. : -Date of Accident : 22.10.2018Time of Accident : 12:45

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Parts (a) Cost / List Price Items \$ 7,550.30Plus/Less 20% \$ 1,510.06Total of Cost / List \$ 6,040.24(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 270.00Total Parts Cost (Appendix A) \$ 6,310.24Labour (Appendix B) \$ 3,910.00Total Repair Cost \$ 10,220.24

Case Owner : _____

Signature : _____

Contact No.
Frt Counter Operation63837103 - Patrick Tia
63837730 - Brenda Ng
63837466 - Rohani
braddell_cr@sparkcarcare.com**Workshop Operation**63837656 - Ngo Toh Wee
63837362 -
63838115 - William Wang
63838115 - Andrew Goh
braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : CKC
 Survey conducted on : 26/10/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 5 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 26/10/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG9154B Case Owner : 0

Make & Model : HONDA SHUTTLE 1.5 HYE Year Manufacture : 2016

Chassis No : GP71043128 Engine No : LEB4262913

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1	<i>Bz</i>	\$ 1,150.60			<i>✓</i>
2	Rear bumper garnish LH	1	<i>Re</i>	\$ 45.00			<i>✓</i>
3	Rear bumper garnish RH	1	<i>Sn</i>	\$ 45.00			<i>X</i>
4	Rear bumper garnish reflector LH	1	<i>Sen</i>	\$ 45.20	<i>52.50</i>		<i>✓</i>
5	Rear bumper garnish reflector RH	1	<i>Sn</i>	\$ 45.20			<i>X</i>
6	Rear bumper retainer LH	1	<i>Dr's</i>	\$ 26.50	<i>38.50</i>		<i>✓</i>
7	Rear bumper retainer RH	1	<i>Sn</i>	\$ 26.50			<i>X</i>
8	Rear bumper clips	10	<i>Re</i>	\$ 39.00			<i>✓</i>
9	Reverse sensor set	1			<i>Short</i>	\$ 200.00	<i>✓</i>
10	Tailgate	1	<i>Bz</i>	\$ 1,193.00			<i>✓</i>
11	Tailgate badge logo	1	<i>Re</i>	\$ 38.60			<i>✓</i>
12	Tailgate emblem - SHUTTLE	1	<i>Re</i>	\$ 55.00			<i>✓</i>
13	Tailgate emblem - HYBRID	1	<i>Re</i>	\$ 80.10			<i>✓</i>
14	Tailgate lamp LH	1	<i>Sn</i>	\$ 395.00			<i>X</i>
15	Tailgate lamp RH	1	<i>Sn</i>	\$ 395.00			<i>X</i>
16	Tailgate upper lock	1	<i>R</i>	\$ 157.60			<i>X</i>
17	Tailgate weatherstrip	1	<i>Sn</i>	\$ 168.50			<i>X</i>
18	Rear windscreen moulding - top	1	<i>Re</i>	\$ 32.10			<i>✓</i>
19	Rear windscreen moulding - lower	1	<i>Re</i>	\$ 80.00			<i>✓</i>
20	Rear windscreen sealant	1	<i>Re</i>			\$ 40.00	<i>✓</i>
21	Rear windscreen inner seal	1	<i>Re</i>			\$ 30.00	<i>✓</i>
22	Taillamp LH	1	<i>Sn</i>	\$ 520.50			<i>X</i>
23	Rear end panel	1	<i>R</i>	\$ 601.50			<i>X</i>
24	Rear end panel LH	1	<i>R</i>	\$ 205.60			<i>X</i>
25	Rear end panel RH	1	<i>R</i>	\$ 205.60			<i>X</i>
26	Rear end panel inner garnish	1	<i>Sn</i>	\$ 155.80			<i>X</i>
27	Rear end buzzer	1	<i>Sn</i>	\$ 95.10			<i>X</i>
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **SLG9154B** Case Owner : **0**
 Make & Model : **DA SHUTTLE 1.5 HYBRID CVT** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	\$120.00	✓
2	To transfer tailgate parts and fittings to new tailgate.	\$180.00	801
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	8
4	Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cutting/welding and replacing damaged parts. (per day \$240.00) (800 - 720)	\$1,680.00	800
5	To replace reverse sensor set.	\$120.00	801
6	To check wiring functions.	\$80.00	801
7	To putty, apply primer & spray-paint the rear bumper, tailgate, RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	\$1,250.00	7501
8	To apply rust-proofing on repaired/replaced panels.	\$200.00	501
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.