

Spark Car Care
ComfortDelgro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bill To : AX	A Vehi	cle Number :s	LG9154B
Attn to : LKK - MR. F	<i>KENNETH</i> Type	Of Claim	TP
A. Spare parts	\$ 2,794.40	F. Total Parts	\$ 2,505.52
B. Supplementary	\$	G. Total Labour	\$ 1,750.00 / 70
C. Nett Price	\$ -	H. Total Repair	\$ 4,255.52
D. Supp Nett Price	\$ -	I. Excess	
E. S/Nett	\$ 270.00	P/P Total	4,255:52 4205.52
Total Spare Parts Price	\$ 2,794.40		100000
Cost plus / List Down 20%	558.88 2,235.52	Lump Sum Less	\$
Total Nett Price Nett Price Less	\$ -	Lump Sum Rounding	
Total	-	Total Finalized	\$ 4,255.52
N.B. If we DO NOT receive you	r reply within 2 weeks, we shall t	treat the above finalized amount as co	onfirmed L correct.
Remarks : Please comfirm and revert b	y Fax or Email		
Date In :	Total Repair Day		
Date Survey :	LOU/ Day		
Date Out ;	Total LOU		
Sat/Sun/Ph. :	Rental/Day	***************************************	
Authorized Repair Day 5	Total Rental		
Submitted By / Date : WILLIAM WANG 29.11.2018	Confirmed By / Date :		

Spark Car Care ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SLG9154B	Case Owner	:	0
Make & Model	:	HONDA SHUTTLE 1.5 HYE	Year Manufacture	:	2016
Chassis No	;	GP71043128	Engine No	:	LEB4262913
Sales Order	:		Supplier	:	
Order By	:		Type of Claim	;	<u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 1,150.60			
2	Rear bumper garnish LH	1		\$ 45.00			
3	Rear bumper garnish RH	1					
4	Rear bumper garnish reflector LH	1		\$ 52.50			
5	Rear bumper garnish reflector RH	1					
6	Rear bumper retainer LH	1		\$ 28.50			
7	Rear bumper retainer RH	1				10	
8	Rear bumper clips	10		\$ 39.00			
9	Reverse sensor set	1			Short	\$ 200.00	
10	Tailgate	1		\$ 1,193.00			
11	Tailgate badge logo	1		\$ 38.60			
12	Tailgate emblem - SHUTTLE	1		\$ 55.00			
13	Tailgate emblem - HYBRID	1		\$ 80.10			
14	Tailgate lamp LH	1					
15	Tailgate lamp RH	1					
16	Tailgate upper lock	1					
17	Tailgate weatherstrip	1 1					
18	Rear windscreen moulding - top	1		\$ 32.10			
19	Rear windscreen moulding - lower	1		\$ 80.00			
20	Rear windscreen sealant	1				\$ 40.00	
21	Rear windscreen inner seal	1				\$ 30.00	
22	Taillamp LH	1 1					
23	Rear end panel	1					
24	Rear end panel LH	11					
25	Rear end panel RH	1					
26	Rear end panel inner garnish	1					
27	Rear end buzzer	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd 205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. :	SLG9154B	Case Owner		0	
Make & Model:	DA SHUTTLE 1.5 HYBRID CVT	Year of Manufacture	*	2016	

Labour Description	Esimated Price	Adjusted Price		
To remove/refit rear windscreen to facilitate repairs.	\$120.00	\$	120.00	
To transfer tailgate parts and fittings to new tailgate.	\$180.00	\$	80.00	
To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	-	X	
Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cuttung/welding and replacing damaged parts. (per day \$240.00)	\$1,680.00	\$	600.00	
To replace reverse sensor set.	\$120.00	\$	80.00	
To check wiring functions.	\$80.00	\$	20.00	
To putty, apply primer & spray-paint the rear bumper, tailgate, RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	\$1,250.00	\$	750.00	
To apply rust-proofing on repaired/replaced panels.	\$200.00	\$	50/ 100.00	
	To remove/refit rear windscreen to facilitate repairs. To transfer tailgate parts and fittings to new tailgate. To remove/refit boot compartment trims and garnish to facilitate repairs. Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cuttung/welding and replacing damaged parts. (per day \$240.00) To replace reverse sensor set. To check wiring functions. To putty, apply primer & spray-paint the rear bumper, tailgate, RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	To remove/refit rear windscreen to facilitate repairs. \$120.00 To transfer tailgate parts and fittings to new tailgate. \$180.00 To remove/refit boot compartment trims and garnish to \$280.00 facilitate repairs. \$1,680.00 Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cuttung/welding and replacing damaged parts. (per day \$240.00) To replace reverse sensor set. \$120.00 To check wiring functions. \$80.00 To putty, apply primer & spray-paint the rear bumper, tailgate, \$1,250.00 RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	To remove/refit rear windscreen to facilitate repairs. \$120.00 \$ To transfer tailgate parts and fittings to new tailgate. \$180.00 \$ To remove/refit boot compartment trims and garnish to \$280.00 - facilitate repairs. \$1,680.00 \$ Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cuttung/welding and replacing damaged parts. (per day \$240.00) To replace reverse sensor set. \$120.00 \$ To check wiring functions. \$80.00 \$ To putty, apply primer & spray-paint the rear bumper, tailgate, RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.