



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLG9154BMake & Model : HONDA SHUTTLE 1.5 HYBRID CYear of Manufacture : 2016Chassis No. : GP71043128Ins Company : AIG VS AXAEngine No. : LEB4262913Excess : -Policy No. : -Date of Accident : 22.10.2018Time of Accident : 12:45

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimate**Parts (a) Cost / List Price Items \$ 7,550.30Plus/Less 20% \$ 1,510.06Total of Cost / List \$ 6,040.24(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 270.00Total Parts Cost (Appendix A) \$ 6,310.24Labour (Appendix B) \$ 3,910.00Total Repair Cost \$ 10,220.24

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell\_cr@sparkcarcare.com

**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell\_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
 Company : CKK  
 Survey conducted on : 26/10/18 at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 26/10/18

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : **SLG9154B** Case Owner : **0**

Make & Model : **HONDA SHUTTLE 1.5 HYE** Year Manufacture : **2016**

Chassis No : **GP71043128** Engine No : **LEB4262913**

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : **TP**

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1	<i>Bj</i>	\$ 1,150.60			✓
2	Rear bumper garnish LH	1	<i>Re</i>	\$ 45.00			✓
3	Rear bumper garnish RH	1		\$ 45.00			?
4	Rear bumper garnish reflector LH	1	<i>Sen</i>	\$ 45.20			✓
5	Rear bumper garnish reflector RH	1	<i>Sen</i>	\$ 45.20			X
6	Rear bumper retainer LH	1	<i>Di's</i>	\$ 26.50			✓
7	Rear bumper retainer RH	1	<i>Sen</i>	\$ 26.50			X
8	Rear bumper clips	10	<i>Re</i>	\$ 39.00			✓
9	Reverse sensor set	1				\$ 200.00	?
10	Tailgate	1	<i>Bj</i>	\$ 1,193.00			✓
11	Tailgate badge logo	1	<i>Re</i>	\$ 38.60			✓
12	Tailgate emblem - SHUTTLE	1	<i>Re</i>	\$ 55.00			✓
13	Tailgate emblem - HYBRID	1	<i>Re</i>	\$ 80.10			✓
14	Tailgate lamp LH	1	<i>Sen</i>	\$ 395.00			X
15	Tailgate lamp RH	1	<i>Sen</i>	\$ 395.00			X
16	Tailgate upper lock	1	<i>R</i>	\$ 157.60			X
17	Tailgate weatherstrip	1	<i>Sen</i>	\$ 168.50			X
18	Rear windscreen moulding - top	1	<i>Re</i>	\$ 32.10			✓
19	Rear windscreen moulding - lower	1	<i>Re</i>	\$ 80.00			✓
20	Rear windscreen sealant	1	<i>Re</i>			\$ 40.00	✓
21	Rear windscreen inner seal	1	<i>Re</i>			\$ 30.00	✓
22	Taillamp LH	1	<i>Sen</i>	\$ 520.50			X
23	Rear end panel	1		\$ 601.50			?
24	Rear end panel LH	1		\$ 205.60			?
25	Rear end panel RH	1		\$ 205.60			?
26	Rear end panel inner garnish	1	<i>Sen</i>	\$ 155.80			X
27	Rear end buzzer	1		\$ 95.10			?
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Labour

Vehicle No. : **SLG9154B** Case Owner : **0**  
 Make & Model : **DA SHUTTLE 1.5 HYBRID CVT** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	\$120.00	✓
2	To transfer tailgate parts and fittings to new tailgate.	\$180.00	801
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	?
4	Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cutting/welding and replacing damaged parts. (per day \$240.00) (800 - 720)	\$1,680.00	?
5	To replace reverse sensor set.	\$120.00	801
6	To check wiring functions.	\$80.00	801
7	To putty, apply primer & spray-paint the rear bumper, tailgate, RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	\$1,250.00	7501
8	To apply rust-proofing on repaired/replaced panels.	\$200.00	?
<div style="border: 1px solid black; padding: 5px;"> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer                      Signature:                      Date:</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.