



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLG9154BMake & Model : HONDA SHUTTLE 1.5 HYBRID CYear of Manufacture : 2016Chassis No. : GP71043128Ins Company : AIG VS AXAEngine No. : LEB4262913Excess : -Policy No. : -Date of Accident : 22.10.2018Time of Accident : 12:45

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 7,550.30Plus/Less 20% \$ 1,510.06Total of Cost / List \$ 6,040.24(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 270.00Total Parts Cost (Appendix A) \$ 6,310.24Labour (Appendix B) \$ 3,910.00Total Repair Cost \$ 10,220.24

Contact No

Frnt Counter Operation

63837103 – Patrick Tia

63837730 - Brenda Ng

63837466 – Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLG9154B Case Owner : 0

Make & Model : HONDA SHUTTLE 1.5 HYE Year Manufacture : 2016

Chassis No : GP71043128 Engine No : LEB4262913

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 1,150.60			
2	Rear bumper garnish LH	1		\$ 45.00			
3	Rear bumper garnish RH	1		\$ 45.00			
4	Rear bumper garnish reflector LH	1		\$ 45.20			
5	Rear bumper garnish reflector RH	1		\$ 45.20			
6	Rear bumper retainer LH	1		\$ 26.50			
7	Rear bumper retainer RH	1		\$ 26.50			
8	Rear bumper clips	10		\$ 39.00			
9	Reverse sensor set	1				\$ 200.00	
10	Tailgate	1		\$ 1,193.00			
11	Tailgate badge logo	1		\$ 38.60			
12	Tailgate emblem - SHUTTLE	1		\$ 55.00			
13	Tailgate emblem - HYBRID	1		\$ 80.10			
14	Tailgate lamp LH	1		\$ 395.00			
15	Tailgate lamp RH	1		\$ 395.00			
16	Tailgate upper lock	1		\$ 157.60			
17	Tailgate weatherstrip	1		\$ 168.50			
18	Rear windscreen moulding - top	1		\$ 32.10			
19	Rear windscreen moulding - lower	1		\$ 80.00			
20	Rear windscreen sealant	1				\$ 40.00	
21	Rear windscreen inner seal	1				\$ 30.00	
22	Taillamp LH	1		\$ 520.50			
23	Rear end panel	1		\$ 601.50			
24	Rear end panel LH	1		\$ 205.60			
25	Rear end panel RH	1		\$ 205.60			
26	Rear end panel inner garnish	1		\$ 155.80			
27	Rear end buzzer	1		\$ 95.10			
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Vehicle No.	: <u>SLG9154B</u>	Case Owner	: <u>0</u>
Make & Model	: DA SHUTTLE 1.5 HYBRID CVT	Year of Manufacture	: <u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.