51 Ubi Ave 1

#01-25 Paya Ubi Industrial Park

(S) 408933 DID: 6742 3197 Fax: 6741 4108

Email: chewht@lkkauto.com

From: Hsiao Tong

Sent: Thursday, 17 October, 2013 8:42 AM

To: 'Ruth Chua'

Subject: RE: Your Ref: C0275392 *Our ref: CC3/AXA13012663/H1py3 *ACCIDENT INVOLVING SJA 9393H & SHD

4031T & OTHERS ON 10/07/2013

Dear Ruth,

The repair cost is \$19,410.20 (before GST).

Best regards, Chew Hsiao Tong LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park (S) 408933

DID: 6742 3197 Fax: 6741 4108

Email: chewht@lkkauto.com

From: Ruth Chua [mailto:ruth.chua@axa.com.sg]
Sent: Wednesday, 16 October, 2013 5:35 PM

To: Hsiao Tong

Subject: RE: Your Ref: C0275392 *Our ref: CC3/AXA13012663/H1py3 *ACCIDENT INVOLVING SJA 9393H & SHD

4031T & OTHERS ON 10/07/2013

Hi Hsiao Tong.

How much is the repair cost?

Thanks & Regards,

Ruth

Ruth Chua (Ms)
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
ruth.chua@axa.com.sq
DID: (65) 6880 4087 Fax: (65) 6880 4838

Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From 14 March 2011, AXA Insurance has moved to 8 Shenton Way, #27-01 AXA Tower Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.



Please consider the environment before printing this email

From: Ruth Chua

Sent: Wednesday, October 09, 2013 2:08 PM

To: 'Hsiao Tong'

Subject: FW: Your Ref: C0275392 *Our ref: CC3/AXA13012663/H1py3 *ACCIDENT INVOLVING SJA 9393H & SHD 4031T & OTHERS ON 10/07/2013

Hi Hsiao Tong

Please advise insured that MCF BOLA is an agreement made between insurers. In such chain collisions, the vehicle behind will be 100% liable for the property damage caused to the vehicle in front. It is unfortunate that this should happen to him but we still have to abide by it.

Thanks & Regards,

Ruth

Ms. Ruth Chua

Executive - Motor Claims

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

ruth.chua@axa.com.sg

DID: (65) 6880 4087 Fax: (65) 6880 4838

Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From 14 March 2011, AXA Insurance has moved to 8 Shenton Way, #27-01 AXA Tower Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.



Please consider the environment before printing this email

From: Hsiao Tong [mailto:chewht@lkkauto.com] Sent: Wednesday, October 09, 2013 11:42 AM

To: Ruth Chua

Subject: Your Ref: C0275392 *Our ref: CC3/AXA13012663/H1py3 *ACCIDENT INVOLVING SJA 9393H & SHD 4031T

& OTHERS ON 10/07/2013

Your Ref: C0275392

Our ref: CC3/AXA13012663/H1py3

Dear Sirs.

ACCIDENT INVOLVING SJA 9393H & SHD 4031T & OTHERS ON 10/07/2013

We refer to the above matter.

Please be informed that this is a total 8 vehicles chain collision where our insured was the last vehicle.

We did clarify with insured the nature of the accident and explained to insured the claim fall under MCF BOLA 28. However insured insist that TP had hit onto the front vehicle before insured collided onto TP's vehicle. Insured is the opinion that he is responsible for the rear portion only.

TP insist to settle the matter under MCF BOLA 28: -

- C. General Rules and Exclusions for Chain Collision
- It shall apply: 4.
- Regardless whether the damage caused by the impact is serious or minor or whether the impact has caused ii) visible damage.
- Claim submission where it involves lawyers. If third party lawyer/workshop/claimant submit combined claim (i.e. both PD & PI), the rear vehicle insurer is to settle PD at 100% (regardless of quantum) and offer to settle for PI (according to liability).

Kindly advise.

Best regards, Chew Hsiao Tong
LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Park
(S) 408933
DID: 6742 3197

Fax: 6741 4108

Email: chewht@lkkauto.com

Hsiao Tong

From: Hsiao Tong

Thursday, 14 November, 2013 4:13 PM 'Catherine Koh Mui Gek' Sent:

To: William Tan Thoo Seng Cc:

Subject: DOA: 10/07/2013; Your ref: T 0713/ SHD 4031T/ WT (J) *Our ref:

CC3/AXA13012663/H1py3 [ACCIDENT INVOLVING SJA 9393H AND SHD 4031T]

Attachments: OI report_SJA 9393H.pdf

Your ref: T 0713/ SHD 4031T/ WT (J) Without Prejudice Our ref: CC3/AXA13012663/H1py3

Dear Sirs,

ACCIDENT INVOLVING SJA 9393H AND SHD 4031T ON 10/07/2013

We refer to the above matter.

Enclosed herewith our insured report for your perusal.

Our insured is disputing the circumstances of the accident as there was a prior collision for the vehicle in front.

In view of the above, we would like to inform your that our principal AXA is unable to look into your client's claim.

Best regards, Chew Hsiao Tong LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park (S) 408933

DID: 6742 3197 Fax: 6741 4108

Email: chewht@lkkauto.com

Hsiao Tong (LKKAuto)

From: CHAN Kian Chuan <kianchuan.chan@axa.com.sg>

Sent: Tuesday, 23 October 2018 11:04 AM

To: Mei Kwan (LKKAuto); Hsiao Tong (LKKAuto)

Cc: Admin A

Subject: RE: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref:

T0713/SHD4031T/AT | AXA Ref: C0275392MC/NPS

Attachments: img-X22091833-0001.pdf

Importance: High

Hi Hsiao Tong,

Please forward us a copy of the survey report. TP LOD as attached for your handling. Please handle this matter on an urgent basis.

Thank you.

Warmest Regards

KC Chan | Senior Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: kianchuan.chan@axa.com.sg
Customer Care No. 1800 8804888



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, October 22, 2018 9:39 AM

To: CHAN Kian Chuan <kianchuan.chan@axa.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref: T0713/SHD4031T/AT | AXA

Ref: C0275392MC/NPS

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge	
CC3/AXA13012663/H1py3w2	Hsiao Tong - 6742 3197	

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CHAN Kian Chuan < kianchuan.chan@axa.com.sg>

Sent: Monday, 22 October, 2018 9:37 AM

To: Admin A <admin-a@lkkauto.com>; Admin-B <admin-b@lkkauto.com>

Subject: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref: T0713/SHD4031T/AT | AXA Ref:

C0275392MC/NPS Importance: High

Hi LKK,

Please forward us a copy of the survey report for this matter on an urgent basis.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

Warmest Regards

KC Chan | Senior Specialist, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: kianchuan.chan@axa.com.sg Customer Care No. 1800 8804888



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.
-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are

not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 30 October 2018 3:13 PM

To:

'aileentan@cdge.com.sg'

Cc:

Admin A

Subject:

Your Ref: T 0713/ SHD 4031T/ WT(J) *Our Ref: CC3/AXA13012663/H1py3w2 -1 [ACCIDENT INVOLVING SJA 9393H(AXA) / SHD 4031T/ OTHERS ON 10/07/2013]

Your Ref: T 0713/ SHD 4031T/ WT(J)

Without Prejudice

Our Ref: CC3/AXA13012663/H1py3w2 -1

Dear Sirs/Madam,

ACCIDENT INVOLVING SJA 9393H(AXA) / SHD 4031T/ OTHERS ON 10/07/2013

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$22,800.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Aileen Tan Lee Noi <aileentan@cdge.com.sg>
Sent: Wednesday, 31 October 2018 8:29 AM

To: Hsiao Tong (LKKAuto)

Cc: Admin A

Subject: [Accept Offer] LKK Ref: CC3/AXA13012663/H1py3w2 CDGE Ref: T 0713/ SHD

4031T/ AT >> Acc on 10.07.2013 invig SHD4031T, SJA9393H [AXA] & Ors

WITHOUT PREJUDICE

Ms Chew Hsiao Tong M/s LKK Auto Consultants Pte Ltd

Your email dated 30 October 2018 refers.

Strictly without admission of liability and solely for quick amicable settlement, we accept your global offer of S\$22,800.00. Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim, if any of the taxi driver.

Kindly arrange to let us have discharge voucher for early execution. Thank you.

Best Regards Aileen Tan

Claims Department | ComfortDelGro Engineering Pte Ltd

Off: 6214 8735 | Fax: 6214 1843

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Tuesday, 30 October 2018 15:12

To: Aileen Tan Lee Noi

Cc: Admin A

Subject: Your Ref: T 0713/ SHD 4031T/ WT(J) *Our Ref: CC3/AXA13012663/H1py3w2 -1 [ACCIDENT INVOLVING SJA

9393H(AXA) / SHD 4031T/ OTHERS ON 10/07/2013]

Your Ref: T 0713/ SHD 4031T/ WT(J)

Our Ref: CC3/AXA13012663/H1py3w2 -1

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SJA 9393H(AXA) / SHD 4031T/ OTHERS ON 10/07/2013

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$22,800.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDetGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Hsiao Tong (LKKAuto)

From:

CHAN Kian Chuan <kianchuan.chan@axa.com.sg>

Sent:

Monday, 29 October 2018 2:59 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A

Subject:

RE: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref:

T0713/SHD4031T/AT | AXA Ref: C0275392MC/NPS // LKK REF:

CC3/AXA13012663/H1py3w2 -1

Importance:

High

Hi Hsiao Tong,

Please proceed for settlement not exceeding \$22,897.36

1. Cost of Repair(w/GST)

\$ 20,768.91(\$19,410.20 +7%)

2. Loss of Rental (14 days x \$101.65)

\$ 1,423.10

3. Loss of Income (14 days x \$50.00)

\$ 700.00

4. LTA/GIA search fee

\$ 5.35

Total \$ 22,897.36

Thank you.

Warmest Regards

KC Chan | Senior Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: kianchuan.chan@axa.com.sg Customer Care No. 1800 8804888





Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, October 29, 2018 10:07 AM

To: CHAN Kian Chuan <kianchuan.chan@axa.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref: T0713/SHD4031T/AT | AXA

Ref: C0275392MC/NPS // LKK REF: CC3/AXA13012663/H1py3w2 -1

Hi KC,

We refer to the above matter.

We enclosed here with a copy of survey report & survey photos as requested.

As per AXA instruction on year 2013, our last offer to third party is to offer settlement for rear portion and contribute 10% to the frontal damages.

Ms Aileen from CDGE has called us on last Friday (26 Oct 2018) and informed us that AXA will settle the matter based on BOLA 28.

The breakdown of third party claim as per LOD is as follows: -

1. Cost of Repair(w/GST) \$ 20,768.91(\$19,410.20 +7%)
2. Loss of Rental (14.5days x \$101.65) \$ 1,473.93
3. Loss of Income (14.5days x \$80.00) \$ 1,160.00
4. LTA/GIA search fee \$ 5.35

Total \$ 23,408.19

In view of this, kindly let us have you instruction/ mandate on this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CHAN Kian Chuan <kianchuan.chan@axa.com.sg>

Sent: Tuesday, 23 October 2018 11:04 AM

To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com >; Hsiao Tong (LKKAuto) < chewht@lkkauto.com >

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref: T0713/SHD4031T/AT | AXA

Ref: C0275392MC/NPS Importance: High

Hi Hsiao Tong,

Please forward us a copy of the survey report. TP LOD as attached for your handling. Please handle this matter on an urgent basis.

Thank you.

Warmest Regards

KC Chan | Senior Specialist, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: kianchuan.chan@axa.com.sg

Customer Care No. 1800 8804888



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, October 22, 2018 9:39 AM

To: CHAN Kian Chuan < kianchuan.chan@axa.com.sg>; Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref: T0713/SHD4031T/AT | AXA

Ref: C0275392MC/NPS

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge	
CC3/AXA13012663/H1py3w2	Hsiao Tong - 6742 3197	

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CHAN Kian Chuan <kianchuan.chan@axa.com.sg>

Sent: Monday, 22 October, 2018 9:37 AM

To: Admin A <admin-a@lkkauto.com>; Admin-B <admin-b@lkkauto.com>

Subject: Acc invlg SHD4031T, SJA9393H [AXA] & 6 others on 10.07.2013 | CDGE Ref: T0713/SHD4031T/AT | AXA Ref:

C0275392MC/NPS Importance: High

Hi LKK.

Please forward us a copy of the survey report for this matter on an urgent basis.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

Warmest Regards

KC Chan | Senior Specialist, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: kianchuan.chan@axa.com.sg Customer Care No. 1800 8804888



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	ationale Des Experts En Autom	nobile
AXA	INSURANCE PTE	LTD	Ref : CC3/AXA13012	2663/H1py3w2
	IENTON WAY #27	7-01SINGAPORE 068811	Date: 11-12-2014 Code: AXA2	
1.	V.HOTH CHOA	Policy Particula	rs :- THIRD PARTY CLAI	М
	Insured Veh.	SJA 9393H	Veh. Inspected	SHD 4031T
	Policy No.	P0724115	Coverage (\$)	0.00
	Claim No.	C0275392	Excess (\$)	0.00
	Assign From		Assign Date	12/07/2013
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	HYUNDAI SONATA (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	KMHET41VMCA820784	Colour	BLUE
	Odometer	ometer 163073	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cond	litions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
4.		The second secon	otion of Damages	EDES PERMISSION
	THE VEHICLE SU DAMAGES SEE D	STAINED DAMAGES AT THE F ETAILS.	FRONT AND REAR PORTIO	N.
5.		Gene	ral Information	
	Accident Date	10/07/2013	Inspection Date	12/07/2013
	Survey held at	COMFORTDELGRO ENGINE 59 LOYANG DRIVE SINGAPORE 508969	ERING PTE LTD	,
5a.		CHICAL ONE SUGGES	Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"VICE TO YOUR INSTRUCTIONS,	MTHOUT PREJUDICE" BAS	IS. ED REPAIRS.
5b.			te Days of Repair	LAST LAND DE
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	14 Working Da	ys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4031T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE	503.00	(3)
10	REAR BUMPER CLIP (CONSISTENT)	NOT NECESSARY	19.00	15
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	299.10	18
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,683.40	8
1	REAR FENDER INNER LINING RH (CONSISTENT)	NOT NECESSARY	64.50	88
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	51.80	
1	REAR TYRE RH (CONSISTENT)	SERVICEABLE	180.00	1
1	REAR TYRE RIM RH (CONSISTENT)	DENTED	247.60	247.60
1	REAR WHEEL HUP-CAP RH (CONSISTENT)	CRACKED	125.60	125.40
1	REAR WHEELBEARING ING & HUB RH (CONSISTENT)	NOT NECESSARY	334.50	
1	REAR TRAILING ARM RH (CONSISTENT)	NOT NECESSARY	100.00	1 12
1	REAR ASSIST RH (CONSISTENT)	NOT NECESSARY	100.00	10
1	REAR SHOCK ABSORBER RH (CONSISTENT)	NOT NECESSARY	165.80	8
1	REAR SHOCK ABSORBER MOUNTING RH (CONSISTENT)	NOT NECESSARY	48.10	19
1	REAR CROSSMEMBER (CONSISTENT)	NOT NECESSARY	991.70	23
1	STABILIZER BAR (CONSISTENT)	SERVICEABLE	170.50	38
1	STABILIZER LINK (CONSISTENT)	NOT NECESSARY	56.80	
1	REAR UPPER ARM RH (CONSISTENT)	BENT	279.80	279.80
1	REAR LOWER ARM RH (CONSISTENT)	SERVICEABLE	170.30	8
1	REAR KNUCKLE ARM RH (CONSISTENT)	NOT NECESSARY	479.00	1
- 1	BONNET (CONSISTENT)	BUCKLED	1,001.60	1,001.60
1	BONNET RUBBER LH (CONSISTENT)	SERVICEABLE	15.70	
2	BONNET HINGE LH/RH @\$76.10 (CONSISTENT)	BENT	152.20	152.20
1	BONNET MOULDING (CONSISTENT)	CRACKED	105.20	105.20
1	BONNET LOCK (CONSISTENT)	BENT	42.40	42.40
1	BONNET ABSORBER LH (CONSISTENT)	SERVICEABLE	61.60	- 8
1	BONNET INSULATOR (CONSISTENT)	DEFORMED	202.50	202.50
1	BONNET SEAL (CONSISTENT)	NOT NECESSARY	31.90	8
1	BONNET INSULATOR CLIPS (CONSISTENT)	NECESSARY	7.00	7.00
10.50	BONNET CABLE (CONSISTENT)	SERVICEABLE	39.60	
1	RADIATOR GRILLE (CONSISTENT)	CRACKED	245.30	245.30
	RADIATOR GRILLE U MOULDING (CONSISTENT)	CRACKED	94.70	11,000,000,000,000



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER COVER (CONSISTENT)	CRACKED	468.60	468.60
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	118.50	118.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	438.40	438.40
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	CRACKED	114.00	114.00
1	FRONT BUMPER LIP (CONSISTENT)	SERVICEABLE	52.10	
2	FRONT BUMPER PROTECTOR LH/RH @\$25.40 (CONSISTENT)	O/S CRACKED/N/S SERVICEABLE	50.80	25.40
2	FRONT BUMPER BRACKET LH/RH @\$17.50 (CONSISTENT)	CRACKED	35.00	35.00
2	FRONT BUMPER SIDE BRACKET @\$4.60 (CONSISTENT)	CRACKED	9.20	9.20
1	HEADLAMP SUPPORT PANEL ASSY (CONSISTENT)	CRACKED	889.60	889.60
2	HEADLAMP LH/RH @\$693.80 (CONSISTENT)	CRACKED	1,387.60	1,387.60
2	HEADLAMP HALOGEN BULB LH/RH @\$12.00 (CONSISTENT)	N/S SERVICEABLE/O/S NECESSARY	24.00	12.00
1	RADIATOR (CONSISTENT)	BENT	708.50	708.50
1	RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY (CONSISTENT)	CRACKED	566.40	566.40
1	RADIATOR HOSE UPPER (CONSISTENT)	SERVICEABLE	39.50	102
1	RADIATOR HOSE LOWER (CONSISTENT)	SERVICEABLE	39.50	
1	RADIATOR EXPANSION TANK (CONSISTENT)	N/S CRACKED/O/S DENTED	40.00	40.00
2	HORN UNIT LH/RH @\$72.30 (CONSISTENT)	SERVICEABLE	144.60	72.30
1	HORN WIRE (CONSISTENT)	BUCKLED	130.40	9.5
1	FRONT FENDER RH (CONSISTENT)	BUCKLED	515.80	515.80
1	FRONT FENDER APRON PANEL RH (CONSISTENT)	TORN	637.00	637.00
1	FRONT FENDER SHIELD RH (CONSISTENT)	CRACKED	74.80	74.80
1	FRONT FENDER MUDFLAP RH (CONSISTENT)	CRACKED	13.50	13.50
1	FRONT FENDER SIGNAL LAMP RH (CONSISTENT)	SERVICEABLE	39.50	-
1	FRONT FENDER RETAINER RH (CONSISTENT)	CRACKED	3.00	3.00
1	AIR CLEANER ASSY (CONSISTENT)	SERVICEABLE	107.00	72
1	AIR DUCT (CONSISTENT)	DEFORMED	171.70	171.70
1	AIR FLOW SENSOR (CONSISTENT)	SERVICEABLE	527.80	315
1	RESONATOR TANK HOSE (CONSISTENT)	SERVICEABLE	218.30	(3-
1	AIRCON SENSOR PRESSURE -SUC/LIC (CONSISTENT)	SERVICEABLE	203.40	
1	AIRCON CONDENSER (CONSISTENT)	BENT	947.80	947.80
1	AIRCON RECEIVER (CONSISTENT)	REPEATED	59.60	172
1	AIRCON SUCTION & LIQUID HOSE (CONSISTENT)	BENT	549.10	549.10



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON DISCHARGE HOSE (CONSISTENT)	BENT	194.40	194.40
1	AIRCON BLOWER MOTOR (CONSISTENT)	SERVICEABLE	218.50	
1	AIRCON COMPRESSOR (CONSISTENT)	DENTED	2,381.30	2,381.30
1	BATTERY TRAY (CONSISTENT)	CRACKED	46.20	46.20
1	BATTERY STAY (CONSISTENT)	SERVICEABLE	17.40	1870.60
1	ROCKER PANEL OUTER GARNISH (CONSISTENT)	CRACKED	403.00	403.00
1	WIPER PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	76.00	ra ra
1	WIPER LINK (CONSISTENT)	SERVICEABLE	355.00	100
1	WIPER CONTAINER (CONSISTENT)	CRACKED	51.60	51.60
1	WIPER CONTAINER MOTOR (CONSISTENT)	CRACKED	54.90	54.90
2	FRONT SHOCK ABSORBER ASSY LH/RH @\$177.20 (CONSISTENT)	NOT NECESSARY	354.40	3-
2	FRONT SHOCK ABSORBER MOUNTING @\$62.60 (CONSISTENT)	NOT NECESSARY	125.20	82
2	FRONT SUSPENSION UPPER ARM LH/RH @\$208.70 (CONSISTENT)	O/S DISTORTED/N/S SERVICEABLE	417.40	208.70
-1	RACK & PINION ASSY (CONSISTENT)	SERVICEABLE	1,820.00	
2	STG TIE ROD LH/RH @\$135.00 (CONSISTENT)	SERVICEABLE	270.00	156
2	STG TIE END LH/RH @\$57.90 (CONSISTENT)	NOT NECESSARY	115.80	
1	STABILIZER BAR (CONSISTENT)	SERVICEABLE	185.40	74
2	STABILIZER BAR BUSH LH/RH @\$11.20 (CONSISTENT)	SERVICEABLE	22.40	
2	STABILIZER BAR LINK LH/RH @\$68.10 (CONSISTENT)	SERVICEABLE	136.20	29
2	FRONT SUSPENSION LOWER ARM LH/RH @\$595.90 (CONSISTENT)	NOT NECESSARY	1,191.80	85
2	KNUCKLE ARM LH/RH @\$485.80 (CONSISTENT)	NOT NECESSARY	971.60	-
2	KNUCKLE ARM BEARING LH/RH @\$106.20 (CONSISTENT)	NOT NECESSARY	212.40	*
-31	ENGINE MOUNTING (CONSISTENT)	CRACKED	401.60	401.60
1	ENGINE UNDER COVER (CONSISTENT)	SERVICEABLE	285.90	
1	ENGINE MTG (FRONT) (CONSISTENT)	CRACKED	196.10	196.10
1	ENGINE MTG (REAR) (CONSISTENT)	SERVICEABLE	233.00	-
1	POWER STEERING PUMP (CONSISTENT)	JAMMED	628.50	628.50
1	POWER STEERING TANK (CONSISTENT)	CRACKED	151.40	151.40
	POWER STEERING PRESSURE HOSE ASSY (CONSISTENT)	BENT	511.90	511.90
	POWER STEERING OUTLET HOSE & BRACKET (CONSISTENT)	SERVICEABLE	63.70	ē
1	POWER STEERING PIPE ASSY (CONSISTENT)	BENT	63.70	63.70



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	POWER STEERING PULLEY (CONSISTENT)	SERVICEABLE	56.80	8
1	ECU BRACKET (CONSISTENT)	SERVICEABLE	68.10	8-
1	ECU UNIT (CONSISTENT)	SERVICEABLE	3,502.90	
1	OIL COOLER -TUBE ASSY (CONSISTENT)	BENT	222.60	222.60
1	INTER COOLER (CONSISTENT)	BENT	670.90	670.90
4	INTER COOLER MOUNTING @\$21.60 (CONSISTENT)	CRACKED	43.20	43.20
1	HOSE B TO INTER COOLER (CONSISTENT)	SERVICEABLE	191.40	9
1	HOSE C TO INTER COOLER INLET (CONSISTENT)	SERVICEABLE	94.40	
1	PIPE TO INTER COOLER (CONSISTENT)	SERVICEABLE	139.20	13
1	PIPE TO INTER COOLER OUTLET (CONSISTENT)	SERVICEABLE	203.80	
1	CONTROLLER (PWN) (CONSISTENT)	SERVICEABLE	431.20	2.4
1	OIL COOLES ASSY (CONSISTENT)	BENT	236.60	236.60
1	TURBO CHARGE (CONSISTENT)	SERVICEABLE	3,362.40	S.
1	WIRING -ENGINE (CONSISTENT)	NOT NECESSARY	2,771.70	5.
1	WIRING -FRONT (CONSISTENT)	NOT NECESSARY	1,634.00	
1	JUNCTION BOX ASSY (CONSISTENT)	NOT NECESSARY	901.50	13
1	INHIBITOR SWITCH (CONSISTENT)	NOT NECESSARY	87.00	
1	ENGINE ASSY (CONSISTENT)	NOT NECESSARY	23,800.00	(3)
1	ENGINE TOP COVER (CONSISTENT)	SERVICEABLE	321.70	
1	THROTTLE BODY ASSY (CONSISTENT)	SERVICEABLE	936.90	9
1	ALTERNATOR ASSY (CONSISTENT) (ADDITIONAL)	CRACKED	936.60	936.60
1	PANEL ASSY -COWL SIDE (CONSISTENT) (ADDITIONAL)	BENT	52.20	52.20
1	ALT /POWER STEERING -BELT (CONSISTENT) (ADDITIONAL)	CUT	61.70	61.70
	LESS 20% DISCOUNT		-14,055.74	-3,563.80
			56,222.96	14,255.20
	SPECIAL NETT ITEMS			
1	REAR BUMPER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	200.00	200.00
2	REAR FENDER COMFORT STICKER RH @\$40.00 (SN) (CONSISTENT)	NOT NECESSARY	10.00	85
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	8
1	FRONT NUMBER PLATE (SN) (CONSISTENT) }	NECESSARY	25.00	35.00
1	FRONT NO PLATE TRIM COVER (SN) (CONSISTENT) }	CRACKED	30.00	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER ADVERTISEMENT LOGO RH (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	NEW BATTERY (SN) (CONSISTENT)	SERVICEABLE	180.00	29
	Waster State 1		675.00	385.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER RH.		5,000.00	2,400.00
	SPRAY PAINTING CHARGE.		1,400.00	1,260.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		400.00	110.00
	TOWING CHARGE.		100.00	50.00
	REMOVE /REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE /REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	100
	REMOVE /REFIX UNDERCARRIAGE (RR).		300.00	120.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	8
	FRONT CHASSIS ALIGNMENT CHARGE.		220.00	180.00
	REMOVE /REFIX UNDERCARRIAGE (FRT).		400.00	120.00
	FRONT WHEEL ALIGNMENT.		80.00	60.00
	REMOVE /REFIX RADIATOR.		90.00	60.00
	REMOVE /REFIX AIRCON & REFILL GAS.		130.00	100.00
	REMOVE /REFIX ENGINE (JX/SH).		600.00	200.00
	REMOVE /REFIX DASHBOARD.	NOT NECESSARY	400.00	100
	REMOVE /REFIX FUSE BOX.	NOT NECESSARY	120.00	
			9,690.00	4,770.00
1000	GRAND TOTAL		66,587.96	19,410.20

F REPAIRS 19,410.20	RECOMMENDED COST OF REPAIRS
REPAIRS	RECOMMENDED COST OF REPAIRS

Report Ref No. CC3/AXA13012663/H1py3w2

NG KOK HUA

Automotive Assessor

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	No: SJA 9393H (Insd veh)		Model:	HYUNDAI	
	SHD 4031T (TP veh)	1D 4031T (TP veh)		SONATA (A)	
Date of Accident:	10/07/2013				
Global Sum Settlen	nent : [X] Yes	Т	[] No		
Repair Estimate		: \$	71,249.12		
Final Repair Cost		: \$	20,768.91		
Loss of Token Sum	1	: \$	700.00	14 days at \$50.00 per day	
Rental (if any)		: \$	1,423.10	14 days	
LTA / GIA Search F	ee	: \$	5.35		
Others:		: \$			
		: \$			
Final Settlement Su	um (GLOBAL SUM)	: \$	22,800.00		
pelow)	rkshop GIA Registered	12	[X] YES [Agreed Liability] NO (Kindly indicate	
A) For Non GIA	Registered Workshop:		BOLA Applicable		
B) For GIA Regis	stered Workshop:		28	. Tes/ No BOLA Scenario No.	
BOLA Liability	:(%)		Assessed Liability	y (*):(%)	
* Assessed Lie	ability to be filled only fo	r chain	collisions and for ca	ises where BOLA does not apply.	
Remarks					
-					
Payment Instructi	on: Payee's Breakdow	'n			
1) COMFORTDE	LGRO ENGINEERING	PTE L	TD : \$	22,800.0	
5131			1100		
	NILAH BTE ABDOL WAHAB		07/11/2018		
			Date		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	tionale Des Experts En Auton	nobile
AXA	INSURANCE PTE	LTD	Ref : CC3/AXA1301:	2663/H1ps2 -1
AXA	HENTON WAY #24 TOWERSINGAPO N: KIAN CHUAN		Date: 07-11-2018 Code: AXA2	
1.		Policy Particular	rs :- THIRD PARTY CLA	IM
	Insured Veh.	SJA 9393H	Veh. Inspected	SHD 4031T
	Policy No.	P0724115	Coverage (\$)	0.00
	Claim No.	C0275392	Excess (\$)	0.00
	Assign From		Assign Date	12/07/2013
2.		Vehicle Par	rticulars & Condition	
100 110	Make & Model	HYUNDAI SONATA (A)	c.c	1991
=	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	KMHET41VMCA820784	Colour	BLUE
	Odometer	163073	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cond	litions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
k.		Descrip	otion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE F	RONT AND REAR PORTIO	N.
	DAMAGES SEE D	ETAILS.		
5.		Gene	ral Information	
	Accident Date	10/07/2013	Inspection Date	12/07/2013
	Survey held at	COMFORTDELGRO ENGINE	ERING PTE LTD	
		205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		
5a.			Remarks	
		ON WAS CONDUCTED ON A"VICE TO YOUR INSTRUCTIONS,		
5b.			te Days of Repair	
2000	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	14 Working D	avs



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4031T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	503.00	
10	REAR BUMPER CLIP (CONSISTENT)	NOT NECESSARY	19.00	
1	TAILLAMP (RH) (CONSISTENT)	SERVICEABLE	299.10	
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,683.40	i i
1	REAR FENDER INNER LINING (RH) (CONSISTENT)	NOT NECESSARY	64.50	
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	51.80	-
1	REAR TYRE (RH) (CONSISTENT)	SERVICEABLE	180.00	
1	REAR TYRE RIM (RH) (CONSISTENT)	DENTED	247.60	247.60
1	REAR WHEEL HUP-CAP (RH) (CONSISTENT)	CRACKED	125.60	125.40
1	REAR WHEELBEARING ING & HUB (RH) (CONSISTENT)	NOT NECESSARY	334.50	
1	REAR TRAILING ARM (RH) (CONSISTENT)	NOT NECESSARY	100.00	
1	REAR ASSIST (RH) (CONSISTENT)	NOT NECESSARY	100.00	
1	REAR SHOCK ABSORBER (RH) (CONSISTENT)	NOT NECESSARY	165.80	
1	REAR SHOCK ABSORBER MOUNTING (RH) (CONSISTENT)	NOT NECESSARY	48.10	
1	REAR CROSSMEMBER (CONSISTENT)	NOT NECESSARY	991.70	
1	STABILIZER BAR (CONSISTENT)	SERVICEABLE	170.50	
1	STABILIZER LINK (CONSISTENT)	NOT NECESSARY	56.80	
1	REAR UPPER ARM (RH) (CONSISTENT)	BENT	279.80	279.80
1	REAR LOWER ARM (RH) (CONSISTENT)	SERVICEABLE	170.30	1.0
1	REAR KNUCKLE ARM (RH) (CONSISTENT)	NOT NECESSARY	479.00	
1	BONNET (CONSISTENT)	BUCKLED	1,001.60	1,001.60
1	BONNET RUBBER (LH) (CONSISTENT)	SERVICEABLE	15.70	
2	BONNET HINGE (LH/RH) @\$76.10 (CONSISTENT)	BENT	152.20	152.20
1	BONNET MOULDING (CONSISTENT)	CRACKED	105.20	105.20
1	BONNET LOCK (CONSISTENT)	BENT	42.40	42.40
1	BONNET ABSORBER (LH) (CONSISTENT)	SERVICEABLE	61.60	
1	BONNET INSULATOR (CONSISTENT)	DEFORMED	202.50	202.50
1	BONNET SEAL (CONSISTENT)	NOT NECESSARY	31.90	
1	BONNET INSULATOR CLIPS (CONSISTENT)	NECESSARY	7.00	7.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	39.60	
1	RADIATOR GRILLE (CONSISTENT)	CRACKED	245.30	245.30
1	RADIATOR GRILLE U MOULDING (CONSISTENT)	CRACKED	94.70	94.70
1	FRONT BUMPER COVER (CONSISTENT)	CRACKED	468.60	468.60
	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	118.50	118.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	438.40	438.40
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	CRACKED	114.00	114.00
1	FRONT BUMPER LIP (CONSISTENT)	SERVICEABLE	52.10	
2	FRONT BUMPER PROTECTOR (LH/RH) @\$25.40 (CONSISTENT)	O/S CRACKED / N/S SERVICEABLE	50.80	25.40
2	FRONT BUMPER BRACKET (LH/RH) @\$17.50 (CONSISTENT)	CRACKED	35.00	35.00
2	FRONT BUMPER SIDE BRACKET @\$4.60 (CONSISTENT)	CRACKED	9.20	9.20
1	HEADLAMP SUPPORT PANEL ASSY (CONSISTENT)	CRACKED	889.60	889.6
2	HEADLAMP (LH/RH) @\$693.80 (CONSISTENT)	CRACKED	1,387.60	1,387.6
2	HEADLAMP HALOGEN BULB (LH/RH) @\$12.00 (CONSISTENT)	N/S SERVICEABLE / O/S NECESSARY	24.00	12.0
1	RADIATOR (CONSISTENT)	BENT	708.50	708.5
1	RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY (CONSISTENT)	CRACKED	566.40	566.4
1	RADIATOR HOSE UPPER (CONSISTENT)	SERVICEABLE	39.50	
1	RADIATOR HOSE LOWER (CONSISTENT)	SERVICEABLE	39.50	1
1	RADIATOR EXPANSION TANK (CONSISTENT)	CRACKED	40.00	40.0
2	HORN UNIT (LH/RH) @\$72.30 (CONSISTENT)	N/S SERVICEABLE / O/S DENTED	144.60	72.3
1	HORN WIRE (CONSISTENT)	SERVICEABLE	130.40	
1	FRONT FENDER (RH) (CONSISTENT)	BUCKLED	515.80	515.8
1	FRONT FENDER APRON PANEL (RH) (CONSISTENT)	BUCKLED	637.00	637.0
1	FRONT FENDER SHIELD (RH) (CONSISTENT)	TORN	74.80	74.8
1	FRONT FENDER MUDFLAP (RH) (CONSISTENT)	CRACKED	13.50	13.5
1	FRONT FENDER SIGNAL LAMP (RH) (CONSISTENT)	SERVICEABLE	39.50	
1	FRONT FENDER RETAINER (RH) (CONSISTENT)	CRACKED	3.00	3.0
1	AIR CLEANER ASSY (CONSISTENT)	SERVICEABLE	107.00	3
1	AIR DUCT (CONSISTENT)	DEFORMED	171.70	171.7
1	AIR FLOW SENSOR (CONSISTENT)	SERVICEABLE	527.80	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	RESONATOR TANK HOSE (CONSISTENT)	SERVICEABLE	218.30	-
1	AIRCON SENSOR PRESSURE -SUC/LIC (CONSISTENT)	SERVICEABLE	203.40	-
1	AIRCON CONDENSER (CONSISTENT)	BENT	947.80	947.80
1	AIRCON RECEIVER (CONSISTENT)	REPEATED	59.60	
1	AIRCON SUCTION & LIQUID HOSE (CONSISTENT)	BENT	549.10	549.10
1	AIRCON DISCHARGE HOSE (CONSISTENT)	BENT	194.40	194.40
1	AIRCON BLOWER MOTOR (CONSISTENT)	SERVICEABLE	218.50	
1	AIRCON COMPRESSOR (CONSISTENT)	DENTED	2,381.30	2,381.30
1	BATTERY TRAY (CONSISTENT)	CRACKED	46.20	46.20
1	BATTERY STAY (CONSISTENT)	SERVICEABLE	17.40	
	ROCKER PANEL OUTER GARNISH (CONSISTENT)	CRACKED	403.00	403.00
1	WIPER PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	76.00	
1	WIPER LINK (CONSISTENT)	SERVICEABLE	355.00	
1	WIPER CONTAINER (CONSISTENT)	CRACKED	51.60	51.60
1	WIPER CONTAINER MOTOR (CONSISTENT)	CRACKED	54.90	54.90
2	FRONT SHOCK ABSORBER ASSY (LH/RH) @\$177.20 (CONSISTENT)	NOT NECESSARY	354.40	0.
2	FRONT SHOCK ABSORBER MOUNTING (LH/RH) @\$62.60 (CONSISTENT)	NOT NECESSARY	125.20	
2	FRONT SUSPENSION UPPER ARM (LH/RH) @\$208.70 (CONSISTENT)	O/S DISTORTED / N/S SERVICEABLE	417.40	208.70
1	RACK & PINION ASSY (CONSISTENT)	SERVICEABLE	1,820.00	
2	STG TIE ROD (LH/RH) @\$135.00 (CONSISTENT)	SERVICEABLE	270.00	
2	STG TIE END (LH/RH) @\$57.90 (CONSISTENT)	NOT NECESSARY	115.80	
1	STABILIZER BAR (CONSISTENT)	SERVICEABLE	185.40	
2	STABILIZER BAR BUSH (LH/RH) @\$11.20 (CONSISTENT)	SERVICEABLE	22.40	
2	STABILIZER BAR LINK (LH/RH) @\$68.10 (CONSISTENT)	SERVICEABLE	136.20	
2	FRONT SUSPENSION LOWER ARM (LH/RH) @\$595.90 (CONSISTENT)	NOT NECESSARY	1,191.80	
2	KNUCKLE ARM (LH/RH) @\$485.80 (CONSISTENT)	NOT NECESSARY	971.60	
2	KNUCKLE ARM BEARING (LH/RH) @\$106.20 (CONSISTENT)	NOT NECESSARY	212.40	
1	ENGINE MOUNTING (CONSISTENT)	CRACKED	401.60	401.60
1	ENGINE UNDER COVER (CONSISTENT)	SERVICEABLE	285.90	
1	ENGINE MTG (FRONT) (CONSISTENT)	CRACKED	196.10	196.10



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	ENGINE MTG (REAR) (CONSISTENT)	SERVICEABLE	233.00	8=
1	POWER STEERING PUMP (CONSISTENT)	JAMMED	628.50	628.50
1	POWER STEERING TANK (CONSISTENT)	CRACKED	151.40	151.40
1	POWER STEERING PRESSURE HOSE ASSY (CONSISTENT)	BENT	511.90	511.90
1	POWER STEERING OUTLET HOSE & BRACKET (CONSISTENT)	SERVICEABLE	63.70	· ·
1	POWER STEERING PIPE ASSY (CONSISTENT)	BENT	63.70	63.70
1	POWER STEERING PULLEY (CONSISTENT)	SERVICEABLE	56.80	
1	ECU BRACKET (CONSISTENT)	SERVICEABLE	68.10	-
1	ECU UNIT (CONSISTENT)	SERVICEABLE	3,502.90	
1	OIL COOLER - TUBE ASSY (CONSISTENT)	BENT	222.60	222.60
1	INTER COOLER (CONSISTENT)	BENT	670.90	670.90
4	INTER COOLER MOUNTING @\$21.60 (CONSISTENT)	CRACKED	43.20	43.20
1	HOSE B TO INTER COOLER (CONSISTENT)	SERVICEABLE	191.40	28
1	HOSE C TO INTER COOLER INLET (CONSISTENT)	SERVICEABLE	94.40	
1	PIPE TO INTER COOLER (CONSISTENT)	SERVICEABLE	139.20	
1	PIPE TO INTER COOLER OUTLET (CONSISTENT)	SERVICEABLE	203.80	
1	CONTROLLER (PWN) (CONSISTENT)	SERVICEABLE	431.20	
1	OIL COOLES ASSY (CONSISTENT)	BENT	236.60	236.60
1	TURBO CHARGE (CONSISTENT)	SERVICEABLE	3,362.40	
1	WIRING - ENGINE (CONSISTENT)	NOT NECESSARY	2,771.70	
1	WIRING - FRONT (CONSISTENT)	NOT NECESSARY	1,634.00	
1	JUNCTION BOX ASSY (CONSISTENT)	NOT NECESSARY	901.50	
1	INHIBITOR SWITCH (CONSISTENT)	NOT NECESSARY	87.00	
1	ENGINE ASSY (CONSISTENT)	NOT NECESSARY	23,800.00	
1	ENGINE TOP COVER (CONSISTENT)	SERVICEABLE	321.70	
1	THROTTLE BODY ASSY (CONSISTENT)	SERVICEABLE	936.90	
1	ALTERNATOR ASSY (CONSISTENT) (ADDITIONAL)	CRACKED	936.60	936.60
1	PANEL ASSY -COWL SIDE (CONSISTENT) (ADDITIONAL)	BENT	52.20	52.20
1	ALT /POWER STEERING -BELT (CONSISTENT) (ADDITIONAL)	CUT	61.70	61.70
	LESS 20% DISCOUNT		-14,055.74	-3,563.80
			56,222.96	14,255.20



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR BUMPER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	200.00	200.00
1	REAR FENDER COMFORT STICKER (RH) (SN) (CONSISTENT)	NOT NECESSARY	10.00	e
2	REAR WINDSCREEN SEALANT @ \$40.00 (SN) (CONSISTENT)	NOT NECESSARY	80.00	>
1	FRONT NUMBER PLATE (SN) (CONSISTENT) }	NECESSARY	25.00	35.00
1	FRONT NO PLATE TRIM COVER (SN) (CONSISTENT) }	CRACKED	30.00	
1	FRONT FENDER ADVERTISEMENT LOGO (RH) (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	NEW BATTERY (SN) (CONSISTENT)	SERVICEABLE	180.00	
			675.00	385.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER (RH).		5,000.00	2,400.00
	SPRAY PAINTING CHARGE.		1,400.00	1,260.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		400.00	110.00
	TOWING CHARGE.		100.00	50.00
	REMOVE /REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE /REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	
	REMOVE /REFIX UNDERCARRIAGE (RR).		300.00	120.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	
	FRONT CHASSIS ALIGNMENT CHARGE.		220.00	180.00
	REMOVE /REFIX UNDERCARRIAGE (FRT).		400.00	120.00
	FRT WHEEL ALIGNMENT.		80.00	60.00
	REMOVE /REFIX RADIATOR.		90.00	60.00
	REMOVE /REFIX AIRCON & REFILL GAS.		130.00	100.00
	REMOVE /REFIX ENGINE (JX/SH).		600.00	200.00
	REMOVE /REFIX DASHBOARD.	NOT NECESSARY	400.00	



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

19,410.20

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REMOVE /REFIX FUSE BOX.	REPEATED	120.00	=
			9,690.00	4,770.00
	GRAND TOTAL		66,587.96	19,410.20

Report Ref No. CC3/AXA13012663/H1ps2 -1

NG KOK HUA

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.