

ASS. REC. BY:

REF:

CS/MSG18019595/Dad366

Special Instruction:

Surveyor

Bryem

ASSIGNMENT (Office)

From (Person):

Pauline tham

of

MSG

Date/Time:

29/10/18 @ 9:35am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 1277L

Insured:

SLM 66A

at Workshop m/s

Soon Hock Motor

Tel:

65425119

of

Blk 10, Amk Ind. Park 2A # 01-05/06

Policy No:

28795104MCX

Claim No:

574312

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/10/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:44am 29/10/18

Person Contacted:

Lynn

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHA 1277L - CS/FCI 18012796/Uqd3n2

D.O.A: 10/07/2018

SLM 66A - X

2/11/18

Revert

IA

thru

email.

REF:

ASSIGNMENT

COE Sep 2024

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 1277LYr Regn: 2016 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp Reading: 257143 T/Radio: Insured / Std / NI / NAEng/No: D4FDGU672462C/No: KMHLB41UMGU093603Gen. Cond: 6 / Fair / Poor / BurntSteering: 6 / Jammed / Leaked / Burnt orBrake: 6 / Jammed / Leaked / Burnt orModi: 6 / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Campeon

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 24/10/2018 D.O.I. 29/10/2018Survey held at Chunni AMC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/5 Front y o/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSIG SLM66A27/11/18 Insured 2/5 17000/- with 12 days of rev (Red. 19,769.36, 53%)

RECEIVED 05 DEC 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

) .

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$Report Format: TPLump Sum / I.B.I: (\$ 17,000/-)2500260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2018		29 Oct 2018 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA1277L	Date of Loss:	24/10/2018 23:00 - :59 [24 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 574312	Policy/Cover Note No.:	28795104MCX Coverage: 08/08/2018 - 07/08/2019
Vehicle Reg. No. (Insured):	SLM66A	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/10/2018]		
Adj Asg. Remarks:	oi non reporting. liability not clear. TP agree with SJE - assign LKK Auto Consultants Pte Ltd.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 02 Nov 2018

Preliminary Advice

Insured Vehicle No	: SLM66A	Accident Date	: 24/10/2018
TP Vehicle No	: SHA1277L	Assignment Date	: 29/10/2018
Make	: HYUNDAI I40	Est. Duration of Repair	: 9.00
Date of Inspection	: 29/10/2018		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front and o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,769.36
Revised Amount	:S\$	22,236.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	22,236.96
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHA1277L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	D4FDGU672462
Chassis No.:	KMHLB41UMGU093603
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,899.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$18,899.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2024
PARF Rebate Amount:	\$14,174.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$31,026.00
Total Rebate Amount:	\$45,200.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Dec 2018

OK

MCD018138726 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 25/10/2018 14:35
 SUBMITTED BY: Janet Lim Siang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 14:35
Date Of Accident	24/10/2018 23:30
Exact Location Of Accident	CECIL ST INFRONT TAXI STAND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1277L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	YAP HOW KIAK
NRIC No	S1392727H
Date Of Birth	16/09/1959
Occupation	OUTDOOR
Date Of Driving Pass	09/09/1978
Driving Experience	40 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84441236
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 466 CRAWFORD LANE #13-10
Postcode	190466
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM66A
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RH FRONT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

PILLAR

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

YAP HOW KIAK

Approximate Age

Injuries Sustain

LEGS

Injured person in which vehicle?

SHA1277L

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 25.10.2018 @12:30 Hrs


Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24.10.2018 at about 23:30 hrs, I was travelling along Cecil Street with no passenger on board.

I was stationary at the Taxi Stand E10 to pick up a passenger. Suddenly I felt an impact on my left as veh (B) (SLM 66A) hit my taxi (A) front left portion. Due to the impact, my taxi (A) hit the pillar on my right and therefore my taxi (A) also sustain damages on front right portion.

I have company video fixed in my taxi and photos taken at scene to support my claims.

Veh (B) (SLM 66A). Male driver.

After the accident, I suffered pain on leg and will consult doctor later on.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25.10.2018 @12:30 Hrs

Reporting Centre Personnel's Signature
Name: *Rubini*
NRIC/FIN No.:

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 1277 L

Technician:

Mileage: 257143

Time Printed 29.10.18 3:54 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
0°19'		-3°00' 3°00'
7°36'		-0°19' 5°41'
10°00'		-1°30' 1°30'
31°40'		
31°59'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°57'		-3°00' 3°00'
4°07'		-0°19' 5°41'
-2°29'		-1°30' 1°30'
15°44'		
14°47'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
1°16'		-3°00' 3°00'
3°29'		-3°00' 3°00'
15°56'		-3°00' 3°00'
7°31'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
0°50'		-3°30' 2°30'
-0°11'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°40'		-3°30' 2°30'
0°34'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
1°31'		-3°00' 3°00'
0°23'		-3°00' 3°00'
-0°22'		-3°00' 3°00'

CHUNNI MOTOR WORKS PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1277L

DATE : 25.10.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover cut			\$ 1,052.20	✓
	Front Bumper Bracket (LH/RH) s/c	S	24.60	\$ 49.20	X
	Headlamp Support Panel Assy broken			\$ 907.40	✓
	Headlamp (LH/RH) whole mounting	S	1,388.00	\$ 2,776.00	✓
	Front Fender (LH/RH) s/c	S	566.30	\$ 1,132.60	✓
	Front Fender Apron Panel (LH/RH) broken	S	637.00	\$ 1,274.00	✓
	Front Fender Shield (LH/RH) deformed	S	174.90	\$ 349.80	✓
	Front Door (LH/RH) Dented	S	2,256.40	\$ 4,512.80	✓
	Front Door Rubber s/c	S	290.50	\$ 581.00	X
	Front Door Outer Moulding (LH) cut			\$ 47.10	✓
	Front Door Mirror Assy (LH/RH) N/S broken o/s NH	S	670.00	\$ 1,340.00	✓
	Rocker Panel Outer Garnish, LH/RH o/s s/c N/S broken	S	341.40	\$ 682.80	✓
	Rear Door (LH) Dented			\$ 2,201.10	✓
	Front Pillar Upper Cover/Garnish, LH/RH broken cut	S	83.50	\$ 167.00	✓
	Front Windscreen Moulding broken NH			\$ 113.30	X
	Front Windscreen Pillar Outer (RH) broken (lower)			\$ 1,745.50	✓
	Wiper Container NH			\$ 61.90	X
	Wiper Container Motor NH			\$ 75.00	X
	Front Wheel Rim (LH/RH) broken distorted	S	325.30	\$ 650.60	✓
	Front Wheel Hub Cap (LH/RH) broken cut	S	107.10	\$ 214.20	✓
	Front Wheel Bearing broken	S	150.90	\$ 301.80	✓
	Front Shock Absorber (Assy) (LH/RH) broken distorted	S	342.20	\$ 684.40	✓
	Front Shock Absorber Mounting (LH/RH) NH	S	108.80	\$ 217.60	X
	Front Shock Absorber Fork (LH/RH) NH	S	212.15	\$ 424.30	X
	Front Suspension Upper Arm (LH/RH) NH	S	250.40	\$ 500.80	X
	Front Drive Shaft (LH/RH) broken distorted NH	S	1,030.80	\$ 2,061.60	X
	Rack & Pinion Assy broken			\$ 969.60	✓
	STG Tie End broken distorted	S	62.60	\$ 125.20	✓
	Stabilizer Bar broken distorted			\$ 252.30	✓
	Stabilizer Bar Bush (LH/RH) NH	S	16.40	\$ 32.80	X
	Stabilizer Bar Link broken distorted	S	61.10	\$ 122.20	✓
	Stabilizer Bracket NH	S	24.00	\$ 48.00	X
	Front Suspension Lower Arm (LH/RH) broken distorted	S	529.30	\$ 1,058.60	✓
	Knuckle Arm (LH/RH) broken distorted	S	552.00	\$ 1,104.00	✓
	Engine Under Cover NH			\$ 334.60	X
	Engine Crossmember NH			\$ 2,094.40	X
	ABS Sensor (LH/RH) NH	S	234.00	\$ 468.00	X
	Electric Power Steering NH			\$ 4,880.50	X
			23001.20	\$ 35,614.20	
			18400.96	\$ 7,122.84	
				\$ 28,491.36	

SHA 1277L

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (LH/RH) Nec		\$ 100.00	\$ 200.00	Nett ✓
	Front Door Comfort Logo (LH/RH) Nec		\$ 75.00	\$ 150.00	Nett ✓
	Front Door Advertisement Logo (LH/RH) Nec		\$ 100.00	\$ 200.00	Nett ✓
	Rear Door Advertisement Logo (LH) Nec			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) Nec			\$ 80.00	Nett ✓
	Front Windscreen Sealant 2 NH			\$ 46.00	Nett ✓ X
	Front Tyre (LH/RH) 0/3 (1st 1/3 3rd) 50% depreciation		\$ 216.00 108.00	\$ 432.00	Nett ✓
				\$ 1,208.00	
			838.00		
	Labour Charge				
	Panel Beating			\$ 2,200.00	1200/-
	Spray Painting Charge			\$ 1,800.00	1200/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 150.00	40/-
	Towing Charge			\$ 50.00	7/-
	Transfer of Door- 3 pcs	\$	120.00	\$ 360.00	180/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	7/-
	Remove/Refix Dashboard			\$ 450.00	7/-
	Remove/Refix Front Windscreen Glass			\$ 120.00	7/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	7/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00	7/-
	FRT Wheel Alignment			\$ 120.00	60/-
	Re-set Front ABS System (LH/RH)	\$	200.00	\$ 400.00	7/-
	Re-set Front Power Window (LH/RH)	\$	200.00	\$ 400.00	7/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	7/-
	TOTAL LABOUR		2890.00	\$ 7,070.00	
	ESTIMATE TOTAL		22128.96	\$ 36,769.36	
	29/10/2018 @ 1500m		1/5 17000/-		
	Not Antimal				
	2/5m				
	1 year				
	LKK Auto				
	9 12 days.				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Oct 2018		29 Oct 2018 09:35 Edit Adj Rpt	S\$17,000.00 Edit Estimates	S\$17,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SKYWAY MOTOR PTE LTD , Co. Reg. No.: 199904194N									
Main Claimant: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Vehicle Reg. No.: SHA1277L		Date of Loss: 24/10/2018 23:00 - :59 [24 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 574312		Policy/Cover Note No.: 28795104MCX Coverage: 08/08/2018 - 07/08/2019							
Vehicle Reg. No. (Insured): SLM66A		Policy No. (Claimant):							
		Excess:							
Repairer: Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 28/11/2018]									
Adj Asg. Remarks: oi non reporting. liability not clear. TP agree with SJE - assign LKK Auto Consultants Pte Ltd.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents










































*SHA1277L (574312)
[SLM66A]
TP
COMFORT TRANSPORTATION PTE LTD
Oct 24 2018 11:00PM
[SKYWAY MOTOR PTE LTD]
Soon Hock Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	02/11/18 16:28	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/11/18 16:32	Front View Left						Load JPG	<input checked="" type="checkbox"/>	
2	25/11/18 16:32	Front View Right						Load JPG	<input checked="" type="checkbox"/>	
3	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
4	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
5	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
6	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
7	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
8	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
9	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
10	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
11	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
12	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
13	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
14	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
15	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
16	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
17	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
18	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
19	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
20	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
21	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
22	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
23	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
24	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
25	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
26	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
27	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
28	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
29	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
30	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
31	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
32	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
33	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	
34	25/11/18 16:36	General View						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
71	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
73	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
74	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
75	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
76	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
77	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
78	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
79	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
80	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
81	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
82	25/11/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
83	25/11/18 16:36	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	25/11/18 16:36	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
85	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	25/11/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
190	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
191	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
192	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
193	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
194	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
195	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
196	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
197	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
198	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
199	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
200	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
201	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
202	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
203	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
204	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
205	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
206	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
207	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
208	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
209	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
210	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
211	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
212	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
213	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
214	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
215	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
216	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
217	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
218	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
219	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
220	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
221	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
222	25/11/18 16:40	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/10/18 16:16	TP agree SJE - assign LKK	 Load PDF	
2	26/10/18 16:16	tp pri notice and estimate and GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019595/DCD3E2

Date: 11/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28795104MCX

Claimant Vehicle No: SHA1277L

Insured Vehicle No: SLM66A

Date of Loss: 24/10/2018

Nature of Claim: TP

Claim No: 574312

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA1277L

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU672462

Reg. Date: 29/09/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU093603

Colour: Blue

Odometer: 257143 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Campeon 5 mm

Rear Left Side: Campeon 5 mm

Front Right Side: Campeon 5 mm

Rear Right Side: Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,699.36	19,238.96	10,460.40	35.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	2,890.00	4,180.00	59.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,769.36	22,128.96	14,640.40	39.82
Approved Total (Overridden) (S\$)		17,000.00		
(S\$)	36,769.36	17,000.00	19,769.36	53.77
+ GST 7.00/7.00% (S\$)	2,573.86	1,190.00	1,383.86	53.77
Nett Amount (S\$)	39,343.22	18,190.00	21,153.22	53.77

INSPECTION

Date of Assignment: 29/10/2018

Date Inspected: 29/10/2018 Inspected At:

CHUNNI MOTOR WORK PTE LTD
BLK 10 ANG MO KIO IND. PARK 2A,
#03-19 AMK AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1277L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cut	1,052.20 FL	*1,052.20 FL
2	2		*FRONT BUMPER BRACKET (LH/RH)	Serviceable	49.20 FL	*- FL
3	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
4	2		*HEADLAMP (LH/RH)	Mounting Cracked	2,776.00 FL	*2,776.00 FL
5	2		*FRONT FENDER (LH/RH)	Buckled	1,132.60 FL	*1,132.60 FL
6	2		*FRONT FENDER APRON PANEL (LH/RH)	Dented	1,274.00 FL	*1,274.00 FL
7	2		*FRONT FENDER SHIELD (LH/RH)	Deformed	349.80 FL	*349.80 FL
8	2		*FRONT DOOR (LH/RH)	Dented	4,512.80 FL	*4,512.80 FL
9	2		*FRONT DOOR RUBBER	Serviceable	581.00 FL	*- FL
10	1		*FRONT DOOR OUTER MOULDING (LH)	Cut	47.10 FL	*47.10 FL
11	1		*FRONT DOOR MIRROR ASSY (LH/RH)	N/S Broken / O/S Not Necessary	1,340.00 FL	*670.00 FL
12	2		*ROCKER PANEL OUTER GARNISH, LH/RH	O/S Buckled / N/S Bent	682.80 FL	*682.80 FL
13	1		*REAR DOOR (LH)	Dented	2,201.10 FL	*2,201.10 FL
14	2		*FRONT PILLAR UPPER COVER / GARNISH, LH/RH	Bent / Cut	167.00 FL	*167.00 FL
15	1		*FRONT WINDSCREEN MOULDING	Not Necessary	113.30 FL	*- FL
16	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented (Lower)	1,745.50 FL	*1,745.50 FL
17	1		*WIPER CONTAINER	Not Necessary	61.90 FL	*- FL
18	1		*WIPER CONTAINER MOTOR	Not Necessary	75.00 FL	*- FL
19	2		*FRONT WHEEL RIM (LH/RH)	Distorted	650.60 FL	*650.60 FL
20	2		*FRONT WHEEL HUB CAP (LH/RH)	Bent / Cut	214.20 FL	*214.20 FL
21	2		*FRONT WHEEL BEARING	Damaged	301.80 FL	*301.80 FL
22	2		*FRONT SHOCK ABSORBER (ASSY) (LH/RH)	Distorted	684.40 FL	*684.40 FL
23	2		*FRONT SHOCK ABSORBER MOUNTING (LH/RH)	Not Necessary	217.60 FL	*- FL
24	2		*FRONT SHOCK ABSORBER FORK (LH/RH)	Not Necessary	424.30 FL	*- FL
25	2		*FRONT SUSPENSION UPPER ARM (LH/RH)	Not Necessary	500.80 FL	*- FL
26	2		*FRONT DRIVE SHAFT (LH/RH)	Not Necessary	2,061.60 FL	*- FL
27	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
28	2		*STG TIE END	Distorted	125.20 FL	*125.20 FL
29	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
30	2		*STABILIZER BAR BUSH (LH/RH)	Not Necessary	32.80 FL	*- FL
31	2		*STABILIZER BAR LINK	Distorted	122.20 FL	*122.20 FL
32	2		*STABILIZER BRACKET	Not Necessary	48.00 FL	*- FL
33	2		*FRONT SUSPENSION LOWER ARM (LH/RH)	Distorted	1,058.60 FL	*1,058.60 FL
34	2		*KNUCKLE ARM (LH/RH)	Distorted	1,104.00 FL	*1,104.00 FL
35	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
36	1		*ENGINE CROSSMEMBER	Not Necessary	2,094.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	2		*ABS SENSOR (LH/RH)	Not Necessary	468.00 FL	*- FL
38	1		*ELECTRIC POWER STEERING	Not Necessary	4,880.50 FL	*- FL
39	2		*FRONT FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
40	2		*FRONT DOOR COMFORT LOGO (LH/RH)	Necessary	150.00 FS	*150.00 FS
41	2		*FRONT DOOR ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
42	1		*REAR DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
43	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
44	1		*FRONT WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
45	1		*FRONT TYRE (LH/RH) (\$216.00) (50%)	O/S Cut / N/S Serviceable	432.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	36,822.20	23,839.20
- List Item Discount on L Items 20.00/20.00% (S\$)	7,122.84	4,600.24
Total Parts (S\$)	29,699.36	19,238.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,800.00	1,200.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	TRANSFER OF DOOR - 3PCS	New	360.00	180.00
7	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	0.00
8	REMOVE / REFIX DASHBOARD	New	450.00	0.00
9	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
10	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	200.00	180.00
11	FRT WHEEL ALIGNMENT	New	120.00	60.00
12	RE-SET FRONT ABS SYSTEM (LH/RH)	New	400.00	0.00
13	RE-SET FRONT POWER WINDOW (LH/RH)	New	400.00	0.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
15	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
Gross Labour Cost (S\$)			7,070.00	2,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >