

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Wednesday, 20 November 2019 10:58 AM
To: Jumani Bin Masudin
Cc: Guo Qiang (LKKAUTO)
Subject: Vehicle No. SHD 6644L DOA: 26.10.2018

Dear Jumani,

Refer to your tele-conversation with Guo Qiang.

Please assist to amend your finalization at Lump Sum \$2,750.00 and submit your amended invoice to NTUC.

Thank you.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18019606/Grbs2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 07-11-2018



189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 2647H	Veh. Inspected	SHD 6644L
Policy No.	5097615547	Coverage (\$)	0.00
Claim No.	MT/1017276-002	Excess (\$)	0.00
Assign From		Assign Date	26/10/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU091552	Colour	BLUE
Odometer	316955	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/10/2018	Inspection Date	26/10/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6644L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	CUT	544.50	544.50
1	FRONT BUMPER BRACKET TOP (RH)	BENT	22.40	22.40
1	FRONT BUMPER BRACKET (RH)	BENT	24.60	24.60
1	HEADLAMP (RH)	CRACKED	1,388.00	1,388.00
1	FRONT FENDER (RH)	BENT	566.30	566.30
1	FRONT FENDER SHIELD (RH)	DEFORMED	175.90	175.90
1	FRONT FENDER RETAINER	NECESSARY	24.60	24.60
1	FRONT WHEEL RIM (RH)	CUT	325.30	325.30
1	FRONT WHEEL HUB CAP (RH)	CRACKED	107.10	107.10
	LESS 20% DISCOUNT		-635.74	-635.74
			2,542.96	2,542.96
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			125.00	100.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	300.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	WIRING.		30.00	20.00
	TUFF KOTE.		50.00	30.00
	FRT WHEEL ALIGNMENT.		80.00	60.00
			1,160.00	810.00
GRAND TOTAL			3,827.96	3,452.96
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,452.96

Report Ref No. NS/INC18019606/Grbs2

2750.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6644L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	CUT	544.50	544.50
1	FRONT BUMPER BRACKET TOP (RH)	BENT	22.40	22.40
1	FRONT BUMPER BRACKET (RH)	BENT	24.60	24.60
1	HEADLAMP (RH)	CRACKED	1,388.00	1,388.00
1	FRONT FENDER (RH)	BENT	566.30	566.30
1	FRONT FENDER SHIELD (RH)	DEFORMED	175.90	175.90
1	FRONT FENDER RETAINER	NECESSARY	24.60	24.60
1	FRONT WHEEL RIM (RH)	CUT	325.30	325.30
1	FRONT WHEEL HUB CAP (RH)	CRACKED	107.10	107.10
	LESS 20% DISCOUNT		-635.74	-635.74
			2,542.96	2,542.96
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			125.00	100.00
LABOUR				
	PANEL BEATING.		400.00	300.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	WIRING.		30.00	20.00
	TUFF KOTE.		50.00	30.00
	FRT WHEEL ALIGNMENT.		80.00	60.00
			-	-
			-	-
			-	-
			1,160.00	810.00
GRAND TOTAL			3,827.96	3,452.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,750.00

Report Ref No. NS/INC18019606/Grbs2



Page No.:2 of 2

Report Ref No. NS/INC18019606/Grbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.