

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG16016114/H1UB3Q2**Date:** 16/11/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100391378
Claimant Vehicle No :	SHC1947B	Insured Vehicle No :	SKQ1636P
Date of Loss:	25/08/2016	Nature of Claim:	TP
		Claim No:	8153632979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1947B	Engine No:	D4EAC099899
Make & Model:	HYUNDAI SONATA, 2.0 (A)	Chassis No:	KMHET41VMCA825394
Reg. Date:	31/05/2012 (Man. Year: 2012)	Odometer:	601914 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,752.54	3,733.38	2,019.16	35.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,440.00	980.00	40.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,172.54	5,173.38	2,999.16	36.70
Approved Total (Overridden) (S\$)		4,530.00		
(S\$)	8,172.54	4,530.00	3,642.54	44.57
+ GST 7.00/7.00% (S\$)	572.08	317.10	254.98	44.57
Nett Amount (S\$)	8,744.62	4,847.10	3,897.52	44.57
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$100.58/day) (S\$)		603.48		
(S\$)		5,750.58		
Liabe Amount (50.00%) (S\$)		2,875.29		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,880.64		
Global Sum Settlement (S\$)		2,880.00		

INSPECTION

Date of Assignment:	26/08/2016	
Date Inspected:	26/08/2016	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days	

Adjuster: HENRY NG KOK HUA

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	1,349.50 FL	*1,349.50 FL
2	1		*BOOTLID LATCH	Bent	132.10 FL	*132.10 FL
3	1		*BOOTLID STRIKER	Bent	30.30 FL	*30.30 FL
4	1		*BOOTLID WEATHERSTRIP	Torn	110.90 FL	*110.90 FL
5	1		*BOOTLID TRIM	Serviceable	165.40 FL	*- FL
6	1		*BOOTLID HINGE RH	Serviceable	170.60 FL	*- FL
7	1		*BOOTLID HINGE LH	Serviceable	170.60 FL	*- FL
8	1		*EMBLEM HYUNDAI	Necessary	24.20 FL	*24.20 FL
9	1		*EMBLEM SONATA	Necessary	43.60 FL	*43.60 FL
10	1		*EMBLEM CRDI	Necessary	22.70 FL	*22.70 FL
11	1		*EMBLEM H	Necessary	26.10 FL	*26.10 FL
12	1		*BOOTLID KEY LOCK	Cracked	78.20 FL	*78.20 FL
13	1		*TRIM-TRANSVERSE	Cracked	92.80 FL	*92.80 FL
14	1		*TAIL LAMP RH	Cracked	344.00 FL	*344.00 FL
15	1		*TAIL LAMP RH(BOOTLID)	Serviceable	230.20 FL	*- FL
16	1		*TAIL LAMP LH	Cracked	344.00 FL	*344.00 FL
17	1		*TAIL LAMP LH (BOOTLID)	Serviceable	230.20 FL	*- FL
18	2		*LICENSE PLATE LAMP RH/LH	Serviceable	32.50 FL	*- FL
19	1		*TAILLAMP PANEL RH	Repair	217.40 FL	*- FL
20	1		*TAILLAMP PANEL LH	Repair	217.40 FL	*- FL
21	1		*REAR END PANEL	Bent	391.80 FL	*391.80 FL
22	1		*REAR SPARE TYRE PANEL	Repair	863.00 FL	*- FL
23	1		*(SONATA) LOGO REAR COMFORT	Necessary	20.00 FS	*20.00 FS
24	1		*(ALL) LOGO REAR CABBOOKING	Necessary	10.00 FS	*10.00 FS
25	1		*REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
26	1		*BUMPER REAR	Deformed	578.40 FL	*578.40 FL
27	1		*BUMPER SPONGE REAR	Cracked	137.40 FL	*137.40 FL
28	1		*BUMPER REINFORCEMENT REAR	Cracked	483.30 FL	*483.30 FL
29	1		*BUMPER UNDER COVER REAR	Cracked	185.80 FL	*185.80 FL
30	10		*BUMPER CLIP REAR	Necessary	22.00 FL	*22.00 FL
31	1		*BUMPER MOULDING REAR RH	Serviceable	38.00 FL	*- FL
32	1		*BUMPER MOULDING REAR LH	Serviceable	38.00 FL	*- FL
33	1		*REAR TOWING HOOK BRACKET	Not Necessary	77.60 FL	*- FL
34	1		*SPARE TYRE FASTENER	Not Necessary	14.20 FL	*- FL
35	1		*SPARE WHEEL BRACKET	Not Necessary	27.60 FL	*- FL
36	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
37	1		*NO PLATE	Serviceable	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,130.50	4,612.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,377.96	879.42
Total Parts (\$)	5,752.54	3,733.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,120.00	600.00
2	SPRAYPAINT ON AFFECTED AREA	New	1,000.00	720.00
3	CHECK ALL LIGHTING	New	60.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	120.00	50.00
5	R/I REVERSE SENSOR	New	120.00	40.00
Gross Labour Cost (\$)			2,420.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >