

22/03/2002

ASS. REC. BY:

REF: CS3/AIG18019617/Acd301 Special Instruction:

Surveyor: Adrian
MoimenASSIGNMENT (Office)From (Person): Chin Lee Ying

of

AIGDate/Time: 29/10/18 @ 11:50am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 8719H

Insured:

8LE 9623A

at Workshop m/s

Apex Motoring

Tel:

6842 1992

of

25 Kaki Bukit Rd 4 #01-55 Synergy

Policy No:

2100478398

Claim No:

1651817063SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/10/2018CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 1:02pm @ 29/10/18

Person Contacted:

pei jiVehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SMD 8719H - X</u>
	<u>8LE 9623A - X</u>
	<u>Dismantle: 29/10/2018</u>

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD8719 H. Yr Regn: No recordType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Voxy c.c. 1797Colour: Black A/C: Insured / Std / NI / NASp. Reading: 9004 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR800333758Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 29/10/18Survey held at ApexDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

T? AG. 9RS.
No GIA.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

DAR

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

180

S + RS, SI

Photos

Others

TOTAL


20200

TGLM

5/11/18

Your password will expire in 13 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 29/10/2018 11:50:05 AM
Attachments:  [NEW PRI - SLE9623A AND SMD8719H.PDF](#)

Hi LKK,

Kindly assist to survey. Vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



27/10/2018

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Fax : 6415 3727

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SMD 8719 H AND VEHICEL NO. SLE 9623 A ON 27/10/2018 @ 1400 Hrs

We are the appointed repair workshop of vehicle no. **SMD 8719 H**

We understand that you are the insurer of vehicle no. **SLE 9623 A**

The owner of vehicle number **SMD 8719 H** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800
Mobile No. 9234 2543 / peijie@expresscar.com.sg. Mr Wei

Yours faithfully



MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CNT	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	CNT	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber	NEC	✓	
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SMD87194

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 8 Assessor:

TCM
5/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	MALIK GAURAV, ID: G5424952M		
Main Claimant:	-		
Vehicle Reg. No.:	SMD8719H	Date of Loss:	27/10/2018 13:00 - :59
Claim Type:	TP / 1651817063SG	Policy/Cover Note No.:	2100478398 (Comprehensive)
Vehicle Reg. No. (Insured):	SLE9623A	Policy No. (Claimant):	
		Excess:	
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/11/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG (30/10/2018): No OI GIA Report
- AIG_SG (30/10/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMD8719H (1651817063SG)**
[SLE9623A]

TP

-
Oct 27 2018 1:00PM
[MALIK GAURAV]
Apex Motoring

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
2	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
3	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
4	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
5	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
6	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
7	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
8	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
9	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
10	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
11	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
12	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
13	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
14	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
15	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
16	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
17	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
18	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
19	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
20	01/11/18 11:28	General View														Load JPG	<input checked="" type="checkbox"/>	
21	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
22	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
23	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
24	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
25	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
26	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
27	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
28	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
29	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
30	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
31	01/11/18 11:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
Documentation															1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print	
1	05/11/18 11:58	OI GIA REPORT														Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019617/ACD3E2

Date: 14/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100478398
Claimant Vehicle No : SMD8719H **Insured Vehicle No :** SLE9623A
 Date of Loss: 27/10/2018 Nature of Claim: TP Claim No: 1651817063SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD8719H**
 Make & Model: TOYOTA VOXY HYBRID, 1.8 (A) Engine No: HIDDEN
 Reg. Date: (Man. Year:) Chassis No: ZWR800333758
 Colour: Black Odometer: 9004 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/10/2018
 Date Inspected: 29/10/2018 Inspected At: Apex Motoring
 25 Kaki Bukit Road 4, #01-55 Synergy @
 KB
 Singapore 417800
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REVERSE SENSOR	Cut	0.00 F	*- F
3	1		*REAR END PANEL	Repair	0.00 F	*- F
4	1		*REAR END PANEL TOP GARNISH	Cut	0.00 F	*- F
5	1		*TAILGATE	Dented	0.00 F	*- F
6	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
7	1		*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
8	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
10	1		*TAILGATE LOCK	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >