

Lonpac Insured's Veh No : SJX4047U
Date of Accident : 25 October 2018

not Authorized
28/10/18
3 day.
Whip it before
party.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Seet Boon Kian (Xue wengqiang)

Date : 29 October 2018

Lik Marcus -
29/10/18 1030h

Estimate To Repair SLK2447G - Mercedes Benz CLA180 (R18 BI)
Chassis No : WDD1179422N221160

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	rear bumper <i>7000</i>	\$ 0.00
02	1 pc	rear bumper reinforcement <i>?</i>	\$ 0.00
03	1 pc	rear bumper lower centre <i>80-24</i>	\$ 0.00
04	1 pc	rear bumper parking sensor side right <i>Shut -</i>	\$ 0.00
05	1 pc	rear bumper parking sensor centre right <i>11X</i>	\$ 0.00
06	1 pc	rear bumper parking sensor centre holder right <i>11X</i>	\$ 0.00
07	1 pc	rear bumper inner frame <i>11 X</i>	\$ 0.00
08	1 pc	right rear lamp <i>11 X</i>	\$ 0.00
09	1 pc	rear bumper lower tow cover <i>11X</i>	\$ 0.00
10	1 pc	rear bumper lower diffuser <i>11X</i>	\$ 0.00
			\$ 0.00
Less 10 %			\$ 0.00
			\$ 0.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 150.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
04		Putty and spray painting of the affected portion.	\$ 580.00
			\$ 1,190.00
Total			\$ 1,190.00

20
50
250
300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: