

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

6.00	FRONT BONNET HINGE HEX BOLT WITH WASHER	\$	12.00	nei ✓
1.00	FRONT BONNET AIR DUCT	\$	280.00	dis ✓
1.00	FRONT BONNET AIR DUCT GRILL	\$	147.90	xnn ✓
8.00	FRONT BONNET EXPANDING RIVET	\$	12.00	nei ✓
2.00	FRONT BONNET HINGE INTERMEDIATE PLATE ASSY	\$	10.00	bt ✓
1.00	FRONT BONNET SEAL	\$	99.00	mis ✓
1.00	FRONT BONNET SIDE SEAL	\$	82.35	nei ✓
1.00	FRONT LEFT AIR DUCT SEAL	\$	96.00	de ✓
1.00	FRONT RIGHT AIR DUCT SEAL	\$	96.00	de ✓
2.00	FRONT BONNET LOCK	\$	304.95	bt ✓
2.00	CATCH BRACKET	\$	73.18	bt ✓
2.00	TWIST PROTECTION	\$	18.30	de ✓
2.00	FRONT BONNET CABLE LEFT AND RIGHT	\$	440.00	xnn ✓
2.00	EXPANDING RIVET	\$	4.00	nei ✓
2.00	ADJUSTER	\$	20.00	xnn ✓
2.00	DISTANCE SENSOR	\$	10.00	nei ✓
1.00	FRONT LEFT FENDER	\$	1,800.00	cnn ✓
1.00	FRONT RIGHT FENDER	\$	1,800.00	cnn ✓
1.00	FRONT LEFT SUPPORTING STRUT	\$	800.00	xnn ✓
1.00	FRONT RIGHT SUPPORTING STRUT	\$	800.00	bt ✓
1.00	FRONT RIGHT DEFORMATION ELEMENT	\$	81.00	bt ✓
1.00	FRONT LEFT DEFORMATION ELEMENT	\$	81.00	xnn ✓
1.00	REAR LEFT DEFORMATION ELEMENT	\$	80.00	xnn ✓
1.00	REAR RIGHT DEFORMATION ELEMENT	\$	80.00	bt ✓
1.00	CENTER RIGHT DEFORMATION ELEMENT	\$	40.00	bt ✓
1.00	CENTER LEFT DEFORMATION ELEMENT	\$	40.00	bt ✓
2.00	GASKET	\$	10.00	xnn ✓
1.00	FRONT LEFT FENDER SUPPORT	\$	40.00	xnn ✓
1.00	FRONT RIGHT FENDER SUPPORT	\$	40.00	de ✓
16.00	FRONT LEFT AND RIGHT FENDER SCREW	\$	96.00	nei ✓
20.00	Blind rivet nut, flat headed	\$	100.00	nei ✓
2.00	Foam belt	\$	40.00	nei ✓
1.00	Seal, front side panel, left	\$	39.00	nei ✓
1.00	Seal, front side panel, right	\$	39.00	nei ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP	\$	15,500.80	cnn ✓
2.00	HEADLIGHT COVER	\$	86.40	dis ✓
2.00	HEADLIGHT SINK LEFT AND RIGHT	\$	495 990.00	LH-X, RH-dis ✓
2.00	REPAIR KIT OF HEADLAMP	\$	378.00	nei ✓
2.00	Control unit for front light electronics	\$	1400 2,800.00	LH-cnn, RH-xnn ✓
2.00	Alignment element	\$	20.00	nei ✓
2.00	Repair kit for LWR servo motor	\$	150.00	nei ✓
10.00	Countersunk screw	\$	40.00	nei ✓
2.00	Control module, turn signal with gasket	\$	445 890.00	LH-xnn RH-cnn ✓

24562.98

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

4.00	Flat nut	\$	40.00	nei ✓
2.00	GASKET	\$	20.00	nei ✓
1.00	FAN HOUSING WITH FAN MOTOR	\$	2,562.50	ana ✓
4.00	FAN HOUSING LOWER SEALING	\$	10.00	nei ✓
1.00	Radiator Top Inner	\$	1,890.00	bt ✓
1.00	Radiator Top Outer	\$	1,134.00	bt ✓
1.00	Radiator Lower Inner	\$	1,790.00	bt ✓
1.00	Radiator Lower Outer	\$	1,790.00	bt ✓
2.00	Radiator Left Module mount	\$	450.00	ana ✓
2.00	Radiator Right Module mount	\$	450.00	ana ✓
1.00	Radiator Lower Sealing	\$	250.00	de ✓
1.00	Left Bracket for module,	\$	240.00	de ✓
1.00	Right Bracket for module,	\$	240.00	de ✓
1.00	Radiator Upper sealing	\$	250.00	de ✓
4.00	Radiator Upper Sealing Screw self-tapping	\$	12.00	nei ✓
2.00	Fillister head screw	\$	10.00	nei ✓
2.00	Rubber Mounting	\$	50.00	nei ✓
2.00	Support rubber mounting	\$	60.00	nei ✓
6.00	Blind rivet nut, countersunk head	\$	40.00	nei ✓
1.00	Pipe, expansion tank-radiator	\$	90.00	Xan ✓
1.00	Line from expansion tank - thermostat	\$	162.00	Xan ✓
1.00	Line, connection for water pump	\$	220.00	dis ✓
1.00	Hose, expansion tank-return pipe	\$	160.00	Xan ✓
1.00	Hose, expansion tank-	\$	150.00	Xan ✓
3.00	Clip	\$	12.00	Xan ✓
4.00	Hose clamp	\$	30.00	Xan ✓
1.00	Hose clamp	\$	10.00	Xan ✓
1.00	Refrigerant line IWT	\$	650.00	Xan ✓
1.00	Pressure hose assy compressor-condenser	\$	442.00	bt ✓
1.00	Suction pipe	\$	410.00	Xan ✓
1.00	Pressure pipe	\$	620.00	bt ✓
6.00	Gasket ring	\$	120.00	nei ✓
1.00	Sealing cap for suction line	\$	8.00	Xan ✓
1.00	Sealing cap for pressure line	\$	8.00	Xan ✓
1.00	Pressure sensor	\$	180.00	Xan ✓
1.00	A/C Condensor	\$	1,750.00	bt ✓
1.00	Front Left Wheel Rim	\$	4,880.00	Xan ✓
1.00	Front Right wheel Rim	\$	4,880.00	dd ✓
1.00	Wheel center cap with blue ring	\$	200.00	X ✓
1.00	Wheel electr. module RDCi w/ screw valve	\$	500.00	X ✓
1.00	Front Right Side Driveshaft	\$	4,050.00	X ✓
1.00	Front Anti-roll bar,	\$	680.00	X ✓
2.00	Front Stabilizer link	\$	414.00	X ✓

19320.50

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:

SKZ8200U (TP claim)

Date: 22/10/2018

Vehicle No: SLX8977K

Model: BMW 18

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

2.00	Front Absorber Left and Right	\$	4,000.00	Xun
2.00	Front Absorber Spring Lower Pad	\$	60.00	Xun
2.00	Front Absorber Spring Top Pad	\$	68.00	Xun
6.00	Front Absorber Screw self-tapping	\$	60.00	Xun
2.00	Front Absorber Top Mounting	\$	760.00	Xun
2.00	Front Absorber Plug-in connection bracket	\$	34.00	Xun
1.00	Front axle support	\$	3,690.00	bt
1.00	Front Axle Support Cross member	\$	558.00	Xun
12.00	Front Axle Support bolt with washer	\$	208.00	Xun
2.00	Front Right and Left Strut Arm	\$	1,500.00	Xun
2.00	Front Right and Left center Arm	\$	2,000.00	Xun
2.00	Front Right and Left Upper Arm	\$	1,808.30	Xun
2.00	Front Axle Mounting	\$	375.00	all
2.00	Front Headlamp Level Sensor	\$	480.00	Xun
1.00	Front Ringle Knuckle	\$	1,228.00	Xun
1.00	Front right wheel bearing with Hub	\$	696.00	bt
1.00	Front Right and Left Wheel Speed Sensor	\$	640.00	Xun
1.00	At-steering box, electr TKP	\$	6,300.00	H
1.00	Front Right and Left Tie Rod	\$	1,280.00	LH-X, RH-bt
1.00	Sprt steering wheel, leather, shift paddles	\$	2,800.00	cu
1.00	Decor trim cover, steering wheel	\$	600.00	dis
1.00	Cover for steering wheel, rear	\$	250.00	Xun
1.00	connecting line, steering wheel	\$	300.00	Xun
1.00	Airbag module, driver's side	\$	3,240.00	act
1.00	Front Left wiring harness, Live,	\$	468.00	Xun
1.00	Front Right wiring harness, Live	\$	540.00	tu
1.00	SBK wiring harness	\$	72.00	all
1.00	Rain Sensor	\$	387.00	Xun
1.00	Steering Coil Spring catridge	\$	480.00	act
1.00	Horn, high pitch	\$	158.40	can
1.00	Horn, low pitch	\$	158.40	cut
2.00	Horn Screw	\$	10.00	all
1.00	Washer fluid reservoir	\$	225.00	dec
1.00	Wash pump/fluid container	\$	112.35	de
1.00	Gasket	\$	12.00	all
1.00	Strainer f wash pump	\$	14.00	all
1.00	Level sensor	\$	122.40	dis
1.00	Hex bolt with washer	\$	5.00	all
2.00	Pipe support	\$	20.00	Xun
1.00	Cover, windshield	\$	180.00	can
1.00	Filler pipe for wash container	\$	120.00	Xun
1.00	Wiper Washer Tank Cover	\$	28.00	mis
1.00	Hose, windshield washer	\$	80.00	Xun

21 098.55

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Bik K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPIING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

2.00	Wiper Nozzle
1.00	FRONT RIGHT SEAT BELT
1.00	Airbag for front passenger
1.00	Head airbag, right
3.00	Blind rivet nut, flat headed
1.00	FRONT I-CAM
1.00	BY PASS HOSE
2.00	BRACKET FOR MODULE LEFT AND RIGHT
1.00	WIPER RHS MOTOR WITH BRACKET

\$	615.00	x un
\$	984.94	aut
\$	2,466.00	aut
\$	1,224.00	aut
\$	30.00	rel
\$	1,164.16	cut
\$	269.64	cut
\$	821.76	bt
\$	1,155.60	cut
TOTAL:	\$	136,315.56
LESS 5 %:	\$	6,815.77
	\$	129,499.79

4704.94
3411.16
100 231.40
95 219.83

S/NET

Qty	Description	Unit Price	Remarks
1.00	FRONT BUMPER BODY KIT	\$ 15,000.00	cut - 8500
2.00	FRONT OVER FENDER BODY KIT	\$ 10,000.00	cut - 6500
1.00	FRONT WINDSCREEN SEALANT	\$ 120.00	x un
1.00	FRONT PANEL SEALANT	\$ 160.00	rel
1.00	WHEEL ALIGNMENT	\$ 200.00	120
1.00	FRONT WINDSCREEN SOLAR FIRM	\$ 600.00	x un
2.00	SOUND PROOF STICKER ON LEFT AND RIGH	\$ 900.00	rel
1.00	TOWING FEE	\$ 200.00	100
TOTAL:	\$	25,280.00	16280

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 5,000.00	2750
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 5,000.00	1600
1.00	CHECK WIRING	\$ 800.00	200
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 500.00	x un
1.00	REMOVE & REFIT AFFECTED FRONT PORTION	\$ 800.00	600
1.00	REPROGRAMMING AND RESETTNG ON VEHICLE SYSTEM	\$ 1,000.00	100
1.00	TO REMOVE AND REFIT REAR WINDSCREEN	\$ 250.00	x un
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 200.00	100
1.00	SUNDARIES	\$ 50.00	50
1.00	PULL CHASIS	\$ 200.00	5080
TOTAL:	\$	13,800.00	

SUBTOTAL: \$ 168,579.79

Estimate prepared by: TOH KHAR KIAN

170029.28

18 days
10% 1/5 \$ 105,011.85
2/5 \$ 105,000

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		29 Oct 2018 16:56 Edit Adj Rpt	S\$105,000.00 Edit Estimates	S\$105,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	CHOO SEE CHECK (ZHU SIJIE), ID: S8170414G								
Main Claimant:	SHIN JONG HYUN, ID: G3117176N								
Vehicle Reg. No.:	SLX8977K	Date of Loss:	13/10/2018 09:00 - :59 [46 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04905C02	Policy/Cover Note No.:	DMPCSN3032071802 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKZ8200U	Policy No. (Claimant):	SD18V03822/VPC/R00						
		Excess:	S\$0.00						
Repairer:	Li Sheng Automobile Trading (HQ) No. 18 Pandan Loop #01-18 Blk K, 128236 West Coast - Tel: 91474552								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/11/2018]								
Driver/Custodian (Insured):	CHOO SEE CHECK (ZHU SIJIE) (37 / Male), NRIC: S8170414G Email:								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX8977K (SNM18D04905C02)
[SKZB200U]

TP

SHIN JONG HYUN

Oct 13 2018 9:00AM

[CHOO SEE CHECK (ZHU SIJIE)]

Li Sheng Automobile Trading

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)							Thumbnail	Print	
1	16/10/18 11:22	Accident Statement								Load HTML	
Photos/Images									3 per page		☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)							Thumbnail	Print	
1	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
2	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
3	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
4	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
5	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
6	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
7	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
8	16/10/18 11:20	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
9	16/10/18 11:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
10	16/10/18 11:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
11	16/10/18 11:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
12	16/10/18 11:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
13	16/10/18 11:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	15/08/19 16:09	General View								Load JPG	☒
2	15/08/19 16:09	General View								Load JPG	☒
3	15/08/19 16:09	General View								Load JPG	☒
4	15/08/19 16:09	General View								Load JPG	☒
5	15/08/19 16:09	General View								Load JPG	☒
6	15/08/19 16:09	General View								Load JPG	☒
7	15/08/19 16:09	General View								Load JPG	☒
8	15/08/19 16:09	General View								Load JPG	☒
9	15/08/19 16:09	General View								Load JPG	☒
10	15/08/19 16:09	General View								Load JPG	☒
11	15/08/19 16:09	General View								Load JPG	☒
12	15/08/19 16:09	General View								Load JPG	☒
13	15/08/19 16:09	General View								Load JPG	☒
14	15/08/19 16:09	General View								Load JPG	☒
15	15/08/19 16:09	General View								Load JPG	☒
16	15/08/19 16:09	General View								Load JPG	☒
17	15/08/19 16:09	General View								Load JPG	☒
18	15/08/19 16:09	General View								Load JPG	☒
19	15/08/19 16:09	General View								Load JPG	☒
20	15/08/19 16:09	General View								Load JPG	☒
21	15/08/19 16:09	General View								Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
22	15/08/19 16:09	General View		☒
23	15/08/19 16:09	General View		☒
24	15/08/19 16:09	General View		☒
25	15/08/19 16:09	General View		☒
26	15/08/19 16:09	General View		☒
27	15/08/19 16:09	General View		☒
28	15/08/19 16:09	General View		☒
29	15/08/19 16:09	General View		☒
30	15/08/19 16:09	General View		☒
31	15/08/19 16:09	General View		☒
32	15/08/19 16:09	General View		☒
33	15/08/19 16:09	General View		☒
34	15/08/19 16:09	General View		☒
35	15/08/19 16:09	General View		☒
36	15/08/19 16:09	General View		☒
37	15/08/19 16:09	General View		☒
38	15/08/19 16:09	General View		☒
39	15/08/19 16:09	General View		☒
40	15/08/19 16:09	General View		☒
41	15/08/19 16:09	General View		☒
42	15/08/19 16:09	General View		☒
43	15/08/19 16:09	General View		☒
44	15/08/19 16:09	General View		☒
45	15/08/19 16:09	General View		☒
46	15/08/19 16:09	General View		☒
47	15/08/19 16:09	General View		☒
48	15/08/19 16:09	General View		☒
49	15/08/19 16:09	General View		☒
50	15/08/19 16:09	General View		☒
51	15/08/19 16:09	General View		☒
52	15/08/19 16:09	General View		☒
53	15/08/19 16:09	General View		☒
54	15/08/19 16:09	General View		☒
55	15/08/19 16:09	General View		☒
56	15/08/19 16:09	General View		☒
57	15/08/19 16:09	General View		☒
58	15/08/19 16:09	General View		☒
59	15/08/19 16:09	General View		☒
60	15/08/19 16:09	General View		☒
61	15/08/19 16:09	General View		☒
62	15/08/19 16:09	General View		☒
63	15/08/19 16:09	General View		☒
64	15/08/19 16:09	General View		☒
65	15/08/19 16:09	General View		☒
66	15/08/19 16:09	General View		☒
67	15/08/19 16:09	General View		☒
68	15/08/19 16:09	General View		☒
69	15/08/19 16:09	General View		☒
70	15/08/19 16:09	General View		☒
71	15/08/19 16:09	General View		☒
72	15/08/19 16:09	General View		☒
73	15/08/19 16:09	General View		☒
74	15/08/19 16:09	General View		☒
75	15/08/19 16:09	General View		☒
76	15/08/19 16:09	General View		☒
77	15/08/19 16:09	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
78	15/08/19 16:09	General View		☒
79	15/08/19 16:09	General View		☒
80	15/08/19 16:09	General View		☒
81	15/08/19 16:09	General View		☒
82	15/08/19 16:09	General View		☒
83	15/08/19 16:09	General View		☒
84	15/08/19 16:09	General View		☒
85	15/08/19 16:09	General View		☒
86	15/08/19 16:09	General View		☒
87	15/08/19 16:09	General View		☒
88	15/08/19 16:09	General View		☒
89	15/08/19 16:09	General View		☒
90	15/08/19 16:09	General View		☒
91	15/08/19 16:09	General View		☒
92	15/08/19 16:09	General View		☒
93	15/08/19 16:09	General View		☒
94	15/08/19 16:09	General View		☒
95	15/08/19 16:09	General View		☒
96	15/08/19 16:09	General View		☒
97	15/08/19 16:09	General View		☒
98	15/08/19 16:09	General View		☒
99	15/08/19 16:09	General View		☒
100	15/08/19 16:09	General View		☒
101	15/08/19 16:09	General View		☒
102	15/08/19 16:09	General View		☒
103	15/08/19 16:09	General View		☒
104	15/08/19 16:09	General View		☒
105	15/08/19 16:09	General View		☒
106	15/08/19 16:09	General View		☒
107	15/08/19 16:09	General View		☒
108	15/08/19 16:09	General View		☒
109	15/08/19 16:09	General View		☒
110	15/08/19 16:09	General View		☒
111	15/08/19 16:09	General View		☒
112	15/08/19 16:09	General View		☒
113	15/08/19 16:09	General View		☒
114	15/08/19 16:09	General View		☒
115	15/08/19 16:09	General View		☒
116	15/08/19 16:09	General View		☒
117	15/08/19 16:09	General View		☒
118	15/08/19 16:09	General View		☒
119	15/08/19 16:09	General View		☒
120	15/08/19 16:09	General View		☒
121	15/08/19 16:09	General View		☒
122	15/08/19 16:09	General View		☒
123	15/08/19 16:09	General View		☒
124	15/08/19 16:09	General View		☒
125	15/08/19 16:09	General View		☒
126	15/08/19 16:09	General View		☒
127	15/08/19 16:09	General View		☒
128	15/08/19 16:09	General View		☒
129	15/08/19 16:09	General View		☒
130	15/08/19 16:09	General View		☒
131	15/08/19 16:09	General View		☒
132	15/08/19 16:09	General View		☒
133	15/08/19 16:09	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
134	15/08/19 16:09	General View		☒
135	15/08/19 16:09	General View		☒
136	15/08/19 16:09	General View		☒
137	15/08/19 16:09	General View		☒
138	15/08/19 16:09	General View		☒
139	15/08/19 16:09	General View		☒
140	15/08/19 16:09	General View		☒
141	15/08/19 16:09	General View		☒
142	15/08/19 16:09	General View		☒
143	15/08/19 16:09	General View		☒
144	15/08/19 16:09	General View		☒
145	15/08/19 16:09	General View		☒
146	15/08/19 16:09	General View		☒
147	15/08/19 16:09	General View		☒
148	15/08/19 16:09	General View		☒
149	15/08/19 16:09	General View		☒
150	15/08/19 16:09	General View		☒
151	15/08/19 16:09	General View		☒
152	15/08/19 16:09	General View		☒
153	15/08/19 16:09	General View		☒
154	15/08/19 16:09	General View		☒
155	15/08/19 16:09	General View		☒
156	15/08/19 16:09	General View		☒
157	15/08/19 16:09	General View		☒
158	15/08/19 16:09	General View		☒
159	15/08/19 16:09	General View		☒
160	15/08/19 16:09	General View		☒
161	15/08/19 16:09	General View		☒
162	15/08/19 16:09	General View		☒
163	15/08/19 16:09	General View		☒
164	15/08/19 16:09	General View		☒
165	15/08/19 16:09	General View		☒
166	15/08/19 16:09	General View		☒
167	15/08/19 16:09	General View		☒
168	15/08/19 16:09	General View		☒
169	15/08/19 16:09	General View		☒
170	15/08/19 16:09	General View		☒
171	15/08/19 16:09	General View		☒
172	15/08/19 16:09	General View		☒
173	15/08/19 16:09	General View		☒
174	15/08/19 16:09	General View		☒
175	15/08/19 16:09	General View		☒
176	15/08/19 16:09	General View		☒
177	15/08/19 16:09	General View		☒
178	15/08/19 16:09	General View		☒
179	15/08/19 16:09	General View		☒
180	15/08/19 16:09	General View		☒
181	15/08/19 16:09	General View		☒
182	15/08/19 16:09	General View		☒
183	15/08/19 16:09	General View		☒
184	15/08/19 16:09	General View		☒
185	15/08/19 16:09	General View		☒
186	15/08/19 16:09	General View		☒
187	15/08/19 16:09	General View		☒
188	15/08/19 16:09	General View		☒
189	15/08/19 16:09	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
190	15/08/19 16:09	General View		☒
191	15/08/19 16:09	General View		☒
192	15/08/19 16:09	General View		☒
193	15/08/19 16:09	General View		☒
194	15/08/19 16:09	General View		☒
195	15/08/19 16:09	General View		☒
196	15/08/19 16:09	General View		☒
197	15/08/19 16:09	General View		☒
198	15/08/19 16:09	General View		☒
199	15/08/19 16:09	General View		☒
200	15/08/19 16:09	General View		☒
201	15/08/19 16:09	General View		☒
202	15/08/19 16:09	General View		☒
203	15/08/19 16:09	General View		☒
204	15/08/19 16:09	General View		☒
205	15/08/19 16:09	General View		☒
206	15/08/19 16:09	General View		☒
207	15/08/19 16:09	General View		☒
208	15/08/19 16:09	General View		☒
209	15/08/19 16:09	General View		☒
210	15/08/19 16:09	General View		☒
211	15/08/19 16:09	General View		☒
212	15/08/19 16:09	General View		☒
213	15/08/19 16:11	Reinspection Photo		☒
214	15/08/19 16:11	Reinspection Photo		☒
215	15/08/19 16:11	Reinspection Photo		☒
216	15/08/19 16:11	Reinspection Photo		☒
217	15/08/19 16:11	Reinspection Photo		☒
218	15/08/19 16:11	Reinspection Photo		☒
219	15/08/19 16:11	Reinspection Photo		☒
220	15/08/19 16:11	Reinspection Photo		☒
221	15/08/19 16:11	Reinspection Photo		☒
222	15/08/19 16:11	Reinspection Photo		☒
223	15/08/19 16:11	Reinspection Photo		☒
224	15/08/19 16:11	Reinspection Photo		☒
225	15/08/19 16:11	Reinspection Photo		☒
226	15/08/19 16:11	Reinspection Photo		☒
227	15/08/19 16:11	Reinspection Photo		☒
228	15/08/19 16:11	Reinspection Photo		☒
229	15/08/19 16:11	Reinspection Photo		☒
230	15/08/19 16:11	Reinspection Photo		☒
231	15/08/19 16:11	Reinspection Photo		☒
232	15/08/19 16:11	Reinspection Photo		☒
233	15/08/19 16:11	Reinspection Photo		☒
234	15/08/19 16:11	Reinspection Photo		☒
235	15/08/19 16:11	Reinspection Photo		☒
236	15/08/19 16:11	Reinspection Photo		☒
237	15/08/19 16:11	Reinspection Photo		☒
238	15/08/19 16:11	Reinspection Photo		☒
239	15/08/19 16:11	Reinspection Photo		☒
240	15/08/19 16:11	Reinspection Photo		☒
241	15/08/19 16:11	Reinspection Photo		☒
242	15/08/19 16:11	Reinspection Photo		☒
243	15/08/19 16:11	Reinspection Photo		☒
244	15/08/19 16:11	Reinspection Photo		☒
245	15/08/19 16:11	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
246	15/08/19 16:11	Reinspection Photo		☒
247	15/08/19 16:11	Reinspection Photo		☒
248	15/08/19 16:11	Reinspection Photo		☒
249	15/08/19 16:11	Reinspection Photo		☒
250	15/08/19 16:11	Reinspection Photo		☒
251	15/08/19 16:11	Reinspection Photo		☒
252	15/08/19 16:11	Reinspection Photo		☒
253	15/08/19 16:11	Reinspection Photo		☒
254	15/08/19 16:11	Reinspection Photo		☒
255	15/08/19 16:11	Reinspection Photo		☒
256	15/08/19 16:11	Reinspection Photo		☒
257	15/08/19 16:11	Reinspection Photo		☒
258	15/08/19 16:11	Reinspection Photo		☒
259	15/08/19 16:11	Reinspection Photo		☒
260	15/08/19 16:11	Reinspection Photo		☒
261	15/08/19 16:11	Reinspection Photo		☒
262	15/08/19 16:11	Reinspection Photo		☒
263	15/08/19 16:11	Reinspection Photo		☒
264	15/08/19 16:11	Reinspection Photo		☒
265	15/08/19 16:11	Reinspection Photo		☒
266	15/08/19 16:11	Reinspection Photo		☒
267	15/08/19 16:11	Reinspection Photo		☒
268	15/08/19 16:11	Reinspection Photo		☒
269	15/08/19 16:11	Reinspection Photo		☒
270	15/08/19 16:11	Reinspection Photo		☒
271	15/08/19 16:11	Reinspection Photo		☒
272	15/08/19 16:11	Reinspection Photo		☒
273	15/08/19 16:11	Reinspection Photo		☒
274	15/08/19 16:11	Reinspection Photo		☒
275	15/08/19 16:11	Reinspection Photo		☒
276	15/08/19 16:11	Reinspection Photo		☒
277	15/08/19 16:11	Reinspection Photo		☒
278	15/08/19 16:11	Reinspection Photo		☒
279	15/08/19 16:11	Reinspection Photo		☒
280	15/08/19 16:11	Reinspection Photo		☒
281	15/08/19 16:11	Reinspection Photo		☒
282	15/08/19 16:11	Reinspection Photo		☒
283	15/08/19 16:11	Reinspection Photo		☒
284	15/08/19 16:11	Reinspection Photo		☒
285	15/08/19 16:11	Reinspection Photo		☒
286	15/08/19 16:11	Reinspection Photo		☒
287	15/08/19 16:11	Reinspection Photo		☒
288	15/08/19 16:11	Reinspection Photo		☒
289	15/08/19 16:11	Reinspection Photo		☒
290	15/08/19 16:11	Reinspection Photo		☒
291	15/08/19 16:11	Reinspection Photo		☒
292	15/08/19 16:11	Reinspection Photo		☒
293	15/08/19 16:11	Reinspection Photo		☒
294	15/08/19 16:11	Reinspection Photo		☒
295	15/08/19 16:11	Reinspection Photo		☒
296	15/08/19 16:11	Reinspection Photo		☒
297	15/08/19 16:11	Reinspection Photo		☒
298	15/08/19 16:11	Reinspection Photo		☒
299	15/08/19 16:11	Reinspection Photo		☒
300	15/08/19 16:11	Reinspection Photo		☒
301	15/08/19 16:11	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
302	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
303	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
304	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
305	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
306	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
307	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
308	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
309	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
310	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
311	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
312	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
313	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
314	15/08/19 16:11	Reinspection Photo	 Load JPG	☒
315	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
316	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
317	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
318	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
319	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
320	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
321	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
322	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
323	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
324	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
325	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
326	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
327	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
328	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
329	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
330	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
331	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
332	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
333	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
334	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
335	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
336	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
337	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
338	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
339	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
340	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
341	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
342	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
343	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
344	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
345	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
346	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
347	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
348	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
349	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
350	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
351	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
352	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
353	15/08/19 16:12	Reinspection Photo	Load JPG	☒
354	15/08/19 16:12	Reinspection Photo	Load JPG	☒
355	15/08/19 16:12	Reinspection Photo	Load JPG	☒
356	15/08/19 16:12	Reinspection Photo	Load JPG	☒
357	15/08/19 16:12	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
358	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
359	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
360	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
361	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
362	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
363	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
364	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
365	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
366	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
367	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
368	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
369	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
370	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
371	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
372	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
373	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
374	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
375	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
376	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
377	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
378	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
379	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
380	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
381	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
382	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
383	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
384	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
385	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
386	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
387	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
388	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
389	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
390	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
391	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
392	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
393	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
394	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
395	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
396	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
397	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
398	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
399	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
400	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
401	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
402	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
403	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
404	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
405	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
406	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
407	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
408	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
409	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
410	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
411	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
412	15/08/19 16:12	Reinspection Photo	 Load JPG	☒
413	15/08/19 16:12	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
414	15/08/19 16:12	Reinspection Photo		☒
415	15/08/19 16:12	Reinspection Photo		☒
416	15/08/19 16:12	Reinspection Photo		☒
417	15/08/19 16:12	Reinspection Photo		☒
418	15/08/19 16:12	Reinspection Photo		☒
419	15/08/19 16:12	Reinspection Photo		☒
420	15/08/19 16:12	Reinspection Photo		☒
421	15/08/19 16:12	Reinspection Photo		☒
422	15/08/19 16:12	Reinspection Photo		☒
423	15/08/19 16:12	Reinspection Photo		☒
424	15/08/19 16:12	Reinspection Photo		☒
425	15/08/19 16:12	Reinspection Photo		☒
426	15/08/19 16:12	Reinspection Photo		☒
427	15/08/19 16:12	Reinspection Photo		☒
428	15/08/19 16:12	Reinspection Photo		☒
429	15/08/19 16:12	Reinspection Photo		☒
430	15/08/19 16:12	Reinspection Photo		☒
431	15/08/19 16:12	Reinspection Photo		☒
432	15/08/19 16:12	Reinspection Photo		☒
433	15/08/19 16:12	Reinspection Photo		☒
434	15/08/19 16:12	Reinspection Photo		☒
435	15/08/19 16:12	Reinspection Photo		☒
436	15/08/19 16:12	Reinspection Photo		☒
437	15/08/19 16:12	Reinspection Photo		☒
438	15/08/19 16:12	Reinspection Photo		☒
439	15/08/19 16:12	Reinspection Photo		☒
440	15/08/19 16:12	Reinspection Photo		☒
441	15/08/19 16:12	Reinspection Photo		☒
442	15/08/19 16:12	Reinspection Photo		☒
443	15/08/19 16:12	Reinspection Photo		☒
444	15/08/19 16:12	Reinspection Photo		☒
445	15/08/19 16:12	Reinspection Photo		☒
446	15/08/19 16:12	Reinspection Photo		☒
447	15/08/19 16:12	Reinspection Photo		☒
448	15/08/19 16:12	Reinspection Photo		☒
449	15/08/19 16:12	Reinspection Photo		☒
450	15/08/19 16:12	Reinspection Photo		☒
451	15/08/19 16:12	Reinspection Photo		☒
452	15/08/19 16:12	Reinspection Photo		☒
453	15/08/19 16:12	Reinspection Photo		☒
454	15/08/19 16:12	Reinspection Photo		☒
455	15/08/19 16:12	Reinspection Photo		☒
456	15/08/19 16:12	Reinspection Photo		☒
457	15/08/19 16:12	Reinspection Photo		☒
458	15/08/19 16:14	Reinspection Photo		☒
459	15/08/19 16:14	Reinspection Photo		☒
460	15/08/19 16:14	Reinspection Photo		☒
461	15/08/19 16:14	Reinspection Photo		☒
462	15/08/19 16:14	Reinspection Photo		☒
463	15/08/19 16:14	Reinspection Photo		☒
464	15/08/19 16:14	Reinspection Photo		☒
465	15/08/19 16:14	Reinspection Photo		☒
466	15/08/19 16:14	Reinspection Photo		☒
467	15/08/19 16:14	Reinspection Photo		☒
468	15/08/19 16:14	Reinspection Photo		☒
469	15/08/19 16:14	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
470	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
471	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
472	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
473	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
474	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
475	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
476	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
477	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
478	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
479	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
480	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
481	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
482	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
483	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
484	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
485	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
486	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
487	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
488	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
489	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
490	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
491	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
492	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
493	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
494	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
495	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
496	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
497	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
498	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
499	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
500	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
501	15/08/19 16:14	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/10/18 16:55	PRS	 Load PDF	
2	29/10/18 16:55	OI GIA	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	16/10/18 10:38	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	16/10/18 11:22	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	16/10/18 11:20	Accident Photo	 Load JPG	☒
2	16/10/18 11:20	Accident Photo	 Load JPG	☒
3	16/10/18 11:20	Accident Photo	 Load JPG	☒
4	16/10/18 11:20	Accident Photo	 Load JPG	☒
5	16/10/18 11:20	Accident Photo	 Load JPG	☒
6	16/10/18 11:20	Accident Photo	 Load JPG	☒
7	16/10/18 11:20	Accident Photo	 Load JPG	☒
8	16/10/18 11:20	Accident Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
9	16/10/18 11:21	Accident Photo		Load JPG	☒
10	16/10/18 11:21	Accident Photo		Load JPG	☒
11	16/10/18 11:21	Accident Photo		Load JPG	☒
12	16/10/18 11:21	Accident Photo		Load JPG	☒
13	16/10/18 11:21	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	16/10/18 10:38	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18019672/T1VBE2

Date: 18/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3032071802

Claimant
Vehicle No: SLX8977KInsured Vehicle
No: SKZ8200U

Date of Loss: 13/10/2018

Nature of Claim: TP

Claim
No: SNM18D04905C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX8977K

Make & Model: BMW I8, 1.5 E LED HUD NAV (A)

Engine No: A023O826B38K15A

Reg. Date: 28/11/2014 (Man. Year: 2014)

Chassis No: WBY2Z22070VX65215

Colour: White

Odometer: 0 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R20	Rear Tyre Size:	215/45 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	156,329.78	110,744.58	45,585.20	29.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,150.00	5,870.00	8,280.00	58.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	170,479.78	116,614.58	53,865.20	31.60
Approved Total (Overridden) (S\$)		105,000.00		
Nett Amount (S\$)	170,479.78	105,000.00	65,479.78	38.41

INSPECTION

Date of Assignment: 29/10/2018

Date Inspected: 01/11/2018 Inspected At:

Li Sheng Automobile Trading (HQ)
No. 18 Pandan Loop #01-18 Blk K
Singapore 128236

Estimated Period of Repair: 18.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	192	BMW I8 1.5 E LED HUD NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX8977K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, I-CAM	Missing	87.93 FL	*87.93 FL
2	1		*MOUNT I-CAM	Cracked	29.34 FL	*29.34 FL
3	4		*SET OF MOUNTS FOR PDC SENSOR, FRONT	Distorted	434.52 FL	*434.52 FL
4	1		*FRONT BUMPER GRILL PANEL	Distorted	260.28 FL	*260.28 FL
5	1		*FRONT SEAL, ENGINE BONNET	Missing	137.43 FL	*137.43 FL
6	8		*FRONT BUMPER SCREW	Necessary	80.00 FL	*80.00 FL
7	4		*FRONT BUMPER CLIP NUT	Necessary	20.00 FL	*20.00 FL
8	3		*FRONT BUMPER FILLISTER HEAD SCREW	Necessary	9.00 FL	*9.00 FL
9	1		*FRONT BUMPER LEFT TRIM GRILL	Cracked	390.42 FL	*390.42 FL
10	1		*FRONT BUMPER RIGHT TRIM GRILL	Cracked	390.42 FL	*390.42 FL
11	14		*FRONT BUMPER GRILL PANEL SCREW	Necessary	42.00 FL	*42.00 FL
12	1		*FRONT BUMPER CARRIER	Bent	1,180.35 FL	*1,180.35 FL
13	1		*FRONT BUMPER LOWER MOUNT	Missing	749.16 FL	*749.16 FL
14	1		*FRONT LEFT ELEMENT	Bent	381.33 FL	*381.33 FL
15	1		*FRONT RIGHT ELEMENT	Bent	318.33 FL	*318.33 FL
16	1		*FRONT LOWER LEFT ELEMENT	Bent	269.73 FL	*269.73 FL
17	1		*FRONT LOWER RIGHT ELEMENT	Bent	269.73 FL	*269.73 FL
18	2		*FRONT LEFT AND RIGHT CONNECTOR	Bent	207.90 FL	*207.90 FL
19	1		*FRONT LEFT BUMPER SUPPORT	Bent	103.95 FL	*103.95 FL
20	1		*FRONT RIGHT BUMPER SUPPORT	Bent	103.95 FL	*103.95 FL
21	1		*FRONT TOP SPONGE	Cracked	66.42 FL	*66.42 FL
22	1		*FRONT BOTTOM SPONGE	Missing	66.42 FL	*66.42 FL
23	1		*FRONT LEFT SPONGE	Missing	47.07 FL	*47.07 FL
24	1		*FRONT RIGHT SPONGE	Missing	47.07 FL	*47.07 FL
25	1		*FOAM COMPONENT	Missing	38.16 FL	*38.16 FL
26	2		*FRONT LOWER MOUNT BOLT	Necessary	10.00 FL	*10.00 FL
27	2		*FRONT EDGE PROTECTION	Missing	44.00 FL	*44.00 FL
28	1		*FRONT BONNET EMBLEM	Necessary	125.10 FL	*125.10 FL
29	1		*FRONT CROSSLINK	Bent	715.23 FL	*715.23 FL
30	2		*FRONT CROSSLINK STOP BUFFER	Necessary	46.98 FL	*46.98 FL
31	1		*FRONT LEFT ROD	Bent	43.02 FL	*43.02 FL
32	1		*FRONT RIGHT ROD	Bent	43.02 FL	*43.02 FL
33	1		*FRONT UPPER LEFT RADIATOR BRACKET	Bent	56.70 FL	*56.70 FL
34	1		*FRONT UPPER RIGHT RADIATOR BRACKET	Bent	56.70 FL	*56.70 FL
35	2		*FRONT SUPPORT BRACKET	Bent	69.30 FL	*69.30 FL
36	2		*FRONT SUPPORT PANEL BRACKET	Bent	346.68 FL	*346.68 FL
37	2		*FRONT LEFT AND RIGHT BRACE BRACKET	Bent	338.22 FL	*338.22 FL
38	2			Bent	549.18 FL	*549.18 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT LEFT AND RIGHT HEADLAMP SUPPORT			
39	2		*FRONT LEFT AND RIGHT HEADLAMP LEVER	Cracked	186.30 FL	*186.30 FL
40	7		*FRONT SUPPORT HEAD SCREW	Necessary	40.95 FL	*40.95 FL
41	4		*FRONT C-CLIP NUT	Necessary	11.88 FL	*11.88 FL
42	4		*FRONT ISA SCREW	Necessary	24.84 FL	*24.84 FL
43	6		*FRONT BLIND RIVET NUT	Necessary	36.72 FL	*36.72 FL
44	8		*FRONT C-CLIP PLASTIC NUT	Necessary	14.40 FL	*14.40 FL
45	2		*FRONT LEVER TORX BOLT	Necessary	20.00 FL	*20.00 FL
46	2		*FRONT SUPPORT FLAT NUT	Necessary	29.88 FL	*29.88 FL
47	1		*FRONT WINDSHIELD	Not Necessary	2,600.00 FL	*- FL
48	1		*FRONT WINDSHIELD TOP COVER	Not Necessary	93.60 FL	*- FL
49	10		*FRONT WINDSHIELD BUMP STOP	Not Necessary	57.60 FL	*- FL
50	2		*FRONT WINDSHIELD LEFT & RIGHT ROOF FRAME GASKET	Not Necessary	27.36 FL	*- FL
51	1		*HEADLINING (ROOF LINING)	Deformed	2,790.00 FL	*2,790.00 FL
52	1		*FRONT WINDSHIELD COVER	Cracked	180.00 FL	*180.00 FL
53	2		*FRONT LEFT AND RIGHT APRON COVER	Deformed	198.00 FL	*198.00 FL
54	1		*FRONT WINDSHIELD COVER EXPANDING RIVET (3PCS)	Necessary	10.00 FL	*10.00 FL
55	1		*DASHBOARD INSTRUMENT PANNEL, UPPER PART	Deformed	6,390.00 FL	*6,390.00 FL
56	1		*FRONT UNDERHOOD SHIELD	Cracked	392.25 FL	*392.25 FL
57	2		*FRONT LEFT AND RIGHT BOOTOM COVER	Torn	280.90 FL	*280.90 FL
58	1		*FRONT UNDER COVER BOLT (26PCS)	Necessary	36.54 FL	*36.54 FL
59	1		*FRONT LEFT AND RIGHT WHEELHOUSING	N/SNot Necessary/ O/S Deformed	460.80 FL	*230.40 FL
60	2		*FRONT REAR LEFT AND RIGHT WHEELHOUSING	Not Necessary	432.00 FL	*- FL
61	2		*TOP LEFT AND RIGHT WHEEL ARCH COVER	Deformed	256.00 FL	*256.00 FL
62	20		*WHEELHOUSING PLASTIC NUT	Necessary	72.00 FL	*72.00 FL
63	4		*WHEELHOUSING HEX BOLT	Not Necessary	38.00 FL	*- FL
64	1		*FRONT AIR DUCT	Deformed	180.00 FL	*180.00 FL
65	1		*FRONT BOTTOM AIR DUCT	Cracked	577.50 FL	*577.50 FL
66	1		*FRONT LOWER LEFT AIR DUCT	Cracked	135.00 FL	*135.00 FL
67	1		*FRONT LEFT BRAKE AIR DUCT	Deformed	72.00 FL	*72.00 FL
68	1		*FRONT LOWER RIGHT AIR DUCT	Cracked	135.00 FL	*135.00 FL
69	1		*FRONT RIGHT BRACE AIR DUCT	Deformed	72.00 FL	*72.00 FL
70	1		*FRONT UPPER EXHAUST AIR DUCT	Deformed	207.00 FL	*207.00 FL
71	1		*FRONT LOWER SECTION AIR EXHAUST DUCT	Cracked	72.00 FL	*72.00 FL
72	1		*FRONT LOWER LEFT AIR-EXHAUST DUCT	Not Necessary	76.50 FL	*- FL
73	1		*FRONT LOWER RIGHT AIR-EXHAUST DUCT	Not Necessary	76.50 FL	*- FL
74	4		*FRONT BRAKE AIR DUCT HEX BOLT	Necessary	10.08 FL	*10.08 FL
75	4		*C-CLIP FOR PLASTIC NUT	Necessary	10.00 FL	*10.00 FL
76	8		*EXPANDING RIVET	Necessary	12.24 FL	*12.24 FL
77	1		*BATTERY TRAY	Not Necessary	210.00 FL	*- FL
78	4		*FRONT PARKING SENSOR	Distorted	2,000.00 FL	*2,000.00 FL
79	4		*FRONT PARKING SENSOR RING	Necessary	34.00 FL	*34.00 FL
80	1		*FRONT BONNET	Bent	3,964.35 FL	*3,964.35 FL
81	1		*FRONT LEFT BONNET HINGE	Bent	134.00 FL	*134.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
82	1		*FRONT RIGHT BONNET HINGE	Bent	134.00 FL	*134.00 FL
83	4		*FRONT BOONRT HINGE SELF LOCKING COLLAR NUT	Necessary	8.00 FL	*8.00 FL
84	6		*FRONT BONNET HINGE HEX BOLT WITH WASHER	Necessary	12.00 FL	*12.00 FL
85	1		*FRONT BONNET AIR DUCT	Distorted	280.00 FL	*280.00 FL
86	1		*FRONT BONNET AIR DUCT GRILL	Not Necessary	147.90 FL	*- FL
87	8		*FRONT BONNET EXPANING RIVET	Necessary	12.00 FL	*12.00 FL
88	2		*FRONT BONNET HINGE INTERMEDIATE PLATE ASSY	Bent	10.00 FL	*10.00 FL
89	1		*FRONT BONNET SEAL	Missing	99.00 FL	*99.00 FL
90	1		*FRONT BONNET SIDE SEAL	Necessary	82.35 FL	*82.35 FL
91	1		*FRONT LEFT AIR DUCT SEAL	Deformed	96.00 FL	*96.00 FL
92	1		*FRONT RIGHT AIR DUCT SEAL	Deformed	96.00 FL	*96.00 FL
93	1		*FRONT BONNET LOCK (2PCS)	Bent	304.95 FL	*304.95 FL
94	2		*CATCH BRACKET	Bent	73.18 FL	*73.18 FL
95	2		*TWIST PROTECTION	Deformed	18.30 FL	*18.30 FL
96	2		*FRONT BONNET CABLE LEFT AND RIGHT	Not Necessary	440.00 FL	*- FL
97	2		*EXPANDING RIVET	Necessary	4.00 FL	*4.00 FL
98	2		*ADJUSTER	Not Necessary	20.00 FL	*- FL
99	2		*DISTANCE SENSOR	Necessary	10.00 FL	*10.00 FL
100	1		*FRONT LEFT FENDER	Cracked	1,800.00 FL	*1,800.00 FL
101	1		*FRONT RIGHT FENDER	Cracked	1,800.00 FL	*1,800.00 FL
102	1		*FRONT LEFT SUPPORTING STRUT	Not Necessary	800.00 FL	*- FL
103	1		*FRONT RIGHT SUPPORTING STRUT	Bent	800.00 FL	*800.00 FL
104	1		*FRONT RIGHT DEFORMATION ELEMENT	Bent	81.00 FL	*81.00 FL
105	1		*FRONT LEFT DEFORMATION ELEMENT	Not Necessary	81.00 FL	*- FL
106	1		*REAR LEFT DEFORMATION ELEMENT	Not Necessary	80.00 FL	*- FL
107	1		*REAR RIGHT DEFORMATION ELEMENT	Bent	80.00 FL	*80.00 FL
108	1		*CENTER RIGHT DEFORMATION ELEMENT	Bent	40.00 FL	*40.00 FL
109	1		*CENTER LEFT DEFORMATION ELEMENT	Bent	40.00 FL	*40.00 FL
110	2		*GASKET	Not Necessary	10.00 FL	*- FL
111	1		*FRONT LEFT FENDER SUPPORT	Not Necessary	40.00 FL	*- FL
112	1		*FRONT RIGHT FENDER SUPPORT	Deformed	40.00 FL	*40.00 FL
113	16		*FRONT LEFT AND RIGHT FENDER SCREW	Necessary	96.00 FL	*96.00 FL
114	20		*BLIND RIVET NUT, FLAT HEADED	Necessary	100.00 FL	*100.00 FL
115	2		*FOAM BELT	Necessary	40.00 FL	*40.00 FL
116	1		*SEAL, FRONT SIDE PANEL, LEFT	Necessary	39.00 FL	*39.00 FL
117	1		*SEAL, FRONT SIDE PANEL, LEFT	Necessary	39.00 FL	*39.00 FL
118	2		*FRONT LEFT AND RIGHT HEADLAMP	Cracked	15,500.80 FL	*15,500.80 FL
119	2		*HEADLIGHT COVER	Distorted	86.40 FL	*86.40 FL
120	1		*HEADLIGHT SINK LEFT AND RIGHT	N/S NotNecessary/O/S Distorted	990.00 FL	*495.00 FL
121	2		*REPAIR KIT OF HEADLAMP	Necessary	378.00 FL	*378.00 FL
122	1		*CONTROL UNIT FOR FRONT LIGHT ELECTRONICS	N/S Cracked / O/SNot Necessary	2,800.00 FL	*1,400.00 FL
123	2		*ALIGNMENT ELEMENT	Necessary	20.00 FL	*20.00 FL
124	2		*REPAIR KIT FOR LWR SERVO MOTOR	Necessary	150.00 FL	*150.00 FL
125	10		*COUNTERSUNK SCREW	Necessary	40.00 FL	*40.00 FL
126	1		*CONTROL MODULE, TURN SIGNAL WITH GASKET	N/SNot Necessary/O/S Cracked	890.00 FL	*445.00 FL
127	4		*FLAT NUT	Necessary	40.00 FL	*40.00 FL
128	2		*GASKET	Necessary	20.00 FL	*20.00 FL
129	1		*FAN HOUSING WITH FAN MOTOR	Cracked	2,562.50 FL	*2,562.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
130	4		*FAN HOUSING LOWER SEALING	Necessary	10.00 FL	*10.00 FL
131	1		*RADIATOR TOP INNER	Bent	1,890.00 FL	*1,890.00 FL
132	1		*RADIATOR TOP OUTER	Bent	1,134.00 FL	*1,134.00 FL
133	1		*RADIATOR LOWER INNER	Bent	1,790.00 FL	*1,790.00 FL
134	1		*RADIATOR LOWER OUTER	Bent	1,790.00 FL	*1,790.00 FL
135	2		*RADIATOR LEFT MODULE MOUNT	Cracked	450.00 FL	*450.00 FL
136	2		*RADIATOR RIGHT MODULE MOUNT	Cracked	450.00 FL	*450.00 FL
137	1		*RADIATOR LOWER SEALING	Deformed	250.00 FL	*250.00 FL
138	1		*LEFT BRACKET FOR MODULE	Deformed	240.00 FL	*240.00 FL
139	1		*RIGHT BRACKET FOR MODULE	Deformed	240.00 FL	*240.00 FL
140	1		*RADIATOR UPPER SEALING	Deformed	250.00 FL	*250.00 FL
141	4		*RADIATOR UPPER SEALING SCREW SELF-TAPPING	Necessary	12.00 FL	*12.00 FL
142	2		*FILLISTER HEAD SCREW	Necessary	10.00 FL	*10.00 FL
143	2		*RUBBER MOUNTING	Necessary	50.00 FL	*50.00 FL
144	2		*SUPPORT RUBBER MOUNTING	Necessary	60.00 FL	*60.00 FL
145	1		*BLIND RIVET NUT, COUNTERSUNK HEAD (6PCS)	Necessary	40.00 FL	*40.00 FL
146	1		*PIPE, EXPANSION TANK-RADIATOR	Not Necessary	90.00 FL	*- FL
147	1		*LINE FROM EXPANSION TANK - THERMOSTAT	Not Necessary	162.00 FL	*- FL
148	1		*LINE, CONNECTION FOR WATER PUMP	Distorted	220.00 FL	*220.00 FL
149	1		*HOSE, EXPANSION TANK-RETURN PIPE	Not Necessary	160.00 FL	*- FL
150	1		*HOSE, EXPANSION TANK-	Not Necessary	150.00 FL	*- FL
151	3		*CLIP	Not Necessary	12.00 FL	*- FL
152	4		*HOSE CLAMP	Not Necessary	30.00 FL	*- FL
153	1		*HOSE CLAMP	Not Necessary	10.00 FL	*- FL
154	1		*REFRIGERANT LINE IWT	Not Necessary	650.00 FL	*- FL
155	1		*PRESSURE HOSE ASSY COMPRESSOR-CONDENSER	Bent	442.00 FL	*442.00 FL
156	1		*SUCTION PIPE	Not Necessary	410.00 FL	*- FL
157	1		*PRESSURE PIPE	Bent	620.00 FL	*620.00 FL
158	6		*GASKET RING	Necessary	120.00 FL	*120.00 FL
159	1		*SEALING CAP FOR SUCTION LINE	Not Necessary	8.00 FL	*- FL
160	1		*SEALING CAP FOR PRESSURE LINE	Not Necessary	8.00 FL	*- FL
161	1		*PRESSURE SENSOR	Not Necessary	180.00 FL	*- FL
162	1		*A/C CONDENSOR	Bent	1,750.00 FL	*1,750.00 FL
163	1		*FRONT LEFT WHEEL RIM	Not Necessary	4,880.00 FL	*- FL
164	1		*FRONT RIGHT WHEEL RIM	Dented	4,880.00 FL	*4,880.00 FL
165	1		*WHEEL CENTER CAP WITH BLUE RING	Not Necessary	200.00 FL	*- FL
166	1		*WHEEL ELECTR. MODULE RDCI W/ SCREW VALVE	Not Necessary	500.00 FL	*- FL
167	1		*FRONT RIGHT SIDE DRIVESHAFT	Not Necessary	4,050.00 FL	*- FL
168	1		*FRONT ANTI-ROLL BAR	Not Necessary	680.00 FL	*- FL
169	2		*FRONT STABILIZER LINK	Not Necessary	414.00 FL	*- FL
170	2		*FRONT ABSORBER LEFT AND RIGHT	Not Necessary	4,000.00 FL	*- FL
171	2		*FRONT ABSORBER SPRING LOWER PAD	Not Necessary	60.00 FL	*- FL
172	2		*FRONT ABSORBER SPRING TOP PAD	Not Necessary	68.00 FL	*- FL
173	6		*FRONT ABSORBER SCREW SELF-TAPPING	Not Necessary	60.00 FL	*- FL
174	2		*FRONT ABSORBER TOP MOUNTING	Not Necessary	760.00 FL	*- FL
175	2		*FRONT ABSORBER PLUG-IN CONNECTION BRACKET	Not Necessary	34.00 FL	*- FL
176	1		*FRONT AXLE SUPPORT	Bent	3,690.00 FL	*3,690.00 FL
177	1		*FRONT AXLE SUPPORT CROSS MEMBER	Not Necessary	558.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
178	12		*FRONT AXLE SUPPORT BOLT WITH WASHER	Not Necessary	208.00 FL	*- FL
179	2		*FRONT RIGHT AND LEFT STRUT ARM	Not Necessary	1,500.00 FL	*- FL
180	2		*FRONT RIGHT AND LEFT CENTER ARM	Not Necessary	2,000.00 FL	*- FL
181	2		*FRONT RIGHT AND LEFT UPPER ARM	Not Necessary	1,808.30 FL	*- FL
182	2		*FRONT AXLE MOUNTING	Necessary	375.00 FL	*375.00 FL
183	2		*FRONT HEADLAMP LEVEL SENSOR	Not Necessary	480.00 FL	*- FL
184	1		*FRONT RINGLE KNUCKLE	Not Necessary	1,228.00 FL	*- FL
185	1		*FRONT RIGHT WHEEL BEARING WITH HUB	Bent	696.00 FL	*696.00 FL
186	1		*FRONT RIGHT AND LEFT WHEEL SPEED SENSOR	Not Necessary	640.00 FL	*- FL
187	1		*AT-STEERING BOX, ELECTR TKP	Bent	6,300.00 FL	*6,300.00 FL
188	1		*FRONT RIGHT AND LEFT TIE ROD	N/SNotNecessary / O/S Bent	1,280.00 FL	*640.00 FL
189	1		*DECOR TRIM COVER, STEERING WHEEL	Distorted	600.00 FL	*600.00 FL
190	1		*COVER FOR STEERING WHEEL, REAR	Not Necessary	250.00 FL	*- FL
191	1		*CONNECTING LINE, STEERING WHEEL	Not Necessary	300.00 FL	*- FL
192	1		*AIRBAG MODULE, DRIVERS SIDE	Activated	3,240.00 FL	*3,240.00 FL
193	1		*FRONT LEFT WIRING HARNESS, LIVE	Not Necessary	468.00 FL	*- FL
194	1		*FRONT RIGHT WIRING HARNESS, LIVE	Torn	540.00 FL	*540.00 FL
195	1		*SBK WIRING HARNESS	Necessary	72.00 FL	*72.00 FL
196	1		*RAIN SENSOR	Not Necessary	387.00 FL	*- FL
197	1		*STEERING COIL SPRING CATRIDGE	Activated	480.00 FL	*480.00 FL
198	1		*HORN, HIGH PITCH	Cracked	158.40 FL	*158.40 FL
199	1		*HORN, LOW PITCH	Cut	158.40 FL	*158.40 FL
200	2		*HORN SCREW	Necessary	10.00 FL	*10.00 FL
201	1		*WASHER FLUID RESERVIOR	Deformed	225.00 FL	*225.00 FL
202	1		*WASH PUMP / FLUID CONTAINER	Deformed	112.35 FL	*112.35 FL
203	1		*GASKET	Necessary	12.00 FL	*12.00 FL
204	1		*STRAINER F WASH PUMP	Necessary	14.00 FL	*14.00 FL
205	1		*LEVEL SENSOR	Distorted	122.40 FL	*122.40 FL
206	1		*HEX BOLT WITH WASHER	Necessary	5.00 FL	*5.00 FL
207	2		*PIPE SUPPORT	Not Necessary	20.00 FL	*- FL
208	1		*COVER, WINDSHIELD	Cracked	180.00 FL	*180.00 FL
209	1		*FILLER PIPE FOR WASHER CONTAINER	Not Necessary	120.00 FL	*- FL
210	1		*WIPER WASHER TANK COVER	Missing	28.00 FL	*28.00 FL
211	1		*HOSE, WINDSHIELD WASHER	Not Necessary	80.00 FL	*- FL
212	2		*WIPER NOZZLE	Not Necessary	615.00 FL	*- FL
213	1		*FRONT RIGHT SEAT BELT	Activated	984.94 FL	*984.94 FL
214	1		*AIRBAG FOR FRONT PASSENGER	Activated	2,466.00 FL	*2,466.00 FL
215	1		*HEAD AIRBAG, RIGHT	Activated	1,224.00 FL	*1,224.00 FL
216	3		*BLINT RIVET NUT, FLAT HEADED	Necessary	30.00 FL	*30.00 FL
217	1		*FRONT I-CAM	Cut	1,164.16 FL	*1,164.16 FL
218	1		*BY PASS HOSE	Cut	269.64 FL	*269.64 FL
219	2		*BRACKET FOR MODULE LEFT AND RIGHT	Bent	821.76 FL	*821.76 FL
220	1		*WIPER RHS MOTOR WITH BRACKET	Cracked	1,155.60 FL	*1,155.60 FL
221	1		*SPRT STEERING WHEEL, LEATHER, SHIFT PADDLES	Cracked	2,800.00 FL	*2,800.00 FL
222	1		*FRONT BUMPER BODY KIT	Cracked	15,000.00 FS	*8,500.00 FS
223	2		*FRONT OVER FENDER BODY KIT	Cracked	10,000.00 FS	*6,500.00 FS
224	1		*FRONT WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
225	1		*FRONT PANEL SEALANT	Necessary	160.00 FS	*160.00 FS
226	1		*FRONT WINDSCREEN SOLAR FIRM	Not Necessary	600.00 FS	*- FS
227	2		*SOUND PROOF STICKER ON LEFT AND RIGHT	Necessary	900.00 FS	*900.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
228	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	163,145.56 115,726.40
- List Item Discount on L Items 5.00/5.00% (\$\$)					6,815.78	4,981.82
					Total Parts (\$\$)	156,329.78 110,744.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WHEEL ALIGNMENT	New	200.00	120.00
2	TOWING FEE	New	200.00	100.00
3	LABOUR FOR REPAIR ON AFFECTED AREA	New	5,000.00	2,750.00
4	SPRAY PAINT ON AFFECTED AREA	New	5,000.00	1,600.00
5	CHECK WIRING	New	800.00	200.00
6	APPLY RUST PROOF ON AFFECTED PANEL	New	500.00	0.00
7	REMOVE & REFIT AFFECTED FRONT PORTION	New	800.00	600.00
8	REPROGRAMMING AND RESETTING ON VEHICLE SYSTEM	New	1,000.00	200.00
9	TO REMOVE AND REFIT REAR WINDSCREEN	New	250.00	0.00
10	TO REMOVE AND REFIT REVERSE SENSOR	New	200.00	100.00
11	PULL CHASIS	New	200.00	200.00
Gross Labour Cost (\$\$)			14,150.00	5,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >