

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016668/GSBE2-1
Date: 16/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28970951MKC
Claimant Vehicle No : SLG7223Z	Insured Vehicle No :	XE3061T
Date of Loss: 10/09/2018	Nature of Claim:	TP Claim No: 569935

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7223Z	Engine No:	R16B21600519
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT000411
Reg. Date:	11/10/2016 (Man. Year: 2016)	Odometer:	34897 km
Colour:	Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,708.83	7,436.32	6,272.51	45.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,140.00	3,400.00	4,740.00	58.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,848.83	10,836.32	11,012.51	50.40
Approved Total (Overridden) (S\$)		8,650.00		
Nett Amount (S\$)	21,848.83	8,650.00	13,198.83	60.41

INSPECTION

Date of Assignment:	12/09/2018	
Date Inspected:	13/09/2018 Inspected At:	Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82 Singapore 575642
Estimated Period of Repair:	11.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7223Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	795.80 FL	*657.20 FL
2	2		*REAR BUMPER SIDE SPACER L/R	Broken	170.40 FL	*108.00 FL
3	2		*REAR BUMPER SIDE BRACKET L/R	Broken	91.40 FL	*57.40 FL
4	2		*REAR BUMPER CENTER SUPPORT	Bent	95.00 FL	*95.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	525.00 FL	*334.10 FL
6	1		*REAR BUMPER LOWER GARNISH	Cracked	385.70 FL	*385.70 FL
7	1		*REAR BOOT LID	Dented	997.00 FL	*755.90 FL
8	1		*REAR BOOT LID LICENSE LAMP MOULDING	Broken	351.70 FL	*184.20 FL
9	1		*REAR BOOT LID INNER TRIM	Torn	284.90 FL	*284.90 FL
10	1		*REAR BOOT LID LOCK	Bent	194.15 FL	*194.15 FL
11	1		*REAR BOOT LID STRIKER	Bent	38.10 FL	*38.10 FL
12	2		*REAR BOOT LID HINGE L/R	Bent	360.40 FL	*202.00 FL
13	1		*REAR BOOT LID WEATHER-STRIP	Cut	80.70 FL	*80.70 FL
14	1		*REAR BOOT LID OPENER SWITCH	Cut	93.60 FL	*93.60 FL
15	2		*REAR TAIL LAMP PANEL L/R	Dented	197.40 FL	*197.40 FL
16	2		*REAR END PANEL STIFF L/R	Bent	168.60 FL	*168.60 FL
17	1		*REAR END PANEL TOP GARNISH	Dislodged	245.70 FL	*185.40 FL
18	1		*REAR END PANEL	Dented	752.80 FL	*323.90 FL
19	1		*REAR FENDER L/R	N/S Dented/Buckled/O/S Repair	1,703.20 FL	*851.60 FL
20	1		*REAR FENDER INNER TRIM L/R	N/STorn/CrumpledO/SServiceable	633.60 FL	*316.80 FL
21	2		*REAR FENDER AIR OUTLET L/R	Not Necessary	129.40 FL	*- FL
22	2		*REAR FENDER UNDER SHIELD L/R	Not Necessary	364.80 FL	*- FL
23	1		*REAR SPARE TIRE PANEL	Not Necessary	829.40 FL	*- FL
24	1		*REAR EXHAUST SILENCER PIPE	Serviceable	816.60 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	58.00 F	*35.00 FN
26	2		*REAR TAIL LAMP L/R	Broken	1,189.20 F	*972.00 FN
27	2		*REAR BOOT LID LAMP L/R	Broken	790.00 F	*428.00 FN
28	2		*REAR BUMPER REFLECTOR L/R	Broken	109.20 F	*109.20 FN
29	2		*REAR BUMPER REFLECTOR GARNISH L/R	Crumpled	192.80 F	*156.00 FN
30	1		*REAR BUMPER LOWER GARNISH TOW CAP	Not Necessary	27.40 F	*- FN
31	2		*REAR BUMPER SIDE LOWER COVER L/R	Missing	368.60 F	*368.60 FN
32	4		*REAR BUMPER REVERSE SENSOR	Cut	703.60 F	*703.60 FN
33	2		*REAR BOOT LID HINGE COVER L/R	Broken	190.00 F	*190.00 FN
34	1		*REAR FOAM TOOL BOX	Not Necessary	213.50 F	*- FN
35	1		*REAR SPARE TYRE PANEL COVER	Not Necessary	291.70 F	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SPARE TYRE PANEL COATING PAD	Not Necessary	280.00 F	*- FN
37	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	172.80 F	*60.00 FN
38	1		*REAR WINDSCREEN GLASS DAMPER	Necessary	34.50 F	*34.50 FN
39	1		*REAR BOOT LID HONDA LOGO	Necessary	53.95 F	*53.95 FN
40	1		*REAR BUMPER CIVIX EMBLEM	Necessary	39.90 F	*39.90 FN
41	1		*REAR BUMPER I-VTEC EMBLEM	Necessary	22.80 F	*22.80 FN
42	2		*REAR EXHAUST MOUNTING HOOK	Usable	68.00 F	*- FN
43	1		*SET REAR NUMBER PLATE WITH CASING	Cut	80.00 FS	*60.00 FS
44	1		*REAR BOOT LID LICENSE LAMP	Broken	74.90 F	*57.20 FN
45	1		*SET REAR BOOTLID VIEW CAMERA	Cut	503.70 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	15,769.90	9,185.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,061.07	1,102.93
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	646.15

Total Parts (\$\$)	13,708.83	7,436.32
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS	New	2,500.00	1,200.00
2	REMOVE DAMAGED PARTS, KNOCK OUT DENT, STRAIGHTEN, JACK OUT DAMAGED PANEL, PANEL BEATING, CUTTING, WELDING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, RESHAPE, REFIT, ADJUST, REPLACE AND REALIGN ALL RELEVANT PARTS	New	3,500.00	1,400.00
3	TO TRANSFER REAR BOOT LID MECHANISM & COMPONENTS	New	80.00	40.00
4	TO CAVITY PRESERVATION ON ALL AFFECTED AREA & RE-SEAL BODY PANEL JOINT	New	180.00	90.00
5	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH, REPAIR, STRAIGHTEN REAR CHASSIS FRAME AND CONDUCT ALIGNMENT	New	600.00	0.00
6	CHECK WIRING, RECONNECTION SOCKET, LIGHTING SYSTEM, CENTRE LOCKING SYSTEM FOR PROPER FUNCTION & PERFORM WATER LEAK TEST	New	80.00	50.00
7	TO REMOVE & REINSTALL TRIMS GARNISH, CUSHION SEAT, INTERIOR UPHOLSTERY ETC, TO ENABLE NECESSARY REPAIRS, CHECK, REFIT AS SAME	New	250.00	80.00
8	TO CARRY OUT DIAGNOSTIC CHECKS AND RESET	New	350.00	160.00
9	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	120.00	120.00
10	TO SUPPLY REAR WINDSCREEN GLASS SEALANT	New	50.00	40.00
11	TO REINSTALL REAR BUMPER REVERSE SENSOR & VIEW CAMERA	New	180.00	80.00
12	TO STRAIGHTEN & RE-ALIGN REAR EXHAUST PIPE TO POSITION	New	150.00	80.00
13	TO PROVIDE TOWING SERVICE CHARGE	New	100.00	60.00
Gross Labour Cost (S\$)			8,140.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >