

72/09/2003

ASS. REC. BY:

REF: CS3 / MS671801668 / Gsb-1<sup>2</sup> Special Instruction:

SURVEYOR

## ASSIGNMENT (Office)

From (Person): Joelyn Tay of MSH Date/Time: 30.10.2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLH 7232 Insured: XE 3061Tat Workshop m/s Guan Auto Tel: 9388 4110of Blk 7 Sim Ming Ind Est #01-82Policy No: B2397 0951 MKC Claim No: 564935/JT

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10092018  
(Client's Record)


CA / REV / REP. / REV 24 HRS wpt

13.09.2018

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 13092018 451pm Person Contacted: Jacky Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate	Do Not Finalize
	SLH 7232 - X	
	XE 3061T - X	
	Dismantle: 14/9/2018	
15/11/18	Submit H/S \$8,650/- @ 11 days, checked by Simon. ( \$ 6,450/- Red. 43% )	



14/11/2018

Repair days

RECEIVED 15 NOV 2018

TGum

lin

12/11/18

PRS

REF: MSU1

13879

# ASSIGNMENT

From: Date: 13092018

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 72232  
at Workshop m/s: Guan Auto  
of: Blk 7 sin ming #01-82

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / -24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 72232 Yr Regn: 11 Oct 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda civic c.c 1597

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 74897 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR HFC 5650 GT 000411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

13-09-18

12:15pm

W/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$6000 - \$7000

RECEIVED 17 SEP 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

120

10

130

## Catherine Chong (LKK Auto)

---

**From:** Jowyn Tay <jowyn\_tay@sg.msig-asia.com>  
**Sent:** Tuesday, 30 October, 2018 11:13 AM  
**To:** Admin-D (LKKAuto); sur@lkkauto.com  
**Subject:** Paper Survey of SLG7223Z (Our Ref: 569935/JT)

Dear Catherine,

Refer to the subject matter.

Please proceed to do a paper survey for SLG7223Z. Copies of the 3<sup>rd</sup> party survey report has been uploaded and grants rights via merimen.

Thank you.

Best Regards,

Jowyn Tay  
Executive, Claims Services  
D: +65 6643 1307 | F: +65 6225 7402 | [jowyn\\_tay@sg.msig-asia.com](mailto:jowyn_tay@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018		12 Sep 2018 16:13 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:		SAMWOH RESOURCES PTE LTD, Co. Reg. No.: 199105225W							
Main Claimant:		THAM KIN YUEN, ID: S1111387G							
Vehicle Reg. No.:		SLG7223Z	Date of Loss:	10/09/2018 11:00 - :59 [22 Months and 30 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 569935	Policy/Cover Note No.:	B28970951MKC (Comprehensive) Coverage: 07/06/2018 - 06/06/2019					
Vehicle Reg. No. (Insured):		XE3061T	Policy No. (Claimant):						
		Excess:	S\$2,000.00						
Repairer:		Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/11/2018]							
Driver/Custodian (Insured):		YIN JIANGUO (39 / Male), NRIC: G5241696K, Tel: +6587832017							
Adj Asg. Remarks:		SJE - DISAGREED LIABILITY : 100% Please appoint LKK AUTO CONSULTANTS ONLY for this case ( SAMWOH RESOURCES PTE LTD) Kindly contact MR JACKY @ 9388 4210 to arrange for survey .							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (30/10/2018): Report Send Back Alerts - SLG7223Z (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**Daniel Poon & Co.**

Advocates & Solicitors  
Commissioners for Oaths



Daniel Poon Choon Kow  
LL. B. (Hons), LL.M

133 New Bridge Road  
#11-02 Chinatown Point  
Singapore 059413  
Tel: +65 6227-2469  
Fax: +65 6225-2579  
Email: law@dpco.com.sg  
(UEN: 53130838C)

Our Ref: DP.sl.10656.18.GA  
Your Ref: ----- 509935  
Please quote our reference number when replying

DATE: 22 OCT 2018

SAMWOH RESOURCES PTE LTD  
25E SUNGEI KADUT STREET 1  
SINGAPORE 729333  
OWNER OF XE 3061T

**WITHOUT PREJUDICE**  
**CERTIFICATE OF POSTING**

Dear Sir,

**THAM KIN YUEN (OWNER OF SLG 7223Z)**  
**BLK 972 HOUGANG STREET 91**  
**#13-194**

**SINGAPORE 530972**

**ACCIDENT ON 10 SEPTEMBER 2018 INVOLVING SLG 7223Z AND XE 3061T**  
**AT JUNCTION BETWEEN OLD TAMPINES ROAD AND LOYANG AVENUE**

We are instructed by the above named to claim damages (only material damage on our client's vehicle and without prejudice to our client's injuries, if any.) against you/your driver in connection with the above road traffic accident.

We are instructed that the accident was caused by you/your driver's negligent driving and/or management of you/your driver's vehicle no. **XE 3061T**. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of repair	\$15,100.00
2. Rental	\$ 1,950.00
3. Loss of use (02 days @ \$100.00 per day)	\$ 200.00
4. Survey fee	\$ 815.00
5. Cost at this stage	\$ 1,000.00
6. GIA/ LTA/ROC/ police search fee &/reports	\$ 36.49
7. Postages, transport and other incidentals	\$ 50.00
	<b><u>\$19,151.49</u></b>

... 2/-

Yanir, 18/10

(1) upload

(2) M1 & 2

Joey  
25/10/18



**Daniel Poon & Co.**

Advocates & Solicitors  
Commissioners for Oaths

Daniel Poon Choon Kow  
LL. B. (Hons), LLM

133 New Bridge Road  
#11-02 Chinatown Point  
Singapore 059413  
Tel: +65 6227-2469  
Fax: +65 6225-2579  
Email: law@dpco.com.sg  
(UEN: 53130838C)

Our Ref: DP.sl.10656.18.GA

Your Ref: -----

Please quote our reference number when replying

DATE: 22 OCT 2018

SAMWOH RESOURCES PTE LTD  
25E SUNGEI KADUT STREET 1  
SINGAPORE 729333  
OWNER OF XE 3061T

**WITHOUT PREJUDICE**  
**CERTIFICATE OF POSTING**

Dear Sir,

**THAM KIN YUEN (OWNER OF SLG 7223Z)**  
**BLK 972 HOUGANG STREET 91**  
**#13-194**

**SINGAPORE 530972**

**ACCIDENT ON 10 SEPTEMBER 2018 INVOLVING SLG 7223Z AND XE 3061T**  
**AT JUNCTION BETWEEN OLD TAMPINES ROAD AND LOYANG AVENUE**

We are instructed by the above named to claim damages (only material damage on our client's vehicle and without prejudice to our client's injuries, if any.) against you/your driver in connection with the above road traffic accident.

We are instructed that the accident was caused by you/your driver's negligent driving and/or management of you/your driver's vehicle no. **XE 3061T**. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of repair	\$15,100.00
2. Rental	\$ 1,950.00
3. Loss of use (02 days @ \$100.00 per day)	\$ 200.00
4. Survey fee	\$ 815.00
5. Cost at this stage	\$ 1,000.00
6. GIA/ LTA/ROC/ police search fee &/reports	\$ 36.49
7. Postages, transport and other incidentals	\$ 50.00
	<b><u>\$19,151.49</u></b>

... 2/-

Date: 22 OCT 2018

A copy each of the following supporting document has been sent to your insurer:

- 1) Our client's GIA report; police report;
- 2) Our client's certificate of insurance;
- 3) LTA search on vehicle number XE 3061T;
- 4) Repair bill;
- 5) Rental invoice;
- 6) Survey report + invoice;
- 7) One hundred (100) copies of scanned coloured photographs showing damage to our client's vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer.

Please note that you should send us an acknowledgement of receipt of this letter **within 14 days** of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks** of your receipt of this letter.

Yours faithfully,



cc. Client (SLG 7223Z)

c.c. With enclosures to your INSURER:

PDX 8009 (BY HAND)



M/S MSIG INSURANCE (S) PTE LTD  
4 SHENTON WAY  
#23-01 SGX CENTRE 2  
SINGAPORE 068807  
**ATTN: MOTOR CLAIMS DEPARTMENT**

Enquire Vehicle & Owner Information ( Vehicle No. XE3061T As At 10 Sep 2018 / 11:50:00 )

## Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: DP.10656.18.GA

## Current Owner Details

Owner ID Type: Company

Owner ID: 199105225W

Owner Name: SAMWOH RESOURCES PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 25E

Registered Street Name: SUNGEI KADUT STREET 1

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 729333

## Current Vehicle Details

Vehicle No.: XE3061T

Make Description/Model: VOLVO / FMX370 64R RSS SC (B)

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Print

OK





Thank you

Siti Awiyah Bte Senian has successfully logged out.

Your last login date and time was 11 Sep 2018, 09:48:38.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

#### Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)	Log Date/Time
1	Vehicle	XE3061T	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	11 Sep 2018 / 09:50:06

# GUAN AUTO SERVICE

Blk 7, Sin Ming Industrial Estate Sector C, # #01-82 Singapore 575642

TO : Tham Kin Yuen  
Blk 972 Hougang Street 91  
#13-194 Singapore 530972

Date : 09 October 2018

Tax Invoice : GAS/SLG7223Z/TP188011

Vehicle No : SLG 7223 Z  
Make/Model : Honda Civic 1.6 VTI CVT  
Date Of Accident : 10.09.2018

PARTICULAR	Amount S\$
Rear Portion damaged Parts replacement, Repair, Straighten, Alignment Reset, Labour And spraypainting etc.	
Lump-sum repair cost as per surveyor report recommendation -----	\$15,100.00

Singapore Dollars : Fifteen Thousand One Hundred Only

Total \$15,100.00 Nett



GUAN AUTO SERVICE



WIN WIN RENT-A-CAR PTE LTD

## Invoice

THAM KIN YUEN  
S1111387G  
BLK 972 HOUGANG ST 91  
#18-184  
S(530972)

Invoice No : WPLIN0002330  
Invoice Date : 30/9/2018  
Due Date : 30/9/2018  
VHA No : 2708  
Referral ID : G023


Description :	Amount
Rental for 15 Day/s @ \$130 per Day	\$1,950

Vehicle No : SLJ4713E

Vehicle Description : Honda Vezel 1.5 A

Rental Period : 10/09/2018 to 25/09/2018

Total Amount Payable : \$1,950



**WIN WIN RENT-A-CAR PTE LTD**

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807

VHA No: 2708

Invoice No :

Hirer's Vehicle No :

UEN: 201505115E

**VEHICLE RENTAL AGREEMENT**

<b>HIRER'S PARTICULARS</b> Name: (as in I/C) <u>THAM KIN YUEN</u> NRIC / FIN No: <u>S1111387G</u> Address (Res): <u>BLK 972 HOULIM ST 91</u> <u>#18-184 S(530972)</u> Name & Address of Employer: _____ Occupation: _____ Driving Exp: _____ Singapore Driving Licence No: _____ Issue Date: _____ Date of Birth: <u>20/6/55</u> Tel: (O) _____ (R) _____ HP: _____		Vehicle No: <u>SLI4713E</u> Replace Veh No: _____ Mileage Out: <u>70701</u> Mileage Out: _____ Make & Model: <u>HONDA VEZEL</u> Auto / Manual Out : Date <u>10/09/2018</u> Time: <u>18.11</u> HIRE / PERIOD EXPIRY Time: _____ NON-WAIVER EXCESS=\$ <u>2000</u>																																																													
<b>ADDITIONAL DRIVER'S PARTICULARS</b> Name: (as in I/C) _____ NRIC / FIN No: _____ Address (Res): _____ Occupation: _____ Driving Exp: _____ Singapore Driving Licence No: _____ Issue Date: _____ Date of Birth: _____ Tel: (O) _____ (R): _____ H/P: _____		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="4">CHARGES</th> </tr> <tr> <td>Daily</td> <td>15</td> <td>@ \$ 130</td> <td>per day</td> </tr> <tr> <td>Weekly</td> <td></td> <td>@ \$</td> <td>per week</td> </tr> <tr> <td>Monthly</td> <td></td> <td>@ \$</td> <td>per month</td> </tr> <tr> <td>Hours</td> <td></td> <td>@ \$</td> <td>per hour</td> </tr> <tr> <td>Extension</td> <td></td> <td>@ \$</td> <td></td> </tr> <tr> <td colspan="4">Delivery/Collection Service</td> </tr> <tr> <td colspan="4" style="text-align: right;"><b>SUB-TOTAL \$</b></td> </tr> </table>		CHARGES				Daily	15	@ \$ 130	per day	Weekly		@ \$	per week	Monthly		@ \$	per month	Hours		@ \$	per hour	Extension		@ \$		Delivery/Collection Service				<b>SUB-TOTAL \$</b>																															
CHARGES																																																															
Daily	15	@ \$ 130	per day																																																												
Weekly		@ \$	per week																																																												
Monthly		@ \$	per month																																																												
Hours		@ \$	per hour																																																												
Extension		@ \$																																																													
Delivery/Collection Service																																																															
<b>SUB-TOTAL \$</b>																																																															
<b>VEHICLE CHECK LIST</b> <div style="display: flex; align-items: center;"> <div style="writing-mode: vertical-rl; transform: rotate(180deg); font-size: small; margin-right: 5px;">           INDICATE:            D - DENTS            S - SCRATCHES            A - ACCIDENTS         </div> <div style="display: flex; justify-content: space-around; align-items: center;"> </div> <div style="margin-top: 5px;">             RIGHT FRONT TOP LEFT           </div> </div>		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="10">PETROL LEVEL</th> </tr> <tr> <td>Out</td><td>E</td><td>1/8</td><td>1/4</td><td>3/8</td><td>1/2</td><td>5/8</td><td>3/4</td><td>7/8</td><td>F</td> </tr> <tr> <td>In</td><td>E</td><td>1/8</td><td>1/4</td><td>3/8</td><td>1/2</td><td>5/8</td><td>3/4</td><td>7/8</td><td>F</td> </tr> <tr> <td colspan="10">Fuel</td> </tr> <tr> <td colspan="10">Traffic / Parking Fines</td> </tr> <tr> <td colspan="10" style="text-align: right;"><b>TOTAL CHARGES \$</b></td> </tr> </table> <div style="margin-top: 20px;"> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;">             Hirer's Signature  </div> <div style="width: 45%;">             Additional Driver's Signature _____           </div> </div> </div>		PETROL LEVEL										Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F	In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F	Fuel										Traffic / Parking Fines										<b>TOTAL CHARGES \$</b>									
PETROL LEVEL																																																															
Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F																																																						
In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F																																																						
Fuel																																																															
Traffic / Parking Fines																																																															
<b>TOTAL CHARGES \$</b>																																																															
<b>MISSING / FAULTY ACCESSORIES / PARTS</b> REMARKS: _____																																																															

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

**\*IMPORTANT**

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
2. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY. INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN \* SIGNATURE OF HIRER / DRIVER \* FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	
<u>25/9</u>	<u>1905</u>				 <b>SIGNATURE OF HIRER/DRIVER</b>

**KTO Automobile Assessors**

Reg. No: 52941122M

470 Segar Road #09-232 Singapore 670470 Tel: 98505311 Fax: 63107269

\*\*\*\*\*  
\*\*\*INVOICE\*\*\*  
\*\*\*\*\*

M/S: Tham Kin Yuen  
C/O Guan Auto Service.  
Blk 7 Sin Ming Industrial Estate Sector C,  
#01-82 Singapore 575642.

Invoice No : 18-08011

Invoice Ref : TP/GAS/SLG7223Z/8011

Date : 08 October 2018

DESCRIPTION	AMOUNT
For Services Rendered Inspection Report Fees Inclusive Of : Transportation And Photographs One Hundred (100) Copies Vehicle No : SLG 7223 Z Make/Model : Honda Civic 1.6 VTI CVT	\$ 815.00
Singapore Dollars: Eight Hundred And Fifteen Only	\$ 815.00

Cheques should be made payable to KTO AUTOMOBILE ASSESSORS. Please indicate our Invoice No. on the reverse of your cheque.

**KTO AUTOMOBILE ASSESSORS**

Ong Ah Keng (CAE, AMIMI, MSAAA)  
Automotive Appraiser

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Tham Kin Yuen  
C/O Guan Auto Service.  
Blk 7 Sin Ming Industrial Estate Sector C,  
#01-82 Singapore 575642.

Date : 08 October 2018  
Our Ref : TP/GAS/SLG7233Z/8011

**REFERENCE PARTICULARS**

Date of Accident : 10 September 2018  
Date of Inspection : 11 September 2018

Type of Inspection : Third Party Claim  
Date of Re-Inspn : ~

**VEHICLE PARTICULARS**

Registration No : SLG 7223 Z  
Make : Honda  
Model : Civic 1.6 VTI CVT  
Year : 2016

Engine No : R16B21600519  
Chassis No : MRHFC5650GT000411  
Odometer : 034897 km  
Colour : Silver

**CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)**

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

**TYRE CONDITION (Remaining estimated life of tyre in mm)**

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Near side	: Hankook	215/55R16	6 mm
Front Off Side	: Hankook	215/55R16	6 mm
Rear Near Side	: Hankook	215/55R16	6 mm
Rear off Side	: Hankook	215/55R16	6 mm

**GENERAL DESCRIPTION OF DAMAGES**

The vehicle sustained damage at the rear portion.  
For details, refer to assessment for repairs and photographs attached.

**ASSESSMENT SUMMARY**

Our assessment of the repair costs to pre-accident condition was **\$15,100.00 nett** at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Sixteen (16) working days.

Enclosed One Hundred (100) photographs depicting damage to the vehicle.

Inspection conducted at : Guan Auto Service.  
Blk 7 #01-82 Sin Ming Industrial Estate Sector C, Singapore 575642.

In accordance to your instruction, we have **not** authorise repairs and inspection  
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

## ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

### DESCRIPTION OF PARTS AND NATURE OF REPAIRS

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1	Rear bumper	1	Distorted	\$ 795.80	\$ <del>657.20</del> 795.80 BR✓
2	Rear bumper side spacer L/R @ \$85.20 <del>54.00</del>	2	Damaged	\$ 170.40	\$ <del>108.00</del> 170.40 BR✓
3	Rear bumper side bracket L/R @ \$45.70	2	Damaged	\$ 91.40	\$ <del>57.40</del> 91.40 BR✓
4	Rear bumper center support @ \$47.50	2	Bent	\$ 95.00	\$ 95.00 BT✓
5	Rear bumper reinforcement	1	Dented	\$ 525.00	\$ <del>334.10</del> 525.00 BT✓
6	Rear bumper lower garnish	1	Torn	\$ 385.70	\$ 385.70 CRA✓
7	Rear boot lid	1	Dented	\$ 997.00	\$ <del>755.90</del> 997.00 DD✓
8	Rear boot lid license lamp moulding	1	Sheared off	\$ 351.70	\$ <del>184.20</del> 351.70 BR✓
9	Rear boot lid inner trim	1	Torn	\$ 284.90	\$ 284.90 TN✓
10	Rear boot lid lock	1	Jammed	\$ 194.15	\$ 194.15 BT✓
11	Rear boot lid striker	1	Bent	\$ 38.10	\$ 38.10 B✓
12	Rear boot lid hinge L/R @ \$180.20 <del>101.00</del>	2	Bent	\$ 360.40	\$ <del>202.00</del> 360.40 BT✓
13	Rear boot lid weather-strip	1	Torn	\$ 80.70	\$ 80.70 CUT✓
14	Rear boot lid opener switch	1	Damaged	\$ 93.60	\$ 93.60 CUT✓
15	Rear tail lamp panel L/R @ \$98.70	2	Dented	\$ 197.40	\$ 197.40 DD✓
16	Rear end panel stiff L/R @ \$84.30	2	Bent	\$ 168.60	\$ 168.60 BT✓
17	Rear end panel top garnish	1	Deformed	\$ 245.70	\$ <del>185.40</del> 245.70 DL✓
18	Rear end panel	1	Dented	\$ 752.80	\$ <del>323.90</del> 752.80 DD✓
19	Rear fender L/R @ \$851.60	2	Dented/Buckled <del>LH, RH</del>	\$ 1,703.20	\$ <del>1,531.20</del> 1,703.20 DD X
20	Rear fender inner trim L/R @ \$316.80	2 <del>LH</del>	Torn/Crumpled <del>RH</del>	\$ 633.60	\$ <del>316.80</del> 633.60 TN X
21	Rear fender air outlet L/R @ \$64.70	2	Torn	\$ 129.40	\$ 129.40 NN X
22	Rear fender under shield L/R @ \$182.40	2	Torn	\$ 364.80	\$ 364.80 NN X
23	Rear spare tyre panel	1	Crumpled	\$ 829.40	\$ 829.40 NN X
24	Rear exhaust silencer pipe	1	Serviceable	\$ 816.60	\$ ~
				\$ 10,305.35	\$ 9,488.75
Less 20%				\$ 2,061.07	\$ 1,897.75
				\$ 8,244.28	\$ 7,591.00
B)	<u>S/NETT ITEM</u>				
25	Rear bumper clips	1 set	Necessary	\$ 58.00	\$ <del>35.00</del> 58.00 NEC✓
26	Rear tail lamp L/R @ \$594.60 <del>486.00</del>	2	Cracked	\$ 1,189.20	\$ <del>972.00</del> 1,189.20 BR✓
27	Rear boot lid lamp L/R @ \$395.00 <del>214.20</del>	2	Cracked	\$ 790.00	\$ <del>428.00</del> 790.00 BR✓
28	Rear bumper reflector LR @ \$54.60	2	Cracked	\$ 109.20	\$ 109.20 BR✓
29	Rear bumper reflector garnish L/R @ \$96.40 <del>78.00</del>	2	Torn	\$ 192.80	\$ <del>156.00</del> 192.80 CR✓
30	Rear bumper lower garnish tow cap	1	Torn	\$ 27.40	\$ 27.40 NN X
31	Rear bumper side lower cover L/R @ \$184.30	2	Torn	\$ 368.60	\$ 368.60 MIS✓
32	Rear bumper reverse sensor @ \$175.90	4	Malfunction	\$ 703.60	\$ 703.60 CUT✓
33	Rear boot lid hinge cover L/R @ \$95.00	2	Torn/Twisted	\$ 190.00	\$ 190.00 BR✓
34	Rear foam tool box	1	Cracked	\$ 213.50	\$ 213.50 } NN X
35	Rear spare tyre panel cover	1	Torn	\$ 291.70	\$ 291.70 } NN X
36	Rear spare tyre panel coating pad	1	Necessary	\$ 280.00	\$ 280.00 NN X
37	Rear windscreen glass inner seal	1	Necessary	\$ 172.80	\$ <del>60.00</del> 172.80 }
38	Rear windscreen glass damper	1	Necessary	\$ 34.50	\$ 34.50 }
39	Rear boot lid 'Honda' logo	1	Necessary	\$ 53.95	\$ 53.95 } NEC
40	Rear bumper 'Civic' emblem	1	Necessary	\$ 39.90	\$ 39.90 }
41	Rear bumper 'i-VTEC' emblem	1	Necessary	\$ 22.80	\$ 22.80 }
42	Rear exhaust mounting hook @ \$34.00	2	Useable	\$ 68.00	\$ ~
43	Rear number plate with casing	1 set	Cut/Bent	\$ 80.00	\$ <del>60.00</del> 80.00 CUT✓
44	Rear boot lid license lamp	1	Cracked <del>20%</del>	\$ 74.90	\$ <del>57.20</del> 74.90 BR✓
45	Rear boot lid view camera	1 set	Malfunction	\$ 503.70	\$ <del>380.00</del> 503.70 CUT✓
Parts Total :				\$ 13,708.83	\$ 12,987.55

VEHICLE NO: SLG 7223 Z  
MODEL : HONDA CIVIC 1.6 VTI CVT

Our Ref : TP/GAS/SLG7233Z/801

C) LABOUR CHARGES & MISC

46	Spray painting on above new & repaired parts including supply of paint materials.	\$	2,500.00	\$	<del>1,800.00</del> <sup>1,000.00 + 200</sup>
47	Remove damaged parts, knock out dent, straighten, jack out damaged panel, panel beating, cutting, welding, remove & reinstall necessary fittings to facilitate repairs, reshape, refit, adjust, replace and realign all relevant parts.	\$	3,500.00	\$	<del>2,500.00</del> <sup>1,400.00</sup>
48	To transfer rear boot lid mechanism & components.	\$	80.00	\$	40.00
49	To cavity preservation on all affected area & re-seal body panel joint.	\$	180.00	\$	<del>120.00</del> <sup>60.00 + 30</sup>
50	To mount vehicle onto chassis alignment bench, repair, straighten rear chassis frame and conduct alignment.	\$	600.00	\$	<del>450.00</del> <sup>NNX</sup>
51	Check wiring, reconnection socket, lighting system, centre locking system for proper function & perform water leak test.	\$	80.00	\$	50.00
52	To remove & reinstall trims garnish, cushion seat, interior upholstery etc, to enable necessary repairs, check, refit as same.	\$	250.00	\$	<del>160.00</del> <sup>80.00</sup>
53	To carry out diagnostic checks and reset.	\$	350.00	\$	<del>280.00</del> <sup>160</sup>
54	To remove & reinstall rear windscreen glass to assist repair.	\$	120.00	\$	120.00
55	To supply rear windscreen glass sealant.	\$	50.00	\$	40.00
56	To reinstall rear bumper reverse sensor & view camera.	\$	180.00	\$	<del>120.00</del> <sup>80.00</sup>
57	To straighten & re-align rear exhaust pipe to position.	\$	150.00	\$	<del>120.00</del> <sup>80.00</sup>
58	To provide towing service charge.	\$	100.00	\$	<del>100.00</del> <sup>60</sup>
Labour Total :		\$	8,140.00	\$	5,900.00
Total Parts and Labour		\$	21,848.83	\$	18,887.55

FINAL LUMP SUM ADJUSTMENT

\$ 15,100.00

**POINT OF IMPACT**

The impact was confined to the rear portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

Repair days 11

TGUM  
12/11/18



VEHICLE NO: SLG 7223 Z  
MODEL : HONDA CIVIC 1.6 VTI CVT

Our Ref : TP/GAS/SLG7233Z/8011

#### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$15,100.00 nett**, corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)  
Automotive Appraiser



































### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		12 Sep 2018 16:13 <a href="#">Edit Adj Rpt</a>	<b>S\$8,650.00</b> <a href="#">Edit Estimates</a>	<b>S\$8,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>SAMWOH RESOURCES PTE LTD</b> , Co. Reg. No.: 199105225W									
Main Claimant: <b>THAM KIN YUEN</b> , ID: S1111387G									
Vehicle Reg. No.: <b>SLG7223Z</b>		Date of Loss: 10/09/2018 11:00 - :59 [22 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 569935</b>		Policy/Cover Note No.: B28970951MKC (Comprehensive) Coverage: 07/06/2018 - 06/06/2019							
Vehicle Reg. No. (Insured): <b>XE3061T</b>		Policy No. (Claimant):							
		Excess: S\$2,000.00							
Repairer: <b>Guan Auto Service (Sin Ming)</b> Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 01/11/2018]									
Driver/Custodian (Insured): YIN JIANGUO (39 / Male), NRIC: G5241696K, Tel: +6587832017									
Adj Asg. Remarks: SJE - DISAGREED LIABILITY : 100% Please appoint LKK AUTO CONSULTANTS ONLY for this case ( SAMWOH RESOURCES PTE LTD) Kindly contact MR JACKY @ 9388 4210 to arrange for survey .									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (30/10/2018): Report Send Back Alerts - SLG7223Z (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG7223Z (569935)  
[XE3061T]  
TP  
THAM KIN YUEN  
Sep 10 2018 11:00AM  
[SAMWOH RESOURCES PTE LTD]  
Guan Auto Service

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	12/09/18 10:02	Accident Statement From: SC - Reg. No: XE3061T, Claimant: SAMWOH RESOURCES PTE LTD					 Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
2	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
3	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
4	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
5	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
6	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
7	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
8	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
9	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
10	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
11	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
12	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
13	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
14	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
15	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
16	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
17	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
18	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
19	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
20	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
21	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
22	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
23	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
24	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
25	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
26	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
27	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
28	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
29	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
30	16/09/18 21:19	General View					 Load JPG	<input checked="" type="checkbox"/>	
31	16/09/18 21:19	Chassis Number					 Load JPG	<input checked="" type="checkbox"/>	
32	16/09/18 21:19	Odometer Reading					 Load JPG	<input checked="" type="checkbox"/>	
33	17/09/18 11:31	Photographs of Damaged Parts					 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
85	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
86	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
87	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/09/18 10:02	TPD SLG7223Z GIA REPORT From: SC - Reg. No: XE3061T, Claimant: SAMWOH RESOURCES PTE LTD		Load PDF	
2	12/09/18 10:13	Reject email to TP Lawyer & appoint LKK AUTO		Load PDF	
3	12/09/18 10:13	TPD SLG7223Z - PRI		Load PDF	
4	29/10/18 17:48	LOD with supporting documents		Load PDF	
5	29/10/18 17:48	TPD SLG7223Z - COLOUR PHOTO A		Load PDF	
6	29/10/18 17:48	TPD SLG7223Z - COLOUR PHOTO B		Load PDF	
7	30/10/18 11:15	TPD SLG7223Z - REQ FOR PAPER RESURVEY		Load PDF	
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/11/18 08:42	Colour Photo		Load PDF	
2	16/11/18 08:42	PRS Invoice		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016668/GSBE2-1

Date: 16/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28970951MKC

Claimant Vehicle No : SLG7223Z

Insured Vehicle No : XE3061T

Date of Loss: 10/09/2018

Nature of Claim: TP

Claim No: 569935

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLG7223Z

Make &amp; Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B21600519

Reg. Date: 11/10/2016 (Man. Year: 2016)

Chassis No: MRHFC5650GT000411

Colour: Silver

Odometer: 34897 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,708.83	7,436.32	6,272.51	45.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,140.00	3,400.00	4,740.00	58.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,848.83</b>	<b>10,836.32</b>	<b>11,012.51</b>	<b>50.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>21,848.83</b>	<b>8,650.00</b>	<b>13,198.83</b>	<b>60.41</b>

## INSPECTION

Date of Assignment: 12/09/2018

Date Inspected: 13/09/2018 Inspected At:

Guan Auto Service (Sin Ming)  
Block 7 Sin Ming Industrial Estate Sector  
C, #01-80/ # 01-82  
Singapore 575642

Estimated Period of Repair: 11.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
<b>Parts:</b>	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG7223Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	795.80 FL	*657.20 FL
2	2		*REAR BUMPER SIDE SPACER L/R	Broken	170.40 FL	*108.00 FL
3	2		*REAR BUMPER SIDE BRACKET L/R	Broken	91.40 FL	*57.40 FL
4	2		*REAR BUMPER CENTER SUPPORT	Bent	95.00 FL	*95.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	525.00 FL	*334.10 FL
6	1		*REAR BUMPER LOWER GARNISH	Cracked	385.70 FL	*385.70 FL
7	1		*REAR BOOT LID	Dented	997.00 FL	*755.90 FL
8	1		*REAR BOOT LID LICENSE LAMP MOULDING	Broken	351.70 FL	*184.20 FL
9	1		*REAR BOOT LID INNER TRIM	Torn	284.90 FL	*284.90 FL
10	1		*REAR BOOT LID LOCK	Bent	194.15 FL	*194.15 FL
11	1		*REAR BOOT LID STRIKER	Bent	38.10 FL	*38.10 FL
12	2		*REAR BOOT LID HINGE L/R	Bent	360.40 FL	*202.00 FL
13	1		*REAR BOOT LID WEATHER-STRIP	Cut	80.70 FL	*80.70 FL
14	1		*REAR BOOT LID OPENER SWITCH	Cut	93.60 FL	*93.60 FL
15	2		*REAR TAIL LAMP PANEL L/R	Dented	197.40 FL	*197.40 FL
16	2		*REAR END PANEL STIFF L/R	Bent	168.60 FL	*168.60 FL
17	1		*REAR END PANEL TOP GARNISH	Dislodged	245.70 FL	*185.40 FL
18	1		*REAR END PANEL	Dented	752.80 FL	*323.90 FL
19	1		*REAR FENDER L/R	N/S Dented/Buckled/O/S Repair	1,703.20 FL	*851.60 FL
20	1		*REAR FENDER INNER TRIM L/R	N/STorn/CrumpledO/SServiceable	633.60 FL	*316.80 FL
21	2		*REAR FENDER AIR OUTLET L/R	Not Necessary	129.40 FL	*- FL
22	2		*REAR FENDER UNDER SHIELD L/R	Not Necessary	364.80 FL	*- FL
23	1		*REAR SPARE TIRE PANEL	Not Necessary	829.40 FL	*- FL
24	1		*REAR EXHAUST SILENCER PIPE	Serviceable	816.60 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	58.00 F	*35.00 FN
26	2		*REAR TAIL LAMP L/R	Broken	1,189.20 F	*972.00 FN
27	2		*REAR BOOT LID LAMP L/R	Broken	790.00 F	*428.00 FN
28	2		*REAR BUMPER REFLECTOR L/R	Broken	109.20 F	*109.20 FN
29	2		*REAR BUMPER REFLECTOR GARNISH L/R	Cracked	192.80 F	*156.00 FN
30	1		*REAR BUMPER LOWER GARNISH TOW CAP	Not Necessary	27.40 F	*- FN
31	2		*REAR BUMPER SIDE LOWER COVER L/R	Missing	368.60 F	*368.60 FN
32	4		*REAR BUMPER REVERSE SENSOR	Cut	703.60 F	*703.60 FN
33	2		*REAR BOOT LID HINGE COVER L/R	Broken	190.00 F	*190.00 FN
34	1		*REAR FOAM TOOL BOX	Not Necessary	213.50 F	*- FN
35	1		*REAR SPARE TYRE PANEL COVER	Not Necessary	291.70 F	*- FN

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SPARE TYRE PANEL COATING PAD	Not Necessary	280.00 F	*- FN
37	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	172.80 F	*60.00 FN
38	1		*REAR WINDSCREEN GLASS DAMPER	Necessary	34.50 F	*34.50 FN
39	1		*REAR BOOT LID HONDA LOGO	Necessary	53.95 F	*53.95 FN
40	1		*REAR BUMPER CIVIX EMBLEM	Necessary	39.90 F	*39.90 FN
41	1		*REAR BUMPER I-VTEC EMBLEM	Necessary	22.80 F	*22.80 FN
42	2		*REAR EXHAUST MOUNTING HOOK	Usable	68.00 F	*- FN
43	1		*SET REAR NUMBER PLATE WITH CASING	Cut	80.00 FS	*60.00 FS
44	1		*REAR BOOT LID LICENSE LAMP	Broken	74.90 F	*57.20 FN
45	1		*SET REAR BOOTLID VIEW CAMERA	Cut	503.70 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,769.90</b>	<b>9,185.40</b>
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,061.07	1,102.93
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	646.15

<b>Total Parts (\$\$)</b>	<b>13,708.83</b>	<b>7,436.32</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS	New	2,500.00	1,200.00
2	REMOVE DAMAGED PARTS, KNOCK OUT DENT, STRAIGHTEN, JACK OUT DAMAGED PANEL, PANEL BEATING, CUTTING, WELDING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, RESHAPE, REFIT, ADJUST, REPLACE AND REALIGN ALL RELEVANT PARTS	New	3,500.00	1,400.00
3	TO TRANSFER REAR BOOT LID MECHANISM & COMPONENTS	New	80.00	40.00
4	TO CAVITY PRESERVATION ON ALL AFFECTED AREA & RE-SEAL BODY PANEL JOINT	New	180.00	90.00
5	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH, REPAIR, STRAIGHTEN REAR CHASSIS FRAME AND CONDUCT ALIGNMENT	New	600.00	0.00
6	CHECK WIRING, RECONNECTION SOCKET, LIGHTING SYSTEM, CENTRE LOCKING SYSTEM FOR PROPER FUNCTION & PERFORM WATER LEAK TEST	New	80.00	50.00
7	TO REMOVE & REINSTALL TRIMS GARNISH, CUSHION SEAT, INTERIOR UPHOLSTERY ETC, TO ENABLE NECESSARY REPAIRS, CHECK, REFIT AS SAME	New	250.00	80.00
8	TO CARRY OUT DIAGNOSTIC CHECKS AND RESET	New	350.00	160.00
9	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	120.00	120.00
10	TO SUPPLY REAR WINDSCREEN GLASS SEALANT	New	50.00	40.00
11	TO REINSTALL REAR BUMPER REVERSE SENSOR & VIEW CAMERA	New	180.00	80.00
12	TO STRAIGHTEN & RE-ALIGN REAR EXHAUST PIPE TO POSITION	New	150.00	80.00
13	TO PROVIDE TOWING SERVICE CHARGE	New	100.00	60.00
Gross Labour Cost (S\$)			<b>8,140.00</b>	<b>3,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >