

## Vic (LKKAuto)

---

**From:** Foo, Chityan <Chityan.Foo@aig.com>  
**Sent:** Friday, 15 February, 2019 11:44 AM  
**To:** Vic (LKKAuto)  
**Cc:** Admin A  
**Subject:** OUR REF: 9619455707SG; YOUR REF: CC6/AIG18019706/Uha3; ACCIDENT INVOLVING SGD3139K & GBF5886J ON 30.10.18 ALONG UPPER SERANGOON VIADUCT

Hi Vic,

We refer to the above matter

We seek your clarification on the replacement of the following parts:

- Front bumper side retainer <sup>5-6</sup> 57/146 *Sub bumper Dislodge side retainer Bolt*
- Support Panel 115/116 *Support panel dash inward Bolt & Tor. Head*
- Radiator side air guide 106-107 *Pushed push inward to condense*
- Taillamp 141-143 *cracked*

Kindly let us hear from you before approval of mandate in merimen.

Jimmy Foo

AIG

Complex Claims Examiner

AIG Building, 78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1945 | Fax +(65) 6835 7416

[Chityan.foo@aig.com](mailto:Chityan.foo@aig.com) | [www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.