

REC. BY:

REF: CS/CTU8019719/Kvb27 Special Instruction:

SUBVAD

Merimen

ASSIGNMENT (Office)

From (Person): Catherine Thia of CTL Date/Time: 30-10-2018 11:36am

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: S6U 7989H Insured:

at Workshop m/s: Lai Huat (Mong Kae) Tel:

of 160 Sin Ming Drive #04-01

Policy No: DMP/CSN3030541853 Claim No: S/NM18205044601

Sum Insured: Excess: \$ 500.00

Make of Veh: D.O.A. 23-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 31-10-2018 @ 10:30am H.O.D. Endorsement:

Date/Time: 30-10-2018 11:59am Person Contacted: Jenny Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

S6U 7989H - CS/CTU8019719/Kpb3 Date: 23-10-18

1/11/18 Report via merimen

2/11/18 Rate approved \$ 2818.73 from Alfred by merimen

2/11/18 Informed Jenny CIA on part by part ex \$500 by email

3/12/18 @330pm Jenny said vehicle still under repair

Merimen

ASSIGNMENT

Folio: Date: 31-10-2018

Estimated Cost:

ID/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SHU 7989H
at Workshop rms: Lai Huet (Meng Kue)
of: 160 Sin Ming Drive #04-01

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$ 500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value: \$ 766

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res: Yes or No

Lump Sum: 1-B, % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Van No: SGA 7989H Vi Regn: 05 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Estmo CC 2362

Colour: M Gold A/C Insured / Std / Nil / NA

Sp Reading: 153604 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: ACR 50 0033515

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A: 23/10/18 D.O.I: 31/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/11 File pass to Catherine
28/1/19 @ 2:58pm Jenny will check1/4/19 final fig \$ 2786.13 (Red to 40, 2/1)
Confirmed by email

RECEIVED 6 APR 2019

29/3/2019.

Date/Time: File Pass to?

☐ : Prel. Report

1/

☐ : Final Report

Date/Time: File Return to?

2/ 1/4 - typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

1. S-Rail, 2.

Phone:

Other:

TOTAL

Report Format: merimen

Lump Sum / I.B. / 13 2786.13

Add Fee: ☐ Site Insp. 1\$☐ Interview 1\$☐ Tech. Insp. 1\$☐ Weekend 1\$

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Oct 2018 Sendback Est	29 Oct 2018 14:32 S\$2,856.53	30 Oct 2018 11:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TAN CHYE HUAT, ID: S1615667A, Tel: +6597931616, Email: NOEMAIL								
Vehicle Reg. No.:	SGU7989H	Date of Loss:	23/10/2018 10:00 - :59 [136 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D05044C01	Policy/Cover Note No.:	DMPCSN3030541803 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/11/2018]								
Driver/Custodian:	TAN CHYE HUAT (55 / Male), NRIC: S1615667A, Tel: +6597931616								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 2 November 2018 2:43 PM
To: Jenny Lim
Cc: SUR
Subject: SGU 7989H-DOA: 23/10/2018 (CHINA TAIPIING)

Dear Jenny,

As instructed by our client , please proceed to repair the **insured vehicle SGU 7989H on part by part basis (Excess S500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SGU7989H (SNM18D05044C01)

OD

Oct 23 2018 10:00AM

[TAN CHYE HUAT]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 02/11/2018 14:00 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2818.73) - SGU7989H - Claim Handler: Catherine Thia

Approved:2818.73:Please proceed to authorize repairs UP TO \$2,818.73 BEFORE Excess of \$500.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Catherine Thia	Date: 01 Nov 2018

Preliminary Advice

Vehicle No	: SGU7989H	Accident Date	: 23/10/2018
Make	: TOYOTA ESTIMA	Policy No.	: DMPCSN3030541803
Assignment Date	: 30/10/2018	Excess	: S\$500.00
Date of Inspection	: 31/10/2018	Est. Duration of Repair	: 6.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,856.53
Revised Amount	:S\$	2,698.73
Check Items (Estimated)	:S\$	120.00
Total	:S\$	2,818.73

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	44,956.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,044.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part basis.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5667A
Vehicle Details	
Vehicle No.:	SGU7989H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA 2.4 A
Primary Colour:	Gold
Manufacturing Year:	2007
Engine No.:	2AZF021966
Chassis No.:	ACR500033515
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$26,649.00
Original Registration Date:	25 May 2007
First Registration Date:	25 May 2007
Transfer Count:	1
Actual ARF Paid:	\$29,314.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$52,491.00
COE Rebate Amount:	\$44,956.00
Total Rebate Amount:	\$44,956.00

The information contained herein is correct as at 30 Oct 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5667A

Vehicle Details

Vehicle No.: SGU7989H
Vehicle to be Exported: Yes
Intended Deregistration Date: 25 Oct 2018
Vehicle Make: TOYOTA
Vehicle Model: ESTIMA 2.4 A
Primary Colour: Gold
Manufacturing Year: 2007
Engine No.: 2AZF021966
Chassis No.: ACR500033515
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$26,649.00
Original Registration Date: 25 May 2007
First Registration Date: 25 May 2007
Transfer Count: 1
Actual ARF Paid: \$29,314.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 May 2027
COE Category: E - Open Category
COE Period(Years): 10
PQP Paid: \$52,491.00
COE Rebate Amount: \$45,028.00
Total Rebate Amount: \$45,028.00

The information contained herein is correct as at 25 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 12:33
Date Of Accident	23/10/2018 10:15
Exact Location Of Accident	ALONG TANGLIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU7989H
Insured/Policyholder	
Name Of Registered Owner	TAN CHYE HUAT
NRIC No	S1615667A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97931616
Alternative Phone No	OTHERS-97931616

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA 2.4 AERAS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3030541803
Cover Note Number	

Driver

Name of Driver	TAN CHYE HUAT
NRIC No	S1615667A
Date Of Birth	25/03/1963
Occupation	INDOOR
Date Of Driving Pass	06/05/1985
Driving Experience	33 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97931616
Fax Number	
Contact Number	OTHERS-97931616
Email Address	NOEMAIL

Address	BLK 52 LENGKOK BAHRU #04-293
Postcode	150052
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD434R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

23 OCT 2018
12:33:05


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Poh Kwee Choo
S6840583A

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident happened on 23/10/2018 about 10:15am.
 I Was travelling along Tanglin Road near to Phoenix Road.
 The Vehicle (SHD 434R) knocked onto my vehicle on my
 left side doors (Both Sides) and dented that the vehicle
 (SHD 434R) cut into my lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 23 OCT 2018

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.: S6840583A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1615667A



Name

TAN CHYE HUAT

陳財發

Race

CHINESE

Date of birth

25-03-1963

Sex

M

Country/Place of birth

SINGAPORE



S1615667A

REPUBLIC OF SINGAPORE DRIVING LICENCE



S1615667A

TAN CHYE HUAT

Issued Date: 25 Mar 1963

Valid Until: 03 Apr 2003



1000348310J

0001552



UPIC No. S1615667A



Date of issue

16-08-2018

Address

APT BLK 52 LENGKOK BAHRU
#04-293
SINGAPORE 150052

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	06 May 1985
Class 4 Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	10 Nov 1997

NP 428A



Licence No: S1615667A



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1950
Road Transport Act, 1967 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1950 (Malaysia)

I/We hereby Certify

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act, Chapter 189, and Part IV of the Road Transport Act, 1987 (Malaysia).

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Source: <http://www.3v.com>

Authorized Officer

Answer

Authorized Signature _____

Servicing Agent -
Wineston Lim LG / Livruen Enterprises
HP - 9488 9488 / Work - 6698 2521
Email - wineston@hotmail.com

**LAI HUAT (MENG KEE)
MOTOR PTE LTD
SIN MING INDUSTRIAL
ESTATE SECTOR A
BLK 21 #01-58
SINGAPORE 575679**

Claim Reference:
Assessment Number: LHM61235
Version: LAI HUAT/2
Date Calculated: 29/10/2018 06:06

Full Report - V1
Registration: SGU 7989H
Printed: 29/10/2018 14:06

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	23/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3030541803	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	


Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Estima
Sub Model:	BASE MODEL
Model Sheet Number:	YM2 01
Registration:	SGU 7989H
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 05/2007	RR AIR CONDITIONING
XENON HEADLAMPS	2.4 LTR 117/125 KW
TYRES 205/65 HR 16	WHEELS 6.5J X 16
TWO COAT METALLIC	PREPARE OFF VEHICLE

als body

Not with ashw
Refuse by paint
Ex 8500L
fax 62564315

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	28/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61235



Version: LAI HUAT/2

Date Calculated: 29/10/2018 06:06

Full Report - V1

Registration: SGU 7989H

Printed: 29/10/2018 14:06



Addresses

Cost Summary

Total Labour	\$844.20
Total Paint/Material	\$232.33
Total Parts	\$1,680.00
Total of Additional Costs	\$100.00
Excess:	TBA
Grand Total Exc GST:	\$2,856.53
7 % GST:	\$199.96
Grand Total Inc GST:	\$3,056.49

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B210 ZAX	RENEW LEFT FRONT DOOR INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	29.0	121.80
B216 ZAX	RENEW LEFT REAR DOOR INCLUDES: R + R AND ALIGN LEFT REAR DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	142.80
NO NUMBER	RENEW L/C-PILLAR STRIPE	3.0	12.60
0741	REPAIR L/F WING	10.0*	42.00
3485	REPAIR L/R LOWER SIDE PANEL	10.0*	42.00
LABOUR COST			
	Total Work Units	86.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	8.6HRS	\$361.20
	Paint Labour	11.5HRS	\$483.00
	Total Labour	20.1HRS	\$844.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC - PREPARE OFF VEHICLE		
1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1781	L/R DOOR NEW PART PAINTING	20.0	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61235

Version: LAI HUAT/2

Date Calculated: 29/10/2018 06:06

Full Report - V1

Registration: SGU 7989H

Printed: 29/10/2018 14:06

2213	L/R SILL MOULDING NEW PART PAINT K1R	3.0	
2219	L/F SILL MOULDING NEW PART PAINT K1R	3.0	
741	L/F WING REPAIR PAINTING <50%	11.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0	
3485	L/R LOWER SIDE PANEL REPAIR PAINTING <50%	12.0	
LABOUR COST - PAINT			
	TIME(PAINT)	82.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$483.00
MATERIAL COST - PAINT			
	New Part Painting		Cost Price
	New Part Painting - Plastic K1R		\$116.10
	Material-Constant Main Work Metal		\$1.96
	Repair Painting		\$28.60
	Repair Painting Plastic		\$30.04
	Material-Const Main Work Plastic		\$42.93
	Total Excluding Pearlescent Uplift		\$12.70
	Pearlescent Uplift @ 0.0%		\$232.33
	Total Paint Material Cost		\$0.00
			\$232.33

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1949	1	L/DOOR STRIPE	75952 28031		0% 20.00*
1655	1	L/F DOOR REAR STRIP	75958 28030		0% 30.00*
1645	1	L/F PROT MLDG STRIPE	75939 28020		0% 25.00*
2219	1	L/F SILL MOULDING	76914 28070		0% 150.00*
1647	1	L/F UPP DOOR STRIPE	75956 28030		0% 25.00*
1653	1	L/MOULDING	75969 28020		0% 15.00*
1781	1	L/R DOOR	67004 28430		0% 550.00*
1955	1	L/R DOOR FRAME MLDG	75766 28010		0% 25.00*
1947	1	L/R DOOR FRONT STRIP	75934 28030		0% 20.00*
1953	1	L/R DOOR REAR STRIP	75954 28021		0% 25.00*
1943	1	L/R DOOR STRIPE	75932 28030		0% 30.00*
2213	1	L/R SILL MOULDING	76916 28070		0% 185.00*
1945	1	L/R UPP DOOR STRIPE	75938 28021		0% 30.00*
1481	1	LEFT FRONT DOOR	67002 28210		0% 550.00*
f: OEM Parts			Sub Total		\$1,680.00
g: Original			Sundry Parts	(Fixed)	\$0.00
h: Secondhand			Total Parts		\$1,680.00

h: Secondhand

p: Parallel

x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
SUNDRY PARTS	0%	\$100.00
SPECIALIST		
Total Extras		\$100.00

Final Calculation

Total Parts	\$1,680.00
Labour	

LAI HUAT (MENG KEE) MOTOR PTE LTD**Claim Reference:****Assessment Number: LHM61235****Version: LAI HUAT/2****Date Calculated: 29/10/2018 06:06****Full Report - V1****Registration: SGU 7989H****Printed: 29/10/2018 14:06**

Total Panel/Mechanical	\$361.20	310.80	
Total Paintwork	\$483.00	483	
Total Labour			\$844.20
Additional Costs			
Corr Prot Materials External	\$0.00		
Corr Prot Materials Internal	\$0.00		
Cost of Specialist	\$100.00		
Total of Additional Costs			\$100.00
Total Paint/Material Costs			\$232.33 232.33
Grand Total Excludes GST			\$2,856.53
GST @ 7 %			\$199.96
Grand Total Includes GST			\$3,056.49

Assessment Notes

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Report

Claim Reference: SNM18D05044C01
Assessment Number: LHM61235
Version: LKKAUTOC/2
Date Calculated: 01/11/2018 04:13

Full Report - V1
Registration: SGU 7989H
Printed: 01/11/2018 12:15

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	23/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D05044C01	Estimated Repair Time:	
Policy Number:	DMPCSN3030541803	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Estima
Sub Model:	BASE MODEL
Model Sheet Number:	YM2 01
Registration:	SGU 7989H
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 05/2007	RR AIR CONDITIONING
XENON HEADLAMPS	2.4 LTR 117/125 KW
TYRES 205/65 HR 16	WHEELS 6.5J X 16
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	28/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$806.40
Total Paint/Material	\$232.33
Total Parts	\$1,680.00
Total of Additional Costs	\$100.00
Repair Cost Exc GST:	\$2,818.73
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$2,318.73
7 % GST:	\$162.31
Grand Total Inc GST:	\$2,481.04

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
B210 ZAX	RENEW LEFT FRONT DOOR INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	29.0	121.80
B216 ZAX	RENEW LEFT REAR DOOR INCLUDES: R + R AND ALIGN LEFT REAR DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	142.80
NO NUMBER	RENEW L/C-PILLAR STRIPE	3.0	12.60
0741	REPAIR L/F WING	5.0*	21.00
3485	REPAIR L/R LOWER SIDE PANEL	6.0*	25.20

LABOUR COST

Total Work Units	77.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.7HRS	\$323.40
Paint Labour	11.5HRS	\$483.00
Total Labour	19.2HRS	\$806.40

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		

1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1781	L/R DOOR NEW PART PAINTING	20.0	
2213	L/R SILL MOULDING NEW PART PAINT K1R	3.0	
2219	L/F SILL MOULDING NEW PART PAINT K1R	3.0	
741	L/F WING REPAIR PAINTING <50%	11.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0	
3485	L/R LOWER SIDE PANEL REPAIR PAINTING <50%	12.0	
LABOUR COST - PAINT			
	TIME(PAINT)	82.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$483.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$116.10
	New Part Painting - Plastic K1R		\$1.96
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$30.04
	Repair Painting Plastic		\$42.93
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$232.33
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$232.33

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1949	1	L/DOOR STRIPE	75952 28031		0% 20.00*
1655	1	L/F DOOR REAR STRIP	75958 28030		0% 30.00*
1645	1	L/F PROT MLDG STRIPE	75939 28020		0% 25.00*
2219	1	L/F SILL MOULDING	76914 28070		0% 150.00*
1647	1	L/F UPP DOOR STRIPE	75956 28030		0% 25.00*
1653	1	L/MOULding	75969 28020		0% 15.00*
1781	1	L/R DOOR	67004 28430		0% 550.00*
1955	1	L/R DOOR FRAME MLDG	75766 28010		0% 25.00*
1947	1	L/R DOOR FRONT STRIP	75934 28030		0% 20.00*
1953	1	L/R DOOR REAR STRIP	75954 28021		0% 25.00*
1943	1	L/R DOOR STRIPE	75932 28030		0% 30.00*
2213	1	L/R SILL MOULDING	76916 28070		0% 185.00*
1945	1	L/R UPP DOOR STRIPE	75938 28021		0% 30.00*
1481	1	LEFT FRONT DOOR	67002 28210		0% 550.00*
f: OEM Parts			Sub Total		\$1,680.00
g: Original			Sundry Parts	(Fixed)	\$0.00
h: Secondhand			Total Parts		\$1,680.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
SUNDRY PARTS	0%	\$100.00
SPECIALIST		
Total Extras		\$100.00

Final Calculation

Claim Reference: SNM18D05044C01

Full Report - V1

Assessment Number: LHM61235

Registration: SGU 7989H

Version: LKKAUTOC/2

Printed: 01/11/2018 12:15

Date Calculated: 01/11/2018 04:13

Total Parts		\$1,680.00
Labour		
Total Panel/Mechanical	\$323.40	
Total Paintwork	\$483.00	
Total Labour		\$806.40
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$100.00	
Total of Additional Costs		\$100.00
Total Paint/Material Costs		\$232.33
Repair Costs Excludes GST		\$2,818.73
Deductions		
Deduction for Excess (Fixed)	-\$500.00	
Total Deductions		-\$500.00
Grand Total Excludes GST (After Deduction)		\$2,318.73
GST @ 7 %		\$162.31
Grand Total Includes GST (After Deduction)		\$2,481.04

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

LKK Finalised

Claim Reference:
Assessment Number: LHM61235
Version: LKKAUTOC/5
Date Calculated: 28/03/2019 08:07

Full Report - V1
Registration: SGU 7989H
Printed: 28/03/2019 16:07

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	23/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3030541803	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Estima
Sub Model:	BASE MODEL
Model Sheet Number:	YM2 01
Registration:	SGU 7989H
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 05/2007	RR AIR CONDITIONING
XENON HEADLAMPS	2.4 LTR 117/125 KW
TYRES 205/65 HR 16	WHEELS 6.5J X 16
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	28/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$793.80
Total Paint/Material	\$232.33
Total Parts	\$1,660.00
Total of Additional Costs	\$100.00
Excess:	TBA
Grand Total Exc GST:	\$2,786.13
7 % GST:	\$195.03
Grand Total Inc GST:	\$2,981.16

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B210 ZAX	RENEW LEFT FRONT DOOR	29.0	121.80
	INCLUDES: R + R AND ALIGN LEFT FRONT DOOR,		
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
B216 ZAX	RENEW LEFT REAR DOOR	34.0	142.80
	INCLUDES: R + R AND ALIGN LEFT REAR DOOR,		
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
0741	REPAIR L/F WING	5.0*	21.00
3485	REPAIR L/R LOWER SIDE PANEL	6.0*	25.20

LABOUR COST

Total Work Units	74.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.4HRS	\$310.80
Paint Labour	11.5HRS	\$483.00
Total Labour	18.9HRS	\$793.80

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

		WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1781	L/R DOOR NEW PART PAINTING	20.0	
2213	L/R SILL MOULDING NEW PART PAINT K1R	3.0	

Claim Reference:

Full Report - V1

Assessment Number: LHM61235

Registration: SGU 7989H

Version: LKKAUTOC/5

Printed: 28/03/2019 16:07

Date Calculated: 28/03/2019 08:07

2219	L/F SILL MOULDING NEW PART PAINT K1R	3.0	
741	L/F WING REPAIR PAINTING <50%	11.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0	
3485	L/R LOWER SIDE PANEL REPAIR PAINTING <50%	12.0	
LABOUR COST - PAINT			
	TIME (PAINT)	82.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$483.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$116.10
	New Part Painting - Plastic K1R		\$1.96
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$30.04
	Repair Painting Plastic		\$42.93
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$232.33
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$232.33

PARTS

PARTS				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1949	1	L/DOOR STRIPE	75952 28031		0%	20.00*
1655	1	L/F DOOR REAR STRIP	75958 28030		0%	30.00*
1645	1	L/F PROT MLDG STRIPE	75939 28020		0%	25.00*
2219	1	L/F SILL MOULDING	76914 28070		0%	150.00*
1647	1	L/F UPP DOOR STRIPE	75956 28030		0%	25.00*
1653	1	L/MOULding	75969 28020		0%	15.00*
1781	1	L/R DOOR	67004 28430		0%	550.00*
1947	1	L/R DOOR FRONT STRIP	75934 28030		0%	30.00*
1953	1	L/R DOOR REAR STRIP	75954 28021		0%	25.00*
1943	1	L/R DOOR STRIPE	75932 28030		0%	30.00*
2213	1	L/R SILL MOULDING	76916 28070		0%	185.00*
1945	1	L/R UPP DOOR STRIPE	75938 28021		0%	25.00*
1481	1	LEFT FRONT DOOR	67002 28210		0%	550.00*
f: OEM Parts			Sub Total			\$1,660.00
g: Original			Sundry Parts		(Fixed)	\$0.00
h: Secondhand			Total Parts			\$1,660.00

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
SUNDRY PARTS	0%	\$100.00
SPECIALIST		
Total Extras		\$100.00

Final Calculation

Total Parts	\$1,660.00
Labour	
Total Panel/Mechanical	\$310.80
Total Paintwork	\$483.00

Claim Reference:

Full Report - V1

Assessment Number: LHM61235

Registration: SGU 7989H

Version: LKKAUTOC/5

Printed: 28/03/2019 16:07

Date Calculated: 28/03/2019 08:07

Total Labour		\$793.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$100.00	
Total of Additional Costs		\$100.00
Total Paint/Material Costs		\$232.33
Grand Total Excludes GST		\$2,786.13
GST @ 7 %		\$195.03
Grand Total Includes GST		\$2,981.16

Assessment Notes

**LAI HUAT (MENG KEE)
MOTOR PTE LTD
SIN MING INDUSTRIAL
ESTATE SECTOR A
BLK 21 #01-58
SINGAPORE 575679**

Workshop Finalised

Claim Reference:
Assessment Number: LHM61235
Version: LAI HUAT/3
Date Calculated: 28/03/2019 06:20

Full Report - V1
Registration: SGU 7989H
Printed: 28/03/2019 14:21

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	23/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3030541803	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Estima
Sub Model:	BASE MODEL
Model Sheet Number:	YM2 01
Registration:	SGU 7989H
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 05/2007	RR AIR CONDITIONING
XENON HEADLAMPS	2.4 LTR 117/125 KW
TYRES 205/65 HR 16	WHEELS 6.5J X 16
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	28/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61235



Version: LAI HUAT/3

Date Calculated: 28/03/2019 06:20

Full Report - V1

Registration: SGU 7989H

Printed: 28/03/2019 14:21

**Addresses****Cost Summary**

Total Labour	\$793.80
Total Paint/Material	\$232.33
Total Parts	\$1,660.00
Total of Additional Costs	\$100.00
Excess:	TBA
Grand Total Exc GST:	\$2,786.13
7 % GST:	\$195.03
Grand Total Inc GST:	\$2,981.16

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
B210 ZAX	RENEW LEFT FRONT DOOR INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	29.0	121.80
B216 ZAX	RENEW LEFT REAR DOOR INCLUDES: R + R AND ALIGN LEFT REAR DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	142.80
0741	REPAIR L/F WING	5.0*	21.00
3485	REPAIR L/R LOWER SIDE PANEL	6.0*	25.20
LABOUR COST			
	Total Work Units	74.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	7.4HRS	\$310.80
	Paint Labour	11.5HRS	\$483.00
	Total Labour	18.9HRS	\$793.80

PAINT WORK**Guide Number Description**

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

		WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1781	L/R DOOR NEW PART PAINTING	20.0	
2213	L/R SILL MOULDING NEW PART PAINT K1R	3.0	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61235

Version: LAI HUAT/3

Date Calculated: 28/03/2019 06:20

Full Report - V1

Registration: SGU 7989H

Printed: 28/03/2019 14:21

2219	L/F SILL MOULDING NEW PART PAINT K1R	3.0	
741	L/F WING REPAIR PAINTING <50%	11.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0	
3485	L/R LOWER SIDE PANEL REPAIR PAINTING <50%	12.0	
LABOUR COST - PAINT			
	TIME (PAINT)	82.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$483.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$116.10
	New Part Painting - Plastic K1R		\$1.96
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$30.04
	Repair Painting Plastic		\$42.93
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$232.33
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$232.33

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
1949	1	L/DOOR STRIPE	75952 28031		20.00*
1655	1	L/F DOOR REAR STRIP	75958 28030		30.00*
1645	1	L/F PROT MLDG STRIPE	75939 28020		25.00*
2219	1	L/F SILL MOULDING	76914 28070		150.00*
1647	1	L/F UPP DOOR STRIPE	75956 28030		25.00*
1653	1	L/MOULding	75969 28020		15.00*
1781	1	L/R DOOR	67004 28430		550.00*
1947	1	L/R DOOR FRONT STRIP	75934 28030		30.00*
1953	1	L/R DOOR REAR STRIP	75954 28021		25.00*
1943	1	L/R DOOR STRIPE	75932 28030		30.00*
2213	1	L/R SILL MOULDING	76916 28070		185.00*
1945	1	L/R UPP DOOR STRIPE	75938 28021		25.00*
1481	1	LEFT FRONT DOOR	67002 28210		550.00*
f: OEM Parts			Sub Total		\$1,660.00
g: Original			Sundry Parts	(Fixed)	\$0.00
h: Secondhand			Total Parts		\$1,660.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
SUNDRY PARTS	0%	\$100.00
SPECIALIST		
Total Extras		\$100.00

Final Calculation

Total Parts	\$1,660.00
Labour	
Total Panel/Mechanical	\$310.80
Total Paintwork	\$483.00

LAI HUAT (MENG KEE) MOTOR PTE LTD**Claim Reference:****Assessment Number: LHM61235****Version: LAI HUAT/3****Date Calculated: 28/03/2019 06:20****Full Report - V1****Registration: SGU 7989H****Printed: 28/03/2019 14:21**

Total Labour		\$793.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$100.00	
Total of Additional Costs		\$100.00
Total Paint/Material Costs		\$232.33
Grand Total Excludes GST		\$2,786.13
GST @ 7 %		\$195.03
Grand Total Includes GST		\$2,981.16

Assessment Notes



豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67430980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62940802
Fax: 62982158, 62942354, 62935021
Email: fongtat@mbbox.singnet.com.sg
RCB Reg No.: 198301435R

INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
T76914-28070 ✓		1 ✓	150.000		150.00
T67002-28210 ✓		1 PCS	550.000		550.00
T75956-28030 ✓		1 PCS	25.000		25.00
T75939-28020 ✓		1 PCS	25.000		25.00
T75958-28030 ✓		1 PCS	30.000		30.00
T75969-28020 ✓		1 PCS	15.000		15.00
T67004-28440 ✓		1 ✓	550.000		550.00
T75934-28030 ✓		1 PCS	30.000		30.00
T75932-28030 ✓		1 PCS	30.000		30.00
T75952-28031 ✓		1 PCS	20.000		20.00
T75954-28021 ✓		1 PCS	25.000		25.00

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

310

SIGNATURE



豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67430980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62940802
Fax: 62982158, 62942354, 62935021
Email: fongtat@mbbox.singnet.com.sg
RCB Reg No.: 198301435R

INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
T75938-28021 ✓		1 PCS	25.000		25.00
T76916-28070 ✓		1 PCS ✓	185.000		185.00
SGU7989H (ACR50) VICTOR					
			GST Excl Amount :		1660.00
			Special Discount :		
			GST @ 7 % :		116.20

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1776.20

PRINT BY :

WYH 00151 0018 11-00-20

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL GEM PARTS
TEL: 67420000 62949832 67479292
67420678 62985333 67450824

MITSUBISHI/PROTON
TEL: 62964551
67490954

HONDA/HYUNDAI DIV
TEL: 62970688 64542208
67493588

MAZDA/PERODU DIV
TEL: 62935722
67420066

AIRCON/W/S GLASS
TEL: 62952338
67490967

TAX INVOICE

TAX INVOICE NO.: CL390066

INVOICE DATE : 09/11/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL GEM PARTS
TEL: 67420000 62949832 67479292
67420678 62985333 67450824

MITSUBISHI/PROTON
TEL: 62964551
67490954

HONDA/HYUNDAI DIV
TEL: 62970688 64542208
67493588

MAZDA/PERODU DIV
TEL: 62935722
67420066

AIRCON/W/S GLASS
TEL: 62952338
67490967

TAX INVOICE

TAX INVOICE NO.: CL390066

INVOICE DATE : 09/11/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 2

***Veron Chen (LKKAUTO)**

From: Veron Chen (LKKAUTO)
Sent: Monday, 1 April 2019 9:02 AM
To: 'Jenny Lim'; Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: Finalisation - SGU 7989H / Toyota Estima

Dear Jenny,

Confirmed finalize amount \$2786.13 before excess \$500 @ 6 working days

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Thursday, 28 March 2019 2:43 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: Finalisation - SGU 7989H / Toyota Estima

Dear Sir

For your confirmation, please:

- Parts: \$1,660.00
- Sundry: \$ 100.00
- L&P: \$1,026.13
- Total: \$2,786.13 / Excess cost: \$500.00**

Supporting documents and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Oct 2018 Sendback Est	29 Oct 2018 14:32 S\$2,856.53	30 Oct 2018 11:36 Edit Adj Rpt	S\$2,786.13 Edit Estimates	S\$2,786.13 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TAN CHYE HUAT, ID: S1615667A, Tel: +6597931616, Email: NOEMAIL		
Vehicle Reg. No.:	SGU7989H	Date of Loss:	23/10/2018 10:00 - :59 [136 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D05044C01	Policy/Cover Note No.:	DMPCSN3030541803 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/11/2018]		
Driver/Custodian:	TAN CHYE HUAT (55 / Male), NRIC: S1615667A, Tel: +6597931616 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPING (02/11/2018): Alert - Adj Mandate Approved (S\$2818.73) - SGU7989H - Claim Handler: Catherine T...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGU7989H (SNM18D05044C01)
 OD
 Oct 23 2018 10:00AM
 [TAN CHYE HUAT]
 Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/10/18 14:32	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/18 12:22	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/10/18 14:38	Front View	Load JPG	<input checked="" type="checkbox"/>
2	28/10/18 14:38	Front View Right	Load JPG	<input checked="" type="checkbox"/>
3	28/10/18 14:38	Front View Left	Load JPG	<input checked="" type="checkbox"/>
4	28/10/18 14:38	Rear View Left	Load JPG	<input checked="" type="checkbox"/>
5	28/10/18 14:38	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
6	29/10/18 14:09	Front View	Load JPG	<input checked="" type="checkbox"/>
7	29/10/18 14:09	Front View Right	Load JPG	<input checked="" type="checkbox"/>
8	29/10/18 14:09	Front View Left	Load JPG	<input checked="" type="checkbox"/>
9	29/10/18 14:09	Rear View Left	Load JPG	<input checked="" type="checkbox"/>
10	29/10/18 14:09	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/18 12:23	General View	Load PDF	
2	01/04/19 08:51	Reinspection Photo (1)	Load PDF	
3	01/04/19 08:51	Reinspection Photo (2)	Load PDF	









Documentation

1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/10/18 14:32	E-filed GIA report	Load PDF	
2	29/10/18 14:32	Driver NRIC & Driving License	Load PDF	
3	29/10/18 14:32	Certificate of Insurance	Load PDF	
4	29/10/18 14:32	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/18 12:23	MARK ESTIMATE	Load PDF	
2	01/11/18 12:23	AUDATEX	Load PDF	
3	02/04/19 14:26	Parts Invoice	Load PDF	

Linked Accident Report Documents

										View View in Browser	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	23/10/18 17:20	Accident Statement									Load HTM
2	26/10/18 09:49	Addendum Sheet									Load TIF
3	26/10/18 09:50	Accident Statement Addm. #1									Load HTM
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/10/18 17:09	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 17:09	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 17:09	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 17:09	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 17:09	CHASSIS NUMBER		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	23/10/18 17:19	Sketch Plan		Load TIF	
2	23/10/18 17:20	CERTIFICATE OF INSURANCE		Load TIF	
3	23/10/18 17:20	DRIVER'S NRIC + DRIVING LICENCE		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18019719/KVBE2

Date: 02/04/2019

REFERENCE

Insured/Claimant: TAN CHYE HUAT Policy No: DMPCSN3030541803
Date of Loss: 23/10/2018 Nature of Claim: OD Claim No: SNM18D05044C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU7989H**
Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZF021966
Reg. Date: 25/05/2007 (Man. Year: 2007) Chassis No: ACR500033515
Colour: Metallic Gold Odometer: 153604 km
Engine Capacity: 2362 cc
Market Value/New Car Price: S\$76,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,680.00	1,660.00	20.00	1.19
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	1,076.53	1,026.13	50.40	4.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,856.53	2,786.13	70.40	2.46
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	2,856.53	2,286.13	570.40	19.97
+ GST 7.00/7.00% (S\$)	199.96	160.03	39.93	19.97
Nett Amount (S\$)	3,056.49	2,446.16	610.33	19.97

INSPECTION

Date of Assignment: 30/10/2018 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 31/10/2018 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU7989H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/DOOR STRIPE	Necessary	20.00 F	*20.00 F
2	1	NA	*L/F DOOR REAR STRIP	Necessary	30.00 F	*30.00 F
3	1	NA	*L/F PROT MLDG STRIPE	Necessary	25.00 F	*25.00 F
4	1	NA	*L/F SILL MOULDING	Dented / Cut	150.00 F	*150.00 F
5	1	NA	*L/F UPP DOOR STRIPE	Necessary	25.00 F	*25.00 F
6	1	NA	*L/MOULDING	Necessary	15.00 F	*15.00 F
7	1	NA	*L/R DOOR	Bent	550.00 F	*550.00 F
8	1	NA	*L/R DOOR FRAME MLDG	Not Necessary	25.00 F	*- F
9	1	NA	*L/R DOOR FRONT STRIP	Distorted	20.00 F	*30.00 F
10	1	NA	*L/R DOOR REAR STRIP	Cut	25.00 F	*25.00 F
11	1	NA	*L/R DOOR STRIPE	Necessary	30.00 F	*30.00 F
12	1	NA	*L/R SILL MOULDING	Dented / Cut	185.00 F	*185.00 F
13	1	NA	*L/R UPP DOOR STRIPE	Distorted	30.00 F	*25.00 F
14	1	NA	*LEFT FRONT DOOR	Bent	550.00 F	*550.00 F

F=Franchise part.

Total Parts (S\$)	1,680.00	1,660.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	SUNDRY PARTS	100.00	100.00
Sub Total (S\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	483.00	483.00
2	Total Paint Materials	New	232.33	232.33
3	Total Panel/Mechanical Labour	New	361.20	310.80
Gross Labour Cost (S\$)			1,076.53	1,026.13

Report was unsubmitted during this print-out.

< END OF ESTIMATES >