



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**


Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110  Contact No	Cust No/Name LCV05877/Mr Leung Chung Hong
	Reg No/Reg Date SJM179G / 14/06/2018
	Date In/Mileage 29/10/2018/ 0
	Chassis No KNAHU815VJ7208469
	Engine No D4FDJH552923
	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim K7N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000061	Credit	30/10/2018/ 15:23	DS	218 / MarsLer	12707				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS							63 80.00
S	MIPNT88088	DIAGNOSTIC / SCANNING							✓ 250.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL RAD & A/C CONDENSOR TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS							? 280.00
S	MIPNT88088	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT							✓ 180.00
S	MIPNT88088	WHEEL BALANCING							✓ 50.00
S	MIPNT88088	TO REPLACE FRONT BUMPER, LHF FENDER, LHF WHEEL, SUP PANEL, ETC STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS							1200 3600.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL							x 200.00
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS							840 1680.00
M	KS 86511 A4 820	COVER - FRONT BUMPER	2nd	1.00	695.00	0.00	✓	695.00	
M	KS 86521 A4 810	LH COVER - FR BUMPER	cut	1.00	130.00	0.00	✓	130.00	
M	KS 92201 A4 500	LHF FOG LAMP ASSY	new	1.00	206.00	0.00	+	206.00	
P	KS 86320 A4 000	EMBLEM - KIA	new	1.00	76.00	0.00	✓	76.00	
M	KS 86513 A4 800	LH SIDE BRACKET - FR	new	1.00	12.00	0.00	✓	12.00	
M	KS 86514 A4 800	RH SIDE BRACKET - FR	new	1.00	12.00	0.00	+	12.00	
M	KS 86551 A4 000	LH UPR SIDE BRACKET	?	1.00	12.00	0.00	?	12.00	
M	KS 86552 A4 000	RH UPR SIDE BRACKET	new	1.00	12.00	0.00	+	12.00	
M	KS 86520 A4 800	ABSORBER - FRONT BUM		1.00	68.00	0.00	+	68.00	
P	KS 0G032 50 037A	CLIP - BUMPER	new	10.00	2.00	0.00	✓	20.00	
M	KS 64101 A4 000	CARRIER ASSY - FRONT	?	1.00	628.00	0.00	✓	628.00	
P	JJMZ313950	COOLANT	?	4.00	26.00	0.00	✓	104.00	
M	KS 66311 A4 000	LH FENDER PANEL	Repair	1.00	405.00	0.00	+	405.00	
M	KS 84141 A4 000	LH FENDER INSULATOR	Not ne	1.00	48.00	0.00	+	48.00	

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name LCV05877/Mr Leung Chung Hong
Contact No	Reg No/Reg Date SJM179G / 14/06/2018
	Date In/Mileage 29/10/2018/ 0
	Chassis No KNAHU815VJ7208469
	Engine No D4FDJH552923
	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim K7N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000061	Credit	30/10/2018/ 15:23	DS	218 / MarsLer	12707		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	KS 86810 A4 000	LHF WHEEL GUARD ASSY	the car	1.00	75.00	0.00	75.00
P	JJMR200300	CLIP, SPLASH SHIELD	new	10.00	2.00	0.00	20.00
P	KS 92101 A4 160	LH HEADLAMP ASSY	the car	1.00	1558.00	0.00	1558.00
M	KS 52910 A4 750	WHEEL ASSY-ALUMINIUM	the car	1.00	704.00	0.00	704.00
Z	NOTES						
ACCIDENT ON 26/10/2018 ALONG CTE (BUKIT TIMAH EXIT) RIGHT LANE							
OWNER CLAIMING THIRD PARTY							
REQUIRED REPLACEMENT CAR							
TP # SJZ82H TP INS : EQ							

# Estimate

Adrian Leung  
P/P 24/11/18  
Auto Consultants hence notify  
the following:  
1. before spray painting  
2. art is during resurvey  
3. to confirm  
4. on a "Without prejudice" basis  
5. after work is done and  
approved by the insurance company

Signature:  
Date:

Confirm &amp; accepted by

Authorized signatory and company stamp

Parts	4,785.00
Labour	0.00
Standard Menu	0.00
Specialist Job	6,320.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	11,105.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.