

22/03/2002

ASS. REC. BY:

REF: CS

FCI 180197541 R1 + d3 n2

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Serene Ter

of

FCI

Date/Time:

3:59pm 30/10/18

Estimated Cost:

Bill to:

OD - TP - WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 3440Z

Insured:

SH 9019X

at Workshop m/s

T.C Autoclinic

Tel:

G763 8432

of

No. 1 Sixth Lok Yang Road

Policy No:

Claim No:

D18007812MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/10/2018

CA / REV / REP. / REV 24 HRS (DS)

31/10/2018

H.O.D. Endorsement:

Date/Time:

4:46pm 30/10/18

Person Contacted:

Mr. Ho

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 3440Z - NA / TMS 18019664 / r3
	SH 9019X - X
21/11@3:44pm	Revised preli advice via email
	Part by part \$19429.84 (Red: 7370.78/43%)

DOA: 27/10/2018

REF: FCL

30431

ASSIGNMENT

From: Date: 31.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS '09

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ3440Z

Yr Regn:

2016 DC

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prima Mover /

Truck / Trailer or

Make:

NISSAN SYLPHY 1.6 CVT cc 1598

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp Reading:

192

T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No:

MNTB0AB17Z0027796

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

mm

R/Bal:

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

27/10/18

D.O.I:

31/10/18

Survey held at

TC AUTO CLINIC

Des. of Damages

Frd

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 14 JAN 2019

Date/Time: File Pass to?



: Preli. Report

14/1 Typist



: Final Report

Date/Time: File Return to?

3)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week-end (\$)

Report Format:

TP

Lump Sum / 1B (\$)

9429.34

Days Of Repair:

12

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1) \$ - P.S. 31

2) Photos 053

3) Other 15/1/19

4) TOTAL

170 + 90

50

30

97

TOTAL

457

6x15 = 90

MOTOR SURVEY ASSIGNMENT

Date	30-10-2018	Our Ref No. D18007812MFSH
Accident Date	27-10-2018	Claim Type. Third Party
Insured Vehicle	SH9019X	Third Party Vehicle. SLJ3440Z
Survey Location	NO. 1 SIXTH LOK YANG ROAD	
Contact Person.	YM HO	
Contact No.	67038432/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TC AUTOCLINIC PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 2 November 2018 3:44 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007812MFSH/1
Attachments: PRELI ADVISED SLJ 3440Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLJ 3440Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 30 October 2018 4:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007812MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 31/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 October 2018 3:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007812MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007812MFSH

Date: 02/11/2018

Our Ref: CS/FCI18019754/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 3440Z

Please be informed that we had conducted the inspection of the abovementioned vehicle
31/10/2018 at the premises of M/s TC Auto clinic have the following to report: -

Workshop Estimate Amount	: S\$ <u>16,800.62</u>
Revised Estimate Amount	: S\$ <u>9,382.08</u>
"Check" Items Amount	: S\$ <u>2,316.42</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Rear N/S portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

AUTHORISATION LETTER Pg. 1

25 October 2018

To Whom It May Concern


This letter is to confirm that I have authorize the following person for the usage of my car,
Vehicle No. SLJ3440Z:

Ong Shao Yan
NRIC No.: S8631024D
Address: Blk 318C, Yishun Ave 9, #07-142
Singapore 763318



Alan Yeo Keng Sing
NRIC No.: S6803043I

REPUBLIC OF SINGAPORE DRIVING LICENCE



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. 868030431



ALAN YEO KENG SING

楊敬成

Race
CHINESE

Date of birth
22-01-1966

Country of birth
SINGAPORE

Sex
M



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 2A Motor cars without clutch pedals (Auto) <= 3000kg 17 Jan 2007
with <= 7 passengers, exclusive of the driver, and
other motor vehicles without clutch pedals <= 2500kg

Motor Vehicle Licence

3857736



30431

1/05/2015

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8631024D



Name

ONG SHAO YAN

江 劭 彦

Race

CHINESE

Date of birth

07-11-1986

Sex

M

S8631024D

Country/Place of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S8631024D

ONG SHAO YAN

Birth Date: 07 Nov 1986

Issue Date: 23 Jul 2007

001516626J

5691085



NRIC No. S8631024D



Date of issue

19-01-2017

Address


APT BLK 318C YISHUN AVENUE 9
#07-142
SINGAPORE 763318

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

PASS DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 23 Jul 2007

NP 428A





Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MU012052 (Private Car)

- | | | |
|---|-----------------------|--------------------------------|
| 1. Index Mark and Registration Number of Vehicle | SLJ3440Z | Chassis No.: MNTBBAB17Z0027796 |
| 2. Name of Policyholder | ALAN YEO KENG SING | |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 06/12/2017 (00:00:00) | |
| 4. Date of Expiry of Insurance | 05/12/2018 | |
| 5. Persons or Class of Persons entitled to drive* | | |
| (a) The Policyholder. | | |
| (b) Any other person who is driving on the Policyholder's order or with his permission. | | |

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been canceled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than sample) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 86 of the Road Transport Act, 1987 (Malaysia) are not included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part I Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not insurable. During its currency, if the insurance is canceled for whatever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days. If the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Account No: 2417DDA

ADDITIONAL INFORMATION

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess : SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	
	STANDARD CHARTERED BANK SINGAPORE LTD		
Financial Interest:			

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorized Signature

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 230/IC/TC/HO/2018
DATE : 30-OCT-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR ALAN YEO KENG SING
ADDRESS : BLK 635A PUNGGOL DRIVE
#15-617
S(821635)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SLJ34402 (6/12/2016)
MODEL CODE : BDTARC2B17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16992212B
CHASSIS NO : MNTBBAB1720027796
MILEAGE : 1 KM 5572
DATE IN : 30/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 27/10/2018

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ3440Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ACI	VACUUM AIRCOND SYSTEM, TOP UP GAS TO SPECIFICATION & MACHINE LEAKAGE TEST	120.00	X n n
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
3	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT AND REAR	120.00	60
4	RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	/
5	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @ \$120.00/PANEL X 4 PANELS	480.00	360
6	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @ \$100.00/PANEL X 3 PANELS	300.00	200
8	ZZ/001	REMOVE/INSTALL REAR BUMPER, END PANEL, TRUNK LID AND AFFECTED PORTION. REPAIR TRUNK FLOOR PANEL, LH REAR		
9	ZZ/002	FENDER AND RH REAR FENDER	1200.00	1560
10	ZZ/003	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, TRUNK LID, LH REAR FENDER AND RH REAR FENDER	1750.00	1500
11	ZZ/004	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	120
12	ZZ/005	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	/
13	ZZ/006	REMOVE/INSTALL FRONT BUMPER, BONNET AND AFFECTED PORTION. REPAIR RADIATOR SUPPORT PANEL	1560.00	585
14	ZZ/007	RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL AND BONNET	1000.00	500
15	ZZ/008	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	X n n
TOTAL LABOUR CHARGES			7843.00	

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ34402

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT LIST	S/NETT REMARKS
1	GUIDE-AIR, FRONT RH ?	62822-3RA0A	175.50	
2	GUIDE-AIR, FRONT LH ?	62823-3RA0A	175.50	
3	MALE ASSY-HOOD LOCK ?	65601-3SB0A	56.60	
4	BUMPER RUBBER-HOOD @\$5.00EACH X2PCS X	65822-3U010	10.00	
5	HOOD Repair	F510M-3SBMA	906.70	
6	MEMBER ASSY-FRONT SIDE FRONT, LH ?	G5115-3STMA		220.10 X ? ny
7	MEMBER ASSY-FRONT SIDE FRONT, RH ?	G5114-3STMA		115.20 X ? ny
8	CLIP-UPPER RADIATOR GRILLE @\$1.20EACH X18PCS new	01553-10501	21.60	
9	EMBLEM-FRONT new	62890-1KA0A	59.70	
10	BRACKET-RADIATOR GRILLE, LH ?	62397-3SB0A	16.30	
11	BRACKET-RADIATOR GRILLE, RH ?	62396-3SB0A	21.90	
12	RADIATOR GRILLE-CENTER CA	62312-3SB0A	749.40	
13	FRONT BUMPER REINFORCEMENT ?	F2032-3STMH	512.40	
14	FRONT BUMPER ENERGY ABSORBER ?	62090-3ST0A	220.70	
15	RH FRONT BUMPER SIDE BRACKET X	62224-3ST0A	22.60	
16	LH FRONT BUMPER SIDE BRACKET X	62225-3ST1A	22.60	
17	FRONT BUMPER CLIP @\$1.20EACH X14PCS new	01553-10501	16.80	
18	BRACKET-APRON, LOWER ?	62663-3ST0A	194.40	
19	BRACKET-LICENCE PLATE DE	96210-3ST0A	136.60	
20	COVER-BUMPER BRACKET X	622A0-3ST0A	28.60	
21	FRONT BUMPER FASCIA DE	62022-3ST1H	509.70	
22	HEADLAMP ASSY-RH ?	26010-3SB0D	521.70	
23	HEADLAMP ASSY-LH ?	26060-3SB0D	521.70	
24	CARPET-LUGGAGE FLOOR X	84902-3SB0A	411.20	
25	SPACER-LUGGAGE FLOOR TRIM DE	84978-3SB0A	170.50	

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ34402

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
26	PLATE-LUGGAGE, REAR <i>DE /</i>	84921-3SB0A	98.10	✓
27	INSULATOR-FUSIBLE <i>nee /</i>	G5930-89904	126.10	✓
28	HINGE ASSY-TRUNK LID @ \$58.40 EACH X2PCS <i>X</i>	H4400-3RAMA	116.80	+ <i>nn</i>
29	W/STRIP-TRUNK LID <i>nee /</i>	84830-3SB3J	91.20	✓
30	STRIKER-TRUNK LID LOCK <i>PA /</i>	84620-3AW0B	57.90	✓
31	LOCK ASSY-TRUNK LID <i>PA /</i>	84630-3AW0A	64.50	✓
32	TRUNK LID LOWER CHROME MOULDING <i>nee /</i>	H4300-3ST0A		120.80 ✓
33	BUMPER RUBBER-TRUNK LID @ \$4.50 EACH X2PCS <i>X</i>	01658-02091	9.00	X <i>nn</i>
34	EMBLEM-REAR <i>nee /</i>	90892-BG00A	59.70	✓
35	EMBLEM-REAR <i>nee /</i>	84890-3RA1B	94.70	✓
36	EMBLEM-REAR <i>nee /</i>	84890-3RA0B	50.10	✓
37	FINISHER ASSY-TRUNK LID <i>X</i>	84810-3ST1A	198.60	+ <i>nn</i>
38	TRUNK LID <i>PA /</i>	H430M-3SBMA	1244.80	✓
39	RH REAR BUMPER STAY <i>X</i>	85212-EE530	46.90	X <i>nn</i>
40	LH REAR BUMPER STAY <i>PA /</i>	85213-EE530	44.30	✓
41	ENERGY ABSORBER-REAR BUMPER, RH <i>X</i>	85092-3ST0A	91.00	X <i>nn</i>
42	ENERGY ABSORBER-REAR BUMPER, CENTER <i>X</i>	85090-3ST0A	36.30	X <i>nn</i>
43	ENERGY ABSORBER-REAR BUMPER, LH <i>CR /</i>	85093-3ST0A	136.70	✓
44	RH REAR BUMPER SIDE BRACKET <i>nee /</i>	85226-3ST1A	35.90	✓
45	LH REAR BUMPER SIDE BRACKET <i>nee /</i>	85227-3ST1A	35.90	✓
46	SENSOR-REVERSE <i>nee /</i>	SENSOR		200.00 ✓
47	REAR BUMPER FASCIA <i>DE /</i>	85022-3ST4H	649.30	✓
48	REAR END PANEL <i>PA /</i>	G9110-3SBMA	458.20	✓
49	REFLEX REFLECTOR ASSY-LH <i>nee /</i>	26560-5C000	55.00	✓

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ3440Z

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
50	LAMP ASSY-REAR COMBI,RH TRUNK X	26550-3SB3A	151.40	X } an
51	LAMP ASSY-REAR COMBI,LH TRUNK X	26555-3SB3A	151.40	X } an
52	CLIP-REAR COMBI LAMP @\$4.80EACH X2PCS ✓	26398-ED000	9.60	✓
53	LAMP ASSY-REAR COMBI,RH X	26550-3SB0A	390.40	X } an
54	LAMP ASSY-REAR COMBI,LH X	26555-3SB0A	390.40	X } an
SUB TOTAL			10376.90	0.00 656.10
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			2075.38	0.00 0.00
GRAND TOTAL			8301.52	0.00 656.10
OVERALL TOTAL			8957.62	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ3440Z

TOTAL LABOUR CHARGES	7843.00
TOTAL SPARE PARTS CHARGES	8957.62
GRAND TOTAL	16800.62 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Rearu - Hp 900105 68
31/10/18 @ 1420

12 days

Rearu b4 part

[Handwritten signature]
21/11/18

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : 230/IC/TC/HQ/2018
DATE : 30-OCT-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR ALAN YEO KENG SING
ADDRESS : BLK 635A PUNGGOL DRIVE
#15-617
S(821635)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SLJ34402
MODEL CODE : BDTARCEB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16992212B
CHASSIS NO : MNTBBAB1720027796
MILEAGE : 5572 KM
DATE IN : 30/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 27/10/2018

"Finalized B.H"

TC LKTC

ATTN: Mr Rasul

12 days

Best Regards

Y/M Ho

TC AUTOCLINIC PTE LTD
1 SIXTH LOR YANG ROAD
SINGAPORE 628099

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO S1J14402

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	AC1	VACUUM AIRCOND SYSTEM, TOP UP GAS TO SPECIFICATION & MACHINE LEAKAGE TEST	120.00	.00
2	BY01P	**COMPLETE POLISHING & WAXING OF VEHICLE INCLUDE VACUUM INTERIOR**		
3	PH1	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
4	NP1	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT	120.00	60.00
5	RC1	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	120.00
6	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PANEL X 3 PANELS	480.00	360.00
7	RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
8	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANELS	300.00	200.00
9	22/001	REMOVE/INSTALL REAR BUMPER, END PANEL, TRUNK LID AND AFFECTED PORTION. REPAIR TRUNK FLOOR PANEL, LH REAR		
10	22/002	FENDER AND RH REAR FENDER	1950.00	1560.00
11	22/003	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, TRUNK LID, LH REAR FENDER AND RH REAR FENDER	1750.00	1500.00
12	22/004	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	120.00
13	22/005	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	20.00
14	22/006	REMOVE/INSTALL FRONT BUMPER AND AFFECTED PORTION. REPAIR BONNET	1560.00	585.00
15	22/007	RESPRAY PAINT FRONT BUMPER AND BONNET	1000.00	500.00
16	22/008	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	.00
TOTAL LABOUR CHARGES			7843.00	5128.00

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 626099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ3440Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	GUIDE-AIR, FRONT RH	62822-3RA0A	175.50		X
2	GUIDE-AIR, FRONT LH	62823-3RA0A	175.50		X
3	HALE ASSY-HOOD LOCK	65601-3SB0A	56.60		X
4	BUMPER RUBBER-HOOD @\$5.00EACH X2PCS	65822-3U010	10.00		X
5	HOOD	F510M-3SBMA	906.70		X
6	MEMBER ASSY-FRONT SIDE FRONT, LH	G5115-3STMA		220.10	X
7	MEMBER ASSY-FRONT SIDE FRONT, RH	G5114-3STMA		115.20	X
8	CLIP-UPPER RADIATOR GRILLE @\$1.20EACH X18PCS	01553-10501	21.60		OK
9	EMBLEM-FRONT	62890-1KA0A	59.70		OK
10	BRACKET-RADIATOR GRILLE, LH	62397-3SB0A	16.30		X
11	BRACKET-RADIATOR GRILLE, RH	62396-3SB0A	21.90		X
12	RADIATOR GRILLE-CENTER	62312-3SB0A	749.40		OK
13	FRONT BUMPER REINFORCEMENT	F2032-3STHH	512.40		X
14	FRONT BUMPER ENERGY ADSORBER	62090-3ST0A	220.70		X
15	RH FRONT BUMPER SIDE BRACKET	62224-3ST0A	22.60		X
16	LH FRONT BUMPER SIDE BRACKET	62225-3ST1A	22.60		X
17	FRONT BUMPER CLIP @\$1.20EACH X14PCS	01553-10501	16.80		OK
18	BRACKET-APRON, LOWER	62663-3ST0A	194.40		X
19	BRACKET-LICENCE PLATE	96210-3ST0A	136.60		OK
20	COVER-BUMPER BRACKET	622A0-3ST0A	28.60		X
21	FRONT BUMPER FASCIA	62022-3ST1H	509.70		OK
22	HEADLAMP ASSY-RH	26010-3SB0D	521.70		X
23	HEADLAMP ASSY-LH	26060-3SB0D	521.70		X
24	CARPET-LUGGAGE FLOOR	84902-3SB0A	411.20		X
25	SPACER-LUGGAGE FLOOR TRIM	84978-3SB0A	170.50		OK

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGH NO SLJ3440Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	PLATE-LUGGAGE, REAR	04921-35B0A	98.10			OK
27	INSULATOR-FUSIBLE	G5930-89904	126.10			OK
28	HINGE ASSY-TRUNK LID @ \$58.40 EACH X2PCS	H4400-3RAHA	116.80			X
29	W/STRIP-TRUNK LID	84830-35B3J	91.20			OK
30	STRIKER-TRUNK LID LOCK	84620-3AW0B	57.90			OK
31	LOCK ASSY-TRUNK LID	84630-3AW0A	64.50			OK
32	TRUNK LID LOWER CHROME MOULDING	H4300-3ST0A			120.00	OK
33	BUMPER RUBBER-TRUNK LID @ \$4.50 EACH X2PCS	01658-02091	9.00			X
34	EMBLEM-REAR	90892-BG00A	59.70			OK
35	EMBLEM-REAR	84890-3RA1B	94.70			OK
36	EMBLEM-REAR	84890-3RA0B	50.10			OK
37	FINISHER ASSY-TRUNK LID	84810-3ST1A	198.60			X
38	TRUNK LID	H430H-3SBMA	1244.80			OK
39	RH REAR BUMPER STAY	85212-BE530	46.90			X
40	LH REAR BUMPER STAY	85213-BE530	44.30			OK
41	ENERGY ABSORBER-REAR BUMPER, RH	85092-3ST0A	91.00			X
42	ENERGY ABSORBER-REAR BUMPER, CENTER	85090-3ST0A	36.30			X
43	ENERGY ABSORBER-REAR BUMPER, LH	85093-3ST0A	136.70			OK
44	RH REAR BUMPER SIDE BRACKET	85226-3ST1A	35.90			OK
45	LH REAR BUMPER SIDE BRACKET	85227-3ST1A	35.90			OK
46	SENSOR-REVERSE	SENSOR			200.00	OK
47	REAR BUMPER FASCIA	85022-3ST4H	649.30			OK
48	REAR END PANEL	G9110-3SBMA	458.20			OK
49	REFLEX REFLECTOR ASSY-LH	26560-5C000	55.00			OK

TC AUTOCLINIC PTE LTD
1 SIXTH LOX YANG ROAD
SINGAPORE 620099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJ334402

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
50	LAMP ASSY-REAR COMBI,RH TRUNK	26550-3S03A	151.40			X
51	LAMP ASSY-REAR COMBI,LH TRUNK	26555-3S03A	151.40			X
52	CLIP-REAR COMBI LAMP @\$4.00EACH X2PCS	26398-ED000	9.60			OK
53	LAMP ASSY-REAR COMBI,RH	26550-3S00A	390.40			X
54	LAMP ASSY-REAR COMBI,LH	26555-3S00A	390.40			X
SUB TOTAL			4976.30	0.00	320.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			995.26	0.00	0.00	
GRAND TOTAL			3981.04	0.00	320.00	
OVERALL TOTAL			4301.84			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLJ3440X

NETT ITEM	4976.30
LESS 20.00%	-995.26
NETT AMOUNT	3981.04
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	320.80
LESS .00%	0.00
SPECIAL NETT AMOUNT	320.80
TOTAL LABOUR CHARGES	5120.00
TOTAL SPARE PARTS CHARGES	4301.84
TOTAL CHARGES	9429.84
ADD 7 % GST	660.09
GRAND TOTAL	10089.93



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019754/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9019X	Veh. Inspected	SLJ 3440Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007812MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	30/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY 1.6 CVT	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MNTBBAB17Z0027796	Colour	GREY	
Odometer	192	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2018	Inspection Date	31/10/2018	
Survey held at	TC AUTOCLINIC PTE LTD 1 SIXTH LOK YANG ROAD SINGAPORE 628099			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3440Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	GUIDE-AIR,FRONT RH (N)	NOT NECESSARY	175.50	-
1	GUIDE-AIR,FRONT LH (N)	NOT NECESSARY	175.50	-
1	MALE ASSY-HOOD LOCK (N)	NOT NECESSARY	56.60	-
2	BUMPER RUBBER-HOOD @\$5.00 (N)	NOT NECESSARY	10.00	-
1	HOOD (N)	TO REPAIR SEE LABOUR	906.70	-
18	CLIP-UPPER RADIATOR GRILLE @\$1.20 (N)	NECESSARY	21.60	21.60
1	EMBLEM-FRONT (N)	NECESSARY	59.70	59.70
1	BRACKET-RADIATOR GRILLE,LH (N)	NOT NECESSARY	16.30	-
1	BRACKET-RADIATOR GRILLE,RH (N)	NOT NECESSARY	21.90	-
1	RADIATOR GRILLE-CENTER (N)	CRACKED	749.40	749.40
1	FRONT BUMPER REINFORCEMENT (N)	SERVICEABLE	512.40	-
1	FRONT BUMPER ENERGY ABSORBER (N)	SERVICEABLE	220.70	-
1	RH FRONT BUMPER SIDE BRACKET (N)	SERVICEABLE	22.60	-
1	LH FRONT BUMPER SIDE BRACKET (N)	SERVICEABLE	22.60	-
14	FRONT BUMPER CLIP @\$1.20 (N)	NECESSARY	16.80	16.80
1	BRACKET-APRON,LOWER (N)	SERVICEABLE	194.40	-
1	BRACKET-LICENCE PLATE (N)	DEFORMED	136.60	136.60
1	COVER-BUMPER BRACKET (N)	SERVICEABLE	28.60	-
1	FRONT BUMPER FASCIA (N)	DEFORMED	509.70	509.70
1	HEADLAMP ASSY-RH (N)	SERVICEABLE	521.70	-
1	HEADLAMP ASSY-LH (N)	SERVICEABLE	521.70	-
1	CARPET-LUGGAGE FLOOR (N)	SERVICEABLE	411.20	-
1	SPACER-LUGGAGE FLOOR TRIM (N)	DEFORMED	170.50	170.50
1	PLATE-LUGGAGE,REAR (N)	DEFORMED	98.10	98.10
1	INSULATOR-FUSIBLE (N)	NECESSARY	126.10	126.10
2	HINGE ASSY-TRUNK LID @\$58.40 (N)	NOT NECESSARY	116.80	-
1	W/STRIP-TRUNK LID (N)	NECESSARY	91.20	91.20
1	STRIKER-TRUNK LID LOCK (N)	BENT	57.90	57.90
1	LOCK ASSY-TRUNK LID (N)	BENT	64.50	64.50
2	BUMPER RUBBER-TRUNK LID @\$4.50 (N)	NOT NECESSARY	9.00	-

Report Ref No. CS/FCI18019754/R1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EMBLEM-REAR (N)	NECESSARY	59.70	59.70
1	EMBLEM-REAR (N)	NECESSARY	94.70	94.70
1	EMBLEM-REAR (N)	NECESSARY	50.10	50.10
1	FINISHER ASSY-TRUNK LID (N)	NOT NECESSARY	198.60	-
1	TRUNK LID (N)	BENT	1,244.80	1,244.80
1	RH REAR BUMPER STAY (N)	NOT NECESSARY	46.90	-
1	LH REAR BUMPER STAY (N)	BENT	44.30	44.30
1	ENERGY ABSORBER-REAR BUMPER,RH (N)	NOT NECESSARY	91.00	-
1	ENERGY ABSORBER-REAR BUMPER,CENTER (N)	NOT NECESSARY	36.30	-
1	ENERGY ABSORBER-REAR BUMPER,LH (N)	CRACKED	136.70	136.70
1	RH REAR BUMPER SIDE BRACKET (N)	NECESSARY	35.90	35.90
1	LH REAR BUMPER SIDE BRACKET (N)	NECESSARY	35.90	35.90
1	REAR BUMPER FASCIA (N)	DEFORMED	649.30	649.30
1	REAR END PANEL (N)	BENT	458.20	458.20
1	REFLEX REFLECTOR ASSY-LH (N)	MISSING	55.00	55.00
1	LAMP ASSY-REAR COMBI,RH TRUNK (N)	NOT NECESSARY	151.40	-
1	LAMP ASSY-REAR COMBI,LH TRUNK (N)	NOT NECESSARY	151.40	-
2	CLIP-REAR COMBI LAMP @\$4.80 (N)	NECESSARY	9.60	9.60
1	LAMP ASSY-REAR COMBI,RH (N)	NOT NECESSARY	390.40	-
1	LAMP ASSY-REAR COMBI,LH (N)	NOT NECESSARY	390.40	-
	LESS 20% DISCOUNT		-2,075.38	-995.26
			8,301.52	3,981.04
	SPECIAL NETT ITEMS			
1	TRUNK LID LOWER CHROME MOULDING (SN)	NECESSARY	120.80	120.80
1	MEMBER ASSY-FRONT SIDE FRONT,LH (SN)	NOT NECESSARY	220.10	-
1	MEMBER ASSY-FRONT SIDE FRONT,RH (SN)	NOT NECESSARY	115.20	-
1	SENSOR-REVERSE (SN)	NOT WORKING	200.00	200.00
			656.10	320.80
	LABOUR			
	VACUUM AIRCOND SYSTEM,TOP UP GAS TO SPECIFICATION & MACHINE LEAKAGE TEST.	NOT NECESSARY	120.00	-
	FOCUS & ADJUST H/LAMP,RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00

Report Ref No. CS/FCI18019754/R1td3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT AND REAR.		120.00	60.00
	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST.		120.00	120.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		480.00	360.00
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		300.00	200.00
	REMOVE/INSTALL REAR BUMPER, END PANEL, TRUNK LID AND AFFECTED PORTION, REPAIR TRUNK FLOOR PANEL, LH REAR FENDER AND RH REAR FENDER.		1,950.00	1,560.00
	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, TRUNK LID, LH REAR FENDER AND RH REAR FENDER.		1,750.00	1,500.00
	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR.		240.00	120.00
	CHECK REAR LIGHTINGS AND WIRING SYSTEMS.		20.00	20.00
	REMOVE/INSTALL FRONT BUMPER, BONNET AND AFFECTED PORTION, REPAIR RADIATOR SUPPORT PANEL INCLUSIVE OF THE REPAIR OF HOOD.		1,560.00	585.00
	RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL AND BONNET.		1,000.00	500.00
	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS.	NOT NECESSARY	80.00	-
			7,843.00	5,128.00
	GRAND TOTAL		16,800.62	9,429.84
	RECOMMENDED COST OF REPAIRS			9,429.84

Report Ref No. CS/FCI18019754/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.