



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6346C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM (CONSISTENT)	NECESSARY	44.00	44.00
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$16.00 (CONSISTENT)	O/S CRACKED	32.00	16.00
2	FRONT BUMPER O/S & N/S UPPER BRACKET (CONSISTENT)	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @\$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
1	FRONT O/S FENDER (CONSISTENT)	BENT	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD (CONSISTENT)	CRACKED	120.00	120.00
1	WASHER TANK (CONSISTENT)	SERVICEABLE	47.00	-
1	WASHER TANK MOTOR (CONSISTENT)	SERVICEABLE	48.00	-
1	WHEEL COVER (CONSISTENT)	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-138.60	-121.10
			1,247.40	1,089.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	24.00	24.00
1	FRONT O/S FENDER STICKERS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SUNDRY (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			152.00	92.00
<b><u>LABOUR</u></b>				
	TOWING FEE.		50.00	50.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ETC.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER.		400.00	360.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	30.00
			1,260.00	840.00
<b>GRAND TOTAL</b>			<b>2,659.40</b>	<b>2,021.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CC4/ASM18019781/K1pa3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.