Surveyor: RASUL	ASSIGNMENT	(Office)		
From (Person): Irene tay	of CT	C Dat	e/Time: 311101	180 11.50
Estimated Cost:	Bill	to:		
To Inspect Vehicle No:	WC 1032M	Insured:	31163	6]
at Workshop m/s	wts Engineering	Tel:	92994122	
of	& Gill Circle			
Policy No: DM PCS N304	1031800	laim No: SNM18	NA5127 CO	2
Sum Insured:		Excess:		
Make of Veh:	1,110	D.(A 28/10/2	018
(Client's Record)	(dry)		01/11/2018	
CA / REV / REP. / REV 24 H		100	I.O.D. Endorsement:	
Date/Time 2.25 pm 3110	Person Contacted: M	r-chan Vehi	el INJOUT	
	() Estimate			
Date/Time Action/Instruction	L' Comment			
Date/Time Action/Instruction	X			
W(032M-	X NA FOR LOOK	110	Dag. 10	100/10
WC1032M- SIL 6361	X - NA FQT 1201615		Dag: 18	2/08/12
W(032M-	usioned water o	4/e mr Chan Fine		08/12 0, 3 de

Syrvaller Holom REF:	27211
SSITE OF THE STATE	GNMENT COE MIRY: 2022 for
From: Date: t	Veh No: WC 1032M Yr Regn: NO / SEP Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP // WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or CEMENT TRUCK
To Inspect Vehicle No: WC 1032M	Make: 13424 CYH 325 c.c (5681
at Workshop m/s WTS touch Workshop m/s	Colour (NWLT) A/C: Insured / Std / NI / NA
of 8, and circle	Sp.Reading 24278 T/Radio: Insured / Std / NI / NA
Insured: CT	Eng/No:
Policy No.	CNO: JALCYH 52577 000009
Claims No.	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Unorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NiP S/Rim / STD A/Rim or
	Tyre Size: F: 275 80R22-5
(Policy Condition)	R: e -
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF FIRENZA
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 8 mm R/Bal. 8/8 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 8 mm L/Bal. 8/8 mm
Est Repairs: 3 days Res.: Yes or No	D.O.A. 28/10/08 D.O.I. D1/11/18
Lum Sum: % 3 Val.: Yes or No	Survey held at WTS
2	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	PEAR MS
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	murato
RECEIVED 2	0 NOV 2018
KLOLITE	
5	3102/1/191
	, 11 1
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
1) 20/1 ty M87 : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	
2) Add Fe	: Interview (\$) Photos
-	
Report Format: MER TP Lump Sum / I.B.I: (\$ 930)	

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBFO				,			_		
Case N	lotified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main 3	0 Oct 2018		31 Oct 2018 11:50 Assign					New Assignment Cancel Case	
М	ain	Re	ference		Claim Details		Documen	ts	Show All
CLAIM SUB	FOLDER DE	TAILS			material Sales Sal	[Create	d by insurer]	Section of the Serve	
Insured:	ANG ZI Y	ANG, ID: S8410	564C		1077/11	1			
Main Claimant:	WOODLA	NDS TRANSPORT	SERVICE PTE	LTD, Co.	Reg. No.: 19810	2721M			00
Vehicle Reg. No.:	WC1032	M			Date of Loss:	28/10/2018 06:00 - :59 [133 Months and 25 Days From LTA Reg Date (Man Yr)			
Claim Type:	TP / SNN	418D05127C02			Policy/Cover Note No.:				
Vehicle Reg. No. (Insured):	SJL636J				Policy No. (Claimant):				
					Excess:	S\$0.00			
Repairer:	Wts Engir	neering Pte Ltd (HQ) 8 Gul Circle	e, 629564 Tu	as - Tel:				
Handling Insurer:	China Tai	ping Insurance (Singapore) Pt	e. Ltd. (HQ)	- Tel: 6389 611	1 [Hand	dled by Irene Tay	Hui Ping - 6389	86192]
Adjuster:		Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 12/	11/2018]		
Driver/Custo dian (Insured):		NG (34 / Male),	NRIC: S841056	4C					
ASSOCIATE	D MAIL RE	CEIVED						View All Comp	ose Case Ma
There are no	mail for this	case.							
ALL ASSOC	IATED TAS	ks⊟				View Al	Search Tasks	Create New Task	Comple
Due Date	Priority	Type Task	Group Sub	ject Han	dler Assign	ned By	Completed Or	Created C	n Don
No results.									





YOUR REF

: SJL636J

OUR REF

: JW/1018/041

29 October 2018

China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909

Dear Sir

By Fax: 6224 7175

We are instructed by Woodlands Transport Service Pte Ltd to notify you of a road traffic accident on 28/10/2018 at about 06:42hrs at Sliproad from ECP twds Marine East Drive involving our client's/customer's vehicle registration number WC1032M and vehicle registration number SJL636J driven by you at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Please send your surveyor to our premises at No. 8 Gul Circle, Singapore 629564.

Please contact Mr Chan at Tel: 6559 8984 / 9299 4122 for an appointment to view the vehicle.

For your immediate attention and action, please.

Thank you.

Yours faithfully,

Kenji Lee

Claims Department

Direct Line Facsimile

(65) 6559 8954

Email

(65) 6898 2394

kenjilee@woodlandstransport.com.sg



WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163 Company Registration Number: 200505706E

Quotation

DATE:

29/10/18

WC1032M

VEHICLE NO: DRIVER: ATTENTION TO:

PREPARED BY: Chan Soo Lye

AYYASAMY MATHAVAN

LOCATION:

Gul Workshop

Q REF No:

Q18/10/946

DEPARTMENT:

WTS Mixer Truck Department

ACCIDENT DATE: 28/10/18

REF No:

JW-1018-41

S/N	Description	Qty	Cost per Unit	Amount S\$
	Spare Parts			
1	REAR LHS TAIL LAMP ASSY	1	200	200.00
	Labour Costs			
1	TO WELD AND CUT REAR LHS DAMAGED PORTION TO FABRICATE REAR BUMPER AND INSTALL TO REPAIR REAR LHS TAIL LAMP BRACKET.	1	700	600 700.00
	Spray Paint			,
1	Spray Painting TO PAINT REAR BUMPER AND BRACKET.	1	250	200 250.00
			TOTAL:	1,150.00
			Total Amount	SGD 1,150.00

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department

the Repairer of the following:

• To resurvey before spray painting

- To display damaged part(s) during resurvay
- . Parts prices are subject to confirmation
- . Third party survey is on a "Valhout Frejudide" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor Sign: Surveyor Name: Date:

the reviewes

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18019846/R1QD3N2

6WG1405783

24278 km

JALCYH52S77000009

Date:

26/11/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Claimant Vehicle No:

WC1032M

Date of Loss: 28/10/2018 Policy No:

DMPCSN3041031800 Insured Vehicle SJL636J

No:

Nature of Claim:

TP

Claim No:

SNM18D05127C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

WC1032M

Make & Model: Reg. Date:

ISUZU CYH52S, 15.7 D (M) 03/09/2007 (Man. Year: 2007)

Multi-colour

Colour: Engine Capacity:

15681 cc

Market Value/New Car

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

295/80 R22.5 Firenza 8 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 295/80 R22.5 (D) Firenza 8/8 mm Firenza 8/8 mm

Front Right Side: Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 200.00 0.00	Adjuster's 170.00 0.00	30.00 0.00	Diff % 15.00
Labour Paintwork Labour	950.00 0.00	800.00 0.00	150.00 0.00	15.79
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,150.00	970.00	180.00	15.65
+ GST 7.00/7.00% (S\$)	80.50	67.90	12.60	15.65
Nett Amount (S\$)	1,230.50	1,037.90	192.60	15.65

INSPECTION

Date of Assignment:

31/10/2018

Date Inspected:

01/11/2018 Inspected At: Wts Engineering Pte Ltd (HQ)

8 Gul Circle Singapore 629564

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 26 Nov 2018)

Parts:

N/A

ISUZU CYH52S 15.7 D (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for WC1032M)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.		Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LHS TAIL LAMP ASSY	Broken	200.00 F	*200.00 FL
F=Fra	nchise	part. L=ListItem	Disc.	-		
				Sub Total (S\$)	200.00	200.00
			- List Item Discount on L Ite		0.00	30.00
				Total Parts (S\$)	200.00	170.00
			Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO WELD AND CUT REAR LHS DAMAGED PORTION TO FABRICATE REAR BUMPER AND INSTALL TO REPAIR REAR LHS TAIL LAMP BRACKET	New	700.00	600.00
2	SPRAY PAINTING TO PAINT REAR BUMPER AND BRACKET	New	250.00	200.00
	Gross Labo	ur Cost (S\$)	950.00	800.00
	Report was unsubmitted du	ing this print-out.		

< END OF ESTIMATES >