

03/2002

ASS. REC. BY

REF CS3 / MSG18010305 / G40-1

Instruction:

Surveyor
Mehmen

GQ
Lionel fun

ASSIGNMENT (Office)

From (Person):

of MS/G

Date/Time: 01/11/2018

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGS 81328

Insured:

GBD 6871 T

at Workshop m/s

B.L. Garage

Tel:

9240 6288

of

25 Kelki Bkt Rd 4 #03-24

Policy No:

A 28683902Mkc

Claim No:

560231

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/06/2018

CA / REV / REP. / REV 24 HRS

1up

07/06/18

H.O.D. Endorsement:

Date/Time:

5:03pm 6/6/18

Person Contacted:

Amylia

Vehicle

☒ IN / ☐ OUT

Date/Time

Action/Instruction (X) Estimate

Do Not Finalize

SGS 81328 - CC4 / AIG 08022563 / Kph

DOA: 9/8/2008

GBD 6871 T - CS / FCI 17013059 / K/h3n2

DOA: 29/06/2017

\$3050 . 5 Days.

Used \$3150, 51%

RECEIVED 20 NOV 2018


19/11/2018


PKS
XAL

REF: MS1G

808C

ASSIGNMENT

From: Date: 7/6/18
Estimated Cost:
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SGS 8132 S
at Workshop m/s: B.L. Garage
of: 25 Kaki Bkt Rd & #03-24
Insured:
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$24K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / FR Seen: Consistent? : Yes or No
Est. Repairs: days Res: Yes or No
Lump Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS ^{Imp}

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SGS 8132 S Yr Regn: 26 Nov 2007
Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Suzuki swift 1.6 1586
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 21163 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: ISA E8C3/S 00101547
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: Nil / ☒ STD A/Rim /
Tyre Size: F: 205/50 R15
R: 11
BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: R/Bal. 6 mm L/Bal. 6 mm
Rear: R/Bal. 6 mm L/Bal. 6 mm
D.O.I: 07-06-18
Survey held at: w/s 4:30pm
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
Repair Estimate : \$ 2500 - 3500

* 2 days

13/6/18 Submit PKS report.

RECEIVED 13 JUN 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Other

TOTAL

120

10

130

Report Format :

Lump Sum / I.B.I (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018		06 Jun 2018 16:23 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	COLOR PLAY ENTERPRISE PTE LTD, Co. Reg. No.: 199201527C								
Main Claimant:	CHOW CHEE HONG, ID: S7238098C								
Vehicle Reg. No.:	SGS8132S	Date of Loss:	01/06/2018 19:00 - :59 [134 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560231	Policy/Cover Note No.:	A28683902MKC (Comprehensive) Coverage: 16/03/2018 - 15/03/2019						
Vehicle Reg. No. (Insured):	GBD6871T	Policy No. (Claimant):							
		Excess:							
Repairer:	BI Garage Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4 #03-24, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/11/2018]								
Driver/Custodian (Insured):	MOHAMED FAIZAL BIN MOHAMED ZAZALI (36 / Male), NRIC: S8129322H								
Adj Asg. Remarks:	on WP. SJE Disagree Please appoint LKK Auto Consultancy Pte. Ltd and contact Amylia @ 9240 6288 Liability: 100%								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (01/11/2018): Report Send Back Alerts - SGS8132S (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Chow Chee Hong
C/o: B L Garage Pte Ltd
25 Kaki Bukit Road 4
#03-24 Synergy@KB, Singapore 417800

Date : 18 June 2018
Our ref : BLG/06/1801/TP

Accident Date : 01 June 2018
Inspection Date : 05 June 2018
Repairer Name : B L Garage Pte Ltd
25 Kaki Bukit Road 4
#03-24 Synergy@KB, Singapore 417800

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SGS 8132 S
Make / Model : Suzuki Swift
Chassis No : JSAEZC31S00101547
Engine No : M16A1224496

Year / Capacity : 2007 / 1586 cc
Colour : Blue
Mileage : 211163

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Dunlop	205/50 R15	5 mm	Sport
Front Offside	Dunlop	205/50 R15	5 mm	Sport
Rear Nearside	Dunlop	205/50 R15	5 mm	Sport
Rear Offside	Dunlop	205/50 R15	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 68 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 6,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: SGS 8132 S

Our Ref No: BLG/06/1801/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen moulding	Necessary	\$ 119.00	\$ 119.00 NEC ✓
1	Rear tailgate	Damage	\$ 658.30	\$ 658.30 DD ✓
2	Rear tailgate dampers	Intact	\$ 358.00	
1	Rear tailgate lock	Damage	\$ 149.50	\$ X 149.50 NN ✓
1	Rear tailgate rubber	Necessary	\$ 86.70	\$ 86.70 CUT ✓
1	Rear taillamps	O/S Damage	\$ 579.40	\$ 289.70 BR ✓
1	Rear end panel	Damage	\$ 397.60	\$ X 397.60 Repair ✓
1	Rear end panel inner garnish	Damage	\$ 105.80	\$ 105.80 DL ✓
1	Rear bumper	Damage	\$ 578.80	\$ 578.80 BR ✓
1	Rear bumper side bracket	Damage	\$ 68.00	\$ 68.00 BR ✓
1	Rear bumper lamp	Intact	\$ 128.20	
2	Rear bumper side retainers	Necessary	\$ 72.00	\$ 72.00 NEC
2	Rear bumper lower brackets	Damage	\$ 144.00	\$ X 144.00 NN ✓
1	Rear bumper top beam	Damage	\$ 88.30	\$ 88.30 BT ✓
2	Rear number plate lamps	Intact	\$ 84.40	
1	Rear exhaust silencer	Damage	\$ 836.00	\$ X 836.00 NN ✓
2	Rear exhaust mountings	Necessary	\$ 57.20	\$ 57.20 NN X
2	Rear exhaust chrome tail pipes	Damage	\$ 211.00	\$ 211.00 NN X
			\$ 4,722.20	\$ 3,861.90 2066.6
			Less 15%	\$ 579.29
Total Cost - List Items			\$ 4,013.87	\$ 3,282.62 1756.61

SPECIAL NETT ITEMS

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00 ✓
1	Rear bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 ✓
1	Rear bumper lower spoiler	Damage	\$ 1,500.00	\$ 1,500.00 450 ✓
1	Rear number plate with holder	Damage	\$ 50.00	\$ 50.00 40 ✓
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 200 ✓
Total Cost - Special Nett items			\$ 2,025.00	\$ 1,925.00 785

Total cost of parts

\$ 6,038.87 \$ 5,207.62

Vehicle Registration No: SGS 8132 S

Our Ref No: BLG/06/1801/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,038.87	\$ 5,207.62

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 60.00
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 60.00
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00 ✓
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 ✓
6	To remove, refit and replace exhaust silencer and mountings.	\$ 150.00	\$ 120.00 50.00 ✓
7	To apply undercoating on repaired and replaced panel.	\$ 150.00	\$ 90.00 60.00
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,400.00	\$ 1,000.00 400
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ 880.00 500

GRAND TOTAL

\$ 9,548.87	\$ 7,727.62
--------------------	--------------------

Repair days 5

2831.61
20% = 3050

TGim

19/11/18

Vehicle Registration No: SGS 8132 S

Our Ref No: BLG/06/1801/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,200.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.

Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018		06 Jun 2018 16:23 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	COLOR PLAY ENTERPRISE PTE LTD, Co. Reg. No.: 199201527C								
Main Claimant:	CHOW CHEE HONG, ID: S7238098C								
Vehicle Reg. No.:	SGS8132S	Date of Loss:	01/06/2018 19:00 - :59 [134 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560231	Policy/Cover Note No.:	A28683902MKC (Comprehensive) Coverage: 16/03/2018 - 15/03/2019						
Vehicle Reg. No. (Insured):	GBD6871T	Policy No. (Claimant):							
		Excess:							
Repairer:	BI Garage Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4 #03-24, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/11/2018]								
Driver/Custodian (Insured):	MOHAMED FAIZAL BIN MOHAMED ZAZALI (36 / Male), NRIC: S8129322H								
Adj Asg. Remarks:	on WP. SJE Disagree Please appoint LKK Auto Consultancy Pte. Ltd and contact Amylia @ 9240 6288 Liability: 100%								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (01/11/2018): Report Send Back Alerts - SGS8132S (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGS8132S (560231)
[GBD6871T]
TP
CHOW CHEE HONG
Jun 1 2018 7:00PM
[COLOR PLAY ENTERPRISE PTE LTD]
BI Garage Pte Ltd


[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/06/18 10:47	Accident Statement <small>From: SC - Reg. No: GBD6871T, Claimant: COLOR PLAY ENTERPRISE PTE LTD</small>		Load HTM	

Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
2	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
3	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
4	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
5	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
6	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
7	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
8	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
9	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
10	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
11	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
12	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
13	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
14	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
15	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
16	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
17	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
18	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
19	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
20	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
23	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
24	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
25	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>
26	12/06/18 11:21	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/06/18 10:47	Third Party Accident Report <small>From: SC - Reg. No: GBD6871T, Claimant: COLOR PLAY ENTERPRISE PTE LTD</small>		Load PDF	
2	06/06/18 10:48	estimate repair		Load PDF	
3	01/11/18 09:29	3P survey report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/11/18 12:20	PRS Invoice		Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
2	21/11/18 12:20	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Colour Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18010325/GQBE2-1

Date: 21/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28683902MKC

Claimant Vehicle No : SGS8132S

Insured Vehicle No : GBD6871T

Date of Loss: 01/06/2018

Nature of Claim: TP

Claim No: 560231

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS8132S

Make & Model: SUZUKI SWIFT, 1.6 (A)

Engine No: M16A1224496

Reg. Date: 26/03/2007 (Man. Year: 2007)

Chassis No: JSAEJC31S00101547

Colour: Blue

Odometer: 211163 km

Engine Capacity: 1586 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R15

Rear Tyre Size: 205/50 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,038.87	2,541.61	3,497.26	57.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,290.00	2,220.00	63.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,548.87	3,831.61	5,717.26	59.87
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	9,548.87	3,050.00	6,498.87	68.06

INSPECTION

Date of Assignment: 06/06/2018

Date Inspected: 07/06/2018 Inspected At:

BI Garage Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4 #03-24
Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts:	144	SUZUKI SWIFT 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGS8132S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	119.00 FL	*119.00 FL
2	1		*REAR TAILGATE	Dented	658.30 FL	*658.30 FL
3	2		*REAR TAILGATE DAMPERS	Intact	358.00 FL	*- FL
4	1		*REAR TAILGATE LOCK	Not Necessary	149.50 FL	*- FL
5	1		*REAR TAILGATE RUBBER	Cut	86.70 FL	*86.70 FL
6	1		*REAR TAILLAMPS	O/S Broken	579.40 FL	*289.70 FL
7	1		*REAR END PANEL	Repair	397.60 FL	*- FL
8	1		*REAR END PANEL INNER GARNISH	Dislodged	105.80 FL	*105.80 FL
9	1		*REAR BUMPER	Broken	578.80 FL	*578.80 FL
10	1		*REAR BUMPER SIDE BRACKET	Broken	68.00 FL	*68.00 FL
11	1		*REAR BUMPER LAMP	Intact	128.20 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINERS	Necessary	72.00 FL	*72.00 FL
13	2		*REAR BUMPER LOWER BRACKETS	Not Necessary	144.00 FL	*- FL
14	1		*REAR BUMPER TOP BEAM	Bent	88.30 FL	*88.30 FL
15	2		*REAR NUMBER PLATE LAMPS	Intact	84.40 FL	*- FL
16	1		*REAR EXHAUST SILENCER	Not Necessary	836.00 FL	*- FL
17	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.20 FL	*- FL
18	2		*REAR EXHAUST CHROME TAIL PIPES	Not Necessary	211.00 FL	*- FL
19	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
20	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
21	1		*REAR BUMPER LOWER SPOILER	Damaged	1,500.00 FS	*450.00 FS
22	1		*REAR NUMBER PLATE WITH HOLDER	Damaged	50.00 FS	*40.00 FS
23	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,747.20	2,851.60
- List Item Discount on L Items 15.00/15.00% (\$\$)	708.33	309.99
Total Parts (\$\$)	6,038.87	2,541.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
2	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	60.00
3	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
5	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
6	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	150.00	60.00
7	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	400.00
8	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
9	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
Gross Labour Cost (S\$)			3,510.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >