

ASS. REC. BY:

REF:

CS/MSG/8014447/GV10-27

Serial Instruction:

Surveyor

From (Person)

Katherine Wong

ASSIGNMENT (Office)

MSG

Date/Time: 31-10-2018

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 7929 K

Insured:

SKV 973X

at Workshop m/s

E.M. Solution

Tel:

8 456 0226

of

160 Sin Ming Drive # 03-18

Policy No:

A28607381 Arw

Claim No:

566514

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 4/8/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11-06am 08/8/18

Person Contacted:

Bernard

Vehicle IN (OUT)

Date/Time

Action/Instruction

(+) Estimate

Do Not Finalize

GBC 7929K-X

SKV 973X-CS/MSG/6018309/T1gbn2


DoA: 16/9/2016

15/11/18

GUO Qiang go thru already

15/11/18

Submit LS \$4100 (Red 2200, 35%), 5 days



14/11/2018

RECEIVED 15 NOV 2018

Repair days 5

TGM

lin

9/11/18

ASS. REC. BY: Wef

REF: MS1G


B1502C

ASSIGNMENT

From: _____ Date: 13/8/18
 Estimated Cost: _____
 ON (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBC 7929K
 at Workshop m/s EM SOLUTION
 of 160 Sin Ming Drive #03-18 119
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBC 7929K Yr Regn: 11 Nov 2013
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan NV350 c.c. 2488
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 140605 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1MC2E2680001377
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>13-08-18</u>

Survey held at w/s 4:30 pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$3000 - \$4000</u>

18/8/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

120

10

130

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2018		07 Aug 2018 15:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	Ee Huei Wuan, ID: S2511788C		
Main Claimant:	NPN ENGINEERING, Co. Reg. No.: 52971502C		
Vehicle Reg. No.:	GBC7929K	Date of Loss:	04/08/2018 17:00 - :59 [56 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566514	Policy/Cover Note No.:	A28607381AVW (Comprehensive) Coverage: 28/08/2017 - 27/08/2018
Vehicle Reg. No. (Insured):	SKV973X	Policy No. (Claimant):	
		Excess:	
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/11/2018]		
Driver/Custodian (Insured):	Ee Huei Wuan (30 / Female), NRIC: S2511788C		
Adj Asg. Remarks:	on WP. SJE Disagree Please appoint LKK and contact Mr. Bernard (Tel.: 6456-0226 / 9101-8302). Liability is not clear.		
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail	
<ul style="list-style-type: none"> MSIG_SG (31/10/2018): Report Send Back Alerts - GBC7929K (TP) 			
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: NPN Engineering
c/o 160 Sin Ming Drive
#03-18/19 Sin Ming Autocity
Singapore 575722

Date : 01/10/2018

Reference No : CAS/18-10/004

General Information

Registration No. : GBC 7929K
Accident Date : 04/08/2018

Particulars of Damaged Vehicle

Colour	: Silver	Make & Model	: Nissan NV350
Engine Capacity	: 2488 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 140605	Engine No.	: YD25337031A
Chassis No.	: JN1MC2E26Z0001377	Steering	: In Order
Registration Date	: 11/11/2013	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	GREMAX	90%
L/H Front Tyre	195R15	GREMAX	90%
R/H Rear Tyre	195R15	DUNLOP	90%
L/H Rear Tyre	195R15	BRIDGESTONE	70%

Inspection

Repairer : EM Solution Pte Ltd
160 Sin Ming Drive #03-18/19 Sin Ming Autocity, Singapore 575722

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$9,493.67
Revised Amount : \$6,300.00
Less Excess : -
Nett Total : \$6,300.00

Remarks

- (A) Survey was done on 13/08/2018
- (B) Re-survey was done on 14/08/2018
- (C) Re-survey after repair was done on 17/08/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : GBC 7929K

Our ref : CAS/18-10/005

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – LIST ITEMS</u>						
1	1pc	Rear tailgate	Dented/Warped	2,140.40	^{1742.00} 2,140.40	DDV
2	1pc	Rear tailgate outer moulding	Serviceable	350.70	—	
3	1pc	Rear bumper	Dented/Deformed	683.60	683.60	DDV
4	1pc	Rear step panel	Dented/Twisted	361.50	^{192.60} 361.50	DDV
5	1pc	Rear end panel	Dented/Warped	424.80	^{342.80} 424.80	DDV
6	1pc	Rear end panel inner member	Dented	481.60	481.60	RNX
7	1pc	Rear end panel top moulding	Twisted	55.30	55.30	BTV
8	1pc	Rear tailgate emblem 'Nissan'	Necessary	68.60	68.60	NECV
9	1pc	Rear tailgate emblem 'NV350'	Necessary	68.60	68.60	
10	1pc	Rear tailgate emblem 'Urvan'	Necessary	52.70	52.70	
11	1pc	Rear tailgate inner lock	Bent/Jammed	266.10	266.10	NNX
12	1pc	Rear tailgate inner lock cover	Deformed	31.25	31.25	DDV
13	1pc	Rear tailgate inner lock actuator	Damaged	246.20	246.20	DDV
14	1pc	Rear tailgate weatherstrip	Distorted	105.20	105.20	CUTV
15	2pcs	Rear tailgate damper @ \$185.60	Serviceable	371.20	-	
16	2pcs	Rear tailgate side stopper @ \$42.20	Bent	84.40	84.40	NNX
17	2pcs	Rear taillamp @ \$281.60 200.80	Broken	563.20	^{419.60} 563.20	BRV
18	1pc	Rear spare wheel carrier	Serviceable	266.50	-	
19	1pc	Rear spare wheel holder	Serviceable	89.60	-	
20	2pcs	Rear bumper side retainer @ \$35.20	Necessary	70.40	70.40	
				6,781.85	5,703.85	
Less 10%				(678.18)	(570.38)	
Sub total				6,103.67	5,133.47	
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>						
1	1set	Rear windscreen sealant set	Necessary	80.00	60.00	NECV
2	1set	Rear windscreen foam tape	Necessary	60.00	45.00	
3	1set	Rear bumper clip	Necessary	30.00	30.00	
4	1set	Rear reverse sensor	Damaged	280.00	^{200.00} 220.00	
5	1pc	Rear sticker '70km/h'	Necessary	15.00	15.00	
6	1pc	Rear sticker '11pax'	Necessary	15.00	15.00	
Sub total				6,583.67	5,518.47	

Constant Appraiser Services

Vehicle No : GBC 7929K

Our ref : CAS/18-10/005

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES</u>			
1		To remove, refix rear windscreen glass		180.00	80.00 120.00
2		To checkup rear electrical wiring		50.00	20.00
3		To remove, refix reverse sensor		80.00	60.00
4		To respray undercoating		100.00	60.00
5		To respray painting & etc		1,200.00	600.00 1,000.00
6		Panel beating, remove & replacing above parts		1,300.00	600.00 1,100.00
Grand total				9,493.67	7,878.47
Recommended cost of lump sum repair (To its pre-accident condition)					6,300.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$6,300.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

Repair days 5

Tam
lim
9/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2018		07 Aug 2018 15:58 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Ee Huei Wuan , ID: S2511788C								
Main Claimant:	NPN ENGINEERING , Co. Reg. No.: 52971502C								
Vehicle Reg. No.:	GBC7929K	Date of Loss:	04/08/2018 17:00 - :59 [56 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566514	Policy/Cover Note No.:	A28607381AVW (Comprehensive) Coverage: 28/08/2017 - 27/08/2018						
Vehicle Reg. No. (Insured):	SKV973X	Policy No. (Claimant):							
		Excess:							
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/11/2018]								
Driver/Custodian (Insured):	Ee Huei Wuan (30 / Female), NRIC: S2511788C								
Adj Asg. Remarks:	on WP. SJE Disagree Please appoint LKK and contact Mr. Bernard (Tel.: 6456-0226 / 9101-8302). Liability is not clear.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (31/10/2018): Report Send Back Alerts - GBC7929K (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC7929K (566514)
[SKV973X]
TP
NPN ENGINEERING
Aug 4 2018 5:00PM
[Ee Huei Wuan]
E M Solution Pte Ltd


[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	07/08/18 09:05	Accident Statement <small>From: SC - Reg. No: SKV973X, Claimant: EE HUEI WUAN</small>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
2	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
3	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
4	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
5	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
6	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
7	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
8	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
9	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
10	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
11	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
12	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
13	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
14	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
15	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
16	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
17	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
18	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
19	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
20	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
21	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
22	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
23	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
24	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
25	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>
26	18/08/18 11:08	General View	Load JPG		<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	07/08/18 09:09	Third Party Accident Report	Load PDF		
2	07/08/18 10:02	SJE DISAGREE LKK	Load PDF		
3	30/10/18 11:35	COLOURED IMAGES	Load PDF		
4	31/10/18 10:17	SURVEY REPORT	Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	15/11/18 16:09	PRS Invoice	Load PDF		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
2	15/11/18 16:09	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014447/GVBE2-1

Date: 15/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28607381AVW

Claimant Vehicle No : GBC7929K

Insured Vehicle No : SKV973X

Date of Loss: 04/08/2018

Nature of Claim: TP

Claim No: 566514

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC7929K**

Make & Model: NISSAN NV350, 2.5 D Panel Van (M)

Engine No: YD25337031A

Reg. Date: 11/11/2013 (Man. Year: 2013)

Chassis No: JN1MC2E26Z0001377

Colour: Silver

Odometer: 140605 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,583.66	3,727.44	2,856.22	43.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	1,420.00	1,490.00	51.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,493.66	5,147.44	4,346.22	45.78
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	9,493.66	4,100.00	5,393.66	56.81
+ GST 7.00/7.00% (S\$)	664.56	287.00	377.56	56.81
Nett Amount (S\$)	10,158.22	4,387.00	5,771.22	56.81

INSPECTION

Date of Assignment: 07/08/2018

Date Inspected: 13/08/2018 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive,, #03-18, Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Nov 2018)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7929K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,140.40 FL	*1,742.00 FL
2	1		*REAR TAILGATE OUTER MOULDING	Serviceable	350.70 FL	*- FL
3	1		*REAR BUMPER	Dented	683.60 FL	*683.60 FL
4	1		*REAR STEP PANEL	Dented	361.50 FL	*192.60 FL
5	1		*REAR END PANEL	Repair	424.80 FL	*- FL
6	1		*REAR END PANEL INNER MEMBER	Repair	481.60 FL	*- FL
7	1		*REAR END PANEL TOP MOULDING	Bent	55.30 FL	*55.30 FL
8	1		*REAR TAILGATE EMBLEM NISSAN	Necessary	68.60 FL	*68.60 FL
9	1		*REAR TAILGATE EMBLEM NV350	Necessary	68.60 FL	*68.60 FL
10	1		*REAR TAILGATE EMBLEM URVAN	Necessary	52.70 FL	*52.70 FL
11	1		*REAR TAILGATE INNER LOCK	Not Necessary	266.10 FL	*- FL
12	1		*REAR TAILGATE INNER LOCK COVER	Dented	31.25 FL	*31.25 FL
13	1		*REAR TAILGATE INNER LOCK ACTUATOR	Dented	246.20 FL	*246.20 FL
14	1		*REAR TAILGATE WEATHERSTRIP	Cut	105.20 FL	*105.20 FL
15	2		*REAR TAILGATE DAMPER	Serviceable	371.20 FL	*- FL
16	2		*REAR TAILGATE SIDE STOPPER	Not Necessary	84.40 FL	*- FL
17	2		*REAR TAILLAMP	Broken	563.20 FL	*419.60 FL
18	1		*REAR SPARE WHEEL CARRIER	Serviceable	266.50 FL	*- FL
19	1		*REAR SPARE WHEEL HOLDER	Serviceable	89.60 FL	*- FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	70.40 FL	*70.40 FL
21	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
22	1		*SET REAR WINDSCREEEN FOAM TAPE	Necessary	60.00 FS	*45.00 FS
23	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
24	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*REAR STICKER 70KM/H	Necessary	15.00 FS	*15.00 FS
26	1		*REAR STICKER 11PAX	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,261.85	4,101.05
- List Item Discount on L Items 10.00/10.00% (S\$)	678.19	373.61
Total Parts (S\$)	6,583.66	3,727.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX REAR WINDSCREEN GLASS	New	180.00	80.00
2	TO CHECKUP REAR ELECTRICAL WIRING	New	50.00	20.00
3	TO REMOVE, REFIX REVERSE SENSOR	New	80.00	60.00
4	TO RESPRAY UNDERCOATING	New	100.00	60.00
5	TO RESPRAY PAINTING & ETC	New	1,200.00	600.00
6	PANEL BEATING, REMOVE & REPLACING ABOVE PARTS	New	1,300.00	600.00
Gross Labour Cost (\$\$)			2,910.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >