

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

EQ

VEHICLE NO : SHC 8764R

DATE 31/10/2018 14:57

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Revised</i>			\$ 544.50
	Front Bumper Bracket Top (LH) <i>Revised</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>Revised</i>			\$ 24.60
	Headlamp (LH) <i>Revised</i>			\$ 1,388.00
	Front Fender (LH) <i>Revised</i>			\$ 566.30
	Front Fender Shield (LH) <i>Revised</i>			\$ 175.90
	Front Fender Retainer <i>Revised</i>			\$ 24.60
	SUB TOTAL			\$ 2,746.30
	LESS 20%			\$ 549.26
	DISCOUNTED TOTAL			\$ 2,197.04
	Front Fender Advertisement Logo (LH) <i>Revised</i>			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00 400
	Wiring			\$ 30.00 20
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,080.00
	ESTIMATE TOTAL			\$ 3,377.04

Ka lah (LH)

31/10/18 1520 hr

2 DYS

PIP

Before Paint photo

KK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.