



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005142
INV Date 22/07/2020
Reference CC3/CTI18019889/Kka3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9365Y
Insured Veh. GBH 7680A
Claim No. SNM18D05173C02/0
Policy No. DMCVSN1831401800
Accident Date 30/10/2018
Inspection Date 31/10/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18019889/Kka3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 7680A	Veh. Inspected	SHD 9365Y
Policy No.	DMCVSN1831401800	Coverage (\$)	0.00
Claim No.	SNM18D05173C02/0	Excess (\$)	0.00
Assign From		Assign Date	31/10/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB071750	Colour	WHITE / RED
Odometer	526196	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	GITI	7 mm
L/H Front Tyre	195/65R15	GITI	7 mm
R/H Rear Tyre	195/65R15	GITI	8 mm
L/H Rear Tyre	195/65R15	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/10/2018	Inspection Date	31/10/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9365Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR END PANEL OUTER	BUCKLED	623.76	623.76
1	REAR END PANEL INNER TRIM	SERVICEABLE	263.84	-
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	344.28	-
1	BOOTLID LOCK - TOP	DENTED	466.56	466.56
1	BOOTLID 'CHEVROLET' BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID 'EPICA LT' BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	CRACKED	128.40	128.40
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	REAR TAIL LAMP RH	MTG CRACKED	479.30	479.30
1	REAR TAIL LAMP LH	CRACKED	479.30	479.30
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-

Report Ref No. CC3/CTI18019889/Kka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,270.74	-516.87
			11,436.69	4,651.85
	<u>SPECIAL NETT ITEMS</u>			
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	300.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	300.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
			1,390.74	104.00
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR LUGGAGE FLOOR PANEL, REAR EXHAUST BOX (MUFFLER A-EXH,RR), REAR FENDER RH AND REAR FENDER LH.		3,000.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00

Report Ref No. CC3/CTI18019889/Kka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,450.00	1,460.00
GRAND TOTAL			20,277.43	6,215.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CC3/CT118019889/Kka3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.