REF: CS/TP1801	7913/Ktbez
St., REC, BY. ASSI	GNMENT 399/9000
inneth	Veh No: SIAD 50801 Yr Regn: 9 , 900
From: Date	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi? Prime Mover /
Estimated Cost:	
OD TOP I WS I TP RES I OD RES I EVA I INV I MV	Truck / Trailer or
To Inspect Vehicle No:	Make: 707 Wish c.c 1794
at Workshop m/s . Tray Cob	Colour While Red A/C: Insured / Std / NI / NA
of	Sp.Reading 577548 T/Radio: Insured / Std / NI / NA
insured:	Eng/No:
Policy No.	C/No: JTD ER 12W803C03187
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt for
Make of Veh:	Modi: MiL S/Rim / STD A/Rim or
8	Tyre Size: F: 775/70/14
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or /Eillen
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6
Est. Repairs: 04 days Res.: Yes or No	D.O.A. 7/5/19 D.O.I. 7/5/19
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collisi
Date / Time Action / Instruction	Kenio 2 DA: 05/213 No Resurvey
SAD 509 CR - CC3/AL6/3023354/	K5039 2 004:05/213 NO RESULVED
1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1212.741 (70/0) many
lump Sum \$38007 (Red	1200.01,010
	0040
RECEIV	VED 1 5 NOV 2818 VI4/11/2
Billing first then report	
June 31-	
(6)	
Date/Time, File Pass to? Date/Time, File Return to?	Survey Fee: Date:
1) 14[11 Typ18T 2)	TOTAL Basic & Add. 170+15
3) 4)	LOSSS+RS,SI5()
5) 6) .	Photos 12
J	KIV FOR Others 80

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	07/05/2014 09:55	
Date Of Accident	07/05/2014 06:30	
Exact Location Of Accident	PIE TO JURONG	
Country/State of Loss	Singapore	

DETA	LS	OF	OWN	V VE	ΞHI	CL	=

Vehicle Registration Number SHD5090R

Insured/Policyholder

Name Of Registered Owner TRANS-CAB SERVICES PTE LTD

Co Reg No 200303878K

Vehicle Particulars

Manufacturer TOYOTA

Model WISH-1.8 (A)

Exact Purpose for which vehicle was being used

at time of accident

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

No

Vehicle Category Taxi

Insurance Company

Name of Insurance Company First Capital Insurance Ltd

Type Of Coverage Third Party
Fleet Policy Yes

Policy Number D-12047359MFSH/

Cover Note Number

Driver

 Name of Driver
 HENG JING ZEE

 NRIC No
 \$1297594E

 Date Of Birth
 05/12/1957

 Occupation
 Outdoor

Date Of Driving Pass 24/08/1976

Driving Experience 37 Years And 8 Months

Gender Mal

Mobile Number (Local) +65-92227873

Fax Number Contact Number

EMail Address NOEMAIL

Address 61 CLOVER CRESCENT

Postcode 579222

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured

ured Other - RELIEF

Vehicle Registration Number of Driver's Own

=

Vehicle

Insurance Company of Driver's Own Vehicle

=

General Information of the Accident

Type Of Accident

Collision- Chain Collision

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident?

No

Was any body injured in the Accident?

No

Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

No

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

ON 07.05.2014 AT ABOUT 0630HRS, I WAS DRIVING STRAIGHT ALONG PIE HEADING TOWARDS JURONG. WHILE TRAVELLING, THE VEHICLE WHICH WAS IN FRONT OF ME HAD JAMMED BRAKE TO STOP. SO, I FOLLOWED SUIT. WHILE STATIONARY, I SUDDENLY FELT AN IMPACT FROM BEHIND. AFTER ALIGHTING FROM MY TAXI, I REALIZED THAT IT WAS A CHAIN COLLISION INVOLVING TOTAL OF 4 VEHICLES. I ONLY MANAGE TO GET THE VEHICLE NUMBER OF THE TAXI WHICH COLLIDED INTO MY TAXI (VEHICLE B - SH9308L). VEHICLE A - 1 PASSENGER VEHICLE B - NOT AWARE VEHICLE C - NOT AWARE VEHICLE D - NOT AWARE

Are accident photos available for attachment?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SH9308L

Vehicle Make/Model/Colour

COMFORT - SONATA

Details Of Properties

Name of Driver

LAM CHEE SOON

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

ANNE VALEIE

Phone Number Email Address

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan			
	18 AC	<u> </u>	
	E To Jurong	<u>←</u> ←	A: SHDEOGOR B: SH9308L C: Unknown b: Unknown
Describe Circumstances of	the Accident		
	Acter to	514 ROPE	n4·
Declaration			
I/We declare the foregoing particul	ars are true in every respect.		
	Xtfa	0.7 MAY 2014	Andrea
Poscytoider's Signature / Date & Time	Driver's Signature (If driver	r is not the policyholder) / Date	Witnessed by Reporting Centre Personnel

Accident Photo








Accident Photo













Accident Photo





NO.42 EUR TEL NO 62 CO/GST R	CAB AUTO SERVCIES PTE LTD NGEI KADUT :STEET 1 SINGAPORE 729346 87 6666 F'AX NO.6366 8862 EG NO.20101 3626G	Not Sorp &	Andrea 3800k
SHD 5)9	OR - FCIL		
	Vehicle IVo.: Chassis No.: Vehicle I Make: Vehicle I Model: Date of Nocident: Third Party Insurer:	JTDER1 TOYOTA	B BI-FUEL
	PART		LIST
1 1 2 1 3 1 4 1 5 1 10 1 11 1 1 1 1 1 1 1 1 1 1 1 1 1	Rear Bumper Rear Bumper Side Retainer RH Rear Bumper Bracket RH Rear Bumper Reflectors RH Rear Bumper Side Retainer LH Rear Bumper Bracket LH Rear Bumper Reflectors LH Rear Bumper Reflectors LH Rear End Panel Outer Rear End Panel Inner Trim Rear End Panel Inner Tailgate Lid Tailgate Lid Centre 'TOYOTA' Logo Be Tailgate Lid Weatherstrip Tailgate Lid Lock - Top Tailgate Lid lock - bottom Tailgate Lid Outer Chrome Garnish Rear Lamp RH	\$	\$\int_{487.80} \\ \text{Sh} 57.30 \times \\ \text{Sh} 57.30 \times \\ \text{Sh} 57.30 \times \\ \text{Sh} 57.30 \times \\ \text{N} 90.00 \times \\ \text{N} 57.30 \times \\ \text{N} 90.00 \times \\ \text{Sh} 55.00 \times \\ \text{N} 55.00 \times \\ \text{N} 519.80 \\ \text{N} 219.87 \\ \text{N} 280.70 \\ \text{N} 1,233.70 \\ \text{N} 1,233.70 \\ \text{N} 1286.90 \text{50 \text{Sh}} \text{N} 388.80 \times \\ \text{N} 388.80 \times \\ \text{N} 32.83 \times \\ \text{N} 214.50 \times \\ \text{N} 510 496.43 \times \\ \text{N} 510 496.43 \times \\ \text{N} 510 \times 496.43 \\ \text{N} 510 \times 496.43 \times \\ \text{N} 510 \times 496.43
18 1	Rear Lamp LH	* TOTAL	5,130.36 1,282.59 3,847.77
	Specical Nett		
1 Se 1 Se	t Rear Bumper Fastener Clip t Rear Bumper Parking Sensor CNG Sticker t Tailgate Lid Inner Trim Board Clip t Rear Encl Panel Inner Trim Clip Rear Wir dscreen Sealant Rear Wir dscreen Inner Sponge Seal Tailgate 'id inner handle	\$\$\$\$\$\$\$\$	Mer 30.00 Src 300.00 X Ner 15.00 N 18.00 X Ner 30.00 Ner 80.00 405N Ner 60.00 305N Src 17.47 X

TRANS-CAB AUTO SERVCIES PTE LTD NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346 TEL NO 6287 6666 FAX NO.6366 8862 CO/GST REG NO.201013626G SHD 5/990R - FCIL		Andrea
I Rear Tailgate Sticker "Trans-cab "	\$	NE 30.00 -
1 Tailgate Sticker "Tans-link"	\$	30.00
1 Tailgate Sticker "6555-3333"	\$	30.00
1 Rear Bumper Advertisement Sticker	\$	Ma 150.00 10011
Tailgate Advertisement Sticker	\$	New 250.00 1505A-
TOTAL	\$	1,040.47
TOTAL DADTO		4 000 04
TOTAL PARTS	s <u>\$</u>	4,888.24
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal		
Of Parts, Adjust And Realign The Same	\$	2,800.00 606
To Rust-j ² roofing Of The Affected Areas.	\$	200.00 601
To Check: Electrical Lighting Concerned.	\$	120.00 201
Putty And Spray Painting Of The Affected Portion	\$	2,700.00 600
To Reins'all Rear Bumper Parking Sensor.	\$	170.00 50l
To Remove And Refit Rear W/screen Glass To Facilitate Bodywork Repair.	\$	170.00/20
To Transfer Of Tailgate Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 601
To remove and replace corporate sticker	\$	330.00 501
To Reseal Sealant On Gap	\$	120.00 301
TOTAL	\$	6,780,00
Over All Total	\$	11,668.24
REPAIR DAYS	10-DAYS	
	, -	*



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interr	nationale Des Experts En Autor	nobile
TRA	NS-CAB AUTO SE	ERVICES PTE LTD	Ref : CS/TP1801991	13/Ktbe2
NO.	2 ANG MO KIO ST	REET 63SINGAPORE 569	111 Date: 07-12-2018 Code: TP378	
1.		Policy Particula	ars :- THIRD PARTY CLA	IM
	Insured Veh.		Veh. Inspected	SHD 5090R
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	07/05/2014
2.		Vehicle Pa	articulars & Condition	
	Make & Model	TOYOTA WISH (A)	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTDER12W803003147	Colour	WHITE / RED
	Odometer	577548	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	FALKEN	6 mm
	L/H Front Tyre	175/70 R14	FALKEN	6 mm
	R/H Rear Tyre	175/70 R14	FALKEN	6 mm
	L/H Rear Tyre	175/70 R14	FALKEN	6 mm
4.		Descri	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	07/05/2014	Inspection Date	07/05/2014
	Survey held at	TRANS-CAB AUTO SERVIC	ES PTE LTD	
		58 DEFU LANE 1 SINGAPORE 539498		
5a.			Remarks	
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		

Estimate Days of Repair

4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5090R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BENT	487.80	487.80
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	57.30	
1	REAR BUMPER BRACKET RH	BENT	90.00	90.00
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	55.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	57.30	i.=
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	90.00	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	55.00	Let
1	REAR END PANEL OUTER	BENT	519.80	519.80
1	REAR END PANEL INNER TRIM	DENTED	219.87	219.87
1	REAR END PANEL INNER	BENT	280.70	280.70
1	TAILGATE LID	BENT	1,233.70	1,233.70
1	TAILGATE LID CENTRE 'TOYOTA' LOGO BADGE	NECESSARY	68.00	68.00
1	TAILGATE LID LOCK - TOP	TO REPAIR SEE LABOUR	388.80	
1	TAILGATE LID LOCK - BOTTOM	TO REPAIR SEE LABOUR	32.83	
1	TAILGATE LID OUTER CHROME GARNISH	SERVICEABLE	214.50	-
1	REAR LAMP RH	MTG CRACKED	496.43	496.43
1	REAR LAMP LH	SERVICEABLE	496.43	-
	LESS 25% DISCOUNT		-1,210.87	-849.08
			3,632.59	2,547.22
1	TAILGATE LID WEATHERSTRIP (SN) (50%)	сит	286.90	143.45
	LESS 25% DISCOUNT		-71.73	
			215.17	143.45
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	30.00	30.00
	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	300.00	-
1	CNG STICKER (SN)	NECESSARY	15.00	15.00
	SET TAILGATE LID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	18.00	
	SET REAR END PANEL INNER TRIM CLIP (SN)	NECESSARY	30.00	30.00
	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	60.00	100000000000000000000000000000000000000

Report Ref No. CS/TP18019913/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE LID INNER HANDLE (SN)	SERVICEABLE	17.47	15
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	TAILGATE STICKER "TANS-LINK" (SN)	NECESSARY	30.00	30.00
1	TAILGATE STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	150.00	100.00
1	TAILGATE ADVERTISEMENT STICKER (SN)	NECESSARY	250.00	150.00
			1,040.47	485.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE		2,800.00	600.00
	OF THE REPAIR OF REAR BUMPER BRACKET LH, TAILGATE LID LOCK - TOP AND TAILGATE LID LOCK - BOTTOM.			
	TO RUST-PROOFING OF THE AFFECTED AREAS.		200.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	600.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REPLACE CORPORATE STICKER.		330.00	50.00
	TO RESEAL SEALANT ON GAP.		120.00	30.00
		=	6,780.00	1,590.00
	GRAND TOTAL		11,668.23	4,765.67
	RECOMMENDED COST OF LUMP SUM REPAIRS			3,800.00

Report Ref No. CS/TP18019913/Ktbe2

KONG SENG CHEONG

(TO ITS PRE-ACCIDENT CONDITION)

Licensed Appraiser