

ASS. REC. BY:

REF: CS/FCI18019919/Kqd3 112

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Luvene jaw

of FCI

Date/Time: 01/11/18 @ 7:30pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 424U

Insured: SHA 02232

at Workshop m/s: Transcab

Tel: 6287 6666

of No. 2 Amk St-63

Policy No:

Claim No: D18007799mpct

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 26/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 9-17am @ 2/11/18

Person Contacted: Amanda

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 424U - X
	SHA 02232 - X
05/11/18 @ 2:29pm	revised to Luvene by email.

ASSIGNMENT

From: _____ Date: 2/11/2018
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SHD 4244
 at Workshop m/s Transcab
 of No. 2 AMK st. 63
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHD 4244 Yr Regn: 12 16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Renault Latitude C.C. 1995
 Colour M. White / Red A/C: Insured / Std / NI / NA
 Sp. Reading 221788 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VIFI ABC 15AUC 283445
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: NI S/Rim / STD A/Rim or _____
 Tyre Size: F: Giti 215/60R16
 R: G7 _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lum Sum: 1.311 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front 8 mm R/Bal. 6 mm
 L/Bal. 8 mm L/Bal. 6 mm
 D.O.A. 26/10/18 D.O.I. 2/11/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>5/11</u>	<u>File pass to Catherine</u>
	<u>4185.19 (Red @ 45250.36, 92%)</u>
RECEIVED 5 NOV 2018	

Date/Time, File Pass to? : Preli. Report
 1) 05/11 trans : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format : TR
 Lump Sum / I.B.I. (\$) 4185.19
 Days Of Repair: 3
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
 Survey Fee: 39x15=585
 Transportation: 50
 S + RS + ST 580
 Photos 17
 Others 050
TOTAL 822



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007799MFSH

Date: 05 November 2018

Our Ref: CS/FCI18019919/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 424U

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/11/2018 at the premises of M/s TRANSCAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>49,435.55</u>
Revised Estimate Amount	: S\$ <u>4,185.19</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the o/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-10-2018	Our Ref No. D18007799MFSH
Accident Date	26-10-2018	Claim Type. Third Party
Insured Vehicle	SHA0223Z	Third Party Vehicle. SHD424U
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 5 November 2018 2:29 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007799MFSH/1
Attachments: CSFCI18019919Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHD 424U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 2 November 2018 8:43 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007799MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 1 November 2018 7:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007799MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD424U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003228
Chassis No.:	VF1ABL15AUC283445
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	27 Dec 2016
First Registration Date:	27 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$41,017.00
COE Rebate Amount:	\$31,562.00
Total Rebate Amount:	\$46,560.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Oct 2018.

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 424U

AAD1810-280

Not Authored

Recovery B4 point

\$ 4485.19

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 424U
VF1ABL15AUC283445
RENAULT
LATITUDE
26.10.18
FIRST CAPITAL

PART		LIST	
1	1 BUMPER COVER FRT	\$	R 1,259.42
2	1 BUMPER SPOILER FRT	\$	Sm 181.75
3	1 BUMPER ABSORBER FRT	\$	Sm 394.68
4	1 BUMPER SUPPORT FRT	\$	Sm 123.88
5	1 BUMPER RETAINER FRT RH	\$	Sm 150.77
6	1 BUMPER SUPPORT FRT	\$	Sm 123.88
7	1 BUMPER UNDERTRAY FRT	\$	Sm 472.83
8	1 BUMPER GRILLE LOWER FRT	\$	Sm 266.80
9	1 BUMPER FOG LAMP GRILLE RH	\$	Sm 207.21
10	1 BUMPER BEAM FRT	\$	R 914.08
11	1 TOW COVER FRT	\$	Sm 28.61
12	1 FRONT BRACE PANEL	\$	R 177.22
13	1 HEADLAMP RH	\$	Sm 1,184.43
14	1 HEADLAMP PANEL FRT RH	\$	R 152.15
15	1 FENDER PANEL FRT RH	\$	R 783.83
16	1 WHEELARCH FRT RH	\$	Sm 278.84
17	1 FENDER BRACKET LOWER RH	\$	Sm 15.79
18	1 FENDER INSULATOR RH	\$	Sm 130.84
19	1 DOOR PANEL FRT RH	\$	<i>Red/way</i> 2,844.66
20	1 DOOR HINGE UPPER RH	\$	R 261.28
21	1 DOOR HINGE LOWER RH	\$	R 300.55
22	1 DOOR CHECK FRT RH	\$	R 194.77
23	1 DOOR LOCK FRT RH	\$	R 908.75
24	1 DOOR CATCH FRT RH	\$	R 131.23
25	1 DOOR HANDLE OUTER FRT RH	\$	R 477.76
26	1 DOOR HANDLE COVER FRT RH	\$	Sm 13.22
27	1 DOOR HANDLE MODULE FRT RH	\$	Sm 133.60
28	1 DOOR REGULATOR FRT RH	\$	R 505.19

X

X

Trans-cab Auto Services Pte Ltd

AAD1810-280

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 424U

29	1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
30	1	DOOR REGULATOR GUIDE FRT RH	\$	120.97
31	1	DOOR PANEL REAR RH	\$	2,844.66
32	1	DOOR GUIDE REAR RH	\$	176.82
33	1	DOOR HINGE UPPER RH	\$	274.50
34	1	DOOR HINGE LOWER RH	\$	300.55
35	1	DOOR CHECK REAR RH	\$	203.06
36	1	DOOR LOCK REAR RH	\$	908.75
37	1	DOOR HANDLE OUTER REAR RH	\$	126.49
38	1	DOOR HANDLE CAP REAR RH	\$	35.52
39	1	DOOR HANDLE SEAL REAR RH	\$	7.89
40	1	DOOR HANDLE COVER REAR RH	\$	13.22
41	1	DOOR HANDLE MODULE REAR RH	\$	133.60
42	1	DOOR REGULATOR REAR RH	\$	1,135.10
43	1	DOOR REGULATOR MOTOR REAR RH	\$	893.75
44	1	DOOR REGULATOR NUT REAR RH	\$	12.43
45	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
46	1	DOOR FINISHER REAR RH	\$	423.10
47	1	DOOR MOULDING REAR RH	\$	176.82
48	1	DOOR MOULDING CLIP L70Y	\$	5.92
49	1	DOOR MOULDING SCREW L70Y	\$	6.91
50	1	DOOR CASING REAR RH	\$	1,509.06
51	1	DOOR WATER SHIELD REAR RH	\$	30.39
52	1	DOOR CASING CLIP	\$	12.63
53	1	DOOR CASING LIGHT L70Y	\$	48.74
54	1	DOOR FINISHER INNER REAR RH	\$	323.44
55	1	DOOR FINISHER BRACKET INNER REAR RH	\$	46.97
56	1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
57	1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
58	1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
59	1	DOOR GRAB HANDLE REAR RH	\$	210.96
60	1	DOOR BLIND REAR RH	\$	741.80
61	1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
62	1	DOOR SEAL REAR RH	\$	162.02
63	1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31
64	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
65	1	DOOR WAIST SEAL INNER REAR RH	\$	115.64
66	1	DOOR MIRROR ASSY RH	\$	1,483.40

X

Trans-cab Auto Services Pte Ltd

AAD1810-280

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 424U

67	1	ROCKER PANEL INNER GARNISH RH	\$	Sn	466.51	} X
68	1	ROCKER PANEL INNER RH	\$	n	1,024.79	
69	1	ROCKER PANEL CENTER RH	\$	n	990.25	
70	1	ROCKER PANEL OUTER RH	\$	n	1,184.99	
71	1	FENDER PANEL REAR RH	\$	n	3,299.13	
72	1	FENDER PANEL INNER TRIM REAR	\$	Sn	671.45	
73	1	WHEELARCH REAR RH	\$	Sn	543.47	
74	1	BUMPER COVER REAR	\$	n	1,108.46	
75	1	BUMPER LOWER REAR	\$	Sn	768.84	
76	1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	
77	1	BUMPER BRACKET SIDE RH REAR	\$	Sn	135.97	
78	1	BUMPER RETAINER RH REAR	\$	Sn	44.99	
79	1	BUMPER BEAM REAR	\$	n	777.52	
80	1	BUMPER BEAM BRACKET RH REAR	\$	n	225.95	

TOTAL	\$	38,297.35
10%	\$	3,829.74
	\$	34,467.62

Special Nett

1	1	BUMPER CLIP FRT	\$	nn	66.00	} X	
2	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00		
3	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50		
4	1	TOW COVER FRT	\$	Sn	14.50		
5	1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
6	1	Windscreen Moulding	\$	nn	120.00		
7	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	} X	
8	1	WINDSCREEN SEALANT	\$	nn	253.80		
9	1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00		60sn
10	1	FRONT DOOR STICKER 'Classic'	\$	nn	50.00		15sn
11	1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00		60sn
12	1	DOOR CHECK BOLT	\$	Sn	22.69		
13	1	DOOR GUIDE SCREW	\$	Sn	10.85		
14	1	DOOR HINGE BOLT	\$	Sn	10.85		
15	1	DOOR HINGE NUT RH	\$	Sn	14.60		
16	1	DOOR CHECK BOLT	\$	Sn	22.69		

Trans-cab Auto Services Pte Ltd

AAD1810-280

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 424U

17	1	DOOR CHECK NUT	\$	SH	3.75	}
18	1	DOOR LOCK SCREW L70Y	\$	SH	6.12	
19	1	DOOR CATCH SCREW L70Y	\$	SH	10.06	
20	1	WHEELARCH CLIP FRT RH	\$	~	30.50	
21	1SET	REAR BUMPER CLIP	\$	~	66.00	
22	1SET	BUMPER BRACKET CTR CLIP	\$	~	33.00	
23	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	~	10.00	
24	1SET	BUMPER RETAINER RH CLIP RR	\$	~	20.00	
25	1SET	BUMPER LOWER REAR RIVET	\$	~	22.00	
26	1SET	BUMPER LOWER REAR CLIP	\$	~	66.00	
27	1SET	FENDER WHEELARCH REAR RH CLIP	\$	~	35.00	
28	1	FENDER INNER TRIM CLIP RH	\$	~	28.00	

TOTAL	\$	1,267.93	91
--------------	-----------	-----------------	----

TOTAL PARTS	\$	35,735.55
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	5001
Putty and spray painting of the affected portion.	\$	4,500.00	8801
To rust-proofing of the affected areas.	\$	170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~	380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	~	380.00 X
To check steering geometry and computer wheel alignment	\$	~	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1810-280

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 424U

To Check Electrical Lighting Concerned.	\$	201 170.00
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00 601
To transfer of Front bumper fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of Front fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of front windscreen fittings and conduct water seepage test	\$	~ 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00 X
TOTAL	\$	13,700.00

Over All Total \$ 49,435.55

Repair Days (PART BY PART)

15 DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No. of days for repair is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Agreement by Repairer:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18019919/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 223Z	Veh. Inspected	SHD 424U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007799MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	01/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC283445	Colour	METALLIC WHITE / RED	
Odometer	221788	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	6 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2018	Inspection Date	02/11/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 424U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	DENTED / WARPED	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	TO REPAIR SEE LABOUR	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-

Report Ref No. CS/FC118019919/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE OUTER FRT RH	TO REPAIR SEE LABOUR	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	TO REPAIR SEE LABOUR	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR RH	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-

Report Ref No. CS/FCI18019919/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	SERVICEABLE	115.64	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-

Report Ref No. CS/FCI18019919/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
	LESS 10% DISCOUNT		-3,829.73	-284.47
			34,467.61	2,560.19
	<u>SPECIAL NETT ITEMS</u>			
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH 9SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CLASSIC" (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-

Report Ref No. CS/FC118019919/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
			1,267.91	135.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT, BUMPER BEAM FRT, FRONT BRACE PANEL, HEADLAMP PANEL FRT RH. }		4,500.00	500.00
	FENDER PANEL FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR CHECK FRT RH, DOOR LOCK FRT RH, DOOR CATCH FRT RH, DOOR HANDLE OUTER FRT RH, DOOR REGULATOR FRT RH, DOOR PANEL REAR RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR CHECK REAR RH, DOOR LOCK REAR RH, DOOR FINISHER BRACKET INNER REAR RH, ROCKER PANEL INNER RH, ROCKER PANEL CENTER RH, ROCKER PANEL OUTER RH, FENDER PANEL REAR RH, BUMPER COVER REAR, BUMPER BEAM REAR AND BUMPER BEAM BRACKET RH REAR. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			13,700.00	1,490.00
	GRAND TOTAL		49,435.52	4,185.19
RECOMMENDED COST OF REPAIRS				4,185.19

Report Ref No. CS/FC118019919/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.