

ASS. REC. BY:

REF:

REF: CS/SPF18019926 /Ngbez

Special instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Lim Wa Yeg of SPF Date/Time: 31.10.2018 10:16pm

Estimated Cost: _____ Bill to: _____

(OD) / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: QX 4834G Insured:

at Workshop m/s SMRT Tel: _____

of 60 woodland Inl Parks £4

Policy No: _____ Claim No: HUM SP FETA 16000399

Sum Insured: _____ Excess: _____

Make of Veh: DOA

(Client's Record)

CA / ~~REV~~ / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT _____

Person Contacted:

Vehicle IN/OUT

[illegible]

REF:

Surveyor:

NAZ

SPF

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: QX 4834 G Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HIACE C.G. - _____Colour: SILVER A/C: Insured / Std / NI / NASp. Reading: BATT. FLAT T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R 14C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 5 mmL/Bal. 6 mm L/Bal. 5 mmD.O.A. _____ D.O.I. 7/11/18Survey held at KNS Bodywork EngineeringDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Roof or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Materials - \$9812.42 (Exclude check items SPF
\$964)

RECEIVED 14 DEC 2018

Date/Time, File Pass to?

14/12/18

1) Typ. S1
Date/Time, File Return to?

2) _____

☐ : Prelim Report☒ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

200
200

Shirley Hiew (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Friday, 14 December 2018 3:12 PM
To: Shirley Hiew (LKK Auto)
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); assignments; Admin-D (LKKAuto); SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Hi Shirley,

Please proceed to close this and submit the report.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 December 2018 11:44
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Dear Wei Yea,

Please advise whether can we submit our report of QX 4834G accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 30 November 2018 10:59 AM
To: 'Wei Yea LIM (SPF)' <LIM Wei Yea@spf.gov.sg>
Cc: 'Kim Pang CHAY (SPF)' <CHAY Kim Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN Kwee Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG Peng Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid Abu Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Dear Wei Yea,

Please advise whether can we submit our report of QX 4834G accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 21 November 2018 9:42 AM
To: 'Wei Yea LIM (SPF)' <LIM Wei Yea@spf.gov.sg>
Cc: 'Kim Pang CHAY (SPF)' <CHAY Kim Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN Kwee Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG Peng Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid Abu Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

RE-SEND

Dear Wei Yea,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 21 November 2018 9:33 AM
To: 'Wei Yea LIM (SPF)' <LIM Wei Yea@spf.gov.sg>
Cc: 'Kim Pang CHAY (SPF)' <CHAY Kim Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN Kwee Huat@spf.gov.sg>;

'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; 'assignments' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Dear Wei Yea,

Please refer attached.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]

Sent: Monday, 19 November 2018 10:03 AM

To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Dear Wei Yea,

Thank you for your email.

Dear Shirley,

FYNA. Our Ref: CS/SPF18019926/Nsb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]

Sent: Monday, 19 November, 2018 9:47 AM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Hi Catherine,

May I check if there is an update on this appraisal?
Do let me know if there is any obstacle faced with SMRT side.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Wei Yea LIM (SPF)
Sent: Wednesday, 31 October 2018 22:16
To: 'assignments' <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX4834G

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 31 October, 2018 10:16 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)
Attachments: QX4834G.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX4834G

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

Reference No.
4834/SPF/4W/18/09/30
1100011637

~~/CRK~~
~~/NE~~
~~/DEF~~
~~/OD~~
~~/BT~~
✓ /MLJ
✓ MLJ
~~/RK~~ LH
~~/LGF~~ LH
✓ MLJ
~~/DEF~~
x RH OD
LH?

x LH N
RH ✓
punct

8
6
1
2
6
8
22
14
2
23
4

CVR Accident Photos

VEHICLE DETAIL

Vehicle No	QX 4834 G	Date Of accident	
Date Booked In		Date of Submission	


REPAIR DESCRIPTIONS

1. Remove & replace front wind screen (pic 1,2)
2. Replace front wind screen moulding (pic 1,2)
3. Remove & replace front panel (pic 3)
4. Remove & replace radiator grill (pic 4)
5. Remove & replace L/H head lamp housing (pic 5)
6. Remove & replace R/H head lamp & housing (pic 6)
7. Remove & replace front bumper (pic 7)
8. Remove & replace R/H fender (pic 8)
9. Remove & replace R/H fender inner panel (pic 9)
10. Remove & replace front bumper support (pic 10)
11. Repair & align cross member (pic 11)
12. Remove & re-install dash board (pic 12,13)
13. Repair & align dash board frame (pic 12,13)
14. Cut , weld & align wind screen pillar (pic 14)
15. Remove & replace driver door complete assy (pic 15)
16. Cut , weld & align driver floor board (pic 16)
17. Remove & replace R/H window assy (pic 17)
18. Cut , remove & replace R/H panel (pic 18,19)
19. Remove & replace rear R/H tyre & rim (pic 20)
20. Remove & replace front R/H tyre & rim (pic 21)
21. Remove & replace R/H lower arm (pic 22)
22. Remove & replace R/H absorber (pic 23)
23. Remove & replace R/H upper arm (pic 24)
24. Remove & replace rear bumper (pic 25)
25. Cut , weld & repair rear cabin floor board (pic 26)

PHOTOS OF DAMAGED PARTS

Wind screen shattered (pic 1)	Wind screen shattered (pic 2)
	
Front panel dented (pic 3)	Radiator grill crack (pic 4)
	

CVR Accident Photos

	
R/H panel dented (pic 19)	Rear R/H tyre & rim dented (pic 20)
	
Front R/H tyre & rim dented (pic 21)	R/H lower arm dented (pic 22)
	
R/H absorber dented (pic 23)	R/H upper arm dented (pic 24)
	
Rear bumper dented (pic 25)	Rear cabin floor board dented (pic 26)
	
QX 4384 G	
	

Registration No. QX 4834G

S/N	ITEM DESCRIPTION	PARTS			MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP
1	MATERIALS				
1.1	FRONT WIND SCREEN	1	CRACKED	\$ 375.00	\$ 375.00
1.2	WIND SCREEN MOULDING	1	NECESSARY	\$ 120.00	\$ 120.00
1.3	FRONT PANEL	1	DEFORMED	\$ 625.00	\$ 625.00
1.4	RADIATOR GRILLE	1	DENTED	\$ 250.00	\$ 250.00
1.5	L/H HEAD LAMP HOUSING	1	BENT	\$ 88.00	\$ 88.00
1.6	R/H HEAD LAMP	1	MISSING	\$ 300.00	\$ 300.00
1.7	R/H HEAD LAMP HOUSING	1	MISSING	\$ 88.00	\$ 88.00
1.8	FRONT BUMPER	1	CRACKED	\$ 320.00	\$ 320.00
1.9	FRONT BUMPER RETAINER LH	1	UNCONFIRM	\$ 45.00	\$ 45.00
1.10	FRONT BUMPER RETAINER RH	1	MISSING	\$ 45.00	\$ 45.00
1.11	DRIVER DOOR COMPLETE ASSY	1	DEFORMED	\$ 2,100.00	\$ 2,100.00
1.12	R/H WINDOW ASSY	1	MISSING	\$ 550.00	\$ 550.00
1.13	R/H PANEL	1	DEFORMED	\$ 3,200.00	\$ 3,200.00
1.14	15" STEEL RIMS RH	2	DENTED	\$ 112.00	\$ 224.00
1.15	15" STEEL RIMS LH	2	UNCONFIRM	\$ 112.00	\$ 224.00
1.16	R/H LOWER ARM	1	DENTED	\$ 250.00	\$ 250.00
1.17	R/H ABSORBER	1	DENTED	\$ 95.00	\$ 95.00
1.18	R/H UPPER ARM	1	DENTED	\$ 350.00	\$ 350.00
1.19	L/H LOWER ARM	1	UNCONFIRM	\$ 250.00	\$ 250.00
1.20	L/H ABSORBER	1	UNCONFIRM	\$ 95.00	\$ 95.00
1.21	L/H UPPER ARM	1	UNCONFIRM	\$ 350.00	\$ 350.00
1.22	REAR BUMPER	1	CRACKED	\$ 280.00	\$ 280.00

1.23	Tyre 15" (SOR 5B_2) CAT B	2	PUNCTURE	\$	296.21	\$	592.42
1	SCOPE OF REPAIRS						
1.1	WIND SCREEN						8
	REMOVE & REPLACE FRONT WIND SCREEN						
	REPLACE FRONT WIND SCREEN MOULDING						
	CUT, WELD & ALIGN WIND SCREEN PILLAR						
	WATER LEAKAGE TEST FOR WIND SCREEN						
	PUTTY & SPRAY PAINT WIND SCREEN PILLAR						6
1.2	FRONT PANEL						
	REMOVE & REPLACE FRONT PANEL						
	PUTTY & SPRAY PAINT FRONT PANEL						
1.3	REMOVE & REPLACE RADIATOR GRILLE						1
1.4	HEAD LAMP						2
	REMOVE & REPLACE L/H HEAD LAMP HOUSING						
	REMOVE & REPLACE R/H HEAD LAMP HOUSING						
	PUTTY & SPRAY PAINT HEAD LAMP HOUSING						6
1.5	FRONT BUMPER						
	REMOVE & REPLACE FRONT BUMPER						
	REPLACE FRONT BUMPER RETAINER						
	REMOVE & REPLACE FRONT BUMPER SUPPORT						
	REPLACE FRONT BUMPER PLATE						
	PUTTY & SPRAY PAINT FRONT BUMPER						8
1.6	DASH BOARD						
	REMOVE & RE-INSTALL DASH BOARD						
	REPAIR & ALIGN DASH BOARD FRAME						22
1.7	DRIVER DOOR						
	REMOVE & REPLACE DRIVER DOOR COMPLETE ASSY						
	CUT, WELD & ALIGN DRIVER DOOR PILLAR						
	PUTTY & SPRAY PAINT DRIVER DOOR & PILLAR						
1.8	CUT, WELD & ALIGN DRIVER FLOOR BOARD						14

PAINT CORROSION TREATMENT FOR DRIVER FLOOR BOARD									
1.9	REPLACE R/H WINDOW ASSY								2
1.10	CUT, REMOVE & REPLACE R/H PANEL								23
	PUTTY & SPRAY PAINT R/H PANEL								
1.11	TYRE & RIM								4
	REMOVE & REPLACE FRONT R/H TYRE & RIM								
	REMOVE & REPLACE FRONT L/H TYRE & RIM								
	REMOVE & REPLACE REAR R/H TYRE & RIM								
	REMOVE & REPLACE REAR L/H TYRE & RIM								
	PUTTY & SPRAY PAINT ALL TYRE RIM								12
1.12	UNDER CARRIAGE								
	REMOVE & REPLACE R/H LOWER ARM								
	REMOVE & REPLACE L/H LOWER ARM								
	REMOVE & REPLACE R/H ABSORBER								
	REMOVE & REPLACE L/H ABSORBER								
	REMOVE & REPLACE R/H UPPER ARM								
	REMOVE & REPLACE L/H UPPER ARM								
1.13	REPAIR & ALIGN CROSS MEMBER								8
1.14	REPAIR & REPLACE REAR BUMPER								2
	PUTTY & SPRAY PAINT REAR BUMPER								
1.15	REAR CABIN FLOOR BOARD								12
	REMOVE & RE-INSTALL REAR CABIN PASSENGER SEAT								
	CUT, WELD & REPAIR REAR CABIN FLOOR BOARD								
	ANTI CORROSION TREATMENT FOR REAR CABIN FLOOR BOARD								
								TOTAL PARTS COST	\$10,816.42
COSTING								TOTAL MAN-HOUR	130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18019926/Nsbe2

CONTRACT MANAGEMENT SECTION
(SINGAPORE POLICE FORCE) 1 MOUNT
PLEASANT ROAD BLK 8 OLD POLICE
ACADEMY SINGAPORE 298333

Date : 18-12-2018



ATTN : LIM WEI YEA

Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 4834G
Policy No.	Coverage (\$)	0.00
Claim No. HOMSPFETQ16000399	Excess (\$)	0.00
Assign From LIM WEI YEA	Assign Date	31/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	LH1740006297	Colour	SILVER
Odometer	-	Steering	JAMMED
Brakes	JAMMED	Modification	STANDARD ALLOY RIM
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14C	MICHELIN	6 mm
L/H Front Tyre	185 R14C	MICHELIN	6 mm
R/H Rear Tyre	185 R14C	MICHELIN	5 mm
L/H Rear Tyre	185 R14C	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	Inspection Date	07/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	

5a. Remarks

--



Registration No. QX 4834G

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT WIND SCREEN	1	CRACKED	\$ 375.00	\$ 375.00	
1.2	WIND SCREEN MOULDING	1	NECESSARY	\$ 120.00	\$ 120.00	
1.3	FRONT PANEL	1	DEFORMED	\$ 625.00	\$ 625.00	
1.4	RADIATOR GRILLE	1	DENTED	\$ 250.00	\$ 250.00	
1.5	L/H HEAD LAMP HOUSING	1	BENT	\$ 88.00	\$ 88.00	
1.6	R/H HEAD LAMP	1	MISSING	\$ 300.00	\$ 300.00	
1.7	R/H HEAD LAMP HOUSING	1	MISSING	\$ 88.00	\$ 88.00	
1.8	FRONT BUMPER	1	CRACKED	\$ 320.00	\$ 320.00	
1.9	FRONT BUMPER RETAINER LH	1	UNCONFIRM	\$ 45.00	\$ 45.00	
1.10	FRONT BUMPER RETAINER RH	1	MISSING	\$ 45.00	\$ 45.00	
1.11	DRIVER DOOR COMPLETE ASSY	1	DEFORMED	\$ 2,100.00	\$ 2,100.00	
1.12	R/H WINDOW ASSY	1	MISSING	\$ 550.00	\$ 550.00	
1.13	R/H PANEL	1	DEFORMED	\$ 3,200.00	\$ 3,200.00	
1.14	15" STEEL RIMS RH	2	DENTED	\$ 112.00	\$ 224.00	
1.15	15" STEEL RIMS LH	2	UNCONFIRM	\$ 112.00	\$ 224.00	
1.16	R/H LOWER ARM	1	DENTED	\$ 250.00	\$ 250.00	
1.17	R/H ABSORBER	1	DENTED	\$ 95.00	\$ 95.00	
1.18	R/H UPPER ARM	1	DENTED	\$ 350.00	\$ 350.00	
1.19	L/H LOWER ARM	1	UNCONFIRM	\$ 250.00	\$ 250.00	
1.20	L/H ABSORBER	1	UNCONFIRM	\$ 95.00	\$ 95.00	
1.21	L/H UPPER ARM	1	UNCONFIRM	\$ 350.00	\$ 350.00	
1.22	REAR BUMPER	1	CRACKED	\$ 280.00	\$ 280.00	
1.23	Tyre 15" (SOR 5B_2) CAT B	2	PUNCTURE	\$ 296.21	\$ 592.42	
1	SCOPE OF REPAIRS					
1.1	WIND SCREEN					8
	REMOVE & REPLACE FRONT WIND SCREEN					
	REPLACE FRONT WIND SCREEN MOULDING					
	CUT, WELD & ALIGN WIND SCREEN PILLAR					

	WATER LEAKAGE TEST FOR WIND SCREEN					
	PUTTY & SPRAY PAINT WIND SCREEN PILLAR					
1.2	FRONT PANEL					6
	REMOVE & REPLACE FRONT PANEL					
	PUTTY & SPRAY PAINT FRONT PANEL					
1.3	REMOVE & REPLACE RADIATOR GRILLE					1
1.4	HEAD LAMP					2
	REMOVE & REPLACE L/H HEAD LAMP HOUSING					
	REMOVE & REPLACE R/H HEAD LAMP HOUSING					
	PUTTY & SPRAY PAINT HEAD LAMP HOUSING					
1.5	FRONT BUMPER					6
	REMOVE & REPLACE FRONT BUMPER					
	REPLACE FRONT BUMPER RETAINER					
	REMOVE & REPLACE FRONT BUMPER SUPPORT					
	REPLACE FRONT NUMBER PLATE					
	PUTTY & SPRAY PAINT FRONT BUMPER					
1.6	DASH BOARD					8
	REMOVE & RE-INSTALL DASH BOARD					
	REPAIR & ALIGN DASH BOARD FRAME					
1.7	DRIVER DOOR					22
	REMOVE & REPLACE DRIVER DOOR COMPLETE ASSY					
	CUT, WELD & ALIGN DRIVER DOOR PILLAR					
	PUTTY & SPRAY PAINT DRIVER DOOR & PILLAR					
1.8	CUT, WELD & ALIGN DRIVER FLOOR BOARD					14
	ANTI CORROSION TREATMENT FOR DRIVER FLOOR BOARD					
1.9	REPLACE R/H WINDOW ASSY					2
1.10	CUT, REMOVE & REPLACE R/H PANEL					23
	PUTTY & SPRAY PAINT R/H PANEL					
1.11	TYRE & RIM					4
	REMOVE & REPLACE FRONT R/H TYRE & RIM					
	REMOVE & REPLACE FRONT L/H TYRE & RIM					
	REMOVE & REPLACE REAR R/H TYRE & RIM					
	REMOVE & REPLACE REAR L/H TYRE & RIM					
	PUTTY & SPRAY PAINT ALL TYRE RIM					
1.12	UNDER CARRIAGE					12
	REMOVE & REPLACE R/H LOWER ARM					
	REMOVE & REPLACE L/H LOWER ARM					
	REMOVE & REPLACE R/H ABSORBER					
	REMOVE & REPLACE L/H ABSORBER					

	REMOVE & REPLACE R/H UPPER ARM					
	REMOVE & REPLACE L/H UPPER ARM					
1.13	REPAIR & ALIGN CROSS MEMBER					8
1.14	REPAIR & REPLACE REAR BUMPER					2
	PUTTY & SPRAY PAINT REAR BUMPER					
1.15	REAR CABIN FLOOR BOARD					12
	REMOVE & RE-INSTALL REAR CABIN PASSENGER SEAT					
	CUT, WELD & REPAIR REAR CABIN FLOOR BOARD					
	ANTI CORROSION TREATMENT FOR REAR CABIN FLOOR BOARD					
COSTING		TOTAL PARTS COST			\$10,816.42	
		TOTAL MAN-HOUR				130

Registration No. QX 4834G

Vehicle Inspected By

MUHD NAZRIL (NAZ)

Technical Investigator

LL.B. (Hons) London

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

REF:

Assigner:

NA2

SPF

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: QX 4834 G Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HIACE C.G. _____Colour: SILVER A/C: Insured / Std / NI / NASp. Reading: BATT. FLAT T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R 14C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mmRear R/Bal. 5 mmL/Bal. 6 mmL/Bal. 5 mmD.O.A. _____ D.O.I. 7/11/18Survey held at KNS Bodywork EngineeringDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Roof or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Materials - \$9812.42 (Exclude check items SPF
\$964)

RECEIVED 14 DEC 2018

Date/Time, File Pass to?

14/12/18

1) Typ. 51

Date/Time, File Return to?

2) _____

☐ : Prelim Report☒ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

200
200

Shirley Hiew (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Friday, 14 December 2018 3:12 PM
To: Shirley Hiew (LKK Auto)
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); assignments; Admin-D (LKKAuto); SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Hi Shirley,

Please proceed to close this and submit the report.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 December 2018 11:44
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX4834G)

Dear Wei Yea,

Please advise whether can we submit our report of QX 4834G accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315