

REPAIR ESTIMATE*

EQ

VEHICLE NO : SHD 4979J

DATE 1/11/2018 14:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover ✓			\$ 544.50	
	Front Bumper Grille (LH) <i>x rep</i>		\$ 41.60	\$ 41.60	
	Front Bumper Bracket (LH) ?			\$ 24.60	
	Headlamp (LH) ✓			\$ 1,388.00	
	Front Fender (LH) ✓			\$ 566.30	
	SUB TOTAL			\$ 2,565.00	
	LESS 20%			\$ 513.00	
	DISCOUNTED TOTAL			\$ 2,052.00	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge			200	
	Panel Beating			\$ 500.00	
	Spray Painting Charge			\$ 500.00	400
	Wiring			\$ 30.00	20
	TOTAL LABOUR			\$ 1,030.00	
	ESTIMATE TOTAL			\$ 3,182.00	

Kalvin LUKY
 1/11/18 15:16h
 2 Rg,
 4/5
 After Rep p 46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.