

REPAIR ESTIMATE*

EQ

VEHICLE NO : SHD 4979J

DATE 1/11/2018 14:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>cut</i>			\$ 544.50
	Front Bumper Grille (LH) <i>x repair</i>		\$ 41.60	\$ 41.60
	Front Bumper Bracket (LH) <i>✓ nec</i>			\$ 24.60
	Headlamp (LH) <i>cut</i>			\$ 1,388.00
	Front Fender (LH) <i>cut dented</i>			\$ 566.30
	SUB TOTAL			\$ 2,565.00
	LESS 20%			\$ 513.00
	DISCOUNTED TOTAL			\$ 2,052.00
	Front Fender Advertisement Logo (LH) <i>✓ nec</i>			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			200
	Panel Beating			\$ 500.00
	Spray Painting Charge			\$ 500.00 400
	Wiring			\$ 30.00 20
	TOTAL LABOUR			\$ 1,030.00
	ESTIMATE TOTAL			\$ 3,182.00

Kalvin LUKY
 1/11/18 15:16h
 2 Rg,
 4/5
 After Repair p 46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.