

ASS. REC. BY:

REF:

CS/SMD18019947 / Rlsbnz

Special Instruction:

Survivor

Rasul

ASSIGNMENT (Office)

From (Person):

Gnroh Pau Loony

of

SMD

Date/Time:

02.11.2018 2:49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 6793A

Insured:

SJJ 2679H

at Workshop m/s

Kah Motor

Tel:

of

355 Alexandra Rd

Policy No:

DIBTMPV01014319

Claim No:

CMTD1804807

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP.

H.O.D. Endorsement:

Date/Time:

02.11.2018 3:10pm

Person Contacted:

Sin Hui

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 6793A - CS / TML / 7018823 / Rlsbnz

DCA: 280917

SJJ 2679H - X

05/11/18

@ 14:47 p.m. revised IA to Gnroh Pau Loony via memo.

Paul

REF: SMO

2704E

ASSIGNMENT

From: Date 02.11.2018

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 6293A

at Workshop m/s: Koh Malar

of 255 Alexandra Rd

Insured

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Sin Hui

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum. Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLQ 6293A Yr Regn: 2017 July

Type: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV 1.5 LX C.O. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 014437 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 24MRU18306X202419

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: 215/60R15

R:

BS: ☒ BUN / PEXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 02/11/18 D.O.I: 02/11/18

Survey held at: Kant Mason

Des. of Damages: Frt ☒ Read / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/11/18 Confirmed P/P \$ 11,082.79 @ 8 days with Resur L
(\$6,093.24 Red - 36%)

RECEIVED 20 NOV 2018

Date/Time: File Pass to?

20/11/18
Typist

☐ : Preli. Report

☒ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1) S + PS \$

1) Photos

1) Others

1)

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format:

Lump Sum / I.B.I: \$ 11,082.79 P/P

450
10

460

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 05 Nov 2018

Preliminary Advice

Insured Vehicle No	: SJJ2679H	Accident Date	: 02/11/2018
TP Vehicle No	: SLQ6293A	Assignment Date	: 02/11/2018
Make	: HONDA HR-V	Est. Duration of Repair	: 8 days
Date of Inspection	: 02/11/2018		
Inspection At	: Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,454.47
Revised Amount	:S\$	10,186.04
Check Items (Estimated)	:S\$	3,698.43
Total	:S\$	13,884.47

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 14:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MAW SE LWIN, ID: S2713488B								
Main Claimant:	DU SIWEI, ID: S7662704E								
Vehicle Reg. No.:	SLQ6293A	Date of Loss:	02/11/2018 08:00 - :59						
Claim Type:	TP / CMTD1804807	Policy/Cover Note No.:	D18MTPV01014319 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJJ2679H	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]								
Adj Asg. Remarks:	KINDLY ASSIST TO SURVEY THE VEH TODAY PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 20 November 2018 10:56 AM
To: 'Ng Sin Hai'
Cc: Rasul (LKKAuto); SUR
Subject: RE: Submission Pre-Invoice for vehicle SLQ6293A

Hi Sin Hai,

Confirmed final fig of \$ 11,082.79 (part by part) @ 8 days of repairs before GST.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]
Sent: Tuesday, 13 November 2018 7:23 PM
To: Rasul (LKK Auto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SLQ6293A

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$11,082.79 (before GST)
No of working days : 08 days. (LOR)

We will proceed for closing after 1 week of submission to you.
Kindly contact me if there is any discrepancy.

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7662704E



Name

DU SIWEI

杜思威

Race

CHINESE

Date of birth

25-10-1976

Sex

M

Country of birth

CHINA

S7662704E

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S7662704E

Name

DU SIWEI

Birth Date 25 Oct 1976

Issue Date 07 Feb 2012



002040553D



4861419

NRIC No: S7662704E



Date of issue

04-05-2012

APT BLK 6 TAO CHING ROAD #10-09
SINGAPORE 618723

NRIC No: S7662704E

Date: 16/05/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 07 Feb 2012



Licence No: S7662704E

NP 428A



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SLQ6293A
Chassis No : JHMRU1830GX202419
Model : HRV LX-SIN CVT YM 2016
Owner's Name : DU SIWEI
Ins Policy No. :
Date of Accident : 2/11/2018

Document No. : SQT18004708 Page 1
Date : 2. Nov 2018
Customer No. : WZH023
Svc Advisor :
Engine No : L15B4532419
Date | Time : 2. Nov 2018 11:17:56 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:DU SIWEI OWNER INSURER:TOKIO ACC DATE:02/11/2018 SURVEYED BY: DATE: REF NO: TP INSURER:SOMPO TP VEH:SJJ2679H						
BOSUN	SUNDRIES	1	100.00 30		100.00	7.00	107.00 <i>net</i>
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 <i>7X11</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 <i>7X11</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & <i>Align tailgate</i>	1	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BOMISC1	RESET AND CALIBRATE ALL SMART ENTRY	1	380.00		380.00	26.60	406.60
BKRP02M	CUT OFF & RENEW RR PANEL.	1	5000.00 2800		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 2700		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 <i>7X11</i>		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00		380.00	26.60	406.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00 <i>7X11</i>		450.00	31.50	481.50
Sum Labor					12680.00	887.60	13,567.60



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SLQ6293A
Chassis No : JHMRU1830GX202419
Model : HRV LX-SIN CVT YM 2016
Owner's Name : DU SIWEI
Ins Policy No :
Date of Accident : 2/11/2018

Document No. : SQT18004708 Page 2
Date : 2. Nov 2018
Customer No. : WZH023
Svc Advisor :
Engine No : L15B4532419
Date | Time : 2. Nov 2018 11:17:56 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
RS-TMP3040L	VPC 4PCS REAR SENSORS ? X sum	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR. ? } X	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL. ? } X	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R,LID ? } X sum	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL,LID CM /	1	269.90	25	202.42	14.17	216.59
68100-T7A-J20ZZ	TAIL GATE COMP ? X sum	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE ne -	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE X /	1	78.90	25	59.17	4.14	63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE X /	1	136.00	25	102.00	7.14	109.14
75722-T7W-A01	EMBLEMRR. ne -	1	13.30	25	9.97	0.70	10.67
33505-T7A-J01	REFLECTOR ASSYR.RR. ? } X sum	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR. ? } X sum	1	156.30	25	117.22	8.21	125.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER ? } X sum	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER ? } X sum	1	94.10	25	70.57	4.94	75.51
71593-T7A-000	SPACERR.RR.BUMPER SIDE ne -	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE ne -	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER ne -	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. X /	1	373.10	25	279.82	19.59	299.41
84640-T7A-J01ZA	LINING ASSYRR.PANEL X /	1	43.90	25	32.92	2.30	35.22
04655-T7A-310ZZ	PANEL SETRR.FLOOR ? } X sum	1	675.50	25	506.62	35.46	542.08
72841-SH3-315	OILSHEET ? } X sum	3	40.70	25	91.57	6.41	97.98
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER ne -	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 ne -	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER ne -	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT ne -	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD ne -	4	3.50	25	10.50	0.74	11.24
91502-S70-003	FASTENER B ne -	2	5.20	25	7.80	0.55	8.35
91536-SS0-J01	FASTENER AW/SHIELD ne -	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ne -	2	60.00		120.00	8.40	128.40

Printed on 2/11/2018 11:27:29 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SLQ6293A
Chassis No : JHMRU1830GX202419
Model : HRV LX-SIN CVT YM 2016
Owner's Name : DU SIWEI
Ins Policy No :
Date of Accident : 2/11/2018

Document No. : SQT18004708 Page 3
Date : 2. Nov 2018
Customer No. : WZH023
Svc Advisor :
Engine No : L15B4532419
Date | Time : 2. Nov 2018 11:17:56 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Item					3774.47	264.22	4,038.69

Survey By

Date & Time

Excess

Status

Signature

Total Amount 16,454.47 1,151.82 17,606.29

Total (Inclusive of GST) 17,606.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey below/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/11/2018 11:27:29 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: S7662704E / DU SIWEI
Chassis No: JHMRU1830GX202419
License No: SLQ6293A
Mileage: 12810
Engine No: L15B4532419

Document No: SVO18065184
Printed By: SHNG
Order Date: 2. November 2018
Order Time: 4:12:21 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>NE</i>	1	14.50	25	10.87	0.76	11.63
90661-SC7-003	GROMMET SCREW <i>NE</i>	2	2.30	25	3.45	0.24	3.69
04715-T7A-900ZZ	FACE,RR.BUMPER <i>DE</i>	1	463.70	25	347.77	24.34	372.11
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR <i>DE</i>	1	189.80	25	142.35	9.96	152.31
74450-T7A-J01ZQ	PROTECTORL.RR.WHEEL ARCH <i>CRA</i>	1	168.70	25	126.52	8.86	135.38
74940-TZ5-A01	BUZZER ASSYSMART <i>CRA</i>	1	60.40	25	45.30	3.17	48.47
84614-SJD-E01ZA	HOOK ASSYTIE DOWN <i>CRA</i>	2	30.20	25	45.30	3.17	48.47
	SUM PARTS:				721.56	50.50	772.06
	TOTAL SGD				721.56	50.50	772.06

Total Payable (SGD)

772.06

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3863 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRU1830GX202419
License No: SLQ6293A
Mileage: 12810
Engine No: L15B4532419

Document No: SVO18065184
Printed By: SHNG
Order Date: 2. November 2018
Order Time: 4:12:21 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:DU SIWEI							
	OWNER INSURER:TOKIO							
	ACC DATE:02/11/2018							
	SURVEYED BY:rasul							
	DATE:02/11/2018							
	REF NO:							
	TP INSURER:SOMPO							
	TP VEH:SJJ2679H							
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90	25	202.42	14.17		216.59
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04		673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.18		79.20
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14		63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	136.00	25	102.00	7.14		109.14
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70		10.67
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	156.30	25	117.22	8.21		125.43
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	94.10	25	70.57	4.94		75.51
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60		9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60		9.22
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97		14.77
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59		299.41
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30		35.22
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01		15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45		6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01		15.48
76711-T6A-003	CAPPVOT	1	4.80	25	3.60	0.25		3.85
91501-S70-003	FASTENER BW/SHIELD	4	3.50	25	10.50	0.74		11.24
91502-S70-003	FASTENER B	2	5.20	25	7.80	0.55		8.35
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40		6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40		128.40
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76		11.63
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24		3.69
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34		372.11
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	189.80	25	142.35	9.96		152.31
74450-T7A-J01ZQ	PROTECTORL.RR.WHEEL ARCH	1	168.70	25	126.52	8.86		135.38
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17		48.47
84614-SJD-E01ZA	HOOK ASSYTIE DOWN	2	30.20	25	45.30	3.17		48.47
	SUM PARTS:				2,512.79	175.89		2,688.68
BOSUN	0701	1	30.00		30.00	2.10		32.10
	SUNDRIES							
BA02R	1466	1	180.00		180.00	12.60		192.60
	REMOVE & RENEW REVERSE							
	SENSORS-4 PCS (N)							
BOJSE	1718	1	80.00		80.00	5.60		85.60
	SEALANT FOR REAR END PANEL							
BOJSE	1718	1	80.00		80.00	5.60		85.60
	SEALANT FOR TAILGATE							

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRU1830GX202419
License No: SLQ6293A
Mileage: 12810
Engine No: L15B4532419

Document No: SVO18065184
Printed By: SHNG
Order Date: 2. November 2018
Order Time: 4:12:21 PM
Service Advisor: NG SIN HAI

BML02I	0701 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BMI02D	1438 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00	560.00	39.20	599.20
BKTG02R	1466 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00	560.00	39.20	599.20
BG02D	1438 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00	560.00	39.20	599.20
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	80.00	80.00	5.60	85.60
BOMISC1	1466 RESET AND CALIBRATE ALL SMART ENTRY	1	380.00	380.00	26.60	406.60
BKRP02M	1466 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00	2,800.00	196.00	2,996.00
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	2,700.00	2,700.00	189.00	2,889.00
BKBU01R	0701 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00	380.00	26.60	406.60

SUM LABOUR: 8,570.00 599.90 9,169.90**TOTAL SGD** 11,082.79 775.79 11,858.58**Total Payable (SGD)** 11,858.58

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18019947/R1SBN2

Date: 28/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014319
Claimant Vehicle No :	SLQ6293A	Insured Vehicle No :	SJJ2679H
Date of Loss:	02/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1804807

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ6293A	Engine No:	L15B4532419
Make & Model:	HONDA HR-V, 1.5 (A)	Chassis No:	JHMRU1830GX202419
Reg. Date:	18/07/2017 (Man. Year: 2017)	Odometer:	14437 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R15	Rear Tyre Size:	215/60R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,596.03	2,542.79	2,053.24	44.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,580.00	8,540.00	4,040.00	32.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,176.03	11,082.79	6,093.24	35.48
+ GST 7.00/7.00% (\$\$)	1,202.32	775.80	426.52	35.47
Nett Amount (\$\$)	18,378.35	11,858.59	6,519.76	35.48

INSPECTION

Date of Assignment:	02/11/2018	Inspected At:	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937
Date Inspected:	02/11/2018		

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2018)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ6293A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*VPC 4PCS REAR SENSORS	Serviceable	320.00 FS	*- FS
3	1		*LAMP UNITR	Not Necessary	331.12 FS	*- FS
4	1		*LAMP UNITL	Not Necessary	331.12 FS	*- FS
5	1		*LIGHT ASSY,R LID	Serviceable	202.42 FS	*- FS
6	1		*LIGHT ASSYL LID	Cracked	202.42 FS	*202.42 FS
7	1		*TAIL GATE COMP	Buckled	641.77 FS	*629.17 FS
8	1		*WEATHERSTRIP TAILGATE	Necessary	74.02 FS	*74.02 FS
9	1		*LOCK ASSYTAILGATE	Bent	59.17 FS	*59.17 FS
10	1		*LINING ASSYTAILGATE	Deformed	102.00 FS	*102.00 FS
11	1		*EMBLEMRR	Necessary	9.97 FS	*9.97 FS
12	1		*REFLECTOR ASSYR RR	Cracked	117.22 FS	*117.22 FS
13	1		*REFLECTOR ASSYL RR	Serviceable	117.22 FS	*- FS
14	1		*FACER RR BUMPER CORNER	Serviceable	70.57 FS	*- FS
15	1		*FACEL RR BUMPER CORNER	Deformed	70.57 FS	*70.57 FS
16	1		*SPACERR RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
17	1		*SPACERL RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
18	1		*CLIP,BUMPER (8 Pcs)	Necessary	13.80 FS	*13.80 FS
19	1		*PANEL COMPRR	Bent	279.82 FS	*279.82 FS
20	1		*LINING ASSYRR PANEL	Deformed	32.92 FS	*32.92 FS
21	1		*PANEL SETRR FLOOR	Serviceable	506.62 FS	*- FS
22	3		*OILSHEET	Serviceable	91.57 FS	*- FS
23	1		*RUBBER CR WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
24	1		*DAMPERSTD 5X5	Necessary	6.37 FS	*6.37 FS
25	1		*RUBBER CL WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
26	1		*CAPPIVOT	Necessary	3.60 FS	*3.60 FS
27	1		*FASTENER BW/SHIELD (4 Pcs)	Necessary	10.50 FS	*10.50 FS
28	2		*FASTENER B	Necessary	7.80 FS	*7.80 FS
29	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
30	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
31	1		*EMBLEM RR I-VTEC	Necessary	10.87 FS	*10.87 FS
32	1		*GROMMET SCREW (2 Pcs)	Necessary	3.45 FS	*3.45 FS
33	1		*FACE RR BUMPER	Deformed	347.77 FS	*347.77 FS
34	1		*BOARD ASSYTRUNK FLOOR	Deformed	142.35 FS	*142.35 FS
35	1		*PROTECTORL RR WHEEL ARCH	Cracked	126.52 FS	*126.52 FS
36	1		*BUZZER ASSYSMART	Cracked	45.30 FS	*45.30 FS
37	2		*HOOK ASSYTIE DOWN	Cracked	45.30 FS	*45.30 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,596.03	2,542.79
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSOR-4 PCS	New	180.00	180.00
2	SEALANT FOR REAR END PANEL	New	80.00	80.00
3	SEALANT FOR REAR FLOOR PANEL	New	80.00	-
4	SEALANT FOR TAILGATE	New	80.00	80.00
5	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	180.00
6	RREMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	-
7	RREMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
8	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST & ALIGN TAILGATE	New	560.00	560.00
9	REMOVE & INSTALL RR WINDSCREEN	New	560.00	560.00
10	WINDSCREEN DAM KIT	New	80.00	80.00
11	RESET AND CALIBRATE ALL SMART ENTRY	New	380.00	380.00
12	CUT OFF & RENEW RR PANEL	New	5,000.00	2,800.00
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	2,700.00
14	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	-
15	REMOVE,RE-FIX AND ALIGN REAR VIEW CAMERA	New	380.00	380.00
16	APPLY BODY UNDERSIDE COATING	New	450.00	-
Gross Labour Cost (\$\$)			12,580.00	8,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >