

ASS. REC BY:

REF:

CS/FCL18019951/Usbn2

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): CWS - Sithura

of

FCL

Date/Time: 02.11.2018 7:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Gbf 9577M

Insured:

SHA 8632Z

at Workshop m/s

Fastech

Tel:

of

Blk 1Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

D18007901MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS "wp"

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Nany

Vehicle (IN / OUT)

Date/Time

Action/Instruction (✓) Estimate

Gbf 9577M - x

SHA 8632Z - CS/FCL18014223/6

DOA: 08070918

05/11/18

@ 15:06 p.m. revert pending estimate from repairs to
sithura via email.

Insurance (M/100)

REF:

Re. /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G3F9577M

Yr Regn:

5.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

c.c 2982

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

31178

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT 02P 600 215 605

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/11/18

D.O.I.

2/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/11/18 Confirmed final fig \$9893.43 with Alu.

15/11/18 Confirmed P/P \$9,893.43 @ 6 days with meras (\$13,973.42 Red - 59%)

RECEIVED 16 NOV 2018

Date/Time, File Pass to?

16/11/18

1)

Typist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

☐ S / PS / SI

☐ Photos

☐ Others

580
20/11/18
TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

9,893.43

13x15-195

170+195
50

50+50

139

654

MOTOR SURVEY ASSIGNMENT

Date	02-11-2018	Our Ref No. D18007901MFSH
Accident Date	02-11-2018	Claim Type. Third Party
Insured Vehicle	SHA8632Z	Third Party Vehicle. GBF9577M
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 5 November 2018 3:06 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18007901MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle GBF 9577M on 02/11/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 5 November 2018 10:04 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007901MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 2 November, 2018 7:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007901MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1937K
Vehicle Details	
Vehicle No.:	GBF9577M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2683121
Chassis No.:	JTFHT02P600215605
Maximum Power Output:	-
Open Market Value:	\$27,952.00
Original Registration Date:	02 May 2017
First Registration Date:	02 May 2017
Transfer Count:	0
Actual ARF Paid:	\$1,398.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 May 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,099.00
COE Rebate Amount:	\$34,479.00
Total Rebate Amount:	\$34,479.00

The information contained herein is correct as at 05 Nov 2018

OK

Driving License

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8428227H**

Name: **LIU QIMING**

Birth Date: **12 Sep 1984**

Issue Date: **11 Oct 2005**

001374257J



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8428227H



Name: **LIU QIMING**

刘 期 明

Race: **CHINESE**

Date of birth: **12-09-1984**


Country/Place of birth: **SINGAPORE**

Sex: **M**

S8428227H



Driving License



FASTECT AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

VEHICLE NO: GBF 9577M

QTY	PARTICULAR			
1 PCS	TAILGATE	2150.10	body	\$2,419.10
1 PCS	TAILGATE REAR LOGO		neu	\$68.10
1 PCS	TAILGATE 'TOYOTA' STICKER		neu	\$65.00
1 PCS	TAILGATE 'HIALC' STICKER		neu	\$60.35
1 PCS	TAILGATE GLASS OUTER SEAL		neu	\$88.10
1 PCS	TAILGATE GLASS INNER DAM RUBBER		neu	\$55.00
1 PCS	TAILGATE INNER LOCK		fm/tw	\$395.60
1 PCS	TAILGATE INNER LOCK ACTUATOR		fm	\$388.20
1 PCS	TAILGATE LOCK STRICKER		11	\$60.80
1 PCS	TAILGATE WEATHERSTRIP		tw	\$395.10
1 PCS	TAILGATE OUTER GARNISH		11	\$322.50
1 PCS	TAILGATE INNER TRIM BOARD	288.30	de/11	\$480.00
1 SET	TAILGATE INNER TRIM BOARD CLIPS		neu	\$50.00
2 PCS	TAILGATE DAMPERS @\$299.10		11	\$598.20
2 PCS	TAILLAMPS @\$388.50	352.30 x 2 = 704.60	one	\$777.00
2 PCS	TAILLAMP LOWER GARNISHES @169.30	109.50 x 2 = 219	tw/one	\$338.60
2 PCS	TAILLAMP LOWER PANELS @\$399.40		n	\$788.80
1 PCS	TAILLAMP MAIN RAIL PILLAR PANEL N/S		n	\$489.60
1 PCS	REAR BUMPER	596.20	dis	\$681.10
1 SET	REAR BUMPER CLIPS		neu	\$50.00
2 PCS	REAR BUMPER SIDE BRACKETS @\$115.00		neu	\$230.00
4 PCS	REAR BUMPER LOWER BRACKETS @\$85.00	56.20 x 4 = 224.80	neu	\$340.00
1 PCS	REAR BUMPER BEAM		nz	\$197.30
1 PCS	REAR EXHAUST		n	\$971.00
2 PCS	REAR EXHAUST MOUNTINGS @\$35.00		11	\$70.00
1 PCS	REAR END PANEL OUTER		body	\$788.10
1 PCS	REAR END PANEL INNER	1022.10	body	\$1,245.10
1 PCS	REAR END PANEL TOP STEEL PLATE		neu	\$299.50
1 PCS	REAR FLOOR PANEL		n	\$1,280.10
1 PCS	REAR FLOOR PANEL TOP CARPET	650.00	to	\$850.10
1 PCS	REAR SPARE TYRE BRACKET	263.10	neu	\$399.10
1 PCS	REAR FENDER		n	\$1,419.70
1 PCS	REAR WINDSCREEN		11	\$1,015.70
				\$17,676.85
	S.NETT			
1 SET	REAR BUMPER REVERSE SENSOR		one	\$280.00
1 PCS	TAILGATE 70KM/H STICKER		neu	\$20.00
1 PCS	REAR LICENCE PLATE		neu	\$20.00
1 PCS	REAR WINDSCREEN SEALANT		neu	\$50.00

9051.28
25%
6788.43

not allocated
date
2/1/18
P/P \$ 9893.43
body.

1 SET
1 PCS

REAR REVERSE CAMERA
REAR END PANEL SEALANT

shooked / page
rec \$480.00 300
\$50.00 ✓

LABOUR CHARGES:

TO CHECK WIRING

\$50.00 20

TO DISMANTLE & REPLACING REVERSE SENSOR

\$80.00 50

TO DISMANTLE & REFIX REAR EXHAUST

\$100.00 60

TO DISMANTLE & REFIX REAR WINDSCREEN

\$150.00 120

TO DISMANTLE & REFIX TAILGATE MECHANISM

\$150.00 60

TO DISMANTLE & REFIX FRONT UNDERCARRIAGE

\$180.00 X

TO SPRAY RUSF PROOFING

\$200.00 80

TO MOUNT VEHICLE ON CAR O-LINER

\$380.00 X

LABOUR FOR PANEL BEATING & REPLACING PARTS

\$2,200.00 1100

TO PUTTY & SPRAY PAINTING

\$1,800.00 1000

TOTAL

\$23,866.85

L.K.K. Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6788.43

S.N 615

10244-2490

9893.43



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18019951/Usbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8632Z	Veh. Inspected	GBF 9577M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007901MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	02/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFHT02P600215605	Colour	WHITE	
Odometer	31178	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2018	Inspection Date	02/11/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9577M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BADLY DENTED	2,419.10	2,150.10
1	TAILGATE REAR LOGO	NECESSARY	68.10	68.10
1	TAILGATE "TOYOTA" STICKER	NECESSARY	65.00	65.00
1	TAILGATE "HIACE" STICKER	NECESSARY	60.35	60.35
1	TAILGATE GLASS OUTER SEAL	NECESSARY	88.10	88.10
1	TAILGATE GLASS INNER DAM RUBBER	NECESSARY	55.00	55.00
1	TAILGATE INNER LOCK	JAMMED / TWISTED	395.60	395.60
1	TAILGATE INNER LOCK ACTUATOR	JAMMED	388.20	388.20
1	TAILGATE LOCK STRICKER	NOT NECESSARY	60.80	-
1	TAILGATE WEATHERSTRIP	TWISTED	395.10	395.10
1	TAILGATE OUTER GARNISH	NOT NECESSARY	322.50	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / TORN	480.00	288.30
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
2	TAILGATE DAMPERS @\$299.10	NOT NECESSARY	598.20	-
2	TAILLAMPS @\$388.50	CRACKED	777.00	704.60
2	TAILLAMP LOWER GARNISHS @\$169.30	TWISTED / CRACKED	338.60	219.00
2	TAILLAMP LOWER PANELS	TO REPAIR SEE LABOUR	788.80	-
1	TAILLAMP MAIN RAIL PILLAR PANEL N/S	TO REPAIR SEE LABOUR	489.60	-
1	REAR BUMPER	DISTORTED	681.10	596.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE BRACKETS @\$115.00	BENT	230.00	230.00
4	REAR BUMPER LOWER BRACKETS @\$85.00	BENT	340.00	224.80
1	REAR BUMPER BEAM	NOT FITTED	197.30	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	971.00	-
2	REAR EXHAUST MOUNTINGS @\$35.00	NOT NECESSARY	70.00	-
1	REAR END PANEL OUTER	BADLY DENTED	788.10	788.10
1	REAR END PANEL INNER	BADLY DENTED	1,245.10	1,022.10
1	REAR END PANEL TOP STEEL PLATE	BENT	299.50	299.50

Report Ref No. CS/FC118019951/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,280.10	-
1	REAR FLOOR PANEL TOP CARPET	TORN	850.10	650.00
1	REAR SPARE TYRE BRACKET	BENT	399.10	263.10
1	REAR FENDER	TO REPAIR SEE LABOUR	1,419.70	-
1	REAR WINDSCREEN	NOT NECESSARY	1,015.70	-
	LESS 25% DISCOUNT		-	-2,262.82
			17,676.85	6,788.43
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	CRACKED	280.00	200.00
1	TAILGATE 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	15.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED / DAMAGED	480.00	300.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			900.00	615.00
	LABOUR			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		150.00	60.00
	TO DISMENTLE & REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	180.00	-
	TO SPRAY RUSF PROOFING.		200.00	80.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP LOWER PANELS, TAILLAMP MAIN RAIL PILLAR PANEL N/S, REAR EXHAUST, REAR FLOOR PANEL AND REAR FENDER.		2,200.00	1,100.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,000.00
			5,290.00	2,490.00

Report Ref No. CS/FCI18019951/Usbn2



GRAND TOTAL		23,866.85	9,893.43
RECOMMENDED COST OF REPAIRS			9,893.43

Report Ref No. CS/FCI18019951/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.