

22/03/2002

REF: C9/MSH18019962/R1/vbn2 Special Instruction:

ASS. REC. BY:

Supervisor: Rasul ASSIGNMENT (Office)From (Person): Muhammad Christina Wong of MSH Date/Time: 02.11.2018 3:25pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS


To Inspect Vehicle No: SLM 4297Z Insured: GBC 5157Mat Workshop m/s Car Life Auto Tel:of Bk 1002 Bukit Merah Lane 3 #01-75Policy No: 29083853 MKF Claim No: 567773

Sum Insured: Excess:

Make of Veh: D.O.A. 13082018
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' 05.11.2018 H.O.D. Endorsement:Date/Time: 02.11.2018 3:45pm Person Contacted: Vehicle IN / OUTDate/Time Action/Instruction (☒) EstimateSLM 4297Z - XGBC 5157M - X7/11/18 Send preli revised via merimen19/11/18 Final fig \$ 1395.20 confirmed by email (Red 1215.40, 469)

ASSIGNMENT

From: Date:
 Estimated Cost:
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No. SLM 4297Z
 at Workshop m/s Car Life
 of Bk1002 Bt Merah #01-75
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLM 4297Z Yr Regn: 2017 MAR
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: SUBARU FORESTER 2-0 cc 1998
 Colour: GREY A/C Insured / Std / NI / NA
 Sp. Reading: 041542 T/Radio: Insured / Std / NI / NA

Eng/No:
 C/No: JF15JGK8566083134

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18
 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or ROADSTONE

Front:
 R/Bal: 6 mm
 L/Bal: 6 mm
 D.O.A: 13/10/18
 Rear:
 R/Bal: 6 mm
 L/Bal: 6 mm
 D.O.A: 05/11/18

Survey held at CAR LIFE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

RECEIVED 19 NOV 2018

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

1)
 Date/Time: File Return to?

2) 19/11 - typst

Report Format: merimen
 Lump Sum / I.B.I: (\$) 1395.20

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:
☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + R\$ \$

) Photos

) Others

TOTAL

150
 10

160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 07 Nov 2018

Preliminary Advice

Insured Vehicle No	: GBG5157M	Accident Date	: 13/08/2018
TP Vehicle No	: SLM4297Z	Assignment Date	: 02/11/2018
Make	: SUBARU FORESTER	Est. Duration of Repair	: 2.00
Date of Inspection	: 05/11/2018		
Inspection At	: CAR LIFE AUTO ENGINEERING SERVICES (TOWN) BLK 1002 #01-75 BUKIT MERAH LANE 3 SINGAPORE 159719		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,610.60
Revised Amount	:S\$	1,444.20
Check Items (Estimated)	:S\$	306.00
Total	:S\$	1,750.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		02 Nov 2018 15:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RN LEASING PTE LTD, Co. Reg. No.: 201712341E								
Main Claimant:	INFOCUS INTEGRATED ENGINEERING PTE. LTD., Co. Reg. No.: 199609105C								
Vehicle Reg. No.:	SLM4297Z	Date of Loss:	13/08/2018 00:00 - :59 [16 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567773	Policy/Cover Note No.:	29083853MKF Coverage: 31/05/2018 - 30/05/2019						
Vehicle Reg. No. (Insured):	GBG5157M	Policy No. (Claimant):							
Repairer:	Car Life Auto Engineering Services (TOWN) BLK 1002 #01-75 BUKIT MERAH LANE 3, 159719 Bukit Merah - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/11/2018]								
Adj Asg. Remarks:	Liability unclear. Non Reporting. TP agree to use LKK as the SJE. Contact No: 6273 3810.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 19 November 2018 8:44 AM
To: 'Xinya Auto Services'; SUR
Subject: RE: slm4297z photo

Dear Sir,

WITHOUT PREJUDICE

Finalise amount \$1395.20 @ 2 working days.

Spray paint amount \$250.00

Kindly send Final invoice and all supporting documents to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xinya Auto Services <xinyaauto@singnet.com.sg>
Sent: Friday, 16 November 2018 1:21 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: slm4297z photo

Hi, Veron

Pls. check with rasul can the spray paint amount \$250.00

Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, November 15, 2018 3:09 PM
To: Xinya Auto Services <xinyaauto@singnet.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: slm4297z photo

Dear Sir,

WITHOUT PREJUDICE

Finalise amount \$1,345.20 @ 2 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xinya Auto Services <xinyaauto@singnet.com.sg>

Sent: Monday, 12 November 2018 4:23 PM

To: SUR <sur@lkkauto.com>

Subject: slm4297z photo

As attach



Virus-free. www.avg.com

CAR LIFE AUTO ENGINEERING SERVICES

Mailing address: 20, BINCHANG RISE SINGAPORE 579887
W/shop address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
E-mail : autolife_sin@yahoo.com.sg
Tel: 6273 3810 Fax: 6278 7522

Date : 16-Aug-18

Address : INFOCUS INTEGRATED ENGIN.P/L
1090 LOWER DELTA ROAD
04-04
SINGAPORE 169201

Reference : TP1165/08/18
Vehicle No : SLM 4297Z
Make/Model : SUBARU FORESTOR
Insurance Co. : AXA

RE : QUOTATION REPAIRS TO SLM 4297Z FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) REAR BUMPER	1	\$ 540 650.00 DE -
2) REAR BUMPER TOP CHROME	1	\$ 350.00 DE -
3) REAR BUMPER RETAINER	2	\$ 56.00 X 50
4) REAR BUMPER ENFORCEMENT	1	\$ 340.00 ? X 50
5) REAR BUMPER CLIPS	10	\$ 38.00 per -
LIST PRICE TOTAL		\$ 1,434.00
LESS DISCOUNT 10%		\$ 143.40
LIST PRICE TOTAL AFTER LESS		\$ 1,290.60
6) REAR REVERSE SENSOR		\$ 320.00 X 1
NETT PRICE TOTAL		\$ 320.00
TOTAL PARTS COST		\$1,610.60

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPALCE REAR BUMPER & ENFORCEMENT AND TO PANEL BEAT AND ALIGN END PANEL.	\$ 600.00 250 3 DAYS
2)	TO PUTTY & SPRAY PAINT REAR BUMPER AND END PANEL	\$ 600.00 250 3 PANEL 250
3)	TO REMOVE AND REPLACE REAR REVERSE SENSOR.	\$ 120.00 60
LABOUR TOTAL		\$ 1,320.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair (if applicable)
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

TOTAL ESTIMATED REPAIR COST

\$ 2,630.60

Handwritten notes:
8/11/18
Resurvey
4p 90010068
2 days
P/P
5/11/18 @ 1700
Resurvey by paint

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019962/R1VBN2

Date: 21/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29083853MKF
Claimant Vehicle No :	SLM4297Z	Insured Vehicle No :	GBG5157M
Date of Loss:	13/08/2018	Nature of Claim:	TP
		Claim No:	567773

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM4297Z	Engine No:	FA20B903619
Make & Model:	SUBARU FORESTER, 2.0 XT AWD CVT (A)	Chassis No:	JF1SJGK85GG083134
Reg. Date:	30/03/2017 (Man. Year: 2016)	Odometer:	41542 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,610.60	835.20	775.40	48.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	560.00	760.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,930.60	1,395.20	1,535.40	52.39

INSPECTION

Date of Assignment: 02/11/2018

Date Inspected: 05/11/2018 Inspected At:

Car Life Auto Engineering Services
(TOWN)
BLK 1002 #01-75 BUKIT MERAH LANE
3
Singapore 159719

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts: M1-SUV SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM4297Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	650.00 FL	*540.00 FL
2	1		*REAR BUMPER TOP CHROME	Deformed	350.00 FL	*350.00 FL
3	2		*REAR BUMPER RETAINER	Serviceable	56.00 FL	*- FL
4	1		*REAR BUMPER ENFORCEMENT	Serviceable	340.00 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
6	1		*REAR REVERSE SENSOR	Not Necessary	320.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,754.00	928.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					143.40	92.80
Total Parts (\$\$)					1,610.60	835.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REAR BUMPER & ENFORCEMENT AND TO PANEL BEAT AND ALIGN END PANEL	New	600.00	250.00
2	TO PUTTY & SPRAY PAINT REAR BUMPER AND END PANEL	New	600.00	250.00
3	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	120.00	60.00
Gross Labour Cost (\$\$)			1,320.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >