

10/10/2018

ASS. REC. BY

REF CS3/LPC/8017614/TLS/3-1

And Instruction

Surveyor Tguthkh

ASSIGNMENT (Office)

From (Person) Ong Li Hi

of

LPC

Date/Time: 05-11-2018

Estimated Cost

Bill to

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No 8KT 49152

Insured

SLX 5041E

at Workshop no: New Pioneer Auto

Tel

9615 8550

of 1800n lee st # 01-50

Policy No

Claim No

18/18/18/vpos/020942

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A 22/09/18

CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement

Date/Time: 12-18pm @ 27/11/18

Person Contacted

Mr. Tan

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

8KT 49152-X

Repair days 6

Submit P/P \$ 5,665.46 / 6 days
(\$ 2,733.52 Red - 33%)


TGum

8/11/18

RECEIVED 12 NOV 2018

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OO / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop mins _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IOAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
PRG
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SKT 4915Z Yr Regn: _____
 Type: M.Cy / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Wish C.C: 1777
 Colour: Black A/C: Insured / Std / Nil / NA
 Sp. Reading: 109370 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: 26E 206019670
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 145/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 27/1/18 R Spn
 Survey held at: New Pioneer #01-50
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: No GIA

RECEIVED 02 OCT 2016

Date/Time: File Pass to: 02/10/16
Typist
 Date/Time: File Return to: _____
 1) _____
 2) _____

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Survey Fee	<u>150</u>
Transportation	
1) S + RS	
2) PRS	
3) Other	
TOTAL	<u>150</u>

Report Format: PRS
 Lump Sum / I.B.I: (\$)

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 5 November, 2018 12:09 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: 2nd Notice to conduct Pre-Repair Survey: Your ref: 18/18/18/VP05/020942 Our Ref: SKT4915Z/NP/sy/wl
Attachments: 20942 TPD SR.pdf

Dear Catherine/Nivitha

Attached is the TP survey report.

Please let us have your surveyor's comment.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 27 September, 2018 12:50 PM
To: ONG LI LI; assignments@lkkauto.com
Cc: MT_Claim_SG; 'SUR'
Subject: RE: 2nd Notice to conduct Pre-Repair Survey: Your ref: 18/18/18/VP05/020942 Our Ref: SKT4915Z/NP/sy/wl

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Thursday, 27 September 2018 12:05 PM
To: accident@kscgp.com; assignments@lkkauto.com; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; motor@kscgp.com
Subject: RE: 2nd Notice to conduct Pre-Repair Survey: Your ref: 18/18/18/VP05/020942 Our Ref: SKT4915Z/NP/sy/wl

Without Prejudice
Save as to Costs

Dear Wei Lin

We are not agreeable to your proposed surveyors and shall appoint our surveyor to survey your client's vehicle.

Under the NIMA protocol, if your client is not agreeable to our proposed list of surveyors, he has to provide at least 10 surveyors for us to choose. We are of view that your client is in breach of protocol. Therefore, we urge your client not to engage another surveyor but to use our appointed surveyor as a Single Joint Expert in this case.

Dear Nivitha/Catherine

Please see below and assign surveyors to conduct TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: accident@kscgp.com [mailto:accident@kscgp.com]
Sent: Thursday, 27 September, 2018 11:50 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; motor@kscgp.com
Subject: 2nd Notice to conduct Pre-Repair Survey: Your ref: 18/18/18/VP05/020942 Our Ref: SKT4915Z/NP/sy/wl

Dear Sirs,

Please find enclosed herein our 2nd Notice to conduct Pre-Repair Survey. Our client is not agreeable to your proposed list of motor surveyors.

The workshop details are as follows:
New Pioneer Auto Pte Ltd
1 Soon Lee Street
#01-50 Pioneer Centre
Singapore 627605
Contact: Mr Tan Tick Cuan (96158550)

Thank you.

Regards,
Wei Lin
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

To: accident@kscgp.com

Cc: mt_claim@lonpac.com

Sent: Tue, 25 Sep 2018 06:24:44 +0000

Subject:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VP05/020942

Dear Wei Lin,

Please see attached and revert to us.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: accident@kscgp.com [<mailto:accident@kscgp.com>]

Sent: Tuesday, 25 September, 2018 1:47 PM

To: MT_Claim_SG; GERALD POH WEE BIN

Cc: motor@kscgp.com

Subject: Notice to Conduct Pre-Repair Survey - Your insured's vehicle: SLX 5041E Our ref: SKT 4915Z/NP/sy/wl

Dear Sirs,

Please find enclosed herein the Notice to conduct Pre-Repair Survey, for your attention and necessary action.

Thank you.

Regards,

Wei Lin

KSCGP Juris LLP

10 Hoe Chiang Road


#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

MOHD RADZI BIN ABDUL RAHMAN
C/O 1 Soon Lee Street #01-50 Pioneer
Centre Singapore 627605

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 22 September 2018
Assignment Date : 25 September 2018
Inspection Date : 25 September 2018
Our Reference No. : PAS/NP/181013/TP

Inspection Report Date : 08 October 2018

Workshop Name :

New Pioneer Auto Pte. Ltd.

Inspection Address :

1 Soon Lee Street #01-50 Pioneer Centre
Singapore 627605

PARTICULARS OF VEHICLE

Registration No. : SKT 4915 Z
Make/Model : TOYOTA WISH 1.8X A
Yr of Manuf/Regn : 2015
Carrying Capacity : 7 Seater
Chassis No. : ZGE206019670
Engine No. : 2ZR1501843
Colour : Metallic Black
Class : Passenger (Station Wagon)

Mileage : 109370 Km/h
Radio/Cassette : Fitted
CD Disc Player : Fitted
Air Conditioner : Fitted
Clock : Fitted
Seat Belt : Fitted
Wing Mirror Other : Fitted
Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent Eng : None
Modifications

VEHICLE VALUE

Market Value : X
Wreck Value (Part) : X

TYRE SIZE & CONDITION

Front N/s Size : 195/65R15 80 %
Make : BRIDGESTONE
Rear N/s size : 195/65R15 80 %
Make : BRIDGESTONE
Spare Size : 195/65R15 80 %
Make : BRIDGESTONE

Front O/s Size : 195/65R15 80 %
Make : BRIDGESTONE
Rear O/s Size : 195/65R15 80 %
Make Spare : BRIDGESTONE
Size :
Make :
Jack & Tools : Intact/Missing

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO. : SKT 4915 Z


APPENDIX A



POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its Rear Portion.
(see Diagram B)



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The bootlid and centre mldg, rear bumper and panel, both rear fenders and chassis were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 25/09/2018 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s New Pioneer Auto Pte. Ltd. as per attached Appraisalment Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part-By-Part Repair Basis of \$ 8,398.98 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Chares Parts	7412	51	5118	98
Working Charges	X	X	X	X
PB Labour Charges	1800	00	1400	00
Others Misc Charges	700	00	480	00
Paintwork	1800	00	1400	00
Total	\$ 11712	51	\$ 8398	98

Under normal circumstances, the duration of repairs should not exceed Seven (07) days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) & Public Holidays waiting time frame.

Attached photographs taken during inspection Eighty - Four (84) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 28/09/2018, we examined the extent of damages
3. On 04/10/2018, we examined the new replacement parts.
4. On 08/10/2018, we examined the repaired vehicle.

Yours Faithfully,



TF NG PHILIP FOO
ACII CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster

Inspection Report Date: 08 October 2018

VEHICLE REGN NO : SKT 4915 Z
 OUR REFERENCE : PAS/NP/181013/TP
 INSPECTION REPORT DATE : 8-Oct-18

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO : 1


S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
		PARTS SUPPLY - LIST ITEMS			
1	1pc	Bootlid	Badly Dented	\$ 1400.00 ^{cts}	\$ 1400.00 ^{cts}
2	1pc	Bootlid centre logo	Necessary	56.20	56.20
3	1pc	Bootlid 'Valve Matic' emblem	Necessary	41.17	41.17
4	1pc	Bootlid centre mldg	Bent	278.50	278.50
5	1pc	Bootlid upper lock	Bent	311.67	311.67
6	1pc	Bootlid lower lock	Bent	101.75	101.75
7	4pcs	Bootlid stopper@\$10.5	Bent	42.00	42.00
8	2pcs	Bootlid shock absorber@\$198.20	Bent	396.40	396.40
9	2pcs	Bootlid hinges@\$78.50	Bent	157.00	157.00
10	2pcs	Bootlid damper upper stay bracket@\$70	Serviceable	140.00	-
11	2pcs	Bootlid damper lower stay bracket@\$75	Serviceable	150.00	-
12	9pcs	Bootlid nuts@\$5	Necessary	45.00	45.00
13	1pc	Rear bumper	Badly Dented	574.67	574.67
14	2pcs	Rear bumper bracket@\$85.80	Bent	171.60	171.60
15	2pcs	Rear bumper side retainer@\$68.73	Bent	137.46	137.46
16	2pcs	Rear bumper inner side sponge@\$73.60	Serviceable	147.20	-
17	2pcs	Rear bumper reflector@\$57.70	Cracked	115.40	115.40
18	1set	Rear bumper clips	Necessary	46.68	46.68
19	1set	Rear panel	Badly Dented	704.93	704.93
20	1set	Rear panel centre switch	Cracked	171.67	171.67
21	1pc	Rear panel garnish	Bent	298.44	298.44
22	1set	Rear panel garnish clips	Necessary	25.68	25.68
23	1pc	Boot rubber	Torn	341.21	341.21
24	1pc	Rear windscreen upper mldg	Necessary	72.90	72.90
25	1pc	Rear windscreen lower mldg	Necessary	72.90	72.90
26	1pc	Rear windscreen left mldg	Necessary	69.54	69.54
27	1pc	Rear windscreen right mldg	Necessary	69.54	69.54
28	1pc	Spare tyre cover	Bent/Warped	473.00	473.00
29	2pcs	Rear panel beam@\$125	Bent	250.00	250.00
30	2pcs	Rear windscreen spacer@\$75	Serviceable	150.00	-
Less: 25% discount				7012.51	6425.31
				-	1606.33
				7012.51	4818.98
		SPECIAL NETT ITEMS			
1	1set	Rear bumper sensor	Dented	350.00	250.00
2	1pc	Rear windscreen sealant	Necessary	50.00	50.00
Total spare parts				7412.51	5118.98
		LABOUR & MISC. CHARGES			
1		Remove the necessary affected parts, cut/weld rear panel, straighten boot/floor both fenders and chassis and replace parts		1800.00	1400.00
2		Putty and Spraypaint (include rear bumper)		1800.00	1400.00
3		Check electrical		50.00	40.00
4		Tuff Kote		100.00	60.00
5		Remove and refit rear bumper sensors		100.00	60.00
6		Rewire rear portion		50.00	30.00
7		Remove and refit rear windscreen		150.00	120.00
8		Remove and refit bootlid components		100.00	80.00
9		Remove and refit reverse camera		100.00	60.00
10		Rewire reverse camera		50.00	30.00
XXX SUB / GRAND TOTAL				11712.51	8398.98

Repair days 5+1

TGum

8/11/18

PRECISION APPRAISAL SERVICES





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18017614/T1sd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 15-11-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 5041E	Veh. Inspected	SKT 4915Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020942	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1797	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZGE206019670	Colour	BLACK	
Odometer	109370	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2018	Inspection Date	27/09/2017	
Survey held at	NEW PIONEER AUTO - 1 SOON LEE ST #01-50			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 4915Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED	1,400.00	1,400.00
1	BOOTLID CENTRE LOGO	NECESSARY	56.20	56.20
1	BOOTLID 'VALVE MATIC' EMBLEM	NECESSARY	41.17	41.17
1	BOOTLID CENTRE MLDG	CRACKED	278.50	278.50
1	BOOTLID UPPER LOCK	BENT	311.67	311.67
1	BOOTLID LOWER LOCK	NOT NECESSARY	101.75	-
4	BOOTLID STOPPER @\$10.50	NOT NECESSARY	42.00	-
2	BOOTLID SHOCK ABSORBER @\$198.20	NOT NECESSARY	396.40	-
2	BOOTLID HINGES @\$78.50	NOT NECESSARY	157.00	-
2	BOOTLID DAMPER UPPER STAY BRACKET @\$70.00	SERVICEABLE	140.00	-
2	BOOTLID DAMPER LOWER STAY BRACKET @\$75.00	SERVICEABLE	150.00	-
9	BOOTLID NUTS @\$5.00	NECESSARY	45.00	45.00
1	REAR BUMPER	DENTED	574.67	574.67
2	REAR BUMPER BRACKET @\$85.80	BENT	171.60	171.60
2	REAR BUMPER SIDE RETAINER @\$68.73	NECESSARY	137.46	137.46
2	REAR BUMPER INNER SIDE SPONGE @\$73.60	SERVICEABLE	147.20	-
2	REAR BUMPER REFLECTOR @\$57.70	CRACKED	115.40	115.40
1	SET REAR BUMPER CLIPS	NECESSARY	46.68	46.68
1	SET REAR PANEL	DENTED	704.93	704.93
1	SET REAR PANEL CENTRE SWITCH	CRACKED	171.67	171.67
1	REAR PANEL GARNISH	CRACKED	298.44	298.44
1	SET REAR PANEL GARNISH CLIPS	NECESSARY	25.68	25.68
1	BOOT RUBBER	NOT NECESSARY	341.21	-
1	REAR WINDSCREEN UPPER MLDG	NECESSARY	72.90	72.90
1	REAR WINDSCREEN LOWER MLDG	NECESSARY	72.90	72.90
1	REAR WINDSCREEN LEFT MLDG	NECESSARY	69.54	69.54
1	REAR WINDSCREEN RIGHT MLDG	NECESSARY	69.54	69.54
1	SPARE TYRE COVER	NOT NECESSARY	473.00	-
2	REAR PANEL BEAM @\$125.00	BENT	250.00	250.00
2	REAR WINDSCREEN SPACER @\$75.00	SERVICEABLE	150.00	-

Report Ref No. CS3/LPC18017614/T1sd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-1,228.49
			7,012.51	3,685.46
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER SENSOR (SN)	CUT	350.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
			400.00	250.00
	<u>LABOUR</u>			
	REMOVE THE NECESSARY AFFECTED PARTS, CUT/WELD REAR PANEL, STRAIGHTEN BOOTFLOOR BOTH FENDERS AND CHASSIS AND REPLACE PARTS.		1,800.00	800.00
	PUTTY AND SPRAYPAINT (INCLUDE REAR BUMPER)		1,800.00	600.00
	CHECK ELECTRICAL.		50.00	40.00
	TUFF KOTE.		100.00	60.00
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	60.00
	REWIRE REAR PORTION.	NOT NECESSARY	50.00	-
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	80.00
	REMOVE AND REFIT BOOTLID COMPONENTS.		100.00	50.00
	REMOVE AND REFIT REVERSE CAMERA.		100.00	40.00
	REWIRE REVERSE CAMERA.	NOT NECESSARY	50.00	-
			4,300.00	1,730.00
	GRAND TOTAL		11,712.51	5,665.46
	RECOMMENDED COST OF REPAIRS			5,665.46

Report Ref No. CS3/LPC18017614/T1sd3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.