

22/03/2002

ASS. REC. BY:

REF:

CS3/LPC 18016540/Grd3-1<sup>02</sup>

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

05/11/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 9687R

Insured:

SGG 88800

at Workshop m/s

Team Autopro

Tel:

90927279

of

No. 385 Sin Ming Drive #01-02

Policy No:

Claim No: 1818118/vpos/020898

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A. 10/09/2018

CA / REV / REP. / REV 24 HRS

Lup?

H.O.D. Endorsement

Date/Time: 9:30am 11/11/18

Person Contacted

Alan

Vehicle IN/OUT


Date/Time	Action/Instruction (X) Estimate
	SLX 9687R -X
	SGG 88800 -X
	Submit PRS report
08/11/18	Submit LIS \$2800 @ 5 days Reel: \$3700, 571. Submit Paper survey.



RECEIVED 08 NOV 2018

Repair days 4

TGLim



7/11/18

PRG  
XHL

REF: LPC

AGENCY NAME

Event Date: 11/09/18  
Estimated Cost  
OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV  
Claimed Vehicle No: SLX9687R  
Team Autopro  
at Work location: No. 385 Sin Ming Drive #01-02  
Insured  
Policy No.  
Claims No.  
Sum Insured  
Excess  
(Client's Record)  
Make of Veh



(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value  
IDAC Accident Rpt Consistent? Yes or No  
GIA / PR Seen Consistent? Yes or No  
Est. Repairs: 4 days Res: Yes or No  
Lum Sum: 20 % 3 Val: Yes or No  
CA / REV / REP. 1-24 HRS caps

Date Person Contacted Vehicle: IN / OUT

Veh No: SLX9687R  
Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Honda Fit  
Colour: Silver  
Sp Reading: 106734  
Eng/No: 1339  
C/No: AE 61205618  
Gen Cond: ☒ Good / Fair / Poor / Burnt  
Steering: ☒ In order / Jammed / Leaked / Burnt or  
Brake: ☒ In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195/55R15  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or MAXXIS  
Front  
R/Bal: 6 mm  
L/Bal: 6 mm  
D.O.A.  
Survey held at: W/S 11-09-18 3:20pm  
Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
\$2000 - \$3000

RECEIVED

TGrim line  
7/11/18

Classification: ☐ Prel. Report  
☒ Final Report  
typist

Days Of Repair:  
Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. (\$)  
☐ Interview (\$)  
☐ Tech Insp. (\$)  
☐ Weekend (\$)

Survey Fee: 490  
Transportation  
Total: 490

Report Format:  
Lump Sum / L.B.E.C.

## Catherine Chong (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 5 November, 2018 3:25 PM  
**To:** Nivitha (LKK Auto); assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; 'SUR'  
**Subject:** RE: Our Ref: MKR/404/8238/2018/as.wl; Your Ref: Your insured vehicle no. SLX 9687R; Our Ref: 18/18/18/VP05/020898  
**Attachments:** 20898 TP SR.pdf

Dear Catherine/Nivitha

Attached is the TP survey report.

Please let us have your surveyor's review and report.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 11 September, 2018 9:36 AM  
**To:** ONG LI LI; assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; 'SUR'  
**Subject:** RE: Our Ref: MKR/404/8238/2018/as.wl; Your Ref: Your insured vehicle no. SLX 9687R; Our Ref: 18/18/18/VP05/020898

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [mailto:llong@lonpac.com]  
**Sent:** Tuesday, 11 September 2018 9:27 AM  
**To:** William Lee <william@roypartners.com.sg>; MT\_Claim\_SG <mt\_claim@lonpac.com>; assignments@lkkauto.com; catherine <admin-d@lkkauto.com>  
**Cc:** 'TeamAutoPro North' <teamautopl@gmail.com>  
**Subject:** RE: Our Ref: MKR/404/8238/2018/as.wl; Your Ref: Your insured vehicle no. SLX 9687R; Our Ref: 18/18/18/VP05/020898

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor

surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.'

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Dear Catherine/Nivitha

fya

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** William Lee [mailto:william@roypartners.com.sg]  
**Sent:** Monday, 10 September, 2018 6:02 PM  
**To:** MT\_Claim\_SG; ONG LI LI  
**Cc:** 'TeamAutoPro North'  
**Subject:** Our Ref: MKR/404/8238/2018/as.wl; Your Ref: Your insured vehicle no. SLX 9687R;  
**Importance:** High

Our Ref: MKR/404/8238/2018/as.wl;  
Your Ref: Your insured vehicle no. SLX 9687R;

Dear Sirs,

**Attn: Motor claims department**

**CLAIMANT:** MOHAMED NURULHAIZAT BIN MD ROSLAN (OWNER OF SLX 9687R)  
**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLX 9687R AND SGG 8880R ALONG PIE TUAS EXIT KALLANG  
BAHRU ON 10.09.2018 AT ABOUT 0943 HOURS.**

We refer to the above matter.

We act for Mohamed Nurulhaizat Bin Md Roslan, the owner of motor car No. **SLX 9687R**.

We are instructed by our client to notify you of a road traffic accident on 10.09.2018 at about 0943 am along PIE Tuas Exit Kallang Bahru involving our client's motor car registration number **SLX 9687R** and motor car registration number **SGG 8880R** driven by your insured at the material time. A copy of the Singapore Accident Statement is enclosed.

As a result of the accident, our client's motor car **SLX 9687R** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SLX 9687R** at our client's repairer workshop, M/s Team AutoPro Pte Ltd at No. 385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718, Your said surveyor may contact Mr. Alan at 9092 7279. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Thanks & regards,

**William Lee**

M/s Roy & Partners

101 Cecil Street


#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

# UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster  
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875  
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg  
Business Registration Nos. : 200817301N

Our ref. : UAM18.09.16-AK-STP-TAP-SLX9687R-R1  
Date : 15 Oct 2018

Mohamad Nurulhaizat Bin Md Roslan

**WITHOUT PREJUDICE**

Dear Sir,

**Re : Third Party Claim For Vehicle Registration No. SLX9687R**

We refer to your instruction to appraise the above-mentioned vehicle on 11 September 2018

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Team AutoPro Pte Ltd for SGD 11,216.50 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 8,143.68. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 6,500.00 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 8 (Eight) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc  
Motor Vehicle Appraiser

Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

# UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster  
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875  
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg  
Business Registration Nos. : 200817301N

## VEHICLE INSPECTION REPORT

To : Mohamad Nurulhaizat Bin Md Roslan

Our ref. : UAM18.09.16-AK-STP-TAP-SLX9687R-R1

Date : 15 Oct 2018

### REFERENCE

Assign by	: Mohamad Nurulhaizat Bin Md Roslan Insured	: To be advice
Assign on	: 11 Sep 2018	Policy no. : To be advice
Inspection on	: 11 Sep 2018	Claim no. : To be advice
Accident on	: 10 Sep 2018	Sum insured : To be advice
Workshop name	: Team AutoPro Pte Ltd	Excess : Not applicable
Inspection at	: 8, Kaki Bukit Ave 4	3rd party Veh. : To be advice
	#01-07 Premier@Kaki Bukit	3rd party ins. : To be advice
	Singapore 415875	

### PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SLX9687R	Odometer	: 106734 km
Make / Model	: Honda Fit 1.3G A	Chassis no.	: GE61205618
Regn. date	: 16 Jul 2009	Engine no.	: L13A4223206
Body colour	: Grey	Engine cap.	: 1339 cc

### PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

### TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Crucero	195/55R15	70%	Alloy
Front O/S	: Crucero	195/55R15	70%	Alloy
Rear N/S	: Maxxis	195/55R15	70%	Alloy*
Rear O/S	: Maxxis	195/55R15	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

\* Denotes damaged component/s

**POINT OF IMPACT**

On the near side rear in the direction from left to right.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the n/s rear door, rear fender, rear undercarriage, rear bumper and etc...

Please refer to Annex A (Appraisal Schedule) for a detailed account of the damages and photographs taken.

*Note: Reinspection vehicle on 12 Sep 2018 for repair in progress.*

**RECOMMENDATION**

The estimate cost of repair submitted by Messrs Team AutoPro Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 6,500.00 to carry out the repairs. Please refer to Annex A (Appraisal Schedule) for a detailed account of the cost estimates.

**REMARKS**

We have not authorised the repair. However, for information, under normal circumstances, the repair would take approximately 8 (Eight) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,  
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc  
Motor Vehicle Appraiser



## APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLX9687R

Our reference : UAM18.09.16-AK-STP-TAP-SLX9687R-R1

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
-----	-----	-------------	---------------------	-----------------------	------------------

LIST ITEMS

1	1	Rear door n/s	Dented	898.50	898.50 DD ✓
2	1	Rear door weatherstrip n/s	Necessary	165.40	165.40 NN ✓
3	1	Rear door trimboard n/s	Cracked	436.70	436.70 CR ✓
4	1set	Rear door trimboard clip n/s	Necessary	50.00	50.00 NEC ✓
5	1	Rear door inner lock n/s	Distorted	218.90	218.90 BT ✓
6	1	Rear door outer handle n/s	Distorted	176.30	176.30 NN ✓
7	1	Rear door regulator assy n/s	Shorted	373.40	373.40 BT ✓
8	1	Rear fender n/s	Dented	730.20	730.20 DD ✓
9	1	Rear fender glass moulding n/s	Necessary	83.10	83.10 NEC ✓
10	1	Rear fender air vent n/s	Deformed	108.70	108.70 NN ✓
11	1	Rear shock absorber n/s	Distorted	356.50	356.50 NN ✓
12	1	Rear wheel hub n/s	Distorted	382.70	382.70 NN ✓
13	1	Rear wheel hub bearing n/s	Distorted	208.50	208.50 DL ✓
14	1	Rear axle beam	Re-Used	1144.40	0.00
15	1	Rear bumper	Damaged	669.20	669.20 RX ✓
16	1set	Rear bumper clip	Necessary	60.00	60.00 NEC ✓
17	1	Rear bumper side retainer n/s	Distorted	124.00	124.00 NN ✓
				6186.50	5042.10
Less 0% / 20%				0.00	1008.42
				6186.50	4033.68

SPECIAL NETT ITEMS

1	1	Sundries	Necessary	50.00	30.00 NEC ✓
2	1	Rear fender sealant n/s	Necessary	100.00	80.00 50.00 NN ✓
3	1	Rear fender glass primer and cleaner n/s	Necessary	100.00	80.00 NN ✓
4	1	Rear fender glass sealant n/s	Necessary	100.00	80.00 50.00 NN ✓
5	1	Rear fender glass inner seal n/s	Necessary	100.00	80.00 50.00 NN ✓
6	1	Rear alloy rim n/s	Deep Grazed	380.00	360.00 CUT ✓
7	1	Rear tyre n/s	Cut	160.00	120.00 NN ✓
				990.00	830.00
<b>TOTAL</b>				7176.50	4863.68

## APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLX9687R

Our reference : UAM18.09.16-AK-STP-TAP-SLX9687R-R1

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Part Balance C/F	7176.50	4863.68
<u>LABOUR &amp; MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		1500.00	1330.00 <del>800.00</del> 600
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	-60.00 40.00
3		To remove and refit interior upholstery to facilitate the repair.		200.00	180.00 <del>80.00</del>
4		To remove and refit n/s rear door component to replace n/s rear door, check and alignment.		100.00	80.00 <del>100.00</del> 60 ✓
5		To remove and refit n/s rear fender glass to facilitate the repair.		180.00	150.00 <del>80.00</del> X
6		To remove and refit n/s tyre to replace n/s rims To perform tyre balancing.		80.00	60.00 <del>30</del> ✓
7		To remove and refit rear undercarriage for replacement of part.		300.00	280.00 <del>100.00</del>
8		To conduct computerize full wheel alignment.		120.00	100.00 <del>60</del> ✓
9		To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test on the distance and functions.		80.00	60.00 <del>NNX</del>
10		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00 <del>60.00</del>
11		Supply spray paint material and necessary items to respray n/s rear door, rear fender, rear bumper and other affected area / panel.		1200.00	800.00 <del>400.00</del> +200
<b>TOTAL</b>				4040.00	3280.00
<b>Total Parts and Labour Cost of Repair</b>				11216.50	8143.68
<b>Less (Lumpsum repair adjustment)</b>					1643.68
<b>Adjustment Parts and Labour Cost of Repair</b>					6500.00

Repair days 4 + 1 = 5

Team

lim

7/11/18




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18016540/Grd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 09-11-2018	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGG 8880D	Veh. Inspected	SLX 9687R	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020898	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/11/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61205618	Colour	SILVER	
Odometer	106734	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	MAXXIS	6 mm	
L/H Front Tyre	195/55 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/55 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/55 R15	MAXXIS	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/09/2018	Inspection Date	11/09/2018	
Survey held at	385 SIN MING DRIVE			
Repairer	TEAM AUTOPRO PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 9687R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR DOOR N/S	DENTED	898.50	740.00
1	REAR DOOR WEATHERSTRIP N/S	NOT NECESSARY	165.40	-
1	REAR DOOR TRIMBOARD N/S	CRACKED	436.70	436.70
1	SET REAR DOOR TRIMBOARD CLIP N/S	NECESSARY	50.00	30.00
1	REAR DOOR INNER LOCK N/S	BENT	218.90	218.90
1	REAR DOOR OUTER HANDLE N/S	NOT NECESSARY	176.30	-
1	REAR DOOR REGULATOR ASSY N/S	BENT	373.40	373.40
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	730.20	-
1	REAR FENDER GLASS MOULDING N/S	NOT NECESSARY	83.10	-
1	REAR FENDER AIR VENT N/S	NOT NECESSARY	108.70	-
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	356.50	-
1	REAR WHEEL HUB N/S	NOT NECESSARY	382.70	-
1	REAR WHEEL HUB BEARING N/S	DISLodge	208.50	208.50
1	REAR AXLE BEAM	REUSE	1,144.40	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	669.20	-
1	SET REAR BUMPER CLIP	NECESSARY	60.00	30.00
1	REAR BUMPER SIDE RETAINER N/S	DISTORTED	124.00	124.00
	LESS 20% DISCOUNT		-	-432.30
			6,186.50	1,729.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER SEALANT N/S (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER GLASS PRIMER AND CLEANER N/S (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER GLASS SEALANT N/S (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER GLASS INNER SEAL N/S (SN)	NOT NECESSARY	100.00	-
1	REAR ALLOY RIM N/S (SN)	CUT	380.00	250.00
1	REAR TYRE N/S (SN)	NOT NECESSARY	160.00	-
			990.00	250.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR BUMPER.		1,500.00	600.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.		80.00	40.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.		200.00	80.00
	TO REMOVE AND REFIT N/S REAR DOOR COMPONENT TO REPLACE N/S REAR DOOR, CHECK AND ALIGNMENT.		100.00	60.00
	TO REMOVE AND REFIT N/S REAR FENDER GLASS TO FACILITATE THE REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT N/S TYRE TO REPLACE N/S RIMS TO PERFORM TYRE BALANCING.		80.00	30.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGE FOR REPLACEMENT OF PART.		300.00	100.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		120.00	60.00
	TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS.	NOT NECESSARY	80.00	-
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.		200.00	60.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY N/S REAR DOOR, REAR FENDER, REAR BUMPER AND OTHER AFFECTED AREA / PANEL.		1,200.00	600.00
			4,040.00	1,630.00
	<b>GRAND TOTAL</b>		<b>11,216.50</b>	<b>3,609.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,800.00</b>

Report Ref No. CS3/LPC18016540/Grd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.