

ASS. REC. BY:

REF: CS/FCI18020090 /Dvbn2 | Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): CWS Lurene Jaw of FCI Date/Time: 05.11.2018 7:14pm

Estimated Cost: Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 4918K Insured: SHC 7258S

at Workshop m/s Churni Motor Tel: 65425119

of 10 Amk Ind Park 2A # 01-05

Policy No: Claim No: D18007916MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 02.11.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 07.11.2018 9:15am Person Contacted: Lynn Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 4918K - CS / 971715018330 / M1wb392 0A 2510:15
	SHC 7258S - X
13/11/18	Email preli revised to FCI

REF:

ASSIGNMENT

COE 2022 March
March

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 4918 K Yr Regn: 2014

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai I40 cc 1685Colour: Blue A/C: Insured / Std / NI / NASp Reading: 618479 T/Radio: Insured / Std / NI / NAEng/No: D4FDRU411146C/No: KMHLB41UMEU052821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal: S mm R/Bal: S mmL/Bal: S mm L/Bal: S mmD.O.A: 02/11/2018 D.O.I: 07/11/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body y 4/5 Body N/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Report SHC # 7258804/12/18 Final 2/5 13350/- with 9 days of work (Ref 9263-76, 4190)

RECEIVED 05 DEC 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 4/12 - typistReport Format: CWSLump Sum / I.B.I: (\$) 13,350/2Days Of Repair: 9Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation

S - P - C - I

Photo: 580Others: 837

5/12/18

12x15: 180

170+180

50

50+50

126

626



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007916MFSH

Our ref: CS/FCI18020090/Dvb

Date: 13/11/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 4918K


We thank you for your instruction on 5/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 7/11/2018 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$22,613.76
Revised Estimate Amount	: S\$16,742.08
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion and n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	05-11-2018	Our Ref No. D18007916MFSH
Accident Date	02-11-2018	Claim Type. Third Party
Insured Vehicle	SHC7258S	Third Party Vehicle. SHD4918K
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06.	
Contact Person.	LYNN OR IRENE - 65425119	
Contact No.	65425119/ 65427162	Fax No. 65426039
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 13 November 2018 8:56 AM
To: 'CWS Motor Claims'
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007916MFSH/1, SHD 4918K
Attachments: SHD 4918K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 4918K
Date of survey: 7/11/2018
Number of days : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 7 November 2018 9:19 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007916MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 5 November, 2018 7:14 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007916MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 4918K

DATE : 5.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

First Capital

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender With Housing (LH) <i>Dented</i>			\$ 4,736.80	✓
	Rear Windscreen Moulding <i>Hec</i>			\$ 28.30	✓
	Rear Door (LH) <i>Dented</i>			\$ 2,201.10	✓
	Rear Door Gear/Regulator (LH) <i>2 check</i>			\$ 242.80	✓
	Rear Door Hinge Upper (LH) <i>SVL</i>			\$ 45.90	X
	Rear Door Hinge Lower (LH) <i>SVL</i>			\$ 45.90	X
	Rear Door Check (LH) <i>SVL</i>			\$ 62.90	X
	Rear Door Trim Board (LH) <i>2 mounty broken</i>			\$ 808.70	✓
	Front Door (LH) <i>Dented</i>			\$ 2,256.40	✓
	Front Door Mirror Assy (LH) <i>crack</i>			\$ 670.00	✓
	Door Centre Pillar Outer (LH) <i>Dented</i>			\$ 2,527.80	✓
	Rocker Panel Inner (LH) <i>NH</i>			\$ 1,285.50	X
	Rocker Panel Outer Garnish (LH) <i>mounty crack</i>			\$ 341.40	✓
	Rocker Panel Outer <i>NH</i>			\$ 1,310.60	X
	Rear Tyre Rim (LH) <i>2 distorted</i>			\$ 325.30	✓
	Rear Wheel Hub-Cap (LH) <i>cut</i>			\$ 107.10	✓
	Rear Wheelbearing IN & Hub <i>2 dm</i>			\$ 362.00	✓
	Rear Trailing Arm (LH) <i>2 distorted</i>			\$ 192.00	✓
	Rear Assist (LH) <i>2 distorted</i>			\$ 145.70	✓
	Rear Shock Absorber (LH) <i>2 distorted</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (LH) <i>NH</i>			\$ 81.30	X
	Rear Crossmember <i>2 distorted</i>			\$ 1,021.50	✓
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60	✓
	Stabilizer Link <i>2 distorted</i>			\$ 85.90	✓
	Rear Upper Arm (LH) <i>2 distorted</i>			\$ 335.75	✓
	Rear Lower Arm (LH) <i>2 distorted</i>			\$ 353.80	✓
	Rear Knuckle Arm (LH) <i>2 distorted</i>			\$ 545.60	✓
			17763.85		
			14211.08		
	SUB TOTAL			\$ 20,595.95	
	LESS 20%			\$ 4,119.19	
	DISCOUNTED TOTAL			\$ 16,476.76	
	Rear Fender Advertisement Logo (LH/RH) <i>n/s Hec</i>	<i>o/s NH</i>	\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Hec</i>			\$ 80.00	Nett ✓
	Front Door Coloured Comfort Logo (LH) <i>Hec</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Tyre (LH) <i>SVL</i>		501.00	\$ 216.00	Nett X
				\$ 817.00	

SHD 4918K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,800.00 800/-
	Spray Painting Charge			\$ 1,600.00 700/-
	Wiring Charge			\$ 100.00 NH
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 NH
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 80.00 NH
	Transfer of Door	S	80.00	\$ 160.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 ? 150/-
	Rear Wheel Alignment			\$ 80.00 ? 60/-
	Re-set Rear ABS System			\$ 200.00 NH
	Re-set Rear Power Window System		2030.00	\$ 200.00 NH
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 NH
	TOTAL LABOUR			\$ 5,320.00
	ESTIMATE TOTAL			\$ 22,613.76
	07/11/2018 e 1130hrs Not done L/same Pay 9 days. LKK Auto		16742.08 4/5 13350.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHD 4918 K

Technician:

Mileage: 618476

Time Printed 7.11.18 9:37 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-1°46'		-3°00' 3°00'
3°50'		-0°19' 5°41'
-0°19'		-1°30' 1°30'
20°45'		
18°59'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°14'		-3°00' 3°00'
4°14'		-0°19' 5°41'
0°12'		-1°30' 1°30'
13°52'		
14°06'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-2°00'		-3°00' 3°00'
-0°25'		-3°00' 3°00'
6°53'		-3°00' 3°00'
-0°06'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
5°25'		-3°30' 2°30'
6°15'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
1°32'		-3°30' 2°30'
0°17'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
3°53'		-3°00' 3°00'
6°32'		-3°00' 3°00'
2°59'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020090/Dvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7258S	Veh. Inspected	SHD 4918K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007916MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	05/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU052821	Colour	BLUE	
Odometer	618479	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2018	Inspection Date	07/11/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4918K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER WITH HOUSING (LH)	DENTED	4,736.80	4,736.80
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	REAR DOOR GEAR/REGULATOR (LH)	CRACKED	242.80	242.80
1	REAR DOOR HINGE UPPER (LH)	SERVICEABLE	45.90	-
1	REAR DOOR HINGE LOWER (LH)	SERVICEABLE	45.90	-
1	REAR DOOR CHECK (LH)	SERVICEABLE	62.90	-
1	REAR DOOR TRIM BOARD (LH)	MOUNTING BROKEN	808.70	808.70
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR MIRROR ASSY (LH)	CRACKED	670.00	670.00
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	2,527.80	2,527.80
1	ROCKER PANEL INNER (LH)	NOT NECESSARY	1,285.50	-
1	ROCKER PANEL OUTER GARNISH (LH)	MOUNTING CRACKED	341.40	341.40
1	ROCKER PANEL OUTER	NOT NECESSARY	1,310.60	-
1	REAR TYRE RIM (LH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-4,119.19	-3,552.77
			16,476.76	14,211.08

Report Ref No. CS/FC118020090/Dvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	N/S NECESSARY / O/S NOT NECESSARY	200.00	100.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			817.00	501.00
	LABOUR			
	PANEL BEATING.		1,800.00	800.00
	SPRAY PAINTING CHARGE.		1,600.00	700.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR.		160.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		80.00	60.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	200.00	-
	RE-SET REAR WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	-		-	-
	-		-	-
	-		-	-
			5,320.00	2,030.00
	GRAND TOTAL		22,613.76	16,742.08

Report Ref No. CS/FC118020090/Dvbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,350.00
---	--	--	-----------

Report Ref No. CS/FCI18020090/Dvbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.