

S.S. REC. BY:

REF:

CS/FCL18020092/Dsb02

Special Instruction:

Surveyor: Bryan.

ASSIGNMENT (Office)

From (Person):

CWS Lurene Jund

of

FCL

Date/Time:

05/11/2018 728pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3457X

Insured:

SHB 2180U

at Workshop m/s

Chunni motor

Tel:

6542 5119

of

Blk 10 AMK Ind Park 2A #01-05

Policy No:

Claim No:

D18007919 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03.11.2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

07/11/2018 9:15am

Person Contacted:

Lynn

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 3457X - CS/FCL18011483/Ked3g2
	SHB 2180U - CS/TMP15002528/H11bd1
09/11/18	@ 16:39 p.m. revised PA to Lurene Jund via email.

DIA: 160618

DIA: 100715

REF:

ASSIGNMENT

COE Jan 2024

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 3457 X Yr Regn: 2016 JanType: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685Colour: Blue A/C: _____ Insured / Std / NI / NASp Reading: N.A. T/Ratio: Insured / Std / NI / NAEng/No: D4FDP4579758C/No: KMHLB41UMGU083028Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: MM / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Campeon

Front

Rear

R/Bal: S mm R/Bal: S mmL/Bal: S mm L/Bal: S mmD.O.A: 03/11/2018 D.O.I: 07/11/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHB 2180u

04/12/18 Hyundai I40 11350/- with 9 days of rep04/12/18 Confirmed HS \$11,350/- @ 9 days with Bryan.
(\$8,058.96 Red-42%)

RECEIVED 05 DEC 2018

Date/Time: File Pass to?

05/12/18
Typist☐

Preli. Report

☒

Final Report

Date/Time: File Return to?

2)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Days Of Repair: 9Resurvey No. of Trip: 2

Survey Fee

Transportation

) \$ + RS \$

) Photo OSP) Other 11/12/18

) TOTAL

TOTAL

9x15: 135

170+135

50

50+50

125

580

Report Format :

Lump Sum / I.B.I: (\$) 11,350/- 4/5



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007919MFSH

Date: 09 November 2018

Our Ref: CS/FCI18020092/Dsb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 3457X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/11/2018 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,408.96</u> .
Revised Estimate Amount	: S\$ <u>14,247.20</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 7 Days

Yours faithfully,
Bryan Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-11-2018	Our Ref No. D18007919MFSH
Accident Date	03-11-2018	Claim Type. Third Party
Insured Vehicle	SHB2180U	Third Party Vehicle. SHA3457X
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: PENDING BOTH VF TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 9 November 2018 4:39 PM
To: 'Lurene Jaw'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18007919MFSH/1
Attachments: SHA 3457X - Preli Advise -.pdf

Dear Lurene,

Enclosed preliminary revised of vehicle SHA 3457X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 7 November 2018 9:25 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007919MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 5 November, 2018 7:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007919MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

REPAIR ESTIMATE*

VEHICLE NO : SFLA 3457X

DATE : 5.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

First Capital

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>distorted</i>			\$ 1,052.20 ✓
	Front Bumper Sponge <i>S/c</i>			\$ 99.20 X
	Front Bumper Reinforcement <i>NH</i>			\$ 402.10 X
	Front Bumper Grille (LH) <i>S/c</i>			\$ 93.60 X
	Front Bumper Grille Airduct (LH) <i>NH</i>			\$ 26.20 X
	Front Bumper Bracket Top (LH/RH) <i>NH</i>	\$	22.40	\$ 44.80 X
	Front Bumper Bracket (LH/RH) <i>H/S broken o/s NH</i>	\$	(24.60)	\$ 49.20 ✓
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40 ✓ photo
	Headlamp (LH) <i>broken</i>			\$ 1,388.00 ✓
	Front Fender (LH) <i>Dented</i>			\$ 566.30 ✓
	Front Fender Apron Panel (LH) <i>Dented</i>			\$ 637.00 ✓
	Front Fender Shield (LH) <i>torn</i>			\$ 174.90 ✓
	Front Fender Retainer <i>NH</i>			\$ 24.60 X
	Front Door (LH) <i>NH</i>			\$ 2,256.40 X
	Front Door Mirror Assy (LH) <i>Crack</i>			\$ 670.00 ✓
	Front Wheel Rim (LH) <i>& distorted</i>			\$ 325.30 Z ✓
	Front Wheel Hub Cap (LH) <i>crack</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>Z & Dam</i>			\$ 150.90 Z ✓
	Front Shock Absorber (Assy) (LH) <i>& distorted</i>			\$ 342.20 Z ✓
	Front Shock Absorber Mounting (LH) <i>NH</i>			\$ 108.80 X
	Front Drive Shaft (LH) <i>& distorted</i>			\$ 1,030.80 Z ✓
	Rack & Pinion Assy <i>& Dam</i>			\$ 969.60 Z ✓
	STG Tie End <i>& distorted</i>			\$ 62.60 Z ✓
	Stabilizer Bar <i>& distorted</i>			\$ 252.30 Z ✓
	Stabilizer Bar Bush (LH) <i>NH</i>			\$ 16.40 X
	Stabilizer Bar Link <i>& distorted</i>			\$ 61.10 Z ✓
	Stabilizer Bracket <i>NH</i>			\$ 24.00 X
	Front Suspension Lower Arm (LH) <i>& distorted</i>			\$ 529.30 Z ✓
	Knuckle Arm (LH) <i>& distorted</i>			\$ 552.00 Z ✓
	Engine Crossmember <i>& distorted</i>			\$ 2,094.40 Z ✓
	ABS Sensor <i>NH</i>			\$ 234.00 X
	Wiring-Engine housing <i>check</i>			\$ 3,326.00 ✓ photo
	SUB TOTAL			\$ 18,578.70
	LESS 20%			\$ 3,715.74
	DISCOUNTED TOTAL			\$ 14,862.96
	Front Tyre (LH) <i>cut</i>			\$ 216.00 Net ✓
				108.00

15224.00
12179.20

50% dep
108.00

SHA 3457X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,200.00 700/-
	Spray Painting Charge			S 900.00 600/-
	Wiring Charge			S 100.00 30/-
	Tuff Kote			S 100.00 40/-
	Towing Charge			S 50.00 11/-
	Transfer of Door			S 80.00 11/-
	Remove/Refix Undercarriage (FRT)			S 200.00 180/-
	FRT Wheel Alignment			S 120.00 60/-
	Re-set Frt ABS System			S 200.00 11/-
	Remove/Refix Aircon & Refill Gas			S 150.00 11/-
	Remove/Refix Dashboard		1840.00	S 450.00 180/-
	Remove/Refix Fuse Box			S 180.00 50/-
	Diagnostic & Resetting To Erase Fault Code			S 480.00 11/-
	TOTAL LABOUR			S 4,210.00
	ESTIMATE TOTAL			S 19,288.96
				19,408.96
	07/11/2018 c 1145hrs		14127.20	
	Not Author	Syrip	150.00	120.00
	1/1/2019 9 days.		14277.20	
	Tyari		14247.20	
	LKK Auto		1/511350.00	
				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party's survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and approved to final approval from Insurance Company known/edged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3457X (Supplementary)

DATE : 7.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender Side Garnish (LH) <i>cont</i>			\$ 150.00 ✓
	SUB TOTAL			\$ 150.00
	LESS 20%			\$ 30.00
	DISCOUNTED TOTAL			\$ 120.00
	<i>Ryan</i> <i>JKE Auto</i> 			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME

ADDRESS

Home Tel.:

VIN:

Registration: SHA 3457 X

Technician:

Mileage: 418288

Time Printed 7.11.18 9:00 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°57'		-3°00' 3°00'
3°53'		-0°19' 5°41'
6°37'		-1°30' 1°30'
21°06'		
20°08'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°32'		-3°00' 3°00'
4°14'		-0°19' 5°41'
-0°10'		-1°30' 1°30'
10°52'		
13°24'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-3°29'		-3°00' 3°00'
-0°21'		-3°00' 3°00'
10°14'		-3°00' 3°00'
6°27'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°45'		-3°30' 2°30'
0°33'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°36'		-3°30' 2°30'
-0°20'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°09'		-3°00' 3°00'
0°13'		-3°00' 3°00'
0°26'		-3°00' 3°00'

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18020092/Dsbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-12-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2180U	Veh. Inspected	SHA 3457X
Policy No.		Coverage (\$)	0.00
Claim No.	D18007919MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	05/11/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU083028	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	5 mm
L/H Front Tyre	205/60 R16	CAMPEON	5 mm
R/H Rear Tyre	205/60 R16	CAMPEON	5 mm
L/H Rear Tyre	205/60 R16	CAMPEON	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/11/2018	Inspection Date	07/11/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3457X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DISTORTED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	SERVICEABLE	99.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	402.10	-
1	FRONT BUMPER GRILLE (LH)	SERVICEABLE	93.60	-
1	FRONT BUMPER GRILLE AIRDUCT (LH)	NOT NECESSARY	26.20	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	N/S BROKEN / O/S NOT NECESSARY	49.20	24.60
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	BROKEN	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	TORN	174.90	174.90
1	FRONT FENDER RETAINER	NOT NECESSARY	24.60	-
1	FRONT DOOR (LH)	NOT NECESSARY	2,256.40	-
1	FRONT DOOR MIRROR ASSY (LH)	CRACKED	670.00	670.00
1	FRONT WHEEL RIM (LH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	CRACKED	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	150.90	150.90
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT FRIVE SHAFT (LH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	16.40	-
1	STABILIZER BAR LINK	DISTORTED	61.10	61.10
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40

Report Ref No. CS/FCI18020092/Dsbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABS SENSOR	NOT NECESSARY	234.00	-
1	WIRING-ENGINE	MOUNTING CRACKED	3,326.00	3,326.00
1	FRONT FENDER SIDE GARNISH (LH)(ADDITIONAL)	CUT	150.00	150.00
	LESS 20% DISCOUNT		-3,745.74	-3,074.80
			14,982.96	12,299.20
	SPECIAL NETT ITEMS			
1	FRONT TYRE (LH)(50%)(DEPRECIATION)(SN)	CUT	216.00	108.00
			216.00	108.00
	LABOUR			
	PANEL BEATING		1,200.00	700.00
	SPRAY PAINTING CHARGE		900.00	600.00
	WIRING CHARGE		100.00	30.00
	TUFF KOTE		100.00	40.00
	TOWING CHARGE	NOT NECESSARY	50.00	-
	TRANSFER OF DOOR	NOT NECESSARY	80.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT)		200.00	180.00
	FRT WHEEL ALIGNMENT		120.00	60.00
	RE-SET FRT ABS SYSTEM	NOT NECESSARY	200.00	-
	REMOVE/REFIX AIRCON & REFILL GAS	NOT NECESSARY	150.00	-
	REMOVE/REFIX DASHBOARD		450.00	180.00
	REMOVE/REFIX FUSE BOX		180.00	50.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	NOT NECESSARY	480.00	-
			4,210.00	1,840.00
GRAND TOTAL			19,408.96	14,247.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,350.00

Report Ref No. CS/FCI18020092/Dsbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.