



Your Ref: S8M00JUK

Date: 15th Nov 2018

Our Ref: CS3/ASM18010846/Avbe2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn : Chan Kian Chuan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBA 3738G
INSURED VEHICLE: XB 8022P
ACCIDENT DATE: 05/06/2018**

We thank you for your instruction on 07/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBA 3738G from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement and Police Report of Vehicles GBA 3738G.
- c) Final Repair Bill of GBA 3738G from Halland Motor Service.
- d) Colour damaged vehicle photographs of GBA 3738G.

Pre-Repair Inspection Date : 14/06/2018 at M/s Halland Motor Service, No.1 Kaki Bukit Ave 6 #02-24, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBA 3738G
Make & Model	: Daihatsu Hijet 660 M
Year of Registration	: 2007
Chassis Number	: S320V0082042
Engine Capacity	: 659 cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.