

ASS. REC. BY:

REF: CS/FCL18020120/UTbn2 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Meng Chua of FCL Date/Time: 07-11-2018 223pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 5541G Insured: SHC 8650K

at Workshop m/s Jin Auto Tel: 6289 8126

of Bk 14 Defu Lane 1D # 01-410

Policy No: Claim No: D18007920MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 03112018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 07112018 233pm Person Contacted: Jonis Vehicle-IN / OUK

Date/Time	Action/Instruction (✓) Estimate
	GBH 5541G - X
	SHC 8650K - CS / FCL1707463 / Ktbn2 D.O.A. 03192017
12/11/2018 4:39pm	Revised email pending estimate

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

1.3%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3068R

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

G6BH554G

Yr Regn:

7, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Lince DX

c.c

2754

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

16914

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GDI 2212001162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/11/18

D.O.I.

9/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/11/18 LTA 137R
14/11/18 Confirmed find by # 440877 with Jans. Cred. 94668: 17%

RECEIVED 22 NOV 2018

Date/Time, File Pass to?



: Preli. Report

1) 21/11 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 4408.77)

140

50

50

79

319

MOTOR SURVEY ASSIGNMENT

Date	05-11-2018	Our Ref No. D18007920MFSH
Accident Date	02-11-2018	Claim Type. Third Party
Insured Vehicle	SHC8650K	Third Party Vehicle. GBH5541G
Survey Location	BLK 14 #01-410/412 DEFU LANE 10	
Contact Person.	JOUIS SEOW	
Contact No.	62898126/ 0	Fax No. 62870590
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	JIN AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 12 November 2018 4:39 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007920MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBH 5541G on 9/11/2018
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 7 November 2018 2:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007920MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 7 November, 2018 2:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007920MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3608R

Vehicle Details

Vehicle No.:	GBH5541G
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1GD8286771
Chassis No.:	GDH2012001162
Maximum Power Output:	-
Open Market Value:	\$33,914.00
Original Registration Date:	11 Jul 2018
First Registration Date:	11 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$1,696.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	10 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$14,181.00
COE Rebate Amount:	\$13,712.00
Total Rebate Amount:	\$13,712.00

The information contained herein is correct as at 09 Nov 2018

OK

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not allowed
new
2/2 4408.77
5 day
9/11/18

14/11/2018

M/S FIRST CAPITAL INSURANCE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GBH5541G TOYOTA HIACE GDA2012001162

	QTY	List Items	AMOUNT
1	1 PC	REAR TAILGATE <i>Body</i>	\$ 2,072.80 ✓
2	1 PC	"HIACE. " STICKER <i>new</i>	\$ 39.70 ✓
3	1 PC	LOGO <i>new</i>	\$ 66.80 ✓
4	1 PC	TAILGATE RUBBER <i>new</i>	\$ 368.90 X
5	6 PCS	REAR BUMPER CLIPS <i>new</i>	\$ 22.80 ✓
6	1 PC	REAR BUMPER <i>new</i>	\$ 373.90 ✓
7	1 PC	REAR END PANEL outer <i>Body</i>	\$ 323.90 ✓
8	1 PC	STEP PANEL <i>new</i>	\$ 227.50 ✓
9	1 PC	REAR LH LAMP COVER (APRON PANEL) <i>new</i>	\$ 84.30 ✓
			\$ 3,580.60
			less 25% \$ (895.15)
			\$ 2,685.45
10	1 set	REVERSE SENSOR <i>short</i>	\$ 280.00 2005.00
11	1 SET	SEALANT <i>Rear window</i> <i>new</i>	\$ 60.00 40 5.00
12	1 PC	70KM/H STICKER <i>new</i>	\$ 15.00 10 5.00
13		REMOVE AND RENEW SENSOR	\$ 80.00 - 50
14		TUFF KOTE	\$ 80.00 - 60
15		TO REMOVE AND RENEW TAILGATE GLASS	\$ 120.00 - ✓
16		TO PUTTY AND SPRAY PAINTING	\$ 1,000.00 700
17		CHECK HARNESS	\$ 35.00 - 20
18		TO REMOVE, RENEW PARTS, REPAIR INNER PANEL	\$ 1,000.00 - 800
			\$ 5,355.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

2-3211.7
252
2408.77
2000.00
4408.77



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18020120/Utn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8650K	Veh. Inspected	GBH 5541G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007920MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	07/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX (A)	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GDH2012001162	Colour	SILVER	
Odometer	16914	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	195/80 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	195/80 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/80 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2018	Inspection Date	09/11/2018	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5541G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BADLY DENTED	2,072.80	2,072.80
1	"HIACE" STICKER	NECESSARY	39.70	39.70
1	LOGO	NECESSARY	66.80	66.80
1	TAILGATE RUBBER	NOT NECESSARY	368.90	-
6	REAR BUMPER CLIPS	NECESSARY	22.80	22.80
1	REAR BUMPER	DISTORTED	373.90	373.90
1	REAR END PANEL OUTER	BADLY DENTED	323.90	323.90
1	STEP PANEL	BENT	227.50	227.50
1	REAR LH LAMP COVER (APRON PANEL)	DENTED	84.30	84.30
	LESS 25% DISCOUNT		-895.15	-802.93
			2,685.45	2,408.77
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	70KM/H STICKER (SN)	NECESSARY	15.00	10.00
			355.00	250.00
LABOUR				
	REMOVE AND RENEW SENSOR.		80.00	50.00
	TUFF KOTE.		80.00	60.00
	TO REMOVE AND RENEW TAILGATE GLASS.		120.00	120.00
	TO PUTTY AND SPRAY PAINTING.		1,000.00	700.00
	CHECK HARNESS.		35.00	20.00
	TO REMOVE,RENEW PARTS REPAIR INNER PANEL.		1,000.00	800.00
	-		-	-
	-		-	-
	-		-	-
			2,315.00	1,750.00
GRAND TOTAL			5,355.45	4,408.77
RECOMMENDED COST OF REPAIRS				4,408.77

Report Ref No. CS/FC118020120/Utnb2



Report Ref No. CS/FCI18020120/Utbn2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.