



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8807U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	BUCKLED	450.80	450.80
10	FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	107.20	107.20
1	FRONT BUMPER EMBLEM (CONSISTENT)	NECESSARY	87.10	87.10
1	LH FRONT FENDER (CONSISTENT)	BENT	868.70	868.70
1	LH FRONT FENDER UNDERSHIELD (CONSISTENT)	DAMAGED	195.60	195.60
10	LH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	NOT NECESSARY	25.00	-
1	LHF FENDER WORDING 'HYBRID' (CONSISTENT)	NECESSARY	44.17	44.16
1	LH REAR HUB CAB (CONSISTENT)	DENTED	195.65	195.65
	LESS 25% DISCOUNT		-503.56	-497.30
			1,510.66	1,491.91
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(FRONT BUMPER ,LHF FENDER).		600.00	400.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,LHF FENDER).		600.00	400.00
	TO CHECK WIRING .		50.00	15.00
	TO DO WHEEL ALIGNMENT.		150.00	60.00
	TO TUFF COAT.		80.00	30.00
			1,480.00	905.00
	GRAND TOTAL		2,990.66	2,396.91
	RECOMMENDED COST OF REPAIRS			2,396.91

Report Ref No. CC4/ASM18020137/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.