

ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	SL	.S 8807 U	Not Notharh
Parts (a) Cost / List Price Items	\$	2,014.22	rasony Bapains
Plus/Less25%	\$	503.56	
Total of Cost / List	\$	1,510.67	LKK Auto Consultants hence notify the Repairer of the follows:
(b) Nett Price Items	-		• To resurvey bed
Less			Parts prices are subject to confirmation Third parts are:
Total of Nett Item			No illegal modification(s) is allowed Supplemental to the second secon
(c) Special Nett Items			Acknowledged by Ropeins
Total Parts Cost			Signature: Date:
Labour	\$	1,480.00	
Total	\$	2,990.67	
The above total will be subjected to 7	7% G.S.T.		
Name of Surveyor	:		Kennern
Company			LICIC
Survey conducted on	ì		12/11/18 at
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized /	is not authorized until	further notice.
(b) Recommended Days of Rep	pair :	0	<i>⊈</i> day(s)
(c) Resurvey	1	Required / NothBequi	fed
(d) Excess	:\$		
(e) Signature of surveyor	1		Le Date: 12/11/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

-			_	
C			n_{-}	rts
•	na	re	ra	ris

200	G 52 1707	0.000,000	
1/0	hicle	NIO	
VC	HICIE	INO.	

Make & Model:

Chassis No

SLS 8807 U

TOYOTA PRIUS JTDKB3FU403571911

Submit By

Year Manufacture

Carmen Lim

2017

Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	Bu	1	\$450.80		
2	Front bumper clip	Me	10	\$40.00		<u></u>
3	Front bumper side retainer LH	Dig	1	\$107.20		2
4	Front bumper emblem	Me	1	\$87.10		
5	LH front fender	B	1	\$868.70		_
6	LH front fender undershield	Sn	1	\$195.60		
7	LH front fender undershield clip	en	10	\$25.00		X
8	LHF fender wording "HYBRID"	N	i 1	\$44.1/16		
9	LH rear hub cab	A	1	\$195.65		
10						
11						
12						
13						
14						
15						
16						
17						
18						
19					***	
20						
21	2					
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour	L	a	b	0	u	1
--------	---	---	---	---	---	---

Vehicle No.	:	SLS 8807 U	Submit By	:	: Carmen Lim
Make & Model	: -	TOYOTA PRIUS	Year of Manufacture	:	2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,LHF FENDER)	\$600.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,LHF FENDER)	\$600.00	4001
3	To check wiring	\$50.00	15/
4	To do wheel alignment	\$150.00	601
5	To tuff coat	\$80.00	301

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.