

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG18020148/AEA3Q2  
**Date:** 13/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100285466
<b>Claimant Vehicle No :</b>	YM9301H	<b>Insured Vehicle No :</b>	SDA3305Z
Date of Loss:	22/10/2018	Nature of Claim:	TP
		Claim No:	9927324842SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YM9301H</b>		
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Engine No:	HIDDEN
Reg. Date:	01/09/2008 (Man. Year: 2008)	Chassis No:	JAANHR85E87100174
Colour:	Blue	Odometer:	226970 km
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16C	Rear Tyre Size:	185 R14C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,600.00	300.00	6,300.00	95.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,200.00	1,400.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>10,200.00</b>	<b>2,500.00</b>	<b>7,700.00</b>	<b>75.49</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		

**Nett Liability (S\$)****2,907.45**INSPECTION

Date of Assignment: 05/11/2018

Date Inspected: 05/11/2018

Estimated Period of Repair: 4.0 days

Inspected At:

Hua Meng Spray Painting Workshop (HQ)  
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit  
Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HYDRALIC CYLINDER	Not Necessary	3,800.00 FS	*- FS
2	1		*HYDRALIC FLUID	Necessary	300.00 FS	*300.00 FS
3	1		*REAR TOWING STRUCTURE	Repair	2,500.00 FS	*- FS
					<b>Total Parts (S\$)</b>	<b>6,600.00</b>
						<b>300.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REALIGN REAR TOWING STRUCTURE	New	2,500.00	1,600.00
2	SPRAY PAINTING	New	1,000.00	550.00
3	WIRING	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,600.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >